

Phase 2

Stream Geomorphic Assessment of City Stream and Bolles Brook *Woodford, VT*



FINAL REPORT *December 2007*

Prepared for:

Bennington County Conservation District

Prepared by:



GOMEZ AND SULLIVAN
Engineers, P.C.

Executive Summary

A Phase 2 Rapid Stream Assessment was conducted on City Stream and Bolles Brook in Woodford, VT, in September of 2007. Phase 2, the second of three phases of the Vermont Stream Geomorphic Assessment (SGA) protocols, is a detailed method for gathering scientifically sound information about a stream channel and its riparian corridor. Field observations and measurements conducted during the Phase 2 assessment help verify Phase 1 stream geomorphic data and provide more specific information about stream reaches of interest. The geomorphic and habitat assessments performed on City Stream and Bolles Brook provide a picture of the current condition of the streams, will help to identify erosion hazards and understand the changes that stream systems are undergoing, and can be used in watershed planning and protection efforts.

Bolles Brook and City Stream are part of the 156-square mile Walloomsac River drainage basin. Both are high-gradient streams originating from the Green Mountains in southern Vermont. City Stream originates from Woodford Lake (locally known as Big Pond) and flows along a mountaintop plateau before descending steeply from Woodford Mountain to meet Bolles Brook in Woodford Hollow. Bolles Brook originates in the Green Mountain National Forest, flowing through mostly forested, mountainous terrain followed by rural residential development before meeting up with City Stream in Woodford Hollow to form the Roaring Branch. The Roaring Branch flows through the towns of Woodford and Bennington and into the Walloomsac River.

The Phase 2 assessment was conducted on four of the seven reaches of City Stream and two of the three reaches of Bolles Brook, for a total of 5.13 river miles. The remaining reaches were not assessed because they were either impounded (S1.05 and S1.07), or high-gradient, A-type streams (S1.03 and T3.07). In general, Bolles Brook seems to be in slightly better geomorphic condition than City Stream. While all but two of the segments on City Stream have experienced a stream type departure, none of those on Bolles Brook have yet departed from their reference stream type. However, most of the segments on both City Stream and Bolles Brook were found to be in major adjustment (fair condition). Only the uppermost assessed reach of each stream—both braided systems—are in good condition. Most of City Stream—especially in the lower reaches—has lost some or all access to its floodplain through encroachment by Route 9, berms, and, to a lesser extent, development. Bolles Brook is also encroached by a road (Harbour Road), but it is a secondary gravel road and not considered to be the valley wall as Route 9 is for City Stream. The main issue for Bolles Brook is existing and new residential development, which has impacted the majority of the lower reach.

Habitat appears to be in slightly better condition on Bolles Brook as well, although it is suffering from the impact of development along the lower reach. City Stream also has fairly good habitat, but has more areas with sparsely vegetated road embankments and fragmented buffers.

Thirteen bridges and culverts on City Stream and Bolles Brook were assessed during Phase 2. Most of the structures were found to be in good condition with little potential to fail. About half of the structures act as a confinement to the stream or its ability to access its floodplains.

In addition to providing specific information about City Stream and Bolles Brook, the Phase 2 assessment of these two streams will enhance existing knowledge about the geomorphic condition of the entire Walloomsac River watershed. A Phase 2 SGA of the Walloomsac River and its tributary, Roaring Branch, in Bennington, VT was completed in 2006. Due to the active adjustment and erosion hazards observed in these streams, an expansion of scope upstream to include City Stream and Bolles Brook will help to develop a more effective and sustainable River Corridor Protection and Channel Management Plan.

Table of Contents

Executive Summary	i
List of Tables and Figures.....	iii
List of Acronyms and Abbreviations	iv
1.0 Project Background.....	1
1.1 Goals and Objectives	1
1.2 Fluvial Geomorphic Setting	1
1.3 Phase 2 Assessment Study Area	2
2.0 Methods.....	5
2.1 Field Assessment	5
2.2 Data Management	6
2.3 Data Interpretation	6
2.4 Quality Assurance	6
3.0 Results.....	17
3.1 Reach and Segment Descriptions.....	17
3.2 Summary of Reaches and Segments	24
3.2.1 Reach/Segment Condition.....	24
3.2.2 Stream Type Departure and Sensitivity	25
3.2.3 Fluvial Erosion Hazard Mapping.....	25
3.3 Bridge and Culvert Assessments.....	25
4.0 Conclusions and Recommendations	31
5.0 References.....	33

Appendix A: Cross-Section Diagrams

Appendix B: Summary of Stream Features and Impacts

Appendix C: Reach and Segment Impact Maps

Appendix D: Bridge and Culvert Descriptions

Appendix E: Bridge and Culvert Reports

Appendix F: Reach Assessment Photographs

Appendix G: Bridge and Culvert Assessment Photographs

Appendix H: Standard Phase 2 Database Output Reports

List of Tables and Figures

Table 2-1: Stream Impacts Documented with GPS During the Phase 2 Assessment	8
Table 2-2: Summary of Terms	9
Table 2-3: Quality Assurance Check of Field-Measured Bankfull Geometry	10
Table 2-4: Quality Assurance Comparison to VT Hydraulic Geometry Dataset	11
Table 3-1: Phase 1 Stream Characteristics	26
Table 3-2: Phase 2 Stream Characteristics	26
Table 3-3: Cross-Section Measurements	27
Table 3-4: Cross-Section Calculations	27
Table 3-5: Rapid Habitat Assessment (RHA) Results	28
Table 3-6: Rapid Geomorphic Assessment (RGA) Results	28
Table 3-7: Percent of Stream Segments Impacted by Stressors	29
Table 3-8: Fluvial Erosion Hazard (FEH) Ratings	29
Table 3-9: Bridge and Culvert Locations and Dimensions	30
Figure 1-1: Walloomsac River Watershed	3
Figure 1-2: City Stream and Bolles Brook Phase 2 Study Area	4
Figure 2-1: City Stream and Bolles Brook Phase 2 Assessment Reaches and Segments	12
Figure 2-2: Rosgen Stream Classification System (Rosgen, 1996)	13
Figure 2-3: F-Stage Channel Evolution Process (VT ANR, 2007)	14
Figure 2-4: Quality Assurance Comparison of Cross-Sectional Areas for City Stream	15
Figure 2-5: Quality Assurance Comparison of Cross-Sectional Areas for Bolles Brook	16

List of Acronyms and Abbreviations

ANR	Agency of Natural Resources
BCCD	Bennington County Conservation District
CEM	Channel Evolution Model
CR	Confinement Ratio
DEC	Department of Environmental Conservation
DMS	Data Management System
ER	Entrenchment Ratio
FEH	Fluvial Erosion Hazard
FIT	Feature Indexing Tool
ft	Feet
GIS	Geographic Information System
GPS	Global Positioning System
HEF	Human Elevated Floodplain
IR	Incision Ratio
mi	Miles
QA	Quality Assurance
Q ₂	Two-year peak flow
RAF	Recently Abandoned Floodplain
RGA	Rapid Geomorphic Assessment
RHA	Rapid Habitat Assessment
RMP	River Management Program
SGAT	Stream Geomorphic Assessment Tool
USGS	United States Geological Survey
W/D	Width/Depth
WQD	Water Quality Division
QA	Quality Assurance

1.0 Project Background

A Phase 2 Rapid Stream Assessment was conducted on City Stream and Bolles Brook in Woodford, VT, in September of 2007. Phase 2, the second of three phases of the Vermont Stream Geomorphic Assessment (SGA) protocols, is a detailed method for gathering scientifically sound information about a stream channel and its riparian corridor. The geomorphic and habitat assessments performed on City Stream and Bolles Brook will provide a picture of the current condition of the streams, will help to identify erosion hazards and understand the changes that stream systems are undergoing, and can be used in watershed planning and protection efforts.

1.1 Goals and Objectives

The Phase 2 assessment was conducted to collect geomorphic and habitat data on selected reaches of City Stream and Bolles Brook.

The objectives of the Phase 2 assessment were to:

- Collect geomorphic and habitat data according to Vermont's rapid assessment protocols;
- Interpret the data to determine dominant channel processes, channel type, condition, and sensitivity;
- Identify where and how the river channels are responding to historic and ongoing human modifications; and
- Assess bridges and culverts in the study area and determine impact on the stream.

The products of a Phase 2 Rapid Stream Assessment for each assessed reach include (VT ANR, 2007):

- An existing stream type determination;
- A geomorphic condition evaluation that includes:
 - o Reach condition,
 - o Channel adjustment process, and
 - o Reach sensitivity;
- A stream habitat assessment; and
- Field maps and photographs detailing the reach planform, typical condition, and assessed features.

1.2 Fluvial Geomorphic Setting

Bolles Brook and City Stream are part of the 156-square mile Walloomsac River drainage basin shown in Figure 1-1. Both are high-gradient streams originating from the Green Mountains in southern Vermont that converge in Woodford Hollow to form the Roaring Branch. Roaring Branch flows through the towns of Woodford and Bennington and into the Walloomsac River. The Walloomsac River flows generally northwest 16.4 miles to meet the Hoosic River in New York State.

City Stream originates from Woodford Lake, which is locally known as Big Pond. The stream flows along a mountaintop plateau before descending steeply from Woodford Mountain to meet Bolles Brook in Woodford Hollow. Bolles Brook originates in the Green Mountain National Forest, and flows steeply through forested terrain for most of its upper two reaches. In its lower reach its slope decreases and it flows through rural residential development before meeting up with City Stream in Woodford Hollow to form the Roaring Branch.

The assessment area is predominantly forested with some scattered residential areas. Beginning over 200 years ago, the watershed was cleared of its forests, which resulted in an increase in flooding, sediment loads, and erosion. In the 1930s, the Green Mountain National Forest was created, which allowed for more responsible forestry practices. After forests in the watershed were allowed to mature, the input of excess sediment and runoff to the stream system decreased.

Although City Stream and Bolles Brook flow through naturally unconfined valleys for the most part, roads, berms, development, and other encroachments built along these streams have reduced the amount of available floodplain, resulting in increased stream power. These changes in land use can have a direct bearing on the magnitude, duration, and timing of flow in the streams, and can significantly increase sediment loading as well. Often, anthropogenic influences such as increased urbanization, dam construction, culverts, bridges, etc. will impact the normal conveyance of flow and sediment in a river. These influences commonly throw the watershed inputs of flow and sediment out of balance, causing channel instability and uncontrolled down-cutting.

City Stream in particular is artificially confined along much of its length due to the encroachments of State Route 9 and several berms constructed along the lower reaches of the stream to protect the road and a few residential properties from flooding and erosion. City Stream appears to have been straightened in many areas to accommodate these encroachments. Such constraints have likely resulted in increased stream power and sediment transport. According to historical topographical maps of the area dated 1898, City Stream at that time was closely paralleled by the road that is now State Route 9, and Bolles Brook was encroached by both a rail grade and a secondary road. Over 100 years of anthropogenic confinement along these two streams has likely resulted in major stream adjustments throughout that time period.

1.3 Phase 2 Assessment Study Area

The Phase 1 assessment was conducted on seven reaches of City Stream and on three reaches of Bolles Brook (Figure 1-2). A sub-set of stream reaches were selected for the Phase 2 assessment. A total of four of the reaches assessed in Phase 1 were not assessed in Phase 2 for the following reasons:

- Reach M06T3.07 on Bolles Brook is a steep first-order stream that flows through the undeveloped Green Mountain Nation Forest;
- Reaches M06T3.05S1.07 and M06T3.05S1.05 on City Stream are artificially impounded areas, known as Woodford Lake and Bugbee Mill Pond, respectively; and
- Reach M06T3.05S1.03 on City Stream is very steep (>6%), and is narrowly confined by both State Route 9 on the river right side and the natural valley wall on the river left side.




Figure 1-1: Walloomsac River Watershed.




Figure 1-2: City Stream and Bolles Brook Phase 2 Study Area.

2.0 Methods

This study of the geomorphic characteristics of City Stream and Bolles Brook followed the methods presented in the Vermont Agency of Natural Resources' (VT ANR) Phase 2 Rapid Stream Geomorphic Assessment Field Protocols (VT ANR, 2007). Prior to conducting the Phase 2 field assessment, the data generated for the study area during the Phase 1 assessment were reviewed. Phase 1, the remote-sensing phase of the geomorphic assessment, was conducted by the Bennington County Conservation District (BCCD). The Phase 1 assessment involved the collection of data from topographic maps, aerial photographs, existing studies, and field reconnaissance (windshield surveys).

Phase 1 methods included selecting study streams, dividing streams into reaches of homogeneous geomorphic channel and valley characteristics, and evaluating geology, soils, land cover, reach hydrology, in-stream channel modifications, and floodplain modifications on each reach. The evaluation of these parameters allowed for the assignment of a numeric impact rating for each reach, and provisional reference stream types were established based on valley land forms and geology. Predictions of channel condition (departure from reference), adjustment process, and reach sensitivity were based on evaluations of watershed and river corridor land use as well as channel and floodplain modifications.

The Phase 1 assessment was conducted on the entire lengths of City Stream and Bolles Brook, totaling ten reaches (seven on City Stream and three on Bolles Brook). Of these, four reaches of City Stream and two reaches of Bolles Brook were selected for the Phase 2 assessment.

2.1 Field Assessment

Phase 1 reaches were divided into segments where appropriate to distinguish sections of the reaches having different reference and existing conditions. A segment has the same reference stream type as its reach but is distinct from other segments in the reach in one or more of the following parameters: grade controls, channel dimensions, substrate size, planform and slope, depositional features, corridor encroachments, banks and buffers, flow status, property access, valley width, or others. Different segments in a reach are labeled with capital letters (A, B, C...) suffixed to the reach number and assigned sequentially from downstream to upstream (VT ANR, 2007). Segments created during the Phase 2 assessment are shown in Figure 2-1. Reaches and segments not assessed in Phase 2 are shown in grey.

A total of 5.13 river miles on City Stream and Bolles Brook were assessed using Phase 2 protocols during September 2007. Field efforts consisted of identifying bankfull features and collecting field measurements of channel dimensions, stream impacts, bottom substrates, shoreline and riparian conditions, and floodplain encroachments and modifications. The measurements were collected to determine the existing stream type, condition, and sensitivity for each reach.

Each reach was traversed by a field crew of two or three persons. Each crew had a complete set of aerial photographs, topographic maps, and Phase 1 summary reports for each reach. Starting from the downstream end, reaches were covered on foot and the floodplain and terrace areas on each side of the river were examined. A field sketch was completed for each reach and representative photographs were taken.

Cross-section analyses were performed at representative locations within each reach/segment. A survey level, rod, and tape were used to obtain elevation and width measurements. Channel dimensions and ratios were derived from the cross-sections in order to verify (or modify, if needed) the stream type and bedform type classifications. The Phase 2 field work included a Rapid Habitat Assessment (RHA) and Rapid Geomorphic Assessment (RGA) for each stream reach and segment.

Bridges and culverts along both streams were also assessed. This involved visiting each stream crossing and collecting information in accordance with the methods outlined in Appendix G (Bridge and Culvert Assessment) of the Vermont ANR's Phase 2 handbook (VT ANR, 2007).

2.2 Data Management

Standard field forms from Appendix A (Phase 2 Field Forms) of the Vermont ANR's Phase 2 handbook were used to record field data (VT ANR, 2007). For each segment or reach, these forms included rapid stream assessment field notes, a tally sheet, a cross-section worksheet, a photo log, an RHA form, and an RGA form. Stream features and impacts were sketched on forms prepared prior to field mobilization that included an outline of surface water and the Phase 1 stream corridor for each reach at a scale of approximately 1:2500.

The field teams collected GPS data of the in-stream features consistent with the protocols. The feature types collected with GPS are listed in Table 2-1. Data were collected in the field using a Trimble Model Pro-XH high-resolution GPS backpack unit. The GPS data collected in the field were differentially corrected in the office to improve accuracy and then reviewed with ArcGIS software. These data could not be directly imported into the Stream Geomorphic Assessment Tool (SGAT). Rather, the data were uploaded to ArcView 3 and the features collected in the field were re-created within the SGAT extension.

All of the field forms were scanned and archived. Photographs were organized into separate appendices. The field data and cross-section plots were entered and uploaded into the Vermont ANR's online Data Management System (DMS).

2.3 Data Interpretation

The field assessment data were compiled and evaluated using methods detailed in the Vermont ANR's Phase 2 handbook (VT ANR, 2007). Parameters that were measured and calculated to define the stream channel geometry are described in Table 2-2. These parameters—particularly the entrenchment ratio (ER), the width/depth (W/D) ratio, and the Phase 1 parameter sinuosity—were used to determine an existing stream type for each assessed segment. Figure 2-2 provides the Rosgen stream channel classification system flow chart (Rosgen, 1996).

A Rapid Geomorphic Assessment (RGA) was completed to determine the geomorphic condition, major channel adjustment processes, and sensitivity of the stream. Stream condition is classified based on RGA scores as reference (0.85 – 1.0), good (0.65 – 0.84), fair (0.35 – 0.64), or poor (0.00 – 0.34). Per the protocols, stream segments can receive a condition descriptor outside the range of their score as long as justification is given. Channel adjustment processes include degradation, aggradation, widening, and planform adjustment—all of which can be noted as historic processes. Stream sensitivity is dependent on the existing stream type and whether the stream is in regime (reference or good condition), in major adjustment (fair condition), or has experienced a stream type departure (poor condition). All of these factors were considered to determine what stage (I-V) of the Channel Evolution Model (CEM) the stream is currently undergoing. Diagrams and descriptions of the five stages of the F-stage CEM is provided in Figure 2-3.

2.4 Quality Assurance

In order to ensure the collection of accurate and consistent data, users of the Vermont ANR Phase 2 Rapid Stream Geomorphic Assessment Field Protocols need to establish a quality assurance (QA) program for each phase of the assessment. The protocols outline three key components of quality assurance: training,

data review, and use of a data management system. Conducting a QA program at all levels of assessment ensures that data is accurate and complete.

The trained Field Coordinator was on-site during the entire Phase 2 field assessment. The Phase 2 data were first reviewed and interpreted by field assessors and then presented to River Management Program staff for their review and discussion. As a result of the QA review, field data sheets were adjusted at the direction of River Management Program staff. These adjustments resulted in several changes to the stream channel types, conditions, and sensitivities as originally interpreted by the consultant. Data were entered into the DMS and the automatic QA process was performed.

Because so many aspects of the Phase 2 assessment depend on accurate identification and measurement of bankfull features, bankfull elevations were checked by four methods. First, the cross-sectional area at each cross-section location was calculated (bankfull width times mean bankfull depth) and the areas were compared to make sure they decreased moving upstream (Table 2-3). Next, the drainage area and flow statistics were determined for each cross-section location using the U.S. Geological Survey (USGS) Vermont StreamStats basin delineation tool (USGS, 2007). Relative magnitudes of decrease in cross-sectional areas moving upstream were checked to see how well they corresponded with relative magnitudes of decrease in drainage areas and two-year peak flows (Table 2-3). Furthermore, the cross-sectional area for each location was predicted using the following Vermont regional hydraulic geometry curve, which has an R-squared value of 0.95 (VT ANR, 2006):

$$\text{Cross Sectional Area} = 12.38 \times (\text{Drainage Area})^{0.75}$$

The field-determined cross-sectional areas were compared to the predicted cross-sectional areas to make sure magnitudes (Table 2-3) and trends (Figures 2-4 and 2-5) were relatively similar. Finally, the drainage areas, bankfull widths, mean depths, and cross-sectional areas for each cross-section location were compared to those of reference streams contained in the Vermont hydraulic geometry dataset as shown in Table 2-4 (VT ANR, 2006). Based upon this thorough analysis, slight (less than half a foot) changes were made to the bankfull elevation of four segments. Bankfull elevation was raised slightly for segments S1.01B, S1.02A, and S1.04B, and lowered slightly for segment T3.05B. Corresponding changes in channel dimensions, calculated ratios, etc. were made and checked with River Management Program staff.

Table 2-1: Stream Impacts Documented with GPS During the Phase 2 Assessment.

	Impact	Sub-Impact
Point Features	Alluvial Fan	N/A
	Grade Control	Dam
		Ledge
		Waterfall
		Weir
	Mass Failure	N/A
	Dredging	Dredging
		Gravel Mining
		Commercial Mining
	Debris Jam	N/A
	Stormwater Input	N/A
	Beaver Dam	N/A
	Migration	Neck Cut-off
		Flood Chute
		Avulsion
		Braiding
	Head Cut or Steep Riffle	Head Cut
		Steep Riffle
	Stream Crossing	Stream Ford
		Animal Crossing
	Flow Regulation and Water Withdrawal	Drinking
		Irrigation
		Snow Making
		Bypass
	Gully	N/A
	Bridge or Culvert	N/A
	Constriction	N/A
	Segment Break	N/A
	Cross Section Location	N/A
Line Features	Development	N/A
	Encroachment	Berm
		Improved Path
		Road
		Railroad
	Bank Armoring and Revetment	Rip-Rap
		Hard Bank
		Other
	Erosion	N/A
	Straightening	Straightening
		With Windrowing

Table 2-2: Summary of Terms.

Term	Definition
Bankfull Discharge	The stream discharge corresponding to the water stage that first overtops the natural banks onto the active floodplain, occurring on average about once every one to two years
Bankfull Width	The top surface width of a stream channel when flowing at bankfull discharge
Bankfull Mean Depth	The mean depth of a channel within a riffle segment when flowing at bankfull discharge
Bankfull Max Depth	The maximum depth of a channel within a riffle segment when flowing at bankfull discharge
Floodprone Width	The width of a stream when flooded to an elevation twice the maximum depth of the bankfull channel
Recently Abandoned Floodplain (RAF)	The height of the lowest floodplain feature a stream had access to within the past 200 years, but has lost access to at bankfull stage
Human-Elevated Floodplain (HEF)	The height of a feature such as a railroad, road, berm, levee, or improved path that is higher than and blocks access to the RAF
Width/Depth (W/D) Ratio	The bankfull width divided by mean the bankfull mean depth
Entrenchment Ratio (ER)	The width of the floodprone area divided by the bankfull width
Incision Ratio (IR)	The RAF height divided by the bankfull maximum depth

Table 2-3: Quality Assurance Check of Field-Measured Bankfull Geometry.

Stream	Segment ID	Width (ft)	Mean Depth (ft)	Cross-Sectional Area (ft ²)	Drainage Area (mi ²)*	Two-Year Peak Flow, Q ₂ (ft ³ /s)*	Predicted Cross-Sectional Area (ft)**
City Stream	M06T3.05S1.01A	62	1.98	122.6	17.60	589.0	106.4
	M06T3.05S1.01B	57	2.11	119.6	17.00	568.0	103.6
	M06T3.05S1.01C	54	2.19	118.5	16.70	557.0	102.3
	M06T3.05S1.02A	61	1.70	103.1	15.70	522.0	97.6
	M06T3.05S1.02B	52	1.97	102.6	15.50	515.0	96.7
	M06T3.05S1.04B	23	0.89	20.8	2.76	90.9	26.5
	M06T3.05S1.04D	16	1.09	17.5	2.31	74.9	23.2
	M06T3.05S1.06	16	0.95	15.5	1.34	42.2	15.4
Bolles Brook	M06T3.05A	48	2.18	104.8	19.40	763.0	114.4
	M06T3.05B	56	1.87	103.8	19.30	759.0	114.0
	M06T3.05C	32	2.62	83.8	18.10	716.0	108.6
	M06T3.06	29	1.76	51.2	8.66	365.0	62.5

Values in italics were adjusted slightly during the QA.

**Determined using USGS VT StreamStats (USGS, 2007).*

***Calculated based on drainage area using VT hydraulic geometry curve (VT ANR, 2006).*

Table 2-4: Quality Assurance Comparison to VT Hydraulic Geometry Dataset.

Reference Stream or Segment ID	Drainage Area (mi²)	Cross-Sectional Area (ft²)	Width (ft)	Mean Depth (ft)
M06T3.05S1.06	1.34	15.5	16	0.95
M06T3.05S1.04D	2.31	17.5	16	1.09
M06T3.05S1.04B	2.76	20.8	23	0.89
Sucker Brook	3	27.5	22	1.25
Deerfield	5	57.6	32	1.80
M06T3.06	8.66	51.2	29	1.76
East Orange Br.	9	53.2	28	1.90
W. Br. Battenkill	13	63.2	40	1.58
M06T3.05S1.02B	15.50	102.6	52	1.97
M06T3.05S1.02A	15.70	103.1	61	1.70
M06T3.05S1.01C	16.70	118.5	54	2.19
M06T3.05S1.01B	17.00	119.6	57	2.11
M06T3.05S1.01A	17.60	122.6	62	1.98
M06T3.05C	18.10	83.8	32	2.62
M06T3.05B	19.30	103.8	56	1.87
M06T3.05A	19.40	104.8	48	2.18
Ottaquechee	23.0	201.6	63	3.2

This table shows how closely the bankfull measurements taken at each cross-section correlate with bankfull geometry of streams with similar drainage areas in the Vermont hydraulic geometry dataset (VT ANR, 2006).




Figure 2-1: City Stream and Bolles Brook Phase 2 Assessment Reaches and Segments.




Figure 2-2: Rosgen Stream Classification System (Rosgen, 1996).




Figure 2-3: F-Stage Channel Evolution Process (VT ANR, 2007).




Figure 2-4: Quality Assurance Comparison of Cross-Sectional Areas for City Stream.




Figure 2-5: Quality Assurance Comparison of Cross-Sectional Areas for Bolles Brook.

3.0 Results

Reference stream types and other characteristics determined during the Phase 1 assessment for each assessed reach are given in Table 3-1 (data that was modified during QA of Phase 2 data is marked with an asterisk). The field-verified existing stream types and other characteristics determined during the Phase 2 assessment for each assessed segment are given in Table 3-2. Tables 3-3 and 3-4 show the measurements and associated calculations obtained from the cross-section analysis of each segment. Table 3-5 shows the results of the Rapid Habitat Assessment for each segment, and Table 3-6 shows the results of the Rapid Geomorphic Assessment (including stream type departures, adjustment processes, and sensitivity ratings). The percent of each segment's length affected by the stressors of berms, roads, development, and straightening is given in Table 3-7. Table 3-8 shows the Fluvial Erosion Hazard (FEH) ratings determined for each segment.

Cross-section diagrams produced from elevation data for each segment are provided in Appendix A. Each diagram depicts the approximate elevation of the bed/bank surface, current water surface, bankfull height, and floodprone height, as well as the location of the valley walls and any other prominent features. Appendix B presents a summary of all stream impacts and features recorded by the Feature Indexing Tool (FIT) for each segment. Appendix C contains maps of each reach or segment showing the locations of these impacts and features. A detailed description of each bridge and culvert is provided in Appendix D. Reports produced by the DMS concerning failure modes and problem conditions for the bridges and culverts assessed during Phase 2 are given in Appendix E. Appendices F and G contain field photographs taken during the reach assessments and the bridge and culvert assessments, respectively. Standard Phase 2 database output reports from the DMS are included in Appendix H.

A description of each reach and segment evaluated during the Phase 2 assessment is presented below. Note that left and right banks are always identified facing downstream. Also note that all channel evolution stages were identified by the F-stage Channel Evolution Model (CEM). Field data, cross-section plots, and spatially referenced stream features are also accessible online through the DMS.

3.1 Reach and Segment Descriptions

City Stream

M06T3.05S1.01A



Segment M06T3.05S1.01A (S1.01A) of City Stream is a reference C3b step-pool stream that has degraded to a type B3. It is semi-confined (CR=3.7) in its valley, which is generally defined by a steep mountainside on the right and Route 9 on the left. The segment is approximately 2,377 feet long and has a slope of about 2.5%. Encroachments such as berms, roads, and development impact much of its length (52%, 28%, and 35%, respectively). Berms in this segment are generally engineered structures reinforced with concrete and rock slab facing. A few braided areas and flood chutes are present. Both a head cut and a steep riffle (slightly downstream) were observed in the field. The segment is moderately entrenched (ER=1.61) with a high width/depth ratio (W/D=31.3). The incision ratio (IR) based on the recently abandoned floodplain (RAF) is 2.39, but the presence of a berm leads to a human-elevated floodplain (HEF) IR of 3.98. Banks and buffers are relatively well-vegetated with mixed trees and saplings. The segment received an RHA rating of “good” and an RGA rating of “fair.” Because the stream has lost access to the majority of its floodplain, through both bed degradation and floodplain build-up in the form of berms, but is starting to widen, it was

determined to be in Stage III of the CEM. The major adjustment process is degradation. Due to the stream type departure (from C to B), the stream sensitivity is high.

M06T3.05S1.01B




Segment M06T3.05S1.01B (S1.01B) of City Stream is a reference C3b step-pool stream that has degraded to a type F3. The segment is approximately 1,346 feet long and has a slope of about 1.5%. It was segmented from Segment A because its entire length appears to be straightened, and it is narrowly confined (CR=1.4) by a steep mountainside on the right and Route 9 on the left. The left bank, which is essentially the road embankment, is eroded in areas and reinforced with rip-rap in others. A head cut and a bedrock constriction were observed in the field. This segment is entrenched (ER=1.15) with a high W/D ratio (26.9). The IR, based on an RAF at the top of the left bank, is 2.40. The right bank is relatively well-vegetated with mixed trees and saplings, whereas the left bank consists mainly of herbaceous and shrub/sapling vegetation. The segment received an RHA rating of “good.” The RGA condition was modified from “fair” to “poor” due to a stream type departure from C to F. Because the stream has lost access to the majority of its floodplain through bed degradation and floodplain build-up (berms), but is starting to widen, it was determined to be in Stage III of the CEM. The major adjustment processes are degradation and widening, and the stream is extremely sensitive.

M06T3.05S1.01C



Segment M06T3.05S1.01C (S1.01C) of City Stream is a reference C3b step-pool stream that has degraded to a type B3. It is approximately 3,924 feet long and has a slope of about 3.1%. It was segmented because its valley, although narrow (CR=4.4), is relatively wider than that of Segment B and is only encroached by the road for approximately half (45%) of its length. The left bank and buffer vegetation is also more developed, with mixed trees and shrubs/saplings. Similar to Segment A, this segment is characterized by berms on the left side, and even has a section with a double berm (one on the bank and one set back 50-150 feet). The cross-section for the segment was taken through the double berm to capture this representative feature. The valley is defined by Route 9 on the left and the steep mountainside (which is sometimes set back from the bank up to 100 feet due to RAFs or terraces) on the right. There are several sections of erosion on both banks, and a small mass failure on the right. The left bank is reinforced with rip-rap near the downstream and upstream edges of the segment (where the road is closest to the stream). A steep riffle, flood chute, and several stormwater inputs were also observed. The segment is moderately entrenched (ER=1.64) and has a moderate W/D ratio (24.6). The IR based on the RAF behind the first berm is 1.39, but the presence of the berm leads to a human-elevated IR of 4.19. The segment received an RHA rating of “good” and an RGA rating of “fair.” The major adjustment processes are degradation, widening, and planform adjustment. Due to the stream type departure from C to B, the stream sensitivity is high. Because the stream has lost access to the majority of its floodplain through bed degradation and floodplain build-up (berms), but is starting to widen and adjust planform as well, it was determined to be in Stage III of the CEM.


M06T3.05S1.02A



Segment M06T3.05S1.02A (S1.02A) of City Stream is a reference B2 step-pool stream that has degraded to a type F3. The segment is approximately 1,073 feet long and has a slope of about 1.9%. It is narrowly confined (CR=1.2) in its artificial valley of steep, high (>20 feet) road embankments on both sides—Route 9 on the right and Notch Road (old Route 9) on the left. The embankments are reinforced with rip-rap for much of the segment, particularly under/near the Route 9 bridge and on the right bank upstream of the bridge. The bank and buffer vegetation is therefore sparse and of the herbaceous and shrub/sapling type. The segment is entrenched

(ER=1.12) with a high W/D ratio (35.6). Since both banks are over 20 feet high, the stream has no RAF, so the IR of 7.50 (based on the elevation of Notch Road) is human-elevated. The segment received a rating of “fair” for both the RHA and the RGA. Due to the stream type departure, the stream sensitivity is extreme. Because the stream is entrenched and over-widened due to historic floodplain filling, but is beginning to show signs of attempting to regain equilibrium by rebuilding a floodplain within the constraints of the two road embankments, it was determined to be between Stages III and IV of the CEM. The major adjustment processes are aggradation and widening, after historic degradation.

M06T3.05S1.02B



Segment M06T3.05S1.02B (S1.02B) of City Stream is a reference B2 step-pool stream that was classified during Phase 2 as a type B3a. It is slightly more entrenched (ER=1.21) than typical B-type stream, but its ER is within the allowance of ± 0.2 units (Rosgen, 1996). The segment could also have been classified as a type F, but its high slope (4.4%) is not characteristic of F-type streams. This relatively short segment (899 feet) was separated from Segment A due to a sharp change in slope and a shift to significantly coarser bed material (see Photo #100_1013). Also, although its valley is narrow (CR=5.1), this


segment is unconfined. Moving upstream from Segment A to Segment B, the river left valley wall crosses to the far side of Notch Road, and the river right valley wall veers 50-100 feet away from the bank to accommodate a small floodplain. The upstream reach break is marked by the entrance of Stamford Stream, which is actually the larger stream at the confluence. Stamford Stream seems to provide more influence on the downstream system, with its larger flow and sediment inputs. The banks and buffers on both sides of the stream are fairly well vegetated with mixed trees and shrubs/saplings, although the left bank is badly eroded along most of the upper half of the segment, and there is a small section of right bank erosion near the top of the segment as well. The W/D ratio is moderately high (26.4). The IR, based on the river right RAF, is 1.84. The segment is in good RHA condition and fair RGA condition. Because the stream has lost access to some of its floodplain due to degradation and historic floodplain filling, it was determined to be in Stage II of the CEM. The major adjustment process is degradation, and the stream sensitivity is high.

M06T3.05S1.03



Reach M06T3.05S1.03 (S1.03) of City Stream was not assessed because it is very steep ($>6\%$), and is narrowly confined by both State Route 9 on the right and the natural valley wall on the left.

M06T3.05S1.04A



Segment M06T3.05S1.04A (S1.04A) of City Stream was not assessed during Phase 2 because it is a bedrock gorge. Several bedrock constrictions, ledges, and waterfalls were observed along its relatively short length.

M06T3.05S1.04B



Segment M06T3.05S1.04B (S1.04B) of City Stream is distinguished from Segment A (a bedrock gorge) by a marked decrease in slope (to approximately 0.9%), an opening of the canopy and transition from mixed forest to herbaceous vegetation, and a shift in bed material from bedrock and boulders to gravel, sand, and silt. The reference stream type for the reach is C4 riffle-pool, but this segment has degraded to a type F4. The segment is approximately 1,112 feet long. Its valley is very broad ($CR=43.3$), and is defined by Route 9 on the right and the natural and artificial grades of Prospect Mountain ski area on the left.

The W/D ratio is relatively high (26.2). The upper limit of the segment is marked by a large beaver dam, which impounds the entirety of Segment C (Note: The aerial imagery depicts a distinct channel and separate pond in Segment C, but these have combined to form one large wetland/impoundment area and no distinct channel exists). The downstream end of the channel is nearly featureless, but a system of riffles, pools, and runs forms farther upstream. A steep riffle and a series of ledges are present near the top of the segment. The left bank is generally steep with shrub/sapling vegetation, while the right bank is a flat floodplain/wetland area with herbaceous vegetation. The stream was classified as entrenched ($ER=1.30$) because the floodprone height did not quite reach the elevation of the floodplain. This is likely due to a major adjustment process of degradation, and a CEM Stage of II. The IR based on this RAF elevation is 2.01. Due to the stream type departure, the stream sensitivity is extreme. The segment received a fair RGA rating and a good RHA rating.

M06T3.05S1.04C



Segment M06T3.05S1.04C (S1.04C) of City Stream was not assessed because it is an impoundment formed by a beaver dam at the segment break between Segments B and C. Note that although the aerial imagery depicts a distinct channel and pond in Segment C, these features have merged to form one large wetland/impoundment area and no distinct channel exists.

M06T3.05S1.04D



Segment M06T3.05S1.04D (S1.04D) of City Stream was segmented because Segment C is an impoundment that was not assessed. The reference stream type for the reach is C4 riffle-pool, but this segment has degraded to a type F4. The segment is approximately 1,957 feet long with a slope of about 0.8%. Its valley is very broad (CR=64.3), and is defined by Route 9 on the right and the natural and artificial grades of Greenwood Campground on the left. The W/D ratio is low (14.6). Recent beaver activity near bottom of the segment has resulted in a dam and small impoundment about 165 feet from the culvert. The

upper limit of the segment is marked by the dam that impounds Bugbee Mill Pond (reach S1.05). The majority of the channel is nearly featureless, but a system of riffles, pools, and runs forms near the top of the segment. In this upper section, a gravel storage lot with piles of sand, stone, and other materials on the right bank and a newly cut dirt road just off the left bank are likely contributing to the numerous fine sediment deposits found in the channel nearby and further downstream. Vertical banks on both sides flatten out to a wide floodplain covered with meadow-type herbaceous and shrub vegetation. However, the stream was classified as entrenched (ER=1.33) because the floodprone height did not quite reach the elevation of the floodplain. This is likely due to a major adjustment process of degradation, and a CEM Stage of II. The IR based on this RAF elevation is 2.26. Due to the stream type departure, the stream sensitivity is extreme. The segment received a fair RGA rating and a good RHA rating.

M06T3.05S1.05



Reach M06T3.05S1.05 (S1.05) of City Stream was not assessed because it is an impoundment known as Bugbee Mill Pond.

M06T3.05S1.06



Reach M06T3.05S1.06 (S1.06) of City Stream is a reference D4b braided stream that was field-verified to be a type D4b. While the majority of the reach is braided, its upper portion where the stream is close to Route 9 has been channelized and straightened. The stream passes through a culvert and two bridges in this upper section. The valley is very broad (CR=43.3), and is generally defined by Route 9 on the right and natural slopes on the left. The reach is approximately 2,260 feet long and has a slope of about 3.3%. The downstream end of the reach begins in the wetland complex above Bugbee Mill Pond, and

a small dam on a private pond marks the upstream end. Route 9 and patches of development encroach 21% and 14% of the river corridor, respectively. Both stream banks along the majority of the reach are heavily buffered with shrub/sapling vegetation, although larger trees are dominant towards the middle of the reach and near the cross-section. Snags, debris jams, and large woody debris were prevalent. A steep riffle, ledges, and flood chutes were also observed. Old stone fences/bridge abutments/dams have constricted and impacted the stream in two locations. The stream generally has access to a floodplain on one or both sides of the stream, with the exception of the channelized upper section. The reach is moderately entrenched (ER=2.13) with a moderate W/D ratio (17.1). The IR is 1.60. The reach received RHA and RGA ratings of “good.” The reach was determined to be in Stage IV of the CEM, and is mostly adjusting in planform. The stream sensitivity is extreme, which is typical for braided stream types in any condition.

M06T3.05S1.07

Reach M06T3.05S1.07 (S1.07) of City Stream was not assessed because it is an impoundment named Woodford Lake, locally known as Big Pond.

Bolles Brook

M06T3.05A



Data collected along Segment M06T3.05A (T3.05A) of Bolles Brook indicated that this segment is a reference and existing B3 step-pool type stream. However, the segment has been exposed to new development (four new buildings and a large addition have been built within the river corridor since the aerial photographs were taken), which now encroaches 87% of the segment. In several of the developed areas, the buffer is less than 25 feet. The stream is also encroached by Harbour Road, which is gravel, for 43% of the segment. As a result of these encroachments and the associated loss of bank and buffer vegetation, erosion, scour, and mass failures were observed

along much of the banks. Two head cuts and a flood chute are also present. The segment is approximately 2,043 feet long with a slope of about 2.0%. Its natural valley is broad (CR=9.3) but, even though Harbour Road is not a truly confining feature, it will certainly continue to have a confining effect on the stream as long as it is maintained. The valley is defined by steep mountainsides (behind Harbour Road on the left and on the bank or within one bankfull width on the right). This segment is moderately entrenched (ER=1.80) with a moderate W/D ratio (22.0). The IR, based on the river left top of bank, is 2.38. Bank and buffer vegetation, where present, is mostly shrub/sapling or mixed trees. There are several mowed lawn areas where the buffer is less than 25 feet. Therefore, the RHA score of 0.65 was adjusted from “good” to “fair.” The RGA score is also “fair.” Because the stream has lost access to the

majority of its floodplain through bed degradation and floodplain build-up (development), but is starting to widen, it was determined to be in Stage III of the CEM. The stream sensitivity is high.

M06T3.05B



Segment M06T3.05B (T3.05B) of Bolles Brook is a reference B3 step-pool stream that was found to be a B3c. It was segmented from Segment A because it is less encroached by development and has more floodplain access. The stream is still encroached by Harbour Road, for 74% of this segment. The segment is approximately 2,242 feet long with a slope of about 1.8%. Its natural valley is broad (CR=9.6) but, even though Harbour Road is not a truly confining feature, it will certainly continue to have a confining effect on the stream as long as it is maintained. The valley is defined by the mountain slope behind Harbour Road and the residential development on the right, and by a steep bedrock wall and high terrace near the bank on the left. An old railroad grade is present on top of the high terrace on the left. The left bank is a relatively flat or slightly sloping floodplain up to Harbour Road, but the stream has lost access to most of this feature. The IR based on this feature is 1.80. The stream is moderately entrenched (ER=1.57) with a high W/D ratio (29.7). Three steep riffles, two flood chutes and a braided area were observed. Old concrete slabs found along the bank and broken in the channel near the middle of the segment are causing left bank erosion and creating a grade control. More old concrete slabs (possibly from an old bridge) under the Harbour Road bridge in this segment are also creating a grade control and causing downstream deposition. Mixed trees and saplings cover both banks fairly well. The segment received an RHA score of “good” and an RGA score of “fair.” Because the stream has lost access to the majority of its floodplain, but has widened and is reworking through aggradation, it was determined to be in Stage IV of the CEM, with the major adjustment processes being widening and aggradation. The stream sensitivity is high.

M06T3.05C



Segment M06T3.05C (T3.05C) of Bolles Brook is a reference B3 step-pool stream that was also found to be a B3c. It was segmented from Segment B because it is highly channelized, has less adequate bank/buffer vegetation, and is closely encroached by development and Harbour Road for its entire length. The segment is approximately 1,163 feet long with a slope of about 1.7%. Its natural valley is very broad (CR=14.3) but, even though Harbour Road is not a truly confining feature, it will certainly continue to have a confining effect on the stream as long as it is maintained. The valley is defined by a mountain slope behind Harbour Road and the residential development on the right, and by a steep mountainside that angles in to meet the stream at a bedrock wall near the top of the segment on the left. The stream has lost access to most of its floodplain due to residential and road fill, as well as natural bedrock. The human-elevated IR based on the right top of bank is 2.89. The stream is moderately entrenched (ER=1.85) with the lowest W/D ratio (12.2) of all the segments assessed. Near the top of the segment, just below the bridge, is a small dam and water withdrawal that supplies the town with drinking water. The small impoundment between the dam and the bridge was recently dredged in September. The right bank of this segment is steep, high, and armored with rip-rap for about half of its length. The left bank is flatter towards the bottom of the segment, but becomes a bedrock wall towards the top. Bank and buffer vegetation is mostly shrub/sapling, with more herbaceous vegetation on the right. Near the top of the segment, there is no vegetation on the rip-rapped bank, and the only buffer between the bank and the road is a mowed lawn. Because of this, the RHA score of 0.65 was adjusted from “good” to “fair.” The RGA score was also “fair.” Because the stream has lost access to the majority of its floodplain through

residential and road fill, it was determined to be in Stage II of the CEM, with the major adjustment process being degradation. The stream sensitivity is high.

M06T3.06



Reach M06T3.06 (T3.06) of Bolles Brook is a reference D3b braided stream that was field-verified to have the same existing stream type. It is approximately 5,734 feet long with a slope of about 3.4%. Its natural valley is very broad (CR=16.4), and it is only encroached by Harbour Road for 34% of its length. The valley is defined by steep mountain slopes on both sides. This reach is extensively braided, with multiple active channels as well as flood chutes and abandoned channels crisscrossing the floodplain along most of its length. Only two small areas of erosion were observed. A short section of an old berm or railroad grade was found between the left bank and Harbour Road. The cross-section was taken near the top of the reach, where there is one channel with flowing water, an adjacent stagnant channel that is currently blocked by a debris jam, and two abandoned channels or seepage channels on the right floodplain. At this location, the ER was 3.96 and the W/D ratio was 16.4. The IR, based on an RAF on top of the right bank, is 1.98. Both corridors are heavily forested for most of this reach. The reach received RHA and RGA ratings of “good.” The reach was determined to be in Stage IV of the CEM, and is mostly adjusting in planform. The stream sensitivity is extreme.

M06T3.07



Reach M06T3.07 (T3.07) of Bolles Brook was not assessed because it is a steep first-order stream that flows through the undeveloped Green Mountain Nation Forest.

3.2 Summary of Reaches and Segments

3.2.1 Reach/Segment Condition

The majority of the reaches and segments assessed were found to be in good habitat condition. This was generally due to a mix of unembedded substrates and relatively well-vegetated banks and buffers. Three segments received fair RHA ratings because of a lack of adequate bank/buffer vegetation due to rip-rap armoring (S1.02A and T3.05C) or development (T3.05A). Table 3.5 gives a summary of the RHA results for each segment.

The geomorphic condition of the streams was not as good. Most of the segments were found to be in major adjustment (fair condition). This was often due to high incision and/or entrenchment, scoured or eroding banks, evidence of straightening and/or dredging, and human-caused changes in channel confinement and/or valley type. The uppermost assessed reaches on both streams (S1.06 on City Stream and T3.06 on Bolles Brook), which were both braided systems, lacked most of these impacts and were found to be in good geomorphic condition. The RGA rating for S1.01B was adjusted from “fair” to

“poor” due to the segment’s narrow confinement, eroding banks, and stream type departure from C to F. Table 3-6 gives a summary of the RGA results for each segment.

3.2.2 Stream Type Departure and Sensitivity

All but two of the segments on City Stream have experienced a stream type departure, whereas none of those on Bolles Brook have yet departed from their reference stream types. Segment S1.02B of City Stream has not quite departed from its reference type of B, but is very close to becoming an F-type like the segment downstream of it. Reach S1.06 is mostly in its reference braided condition, although it has been straightened and channelized towards the top.

Stream sensitivity is either high or extreme on all assessed segments and reaches. Segments classified as extremely sensitive include S1.01B, S1.02A, S1.04B, S1.04D, and the two braided reaches—S1.06 and T3.06. The rest of the segments, which are all B-type streams, are classified as highly sensitive. Table 3-6 gives a summary of the stream type departures and sensitivities for each segment.

3.2.3 Fluvial Erosion Hazard Mapping

Using the stream sensitivity ratings based on stream type and RGA score, a fluvial erosion hazard (FEH) rating has been proposed for each stream segment in Table 3-8. Fluvial erosion hazard types are derived from six stream sensitivity ratings using two letter descriptors (VL=Very Low; LW=Low; MD=Moderate; HI=High; VH=Very High; and EX=Extreme). The stream sensitivity rating provides a basis for fluvial erosion hazard classification because major vertical or lateral channel adjustments are known to result in extensive erosion of adjacent lands causing damage to private property and public infrastructure (VT ANR, 2005).

FEH ratings for City Stream and Bolles Brook ranged from HI 5 to EX 10. The braided upper reaches of City Stream and Bolles Brook received the highest ratings (EX 10), whereas the B-type streams received the lower ratings (HI 5). These stream sensitivity and FEH ratings can be used to further assess fluvial erosion hazard types and develop an FEH river corridor based on belts widths, valley confinement, and sensitivity characteristics with guidance from the Vermont River Management Program.

3.3 Bridge and Culvert Assessments

Each bridge, culvert, and arch along City Stream and Bolles Brook was assessed according to Phase 2 protocols outlined in Appendix G (Bridge and Culvert Assessment) of the Vermont ANR’s Phase 2 handbook (VT ANR, 2007). A summary of the structure locations, types, and dimensions are given in Table 3-9. A detailed description of each bridge is given in Appendix D. Failure mode and problem condition reports produced by the DMS are provided in Appendix E. Photographs of the inlet, outlet, upstream, and downstream views of each structure are contained in Appendix G.

According to the reports, the major potential failure modes affecting over half of the structures (all on City Stream) are out-flanking and ice or debris jam. Scour and erosion are also concerns to a lesser extent. Existing problems include upstream and downstream scour/erosion, poor location and alignment, and—most frequently—floodplain filled entirely or partially by roadway approaches. Problem conditions affecting the structures are: failing bank armoring (driveway bridge off City Stream Road and Route 9 culvert), higher downstream banks (third bridge Harbour Road bridge), sharp stream approach angle (Route 9 bridge and driveway bridge off City Stream Road), location at a significant valley break (first Harbour Road bridge), and potential avulsion following road (Route 9 bridge, second Harbour Road bridge, and National Forest bridge).

Table 3-1: Phase 1 Stream Characteristics.

Stream	Reach ID	Channel Length (ft)	Channel Slope	Valley Width (ft)	Confinement Type	Sinuosity	Stream Type	Bedform
City Stream	M06T3.05S1.01	7647	2.88%*	184*	Narrow	1.06	C3b*	Step-Pool
	M06T3.05S1.02	1972	3.80%	170*	Semi-Confined*	1.05	B2	Step-Pool
	M06T3.05S1.03**	10443	6.18%	NE	Narrowly Confined	1.03	A2	Step-Pool
	M06T3.05S1.04	4032	1.76%	1021*	Very Broad	1.12	C4	Riffle-Pool
	M06T3.05S1.06	2260	3.32%	705*	Very Broad	1.14	D4b*	Braided*
Bolles Brook	M06T3.05	5448	2.57%*	479*	Broad*	1.03	B3*	Step-Pool
	M06T3.06	5734	3.40%	476*	Very Broad*	1.11	D3b*	Braided*
	M06T3.07**	25432	6.02%	NE	Narrowly Confined	1.05	A	NE

*Modified during Phase 2 QA. **Reach not assessed in Phase 2.

Table 3-2: Phase 2 Stream Characteristics.

Stream	Segment ID	Channel Length (ft)	Channel Slope	Confinement Type	Stream Type	Bedform
City Stream	M06T3.05S1.01A	2377	2.5%	Semi-Confined	B3	Step-Pool
	M06T3.05S1.01B	1346	1.5%	Narrowly Confined	F3	Step-Pool
	M06T3.05S1.01C	3924	3.1%	Narrow	B3	Step-Pool
	M06T3.05S1.02A	1073	1.9%	Narrowly Confined	F3	Step-Pool
	M06T3.05S1.02B	899	4.4%	Narrow	B3a	Step-Pool
	M06T3.05S1.04B	1112	0.9%	Very Broad	F4	Riffle-Pool
	M06T3.05S1.04D	1957	0.8%	Very Broad	F4	Plane Bed
	M06T3.05S1.06	2260	3.3%	Very Broad	D4b	Braided
Bolles Brook	M06T3.05A	2042	2.0%	Broad	B3	Step-Pool
	M06T3.05B	2242	1.8%	Broad	B3c	Step-Pool
	M06T3.05C	1163	1.7%	Very Broad	B3c	Step-Pool
	M06T3.06	5734	3.4%	Very Broad	D3b	Braided

Table 3-3: Cross-Section Measurements.

Stream	Segment ID	Bankfull Width (ft)	Floodprone Width (ft)	Valley Width (ft)	Max Depth (ft)	Mean Depth (ft)	RAF Height (ft)
City Stream	M06T3.05S1.01A	62	100	230	2.92	1.98	6.97
	M06T3.05S1.01B	57	65	82	3.07	2.11	7.36
	M06T3.05S1.01C	54	89	240	3.25	2.19	4.51
	M06T3.05S1.02A	61	68	72	2.94	1.70	22.06
	M06T3.05S1.02B	52	63	267	3.35	1.97	6.16
	M06T3.05S1.04B	23	30	1013	1.74	0.89	3.49
	M06T3.05S1.04D	16	21	1028	1.43	1.09	3.23
	M06T3.05S1.06	16	35	705	1.39	0.95	2.22
Bolles Brook	M06T3.05A	48	87	445	3.00	2.18	7.13
	M06T3.05B	56	87	535	2.88	1.87	5.18
	M06T3.05C	32	59	457	4.22	2.62	12.20
	M06T3.06	29	115	476	2.80	1.76	5.55

Table 3-4: Cross-Section Calculations.

Stream	Segment ID	Confinement Ratio	Entrenchment Ratio	Width/Depth Ratio	Incision Ratio	
					RAF	HEF
City Stream	M06T3.05S1.01A	3.7	1.61	31.3	2.39	3.98
	M06T3.05S1.01B	1.4	1.15	26.9	2.40	N/A
	M06T3.05S1.01C	4.4	1.64	24.6	1.39	4.19
	M06T3.05S1.02A	1.2	1.12	35.6	N/A	7.50
	M06T3.05S1.02B	5.1	1.21	26.4	1.84	N/A
	M06T3.05S1.04B	43.3	1.30	26.2	2.01	N/A
	M06T3.05S1.04D	64.3	1.33	14.6	2.26	N/A
	M06T3.05S1.06	43.3	2.13	17.1	1.60	N/A
Bolles Brook	M06T3.05A	9.3	1.80	22.0	2.38	N/A
	M06T3.05B	9.6	1.57	29.7	1.80	N/A
	M06T3.05C	14.3	1.85	12.2	N/A	2.89
	M06T3.06	16.4	3.96	16.4	1.98	N/A

Table 3-5: Rapid Habitat Assessment (RHA) Results.

Stream	Segment ID	RHA Score	RHA Condition
City Stream	M06T3.05S1.01A	0.74	Good
	M06T3.05S1.01B	0.66	Good
	M06T3.05S1.01C	0.68	Good
	M06T3.05S1.02A	0.60	Fair
	M06T3.05S1.02B	0.76	Good
	M06T3.05S1.04B	0.83	Good
	M06T3.05S1.04D	0.70	Good
	M06T3.05S1.06	0.84	Good
Bolles Brook	M06T3.05A	0.65	Fair*
	M06T3.05B	0.82	Good
	M06T3.05C	0.65	Fair*
	M06T3.06	0.81	Good

**Adjusted due to other factors.*

Table 3-6: Rapid Geomorphic Assessment (RGA) Results.

Stream	Segment ID	RGA Score	RGA Condition	Stream Type Departure	Evolution Stage	Adjustment Processes	Sensitivity
City Stream	M06T3.05S1.01A	0.60	Fair	Yes	III	Degradation	High
	M06T3.05S1.01B	0.51	Poor*	Yes	III	Degradation and Widening	Extreme
	M06T3.05S1.01C	0.48	Fair	Yes	III	Degradation, Widening, and Planform	High
	M06T3.05S1.02A	0.43	Fair	Yes	III-IV	Aggradation and Widening after Historic Degradation	Extreme
	M06T3.05S1.02B	0.51	Fair	No	II	Degradation	High
	M06T3.05S1.04B	0.64	Fair	Yes	II	Degradation	Extreme
	M06T3.05S1.04D	0.59	Fair	Yes	II	Degradation	Extreme
	M06T3.05S1.06	0.73	Good	No	IV	Planform	Extreme
Bolles Brook	M06T3.05A	0.50	Fair	No	III	Degradation and Widening	High
	M06T3.05B	0.56	Fair	No	IV	Widening and Aggradation	High
	M06T3.05C	0.60	Fair	No	II	Degradation	High
	M06T3.06	0.68	Good	No	IV	Planform	Extreme

**Adjusted due to other factors.*

Table 3-7: Percent of Stream Segments Impacted by Stressors.

Stream	Segment ID	Berms	Roads	Development	Straightening
City Stream	M06T3.05S1.01A	52%	28%	35%	5%
	M06T3.05S1.01B	32%	100%	0%	100%
	M06T3.05S1.01C	49%	45%	13%	100%
	M06T3.05S1.02A	0%	94%	0%	98%
	M06T3.05S1.02B	14%	100%	5%	93%
	M06T3.05S1.04B	0%	0%	0%	0%
	M06T3.05S1.04D	0%	40%	24%	53%
	M06T3.05S1.06	0%	21%	14%	11%
Bolles Brook	M06T3.05A	0%	43%	87%	85%
	M06T3.05B	0%	74%	29%	68%
	M06T3.05C	0%	97%	99%	75%
	M06T3.06	6%	34%	8%	0%

Table 3-8: Fluvial Erosion Hazard (FEH) Ratings.

Stream	Segment ID	Sensitivity	Stream Type Group	Existing Stream Type	Natural Valley Type	Departure from Equilibrium	FEH Rating	
City Stream	M06T3.05S1.01A	High	5	B3	Narrow	Stream Type Departure	HI	5
	M06T3.05S1.01B	Extreme	8	F3	Narrow	Stream Type Departure	EX	8
	M06T3.05S1.01C	High	5	B3	Narrow	Stream Type Departure	HI	5
	M06T3.05S1.02A	Extreme	8	F3	Narrowly Confined	Stream Type Departure	EX	8
	M06T3.05S1.02B	High	5	B3a	Narrowly Confined	Major Adjustment	HI	5
	M06T3.05S1.04B	Extreme	9	F4	Very Broad	Stream Type Departure	EX	9
	M06T3.05S1.04D	Extreme	9	F4	Very Broad	Stream Type Departure	EX	9
	M06T3.05S1.06	Extreme	10	D4b	Very Broad	Reference Condition	EX	10
Bolles Brook	M06T3.05A	High	5	B3	Broad	Major Adjustment	HI	5
	M06T3.05B	High	5	B3c	Broad	Major Adjustment	HI	5
	M06T3.05C	High	5	B3c	Very Broad	Major Adjustment	HI	5
	M06T3.06	Extreme	10	D3b	Very Broad	Reference Condition	EX	10

Table 3-9: Bridge and Culvert Locations and Dimensions.

Stream	Segment	Location	Type	Road Width (ft)	Structure Clearance/ Height (ft)	Structure Span/Width (ft)	Structure Width / Bankfull Width
City Stream	M06T3.05S1.01A	1st bridge on Harbour Rd.	Bridge	20.0	11.0	90.0	150%
	M06T3.05S1.02A	Route 9 (at Notch Rd.)	Bridge	45.0	30.0	250.0	556%
	M06T3.05S1.03	City Stream Rd.	Arch	40.0	8.5	16.0	59%
	M06T3.05S1.04A	Driveway off City Stream Rd.	Bridge	13.0	4.5	30.0	150%
	M06T3.05S1.04D	Prospect Access	Culvert	30.0	5.3	10.5	53%
	M06T3.05S1.04D	Greenwood Dr.	Culvert	23.5	6.0	12.0	67%
	M06T3.05S1.06	Driveway off Route 9	Bridge	11.5	4.2	14.5	97%
	M06T3.05S1.06	Snowmobile trail off Route 9	Bridge	7.0	4.7	45.0	300%
	M06T3.05S1.06	Route 9	Culvert	36.0	5.6	3.2	18%
	M06T3.05S1.07	Evergreen Ln.	Culvert	30.0	3.6	7.2	48%
Bolles Brook	M06T3.05B	2nd bridge on Harbour Rd.	Bridge	25.0	14.0	75.0	300%
	M06T3.05C	3rd bridge on Harbour Rd.	Bridge	20.0	7.0	80.0	133%
	M06T3.06	National Forest Rd.	Bridge	16.0	7.5	42.0	105%

4.0 Conclusions and Recommendations

In general, Bolles Brook seems to be in slightly better geomorphic condition than City Stream. While all but two of the segments on City Stream have experienced a stream type departure, none of those on Bolles Brook have yet departed from their reference stream type. However, most of the segments on both City Stream and Bolles Brook were found to be in major adjustment (fair condition). Only the uppermost assessed reach of each stream—both braided systems—are in good condition. Most of City Stream—especially in the lower reaches—has lost some or all access to its floodplain through encroachment by Route 9, berms, and, to a lesser extent, development. Bolles Brook is also encroached by a road (Harbour Road), but it is a secondary gravel road and not considered to be the valley wall as Route 9 is for City Stream. The main issue for Bolles Brook is existing and new residential development, which has impacted the majority of the lower reach. Stream sensitivity is either high or extreme on all assessed segments and reaches.

Habitat appears to be in slightly better condition on Bolles Brook as well, although it is suffering from the impact of development along the lower reach. City Stream also has fairly good habitat, but has more areas with sparsely vegetated road embankments and fragmented buffers.

Thirteen bridges and culverts on City Stream and Bolles Brook were assessed. Most of the structures were found to be in good condition with little potential to fail. About half of the structures act as a confinement to the stream channel or its ability to access its floodplains.

The information obtained from Phase 1 and Phase 2 stream geomorphic assessments can be a useful tool in creating a River Corridor Protection and Channel Management Plan to guide watershed decisions made by federal, state, and local agencies, organizations, and interest groups. Management strategies that resolve immediate site-specific conflicts in the context of broader, problem-solving goals will build community support and prove the most effective. More in-depth Phase 3 stream geomorphic assessments of target areas may be required before site-specific solutions for corridor protection and/or restoration can be developed and implemented.

Although it may be tempting to focus on the restoration of problem areas in fair or poor geomorphic condition, this strategy often requires intensive and potentially expensive in-stream management practices. Furthermore, elaborate channel restoration projects have the potential to fail, especially if the adjustment processes in the reach as well as upstream and downstream are not fully understood. Instead, using a watershed approach that places high priority on protecting those reaches that are currently in good condition or have a high recovery potential has proven to be a cost effective, long-term benefit to both the river and community as a whole. This approach will require coordination at the local, state, and federal level to educate the public and provide incentives to landowners.

Management alternatives can be classified as passive geomorphic approaches, active geomorphic approaches, channelization approaches, or no action approaches. Passive approaches involve strategies that remove constraints to a river's ability to establish geomorphic stability over time, and can include corridor conservation, land acquisition, berm removal/offsetting, and infrastructure alteration. Active geomorphic approaches attempt to restore the river to a geomorphically stable state through the construction of channel bed, bank, and/or floodplain modifications using process-driven and natural channel design concepts. Channelization approaches seek to maintain rivers through dredging and bank armoring applications where the dimension, pattern, and profile are not consistent with the condition. The no action approach takes no action whatsoever to address management conflicts. Erosion of bed and banks are allowed to continue and no effort is made to improve corridor ecological condition and function.

One passive approach that would help to protect undeveloped land from future development within the riparian corridor is to develop a Fluvial Erosion Hazard (FEH) zone. Potential avenues for FEH corridor protection implementation (e.g., ordinance, zoning, overlay districts, etc.) should be examined. A protected FEH corridor would allow for more natural adjustment of the streams, protect floodplain areas required for flow dispersement and sediment storage, decrease erosive forces within the channel, and allow for the rejuvenation and protection of a wooded corridor with increased erosion protection and ecological function. Areas in relatively good condition or with a high recovery potential that would benefit from such protection include the upper reaches of both streams (T3.06, T3.07, and S1.06) and the middle, relatively undeveloped segment of the lower reach on Bolles Brook (T3.05B).

Another protective measure that would help prevent further bank erosion, which can lead to bank armoring and degradation, is to plant stream buffer vegetation to stabilize the banks. Target areas should include locations where the buffer is currently less than 25 feet, such as most of the lower segment on Bolles Brook (T3.05A), as well as the straight, narrowly confined segment on the lower reach of City Stream (S1.01B). Removing or replacing structures such as undersized bridges/culverts or constrictions would provide the stream with more access to its floodplain. Target areas for structure removal could include the concrete slabs under the bridge in segment T3.05B of Bolles Brook or the old stone abutments/dams in reach S1.06 of City Stream. Although the removal or offsetting of berms along the lower reach of City Stream (S1.01) would provide more floodplain access, this strategy may not be feasible due to the potential for uncontrolled migration towards Route 9 and some residential properties. However, areas with a greater distance between the stream and Route 9 (specifically in segment S1.01C) may provide opportunities for offset berms. Finally, natural channel design of stream features such as meanders, bars, riffles, and pools may help restore over-widened reaches such as S1.02 (especially the lower segment) to a more sustainable balance of sediment and flow.

5.0 References

Rosgen, D. (1996). *Applied river morphology*. Pagosa Springs, CO: Wildland Hydrology.

U.S. Geological Survey (USGS). (2007). *Vermont StreamStats*. Available from: <http://streamstats.usgs.gov/vtstreamstats/>


Vermont Agency of Natural Resources, Department of Environmental Conservation, Water Quality Division, River Management Program (VT ANR). (2005). *Vermont fluvial erosion hazard mitigation program*.

Vermont Agency of Natural Resources, Department of Environmental Conservation, Water Quality Division, River Management Program (VT ANR). (2006). *Vermont regional hydraulic geometry curves*. Available from: http://www.anr.state.vt.us/dec/waterq/rivers/docs/rv_hydraulicgeocurves.pdf


Vermont Agency of Natural Resources, Department of Environmental Conservation, Water Quality Division, River Management Program (VT ANR). (2007). *Phase 2 rapid stream geomorphic assessment field protocols*. Available from: http://www.vtwaterquality.org/rivers/htm/rv_geoassesspro.htm

Appendix A: Cross-Section Diagrams


City Stream, Woodford, VT
Segment ID: M6T3.05S1.01A




City Stream, Woodford, VT
Segment ID: M6T3.05S1.01B




City Stream, Woodford, VT
Segment ID: M6T3.05S1.01C




City Stream, Woodford, VT
Segment ID: M6T3.05S1.02A




City Stream, Woodford, VT
Segment ID: M6T3.05S1.02B




City Stream, Woodford, VT
Segment ID: M6T3.05S1.04B







City Stream, Woodford, VT
Segment ID: M6T3.05S1.06




Bolles Brook, Woodford, VT
Segment ID: M6T3.05A




Bolles Brook, Woodford, VT
Segment ID: M6T3.05B



Bolles Brook, Woodford, VT
Segment ID: M6T3.05C



Bolles Brook, Woodford, VT
Segment ID: M6T3.06



Appendix B: Summary of Stream Features and Impacts

Table B-1: Summary of Stream Features and Impacts. (Continued on pages B-2 through B-8)

Reach/Segment	Impact	Sub-Impact	Comment	Length (ft)	Parameter 1	Value 1	Parameter 2	Value 2
M6T3.05S1.01A	Bank Armoring or Revetment	Rip-Rap	Right Bank	9.91	----	0	----	0
M6T3.05S1.01A	Bridge or Culvert	Bridge		0.00	Length	200	----	0
M6T3.05S1.01A	Buffers Less than 25 feet		Left Bank	33.33	----	0	----	0
M6T3.05S1.01A	Buffers Less than 25 feet		Right Bank	181.38	----	0	----	0
M6T3.05S1.01A	Cross Section Location	Representative		0.00	Number	1	----	0
M6T3.05S1.01A	Development		One Side	412.93	----	0	----	0
M6T3.05S1.01A	Development		One Side	242.28	----	0	----	0
M6T3.05S1.01A	Development		One Side	178.63	----	0	----	0
M6T3.05S1.01A	Dredging	Dredging	General Location	0.00	----	0	----	0
M6T3.05S1.01A	Dredging	Dredging	General Location	0.00	----	0	----	0
M6T3.05S1.01A	Dredging	Dredging	General Location	0.00	----	0	----	0
M6T3.05S1.01A	Dredging	Dredging	General Location	0.00	----	0	----	0
M6T3.05S1.01A	Dredging	Dredging	General Location	0.00	----	0	----	0
M6T3.05S1.01A	Encroachment	Berm	One Side	640.43	Height	10	----	0
M6T3.05S1.01A	Encroachment	Berm	One Side	587.73	Height	6	----	0
M6T3.05S1.01A	Encroachment	Road	One Side	569.79	Height	11	----	0
M6T3.05S1.01A	Encroachment	Road	One Side	105.69	Height	8	----	0
M6T3.05S1.01A	Erosion		Left Bank	109.64	Height	6	----	0
M6T3.05S1.01A	Migration	Braiding		0.00	----	0	----	0
M6T3.05S1.01A	Migration	Braiding		0.00	----	0	----	0
M6T3.05S1.01A	Migration	Flood Chute		0.00	----	0	----	0
M6T3.05S1.01A	Migration	Flood Chute		0.00	----	0	----	0
M6T3.05S1.01A	Steep Riffle or Head Cut	Head Cut		0.00	----	0	----	0
M6T3.05S1.01A	Steep Riffle or Head Cut	Steep Riffle		0.00	----	0	----	0
M6T3.05S1.01A	Straightening	Straightening		125.93	----	0	----	0
M6T3.05S1.01A	Stream Crossing	Stream Ford		0.00	----	0	----	0
M6T3.05S1.01B	Bank Armoring or Revetment	Rip-Rap	Left Bank	172.18	----	0	----	0
M6T3.05S1.01B	Bank Armoring or Revetment	Rip-Rap	Left Bank	107.81	----	0	----	0
M6T3.05S1.01B	Bank Armoring or Revetment	Rip-Rap	Left Bank	22.73	----	0	----	0
M6T3.05S1.01B	Cross Section Location	Representative		0.00	Number	1	----	0

Reach/Segment	Impact	Sub-Impact	Comment	Length (ft)	Parameter 1	Value 1	Parameter 2	Value 2
M6T3.05S1.01B	Dredging	Dredging	General Location	0.00	----	0	----	0
M6T3.05S1.01B	Encroachment	Berm	One Side	434.00	Height	6	----	0
M6T3.05S1.01B	Encroachment	Road	One Side	1346.22	Height	8	----	0
M6T3.05S1.01B	Erosion		Left Bank	221.92	Height	5	----	0
M6T3.05S1.01B	Steep Riffle or Head Cut	Head Cut		0.00	----	0	----	0
M6T3.05S1.01B	Straightening	Straightening		1346.22	----	0	----	0
M6T3.05S1.01C	Bank Armoring or Revetment	Rip-Rap	Left Bank	278.60	----	0	----	0
M6T3.05S1.01C	Cross Section Location	Representative		0.00	Number	1	----	0
M6T3.05S1.01C	Development		One Side	109.83	----	0	----	0
M6T3.05S1.01C	Development		One Side	412.34	----	0	----	0
M6T3.05S1.01C	Dredging	Dredging	General Location	0.00	----	0	----	0
M6T3.05S1.01C	Dredging	Dredging	General Location	0.00	----	0	----	0
M6T3.05S1.01C	Dredging	Dredging	General Location	0.00	----	0	----	0
M6T3.05S1.01C	Dredging	Dredging	General Location	0.00	----	0	----	0
M6T3.05S1.01C	Encroachment	Berm	One Side	678.81	Height	6	----	0
M6T3.05S1.01C	Encroachment	Berm	One Side	199.67	Height	4	----	0
M6T3.05S1.01C	Encroachment	Berm	One Side	412.50	Height	6	----	0
M6T3.05S1.01C	Encroachment	Berm	One Side	463.99	Height	8	----	0
M6T3.05S1.01C	Encroachment	Berm	One Side	249.34	Height	10	----	0
M6T3.05S1.01C	Encroachment	Berm	One Side	613.01	Height	6	----	0
M6T3.05S1.01C	Encroachment	Road	One Side	689.51	Height	8	----	0
M6T3.05S1.01C	Encroachment	Road	One Side	1068.22	Height	20	----	0
M6T3.05S1.01C	Erosion		Left Bank	222.80	Height	6	----	0
M6T3.05S1.01C	Erosion		Left Bank	58.75	Height	5	----	0
M6T3.05S1.01C	Erosion		Left Bank	109.87	Height	4	----	0
M6T3.05S1.01C	Erosion		Left Bank	36.62	Height	4	----	0
M6T3.05S1.01C	Erosion		Left Bank	60.87	Height	4	----	0
M6T3.05S1.01C	Erosion		Right Bank	99.81	Height	8	----	0
M6T3.05S1.01C	Erosion		Left Bank	62.11	Height	8	----	0
M6T3.05S1.01C	Erosion		Right Bank	60.45	Height	8	----	0
M6T3.05S1.01C	Erosion		Right Bank	158.43	Height	4	----	0
M6T3.05S1.01C	Mass Failure		Right Bank	43.27	Height	20	----	0

Reach/Segment	Impact	Sub-Impact	Comment	Length (ft)	Parameter 1	Value 1	Parameter 2	Value 2
M6T3.05S1.01C	Migration	Flood Chute		0.00	----	0	----	0
M6T3.05S1.01C	Steep Riffle or Head Cut	Steep Riffle		0.00	----	0	----	0
M6T3.05S1.01C	Stormwater Input	Road Ditch		0.00	----	0	----	0
M6T3.05S1.01C	Stormwater Input	Road Ditch		0.00	----	0	----	0
M6T3.05S1.01C	Stormwater Input	Road Ditch		0.00	----	0	----	0
M6T3.05S1.01C	Straightening	Straightening		953.63	----	0	----	0
M6T3.05S1.01C	Straightening	Straightening		1384.35	----	0	----	0
M6T3.05S1.01C	Straightening	Straightening		1573.17	----	0	----	0
M6T3.05S1.02A	Bank Armoring or Revetment	Hard Bank	Left Bank	280.23	----	0	----	0
M6T3.05S1.02A	Bank Armoring or Revetment	Hard Bank	Left Bank	236.23	----	0	----	0
M6T3.05S1.02A	Bank Armoring or Revetment	Rip-Rap	Left Bank	241.26	----	0	----	0
M6T3.05S1.02A	Bank Armoring or Revetment	Rip-Rap	Right Bank	392.71	----	0	----	0
M6T3.05S1.02A	Bank Armoring or Revetment	Rip-Rap	Left Bank	87.06	----	0	----	0
M6T3.05S1.02A	Cross Section Location	Representative		0.00	Number	1	----	0
M6T3.05S1.02A	Encroachment	Road	One Side	409.25	Height	20	----	0
M6T3.05S1.02A	Encroachment	Road	Both Sides	353.08	Height	25	----	0
M6T3.05S1.02A	Encroachment	Road	One Side	246.10	Height	13	----	0
M6T3.05S1.02A	Erosion		Left Bank	75.43	Height	8	----	0
M6T3.05S1.02A	Erosion		Right Bank	57.96	Height	8	----	0
M6T3.05S1.02A	Steep Riffle or Head Cut	Steep Riffle		0.00	----	0	----	0
M6T3.05S1.02A	Stormwater Input	Road Ditch		0.00	----	0	----	0
M6T3.05S1.02A	Stormwater Input	Road Ditch		0.00	----	0	----	0
M6T3.05S1.02A	Stormwater Input	Road Ditch		0.00	----	0	----	0
M6T3.05S1.02A	Straightening	Straightening		332.34	----	0	----	0
M6T3.05S1.02A	Straightening	Straightening		716.22	----	0	----	0
M6T3.05S1.02B	Bank Armoring or Revetment	Hard Bank	Left Bank	70.23	----	0	----	0
M6T3.05S1.02B	Cross Section Location	Representative		0.00	Number	1	----	0
M6T3.05S1.02B	Development		One Side	42.40	----	0	----	0
M6T3.05S1.02B	Dredging	Dredging	General Location	0.00	----	0	----	0
M6T3.05S1.02B	Encroachment	Berm	One Side	126.96	Height	6	----	0
M6T3.05S1.02B	Encroachment	Road	One Side	898.92	Height	13	----	0
M6T3.05S1.02B	Erosion		Right Bank	39.49	Height	8	----	0

Reach/Segment	Impact	Sub-Impact	Comment	Length (ft)	Parameter 1	Value 1	Parameter 2	Value 2
M6T3.05S1.02B	Erosion		Left Bank	321.24	Height	3	----	0
M6T3.05S1.02B	Erosion		Right Bank	132.81	Height	4	----	0
M6T3.05S1.02B	Straightening	Straightening		837.61	----	0	----	0
M6T3.05S1.03-	Bridge or Culvert	Bridge		0.00	Length	200	----	0
M6T3.05S1.03-	Bridge or Culvert	Culvert		0.00	Length	75	----	0
M6T3.05S1.03-	Buffers Less than 25 feet		Left Bank	119.51	----	0	----	0
M6T3.05S1.03-	Buffers Less than 25 feet		Left Bank	28.05	----	0	----	0
M6T3.05S1.03-	Buffers Less than 25 feet		Right Bank	649.46	----	0	----	0
M6T3.05S1.03-	Buffers Less than 25 feet		Right Bank	2980.00	----	0	----	0
M6T3.05S1.03-	Buffers Less than 25 feet		Right Bank	255.25	----	0	----	0
M6T3.05S1.03-	Development		One Side	984.95	----	0	----	0
M6T3.05S1.03-	Development		One Side	103.62	----	0	----	0
M6T3.05S1.03-	Encroachment	Road	One Side	118.24	Height	13	----	0
M6T3.05S1.03-	Encroachment	Road	One Side	6267.29	Height	0	----	0
M6T3.05S1.03-	Encroachment	Road	One Side	294.43	Height	0	----	0
M6T3.05S1.03-	Encroachment	Road	Both Sides	62.16	Height	0	----	0
M6T3.05S1.03-	Encroachment	Road	One Side	568.77	Height	6	----	0
M6T3.05S1.03-	Grade Control	Ledge	Picture	0.00	Height	0	HtAbvWater	0
M6T3.05S1.04A	Buffers Less than 25 feet		Left Bank	35.83	----	0	----	0
M6T3.05S1.04A	Encroachment	Road	One Side	72.78	Height	6	----	0
M6T3.05S1.04A	Grade Control	Ledge	Picture	0.00	Height	1	HtAbvWater	0
M6T3.05S1.04A	Grade Control	Waterfall	Picture	0.00	Height	6	HtAbvWater	5
M6T3.05S1.04B	Cross Section Location	Representative		0.00	Number	1	----	0
M6T3.05S1.04B	Encroachment	Improved Path	One Side	300.92	Height	10	----	0
M6T3.05S1.04B	Grade Control	Ledge	Picture	0.00	Height	2	HtAbvWater	1
M6T3.05S1.04B	Grade Control	Ledge	Picture	0.00	Height	1	HtAbvWater	1
M6T3.05S1.04B	Steep Riffle or Head Cut	Steep Riffle		0.00	----	0	----	0
M6T3.05S1.04C	Bank Armoring or Revetment	Rip-Rap	Left Bank	22.63	----	0	----	0
M6T3.05S1.04C	Bank Armoring or Revetment	Rip-Rap	Right Bank	14.87	----	0	----	0
M6T3.05S1.04C	Beaver Dam			0.00	Length	420	----	0
M6T3.05S1.04C	Bridge or Culvert	Culvert		0.00	Length	75	----	0
M6T3.05S1.04C	Development		Both Sides	263.48	----	0	----	0

Reach/Segment	Impact	Sub-Impact	Comment	Length (ft)	Parameter 1	Value 1	Parameter 2	Value 2
M6T3.05S1.04C	Encroachment	Road	One Side	60.14	Height	6	----	0
M6T3.05S1.04C	Straightening	Straightening		254.45	----	0	----	0
M6T3.05S1.04D	Bank Armoring or Revetment	Rip-Rap	Right Bank	56.06	----	0	----	0
M6T3.05S1.04D	Bank Armoring or Revetment	Rip-Rap	Right Bank	131.06	----	0	----	0
M6T3.05S1.04D	Beaver Dam			0.00	Length	150	----	0
M6T3.05S1.04D	Bridge or Culvert	Bridge		0.00	Length	0	----	0
M6T3.05S1.04D	Bridge or Culvert	Bridge		0.00	Length	0	----	0
M6T3.05S1.04D	Bridge or Culvert	Culvert		0.00	Length	75	----	0
M6T3.05S1.04D	Buffers Less than 25 feet		Right Bank	509.01	----	0	----	0
M6T3.05S1.04D	Development		One Side	243.75	----	0	----	0
M6T3.05S1.04D	Development		Both Sides	30.80	----	0	----	0
M6T3.05S1.04D	Development		Both Sides	196.25	----	0	----	0
M6T3.05S1.04D	Encroachment	Improved Path	One Side	501.48	Height	0	----	0
M6T3.05S1.04D	Encroachment	Road	One Side	255.90	Height	6	----	0
M6T3.05S1.04D	Encroachment	Road	One Side	530.25	Height	7	----	0
M6T3.05S1.04D	Straightening	Straightening		700.14	----	0	----	0
M6T3.05S1.04D	Straightening	Straightening		332.00	----	0	----	0
M6T3.05S1.05-	Buffers Less than 25 feet		Right Bank	20.59	----	0	----	0
M6T3.05S1.05-	Grade Control	Dam	No Picture	0.00	Height	0	HtAbvWater	0
M6T3.05S1.06-	Bridge or Culvert	Bridge		0.00	Length	200	----	0
M6T3.05S1.06-	Bridge or Culvert	Culvert		0.00	Length	75	----	0
M6T3.05S1.06-	Buffers Less than 25 feet		Left Bank	26.49	----	0	----	0
M6T3.05S1.06-	Buffers Less than 25 feet		Left Bank	330.04	----	0	----	0
M6T3.05S1.06-	Buffers Less than 25 feet		Right Bank	29.74	----	0	----	0
M6T3.05S1.06-	Buffers Less than 25 feet		Right Bank	335.45	----	0	----	0
M6T3.05S1.06-	Debris Jam			0.00	----	0	----	0
M6T3.05S1.06-	Debris Jam			0.00	----	0	----	0
M6T3.05S1.06-	Debris Jam			0.00	----	0	----	0
M6T3.05S1.06-	Debris Jam			0.00	----	0	----	0
M6T3.05S1.06-	Debris Jam			0.00	----	0	----	0
M6T3.05S1.06-	Development		Both Sides	307.47	----	0	----	0
M6T3.05S1.06-	Encroachment	Road	One Side	467.26	Height	8	----	0

Reach/Segment	Impact	Sub-Impact	Comment	Length (ft)	Parameter 1	Value 1	Parameter 2	Value 2
M6T3.05S1.06-	Grade Control	Ledge	Picture	0.00	Height	1	HtAbvWater	1
M6T3.05S1.06-	Grade Control	Ledge	Picture	0.00	Height	2	HtAbvWater	1
M6T3.05S1.06-	Migration	Braiding		0.00	----	0	----	0
M6T3.05S1.06-	Migration	Braiding		0.00	----	0	----	0
M6T3.05S1.06-	Migration	Braiding		0.00	----	0	----	0
M6T3.05S1.06-	Migration	Braiding		0.00	----	0	----	0
M6T3.05S1.06-	Migration	Braiding		0.00	----	0	----	0
M6T3.05S1.06-	Migration	Flood Chute		0.00	----	0	----	0
M6T3.05S1.06-	Steep Riffle or Head Cut	Steep Riffle		0.00	----	0	----	0
M6T3.05S1.06-	Straightening	Straightening		249.38	----	0	----	0
M6T3.05S1.07-	Bridge or Culvert	Culvert		0.00	Length	75	----	0
M6T3.05S1.07-	Buffers Less than 25 feet		Left Bank	32.20	----	0	----	0
M6T3.05S1.07-	Buffers Less than 25 feet		Left Bank	229.55	----	0	----	0
M6T3.05S1.07-	Buffers Less than 25 feet		Right Bank	54.71	----	0	----	0
M6T3.05S1.07-	Buffers Less than 25 feet		Right Bank	143.65	----	0	----	0
M6T3.05S1.07-	Development		One Side	367.13	----	0	----	0
M6T3.05S1.07-	Development		Both Sides	62.44	----	0	----	0
M6T3.05S1.07-	Grade Control	Dam	No Picture	0.00	Height	0	HtAbvWater	0
M6T3.05S1.07-	Straightening	Straightening		800.18	----	0	----	0
M6T3.05A	Buffers Less than 25 feet		Left Bank	421.69	----	0	----	0
M6T3.05A	Buffers Less than 25 feet		Left Bank	188.90	----	0	----	0
M6T3.05A	Buffers Less than 25 feet		Right Bank	185.49	----	0	----	0
M6T3.05A	Buffers Less than 25 feet		Left Bank	87.73	----	0	----	0
M6T3.05A	Cross Section Location	Representative		0.00	Number	1	----	0
M6T3.05A	Development		One Side	1775.28	----	0	----	0
M6T3.05A	Encroachment	Road	One Side	647.10	Height	8	----	0
M6T3.05A	Encroachment	Road	One Side	234.89	Height	13	----	0
M6T3.05A	Erosion		Right Bank	54.29	Height	4	----	0
M6T3.05A	Erosion		Left Bank	137.59	Height	7	----	0
M6T3.05A	Erosion		Right Bank	127.31	Height	4	----	0
M6T3.05A	Mass Failure		Right Bank	102.66	Height	20	----	0
M6T3.05A	Mass Failure		Right Bank	44.99	Height	20	----	0

Reach/Segment	Impact	Sub-Impact	Comment	Length (ft)	Parameter 1	Value 1	Parameter 2	Value 2
M6T3.05A	Migration	Braiding		0.00	----	0	----	0
M6T3.05A	Migration	Flood Chute		0.00	----	0	----	0
M6T3.05A	Steep Riffle or Head Cut	Head Cut		0.00	----	0	----	0
M6T3.05A	Steep Riffle or Head Cut	Head Cut		0.00	----	0	----	0
M6T3.05A	Straightening	Straightening		1727.14	----	0	----	0
M6T3.05B	Bank Armoring or Revetment	Other	Left Bank	51.54	----	0	----	0
M6T3.05B	Bank Armoring or Revetment	Rip-Rap	Left Bank	99.47	----	0	----	0
M6T3.05B	Bank Armoring or Revetment	Rip-Rap	Right Bank	61.55	----	0	----	0
M6T3.05B	Bridge or Culvert	Bridge		0.00	Length	200	----	0
M6T3.05B	Buffers Less than 25 feet		Right Bank	136.32	----	0	----	0
M6T3.05B	Cross Section Location	Representative		0.00	Number	1	----	0
M6T3.05B	Development		One Side	109.31	----	0	----	0
M6T3.05B	Development		One Side	396.61	----	0	----	0
M6T3.05B	Development		One Side	140.86	----	0	----	0
M6T3.05B	Encroachment	Road	One Side	1663.74	Height	8	----	0
M6T3.05B	Erosion		Right Bank	95.23	Height	4	----	0
M6T3.05B	Erosion		Left Bank	236.34	Height	8	----	0
M6T3.05B	Grade Control	Ledge	Picture	0.00	Height	5	HtAbvWater	4
M6T3.05B	Grade Control	Ledge	Picture	0.00	Height	3	HtAbvWater	2
M6T3.05B	Migration	Braiding		0.00	----	0	----	0
M6T3.05B	Migration	Flood Chute		0.00	----	0	----	0
M6T3.05B	Migration	Flood Chute		0.00	----	0	----	0
M6T3.05B	Steep Riffle or Head Cut	Steep Riffle		0.00	----	0	----	0
M6T3.05B	Steep Riffle or Head Cut	Steep Riffle		0.00	----	0	----	0
M6T3.05B	Steep Riffle or Head Cut	Steep Riffle		0.00	----	0	----	0
M6T3.05B	Straightening	Straightening		1404.26	----	0	----	0
M6T3.05B	Straightening	Straightening		114.52	----	0	----	0
M6T3.05C	Bank Armoring or Revetment	Rip-Rap	Right Bank	108.52	----	0	----	0
M6T3.05C	Bank Armoring or Revetment	Rip-Rap	Right Bank	188.47	----	0	----	0
M6T3.05C	Bank Armoring or Revetment	Rip-Rap	Right Bank	340.02	----	0	----	0
M6T3.05C	Bridge or Culvert	Bridge		0.00	Length	200	----	0
M6T3.05C	Buffers Less than 25 feet		Left Bank	91.27	----	0	----	0

Reach/Segment	Impact	Sub-Impact	Comment	Length (ft)	Parameter 1	Value 1	Parameter 2	Value 2
M6T3.05C	Buffers Less than 25 feet		Right Bank	116.08	----	0	----	0
M6T3.05C	Buffers Less than 25 feet		Right Bank	773.29	----	0	----	0
M6T3.05C	Cross Section Location	Representative		0.00	Number	1	----	0
M6T3.05C	Development		One Side	1150.13	----	0	----	0
M6T3.05C	Dredging	Dredging	Exact Location	0.00	----	0	----	0
M6T3.05C	Encroachment	Road	Both Sides	171.69	Height	15	----	0
M6T3.05C	Encroachment	Road	One Side	961.23	Height	15	----	0
M6T3.05C	Flow Regs and Withdrawals	Small Bypass	Drinking Water	0.00	----	0	----	0
M6T3.05C	Grade Control	Dam	Picture	0.00	Height	8	HtAbvWater	5
M6T3.05C	Straightening	Straightening		870.98	----	0	----	0
M6T3.06-	Bridge or Culvert	Bridge		0.00	Length	0	----	0
M6T3.06-	Buffers Less than 25 feet		Left Bank	241.36	----	0	----	0
M6T3.06-	Buffers Less than 25 feet		Left Bank	98.57	----	0	----	0
M6T3.06-	Cross Section Location	Representative		0.00	Number	1	----	0
M6T3.06-	Development		One Side	480.93	----	0	----	0
M6T3.06-	Encroachment	Berm	One Side	344.70	Height	0	----	0
M6T3.06-	Encroachment	Road	One Side	172.55	Height	0	----	0
M6T3.06-	Encroachment	Road	One Side	123.21	Height	0	----	0
M6T3.06-	Encroachment	Road	One Side	259.91	Height	0	----	0
M6T3.06-	Encroachment	Road	One Side	832.39	Height	0	----	0
M6T3.06-	Encroachment	Road	One Side	559.08	Height	0	----	0
M6T3.06-	Erosion		Left Bank	100.67	Height	8	----	0
M6T3.06-	Erosion		Right Bank	108.41	Height	6	----	0
M6T3.06-	Migration	Braiding		0.00	----	0	----	0
M6T3.06-	Migration	Braiding		0.00	----	0	----	0
M6T3.06-	Migration	Braiding		0.00	----	0	----	0
M6T3.06-	Migration	Braiding		0.00	----	0	----	0
M6T3.06-	Migration	Braiding		0.00	----	0	----	0
M6T3.06-	Migration	Braiding		0.00	----	0	----	0
M6T3.06-	Migration	Braiding		0.00	----	0	----	0
M6T3.06-	Migration	Braiding		0.00	----	0	----	0
M6T3.06-	Migration	Braiding		0.00	----	0	----	0

Reach/Segment	Impact	Sub-Impact	Comment	Length (ft)	Parameter 1	Value 1	Parameter 2	Value 2
M6T3.06-	Migration	Braiding		0.00	----	0	----	0
M6T3.06-	Migration	Braiding		0.00	----	0	----	0
M6T3.06-	Migration	Flood Chute		0.00	----	0	----	0
M6T3.06-	Migration	Flood Chute		0.00	----	0	----	0
M6T3.06-	Migration	Flood Chute		0.00	----	0	----	0
M6T3.06-	Migration	Flood Chute		0.00	----	0	----	0
M6T3.06-	Migration	Flood Chute		0.00	----	0	----	0
M6T3.06-	Migration	Flood Chute		0.00	----	0	----	0
M6T3.06-	Migration	Flood Chute		0.00	----	0	----	0
M6T3.06-	Migration	Flood Chute		0.00	----	0	----	0
M6T3.06-	Migration	Flood Chute		0.00	----	0	----	0
M6T3.06-	Migration	Flood Chute		0.00	----	0	----	0

Appendix C: Reach and Segment Impact Maps

Figure C-1: Segment M06T3.05S1.01A Impact Map




Figure C-2: Segment M06T3.05S1.01B Impact Map




Figure C-3: Segment M06T3.05S1.01C Impact Map




Figure C-4: Reach M06T3.05S1.02 (Segments A and B) Impact Map




Figure C-5: Reach M06T3.05S1.04 (Segments A, B, C, and D) Impact Map




Figure C-6: Reach M06T3.05S1.06 Impact Map




Figure C-7: Segment M06T3.05A Impact Map




Figure C-8: Segment M06T3.05B Impact Map




Figure C-9: Segment M06T3.05C Impact Map





Figure C-10: Reach M06T3.06 Impact Map



Appendix D: Bridge and Culvert Descriptions


Bridge and Culvert Descriptions

S1.01A Harbour Road Bridge



The most downstream bridge on City Stream is located on Harbour Road, which is gravel, in segment S1.01A. The bridge width is 150% of the channel width, and does not confine the stream any more than the left bank berm already does. An adequate buffer of mixed trees surrounds the bridge in all directions except the downstream right bank, where there has been recent lot clearing and fill for the construction of a new house. Sediment deposits downstream of the bridge are more likely due to the confluence with Bolles Brook than the bridge itself. Overall, the bridge seems to be in relatively good condition with a low potential to fail or to have future significant impacts on the stream.

S1.02A Route 9 Bridge



This bridge is located in segment S1.02A of City Stream on Route 9 at its intersection with Notch Road (old Route 9). With a 250-foot span, this concrete and steel bridge was by far the largest structure assessed. The bridge width is over 500% of the channel width, and does not appear to confine the stream. Contrarily, alterations made to the stream during the re-routing of Route 9 and the construction of the bridge seem to have drastically over-widened the channel through the bridge opening as well as upstream. Because of this, the sediment loads from the high-gradient tributary Stamford Stream (which is actually the larger stream) just upstream do not have enough velocity to be carried through the reach, and have formed large deposits above, underneath, and just below the bridge. The high banks in all directions except downstream right are heavily armored with rip-rap and have minimal herbaceous or shrub/sapling vegetation. The structure itself does not appear to be affecting the stream or have the potential to fail, but the extensive fill and channel alterations to accommodate both Route 9 and Notch Road have certainly impacted this reach.

S1.03 City Stream Road Arch



This structure is a small arch near the top of reach S1.03 of City Stream, just off Route 9 on City Stream Road (gravel). With a width 59% of the channel width, this structure acts as both a channel and floodplain confinement. Shrub/sapling vegetation lines both upstream and downstream banks, more densely on the left side. The arch seems to be in relatively good condition with a low potential to fail, although it does confine the stream somewhat.

S1.04A Driveway Bridge



This structure is a small wooden bridge across a driveway just upstream at the break between reaches S1.03 and S1.04 of City Stream. A new bridge with steel beams and a timber deck was recently built over top of the old, failing bridge by its private owner. The bridge is located at the base of a bedrock gorge at a bend in the stream, and the effect of the high stream power is evidenced by failing bank armoring on the upstream side of the bridge. The banks and buffers are well-forested in all directions. Now that the bridge has been reinforced and rebuilt, it appears to

have a low potential to fail, but the remaining old bridge materials may soon fail and impede the stream flow.

S1.04D Prospect Access Culvert



This structure is a culvert across a gravel access road at the base of Prospect Mountain ski area, located at the break between segments S1.04C and S1.04D of City Stream. The combined width of the two culverts is 53% of the channel width. An overflow pipe is also present. Below the culvert, the entire length of segment S1.01C is impounded by a beaver dam at its downstream end. A relatively new beaver dam about 165 feet upstream of the culvert has created a small impoundment in segment S1.01D as well. A potential problem for this structure

is sediment runoff since the surrounding area is relatively bare (gravel parking lot and mowed lawn), although little evidence of sedimentation was observed in the immediate vicinity of the culvert. The structure itself appears to be in good condition with little potential to fail, although it does confine the stream.

S1.04D Greenwood Drive Culvert




This culvert is located just below the outlet of Bugbee Mill Pond near the top of segment S1.04D on Greenwood Drive. It has two openings with a combined width 67% of the channel width. Herbaceous and shrub vegetation lines both banks, although just downstream a new dirt road is being cut on the left and a gravel lot is on the right. Both of these developments are contributing to heavy sediment runoff and deposition in the channel downstream. The structure itself appears to be in good condition with little potential to fail, although it does confine the stream.

S1.06 Driveway Bridge



This bridge is located on a driveway just off Route 9 in reach S1.06 of City Stream. Although the structure span is as wide as the channel, large stone abutments beneath the bridge confine the stream. Shrub/sapling vegetation lines both banks, more extensively in the left corridor. The stone abutments do not appear to be in the best condition and could possibly fail during a flood event.

S1.06 Snowmobile Trail Bridge



This bridge is on a snowmobile trail that crosses Route 9 in reach S1.06 of City Stream. The bridge's light timber deck, with a span 300% of the channel width, does not appear to confine the stream. Rip-rap armoring is intact. The left bank is buffered with shrub/sapling vegetation, whereas the right is the Route 9 embankment. The structure seems to be in good condition with a low potential to fail or impact the stream.

S1.06 Route 9 Culvert



This structure is a culvert across Route 9 near the upper end of reach S1.06 of City Stream. The structure is skewed to the roadway to accommodate the sharp angle of the stream. With a width of only 3.2 feet (18% of the channel width), this culvert is the most confining structure assessed on either City Stream or Bolles Brook. The stream is highly channelized in this area, especially above the culvert where concrete wingwalls extend upstream. Still, the structure seems to be in good condition with little potential to fail. It is likely that the small dam and impoundment just upstream of the culvert (at the reach break) provide some flow regulation to protect the structure.

S1.07 Evergreen Lane Culvert



The most upstream structure on City Stream is a culvert across Evergreen Lane below Woodford Lake (Big Pond) on reach S1.07. Two corrugated plastic culverts have a combined width that is 48% of the channel width. Shrub/sapling vegetation lines the banks in both directions. The structure seems to be in good condition with a low potential to fail or impact the stream, although it does confine the stream.

T3.05B Harbour Road Bridge




The most downstream structure on Bolles Brook is the second bridge on Harbour Road, just above the segment break between T3.05A and T3.05B. With a span 300% of the channel width, this bridge does not appear to confine the stream, but does create a floodplain confinement. The stream is relatively straight approaching the bridge, but passes through the bridge at an angle and bends to the left just downstream, where a small mass failure has occurred on the right bank. Shrub/sapling vegetation and mixed trees provide buffer in both directions. A potential problem is the presence of multiple large concrete slabs, possibly from an old bridge, in the channel underneath the structure. These slabs have created a steep grade control and may be partially responsible for the large sediment deposits downstream (which may also be due to the entrance of a tributary). Otherwise, the bridge is in relatively good condition, with a low potential to fail or impact the stream.

T3.05C Harbour Road Bridge



This structure is the third bridge on Harbour Road, near the top of segment T3.05C of Bolles Brook. It is located just above the small dam and drinking water withdrawal. Just upstream of the bridge, a tributary (Bickford Hollow Brook) enters Bolles Brook. The stream makes 90-degree bends just above and below the bridge. A bedrock wall on the outside of the downstream bend has likely prevented bank erosion. Above the bridge, Bolles Brook is extensively braided, whereas downstream it has been channelized. Although the span of the bridge is 133% of the stream width, the concrete abutments act as a channel and floodplain confinement. The small impoundment between the bridge and the dam was recently dredged in September 2007. Overall, the bridge itself is in relatively good condition, with a low potential to fail or impact the stream.

T3.06 National Forest Road Bridge



The most upstream structure on Bolles Brook is a timber bridge near the top of reach T3.06 on the Green Mountain National Forest dirt road that continues from Harbour Road. This bridge spans approximately the same width as the channel, and does not seem to confine the stream. Mixed forest vegetation provides adequate buffer on both sides. The bridge is in good condition with a low potential to fail or impact the stream.

Appendix E: Bridge and Culvert Reports

Key for Tables E-1 and E-2:

Width: Structure width divided by channel width as a percent (% bankfull width)

Failure Modes

- F1:** Concern for structure due to fluvial condition or process
- F2:** Potential failure due to out-flanking
- F3:** Potential failure due to scour
- F4:** Potential failure due to ice or debris jam
- F5:** Structure related damage due to flooding of adjacent property
- F6:** Structure related damage due to erosion of adjacent property

Existing Problems

- P1:** Upstream sediment deposit
- P2:** Upstream Scour and/or erosion present
- P3:** Downstream Scour and/or erosion present
- P4:** Inlet obstruction present
- P5:** Poor location or alignment
- P6:** Beaver activity
- P7:** Floodplain filled entirely or partially by roadway approaches

Upstream Sediment Deposition

- C1:** Opening obstructed by sediment
- C2:** Sediment deposits $\geq$ half bankfull
- C3:** Steep riffle upstream

Upstream Scour and Erosion

- C4:** Bank armoring failing
- C5:** Bank erosion high
- C6:** Scour under structure

Downstream Scour and Erosion

- C7:** Bank armoring failing
- C8:** Bank erosion high
- C9:** Scour under structure
- C10:** Banks higher downstream than upstream
- C11:** Culvert outlet is cascade or freefall

Poor Location or Alignment

- C12:** Stream approach angle is sharp bend
- C13:** Located at significant valley break
- C14:** Avulsion follow road

Table E-1: Bridge and Culvert Failure Mode Report

Stream	Segment	Location	Type	Width	F1	F2	F3	F4	F5	F6	P1	P2	P3	P4	P5	P6	P7
City Stream	M06T3.05S1.01A	1st bridge on Harbour Rd.	Bridge	150%	X	-	X	-	-	-	-	-	X	-	X	-	-
	M06T3.05S1.02A	Route 9 (at Notch Rd.)	Bridge	556%	-	-	-	X	-	X	-	-	-	-	X	-	X
	M06T3.05S1.03	City Stream Rd.	Arch	59%	-	X	-	X	-	-	-	-	-	-	-	-	X
	M06T3.05S1.04A	Driveway off City Stream Rd.	Bridge	150%	-	-	-	X	-	X	-	X	-	-	X	-	-
	M06T3.05S1.04D	Prospect Access	Culvert	53%	-	X	-	X	-	-	-	-	-	-	-	-	-
	M06T3.05S1.04D	Greenwood Dr.	Culvert	67%	-	X	-	X	-	-	-	-	-	-	-	-	X
	M06T3.05S1.06	Driveway off Route 9	Bridge	97%	-	-	-	-	-	-	-	-	-	-	-	-	X
	M06T3.05S1.06	Snowmobile trail off Route 9	Bridge	300%	-	-	-	X	-	-	-	-	-	-	-	-	-
	M06T3.05S1.06	Route 9	Culvert	18%	-	X	X	X	-	X	-	X	-	-	-	-	X
	M06T3.05S1.07	Evergreen Ln.	Culvert	48%	-	X	-	X	-	-	-	-	-	-	-	-	X
Bolles Brook	M06T3.05B	2nd bridge on Harbour Rd.	Bridge	300%	-	-	-	-	-	X	-	-	-	-	X	-	-
	M06T3.05C	3rd bridge on Harbour Rd.	Bridge	133%	-	-	-	-	-	-	-	-	X	-	-	-	-
	M06T3.06	National Forest Rd.	Bridge	105%	-	-	-	-	-	X	-	-	-	-	X	-	X

Table E-2: Bridge and Culvert Failure Mode Problem Conditions

Stream	Segment	Location	Type	Width	C1	C2	C3	C4	C5	C6	C7	C8	C9	C10	C11	C12	C13	C14
City Stream	M06T3.05S1.01A	1st bridge on Harbour Rd.	Bridge	150%	-	-	-	-	-	-	-	-	-	-	-	-	X	-
	M06T3.05S1.02A	Route 9 (at Notch Rd.)	Bridge	556%	-	-	-	-	-	-	-	-	-	-	-	X	-	X
	M06T3.05S1.03	City Stream Rd.	Arch	59%	-	-	-	-	-	-	-	-	-	-	-	-	-	-
	M06T3.05S1.04A	Driveway off City Stream Rd.	Bridge	150%	-	-	-	X	-	-	-	-	-	-	-	X	-	-
	M06T3.05S1.04D	Prospect Access	Culvert	53%	-	-	-	-	-	-	-	-	-	-	-	-	-	-
	M06T3.05S1.04D	Greenwood Dr.	Culvert	67%	-	-	-	-	-	-	-	-	-	-	-	-	-	-
	M06T3.05S1.06	Driveway off Route 9	Bridge	97%	-	-	-	-	-	-	-	-	-	-	-	-	-	-
	M06T3.05S1.06	Snowmobile trail off Route 9	Bridge	300%	-	-	-	-	-	-	-	-	-	-	-	-	-	-
	M06T3.05S1.06	Route 9	Culvert	18%	-	-	-	X	-	-	-	-	-	-	-	-	-	-
	M06T3.05S1.07	Evergreen Ln.	Culvert	48%	-	-	-	-	-	-	-	-	-	-	-	-	-	-
Bolles Brook	M06T3.05B	2nd bridge on Harbour Rd.	Bridge	300%	-	-	-	-	-	-	-	-	-	-	-	-	-	X
	M06T3.05C	3rd bridge on Harbour Rd.	Bridge	133%	-	-	-	-	-	-	-	-	-	X	-	-	-	-
	M06T3.06	National Forest Rd.	Bridge	105%	-	-	-	-	-	-	-	-	-	-	-	-	-	X

Appendix F: Reach Assessment Photographs

Segment ID: S1.01A		Photo #: 100_0875	Date: 9/11/2007	Segment ID: S1.01A		Photo #: 100_0976	Date: 9/17/2007
View: US	Description: Bottom of segment S1.01A			View: US	Description: Bedrock wall and steep riffle		
							
Segment ID: S1.01A		Photo #: 100_0977	Date: 9/17/2007	Segment ID: S1.01A		Photo #: 100_0978	Date: 9/17/2007
View: US	Description: Close-up of bedrock wall and steep riffle			View: DS	Description: Left bank erosion along Rt. 9		
							

Segment ID: S1.01A		Photo #: 100_0987	Date: 9/17/2007	Segment ID: S1.01A		Photo #: 100_0988	Date: 9/17/2007
View: US	Description: Cross-section of segment S1.01A			View: DS	Description: Cross-section of segment S1.01A		
							
Segment ID: S1.01A		Photo #: 100_0989	Date: 9/17/2007	Segment ID: S1.01A		Photo #: 100_0992	Date: 9/18/2007
View: RB	Description: Cross-section of segment S1.01A			View: DS	Description: Top of segment S1.01A		
							

Segment ID: S1.01B		Photo #: 100_0993		Date: 9/18/2007	
View: US		Description: Bottom of segment S1.01B			
					

Segment ID: S1.01B		Photo #: 100_0995		Date: 9/18/2007	
View: LB		Description: Rip-rap on berm			
					

Segment ID: S1.01B		Photo #: 100_0997		Date: 9/18/2007	
View: LB		Description: Bank erosion along Rt. 9 (near cross-section)			
					

Segment ID: S1.01B		Photo #: 100_0998		Date: 9/18/2007	
View: US		Description: Head cut			
					

Segment ID: S1.01B	Photo #: 100_1000	Date: 9/18/2007	Segment ID: S1.01B	Photo #: 100_0990	Date: 9/17/2007
View: US	Description: Bedrock constriction/steep riffle (segment break)		View: US	Description: Cross-section of segment S1.01B	
					
Segment ID: S1.01B	Photo #: 100_0991	Date: 9/17/2007	Segment ID: S1.01C	Photo #: 100_1003	Date: 9/18/2007
View: DS	Description: Cross-section of segment S1.01B		View: LB	Description: Berm erosion	
					

Segment ID: S1.01C		Photo #: 100_1004		Date: 9/18/2007	
View: US		Description: Berm erosion and sedimentation upstream			
					


Segment ID: S1.01C		Photo #: 100_1005		Date: 9/18/2007	
View: US		Description: Large mid-channel bar upstream of berm erosion			
					

Segment ID: S1.01C		Photo #: 100_1007		Date: 9/18/2007	
View: DS		Description: Top of segment S1.01C			
					

Segment ID: S1.01C		Photo #: 100_1009		Date: 9/18/2007	
View: US		Description: Cross-section of segment S1.01C			
					

Segment ID: S1.01C		Photo #: 100_1010		Date: 9/18/2007	
View: LB		Description: Cross-section of segment S1.01C			
					

Segment ID: S1.01C		Photo #: 100_1011		Date: 9/18/2007	
View: DS		Description: Cross-section of segment S1.01C			
					

Segment ID: S1.02A		Photo #: 100_1008		Date: 9/18/2007	
View: US		Description: Bottom of segment S1.02A			
					
Segment ID: S1.02A		Photo #: 100_0918		Date: 9/12/2007	
View: US		Description: Deposition under Rt. 9 bridge			
					
Segment ID: S1.02A		Photo #: 100_0919		Date: 9/12/2007	
View: DS		Description: Sedimentation above Rt. 9 bridge			
					
Segment ID: S1.02A		Photo #: 100_1012		Date: 9/18/2007	
View: US		Description: Left bank erosion upstream of Rt. 9 bridge			
					

Segment ID: S1.02A		Photo #: 100_1029	Date: 9/19/2007	Segment ID: S1.02A		Photo #: 100_1028	Date: 9/19/2007
View: US	Description: Cross-section of segment S1.02A			View: DS	Description: Cross-section of segment S1.02A		
							
Segment ID: S1.02A		Photo #: 100_1025	Date: 9/18/2007	Segment ID: S1.02B		Photo #: 100_1027	Date: 9/18/2007
View: DS	Description: Top of segment S1.02A			View: US	Description: Bottom of segment S1.02B		
							

Segment ID: S1.02B		Photo #: 100_1013	Date: 9/18/2007	Segment ID: S1.02B		Photo #: 100_1015	Date: 9/18/2007
View: US	Description: Enlargement of bed material at reach break			View: LB	Description: Piled dredging material along left bank		
							
Segment ID: S1.02A		Photo #: 100_1017	Date: 9/18/2007	Segment ID: S1.02B		Photo #: 100_1018	Date: 9/18/2007
View: DS	Description: Left bank erosion and leaning trees			View: US	Description: Left bank erosion		
							


Segment ID: S1.02B		Photo #: 100_1020		Date: 9/18/2007	
View: RB		Description: Right bank erosion where valley wall meets bank			
					

Segment ID: S1.02B		Photo #: 100_1022		Date: 9/18/2007	
View: DS		Description: Top of segment S1.02B			
					




Segment ID: S1.03		Photo #: 100_1021		Date: 9/18/2007	
View: US		Description: Top of reach S1.03			
					

Segment ID: S1.02B		Photo #: 100_1023		Date: 9/18/2007	
View: US		Description: Confluence with Stamford Stream			
					

Segment ID: S1.02B		Photo #: 100_1024		Date: 9/18/2007	
View: US		Description: Stamford Stream			
					

Segment ID: S1.02B		Photo #: 100_1033		Date: 9/19/2007	
View: US		Description: Cross-section of segment S1.02B			
					

Segment ID: S1.02B		Photo #: 100_1030		Date: 9/19/2007	
View: DS		Description: Cross-section of segment S1.02B			
					

Segment ID: S1.03		Photo #: 100_0947	Date: 9/14/2007	Segment ID: S1.04A		Photo #: 100_0946	Date: 9/14/2007
View: DS	Description: Top of reach S1.03 (not assessed)			View: US	Description: Bottom of segment S1.04A (bedrock gorge)		
							
Segment ID: S1.04A		Photo #: 100_0948	Date: 9/14/2007	Segment ID: S1.04A		Photo #: 100_0949	Date: 9/14/2007
View: US	Description: Bedrock outcrops causing channel constriction			View: DS	Description: Bedrock outcrops causing channel constriction		
							

Segment ID: S1.04A		Photo #: 100_0952	Date: 9/14/2007	Segment ID: S1.04A		Photo #: 100_0956	Date: 9/14/2007
View: US		Description: Grade control (waterfall)		View: DS		Description: Top of segment S1.04A (bedrock gorge)	
							
Segment ID: S1.04B		Photo #: 100_0957	Date: 9/14/2007	Segment ID: S1.04B		Photo #: 100_0958	Date: 9/14/2007
View: US		Description: Bottom of segment S1.04B		View: US		Description: Steep riffle	
							

Segment ID: S1.04B		Photo #: 100_0959	Date: 9/14/2007	Segment ID: S1.04B		Photo #: 100_0961	Date: 9/14/2007
View: US	Description: Grade controls (series of ledges)			View: DS	Description: Top of segment S1.04B		
							
Segment ID: S1.04B		Photo #: 100_0974	Date: 9/17/2007	Segment ID: S1.04B		Photo #: 100_0975	Date: 9/17/2007
View: US	Description: Cross section of segment S1.04B			View: DS	Description: Cross section of segment S1.04B		
							

Segment ID: S1.04B		Photo #: 100_0960		Date: 9/14/2007	
View: US		Description: Beaver dam (bottom of segment S1.04C)			
					

Segment ID: S1.04C		Photo #: 100_0962		Date: 9/14/2007	
View: US		Description: Impoundment above beaver dam (not assessed)			
					

Segment ID: S1.04C		Photo #: 100_0964		Date: 9/14/2007	
View: DS		Description: Top of segment S1.04C (not assessed)			
					

Segment ID: S1.04D		Photo #: 100_0963		Date: 9/14/2007	
View: US		Description: Bottom of segment S1.04D			
					

Segment ID: S1.04D		Photo #: 100_0945		Date: 9/14/2007	
View: US		Description: New beaver dam near bottom of segment S1.04D			
					

Segment ID: S1.04D		Photo #: 100_0965		Date: 9/14/2007	
View: DS		Description: Characteristic view of segment			
					

Segment ID: S1.04D		Photo #: 100_0966		Date: 9/14/2007	
View: US		Description: Steel bridge support (no deck)			
					

Segment ID: S1.04D		Photo #: 100_0967		Date: 9/14/2007	
View: DS		Description: Top of segment S1.04D (dam spillway)			
					

Segment ID: S1.05		Photo #: 100_0968		Date: 9/14/2007		Segment ID: S1.04D		Photo #: 100_0969		Date: 9/14/2007	
View: US		Description: Bottom of segment S1.05 (Bugbee Mill Pond)				View: RB		Description: Cross section of segment S1.04D			
											
Segment ID: S1.04D		Photo #: 100_0970		Date: 9/14/2007							
View: US		Description: Cross section of segment S1.04D									
											

Segment ID: S1.06		Photo #: 100_0934		Date: 9/13/2007	
View: US		Description: Bottom of reach S1.06			
					

Segment ID: S1.06		Photo #: 100_0935		Date: 9/13/2007	
View: DS		Description: Top of reach S1.05 (impoundment—not assessed)			
					

Segment ID: S1.06		Photo #: 100_0936		Date: 9/13/2007	
View: US		Description: Old stone fence causing channel constriction			
					

Segment ID: S1.06		Photo #: 100_0937		Date: 9/13/2007	
View: US		Description: Wooden footbridge			
					

Segment ID: S1.06		Photo #: 100_0938	Date: 9/13/2007	Segment ID: S1.06		Photo #: 100_0939	Date: 9/13/2007
View: US	Description: Old stone fence/dam causing channel constriction			View: DS	Description: Channel caused by old stone fence/dam		
							
Segment ID: S1.06		Photo #: 100_0900	Date: 9/12/2007	Segment ID: S1.06		Photo #: 100_0901	Date: 9/12/2007
View: US	Description: Upstream of snowmobile bridge			View: DS	Description: Downstream of snowmobile bridge		
							



Segment ID: S1.06		Photo #: 100_0940		Date: 9/13/2007	
View: US		Description: Pond above dam at reach break			
					

Segment ID: S1.06		Photo #: 100_0941		Date: 9/13/2007	
View: DS		Description: Reach break dam and channel below			
					

Segment ID: S1.06		Photo #: 100_0943		Date: 9/13/2007	
View: US		Description: Cross-section			
					

Segment ID: S1.06		Photo #: 100_0944		Date: 9/13/2007	
View: DS		Description: Cross-section			
					

Segment ID: T3.05A	Photo #: 100_1034	Date: 9/19/2007	Segment ID: T3.05A	Photo #: 100_1035	Date: 9/19/2007
View: DS	Description: Muddy water from dredging above dam		View: US	Description: Left bank erosion	
					
Segment ID: T3.05A	Photo #: 100_1036	Date: 9/19/2007	Segment ID: T3.05A	Photo #: 100_1037	Date: 9/19/2007
View: DS	Description: Left bank erosion and development		View: US	Description: Head cut	
					



Segment ID: T3.05A		Photo #: 100_1069	Date: 9/25/2007		Segment ID: T3.05A		Photo #: 100_1070	Date: 9/25/2007	
View: US		Description: Cross section			View: DS		Description: Cross section and development		
									
Segment ID: T3.05A		Photo #: 100_1067	Date: 9/25/2007		Segment ID: T3.05A		Photo #: 100_1038	Date: 9/19/2007	
View: RB		Description: Cross section			View: US		Description: Diagonal bar (bottom of segment T3.05B)		
									

Segment ID: T3.05B		Photo #: 100_1043		Date: 9/19/2007	
View: US		Description: Old concrete slabs under bridge (grade control)			
					

Segment ID: T3.05B		Photo #: 100_1044		Date: 9/24/2007	
View: US		Description: Bedrock outcrop and steep riffle/diagonal bar			
					

Segment ID: T3.05B		Photo #: 100_1046		Date: 9/24/2007	
View: LB		Description: Old concrete slab bank revetment			
					


Segment ID: T3.05B		Photo #: 100_1049		Date: 9/24/2007	
View: US		Description: Old concrete slabs in channel (grade control)			
					

Segment ID: T3.05B		Photo #: 100_1050	Date: 9/24/2007	Segment ID: T3.05B		Photo #: 100_1052	Date: 9/24/2007
View: US	Description: Left bank erosion			View: US	Description: Large point bar, steep riffle, and bedrock outcrop		
							
Segment ID: T3.05B		Photo #: 100_1053	Date: 9/24/2007	Segment ID: T3.05B		Photo #: 100_1072	Date: 9/25/2007
View: US	Description: Steep riffle (top of segment T3.05B)			View: US	Description: Cross section		
							

Segment ID: T3.05B		Photo #: 100_1074	Date: 9/25/2007		Segment ID: T3.05C		Photo #: 100_0887	Date: 9/24/2007	
View: LB		Description: Cross section			View: LB		Description: Small dam and drinking water withdrawal		
									
Segment ID: T3.05C		Photo #: 100_1078	Date: 9/25/2007		Segment ID: T3.05C		Photo #: 100_1079	Date: 9/25/2007	
View: DS		Description: Cross section			View: US		Description: Cross section		
									

Segment ID: T3.05C	Photo #: 100_1054	Date: 9/24/2007
View: DS	Description: Top of segment T3.05C	



Segment ID: T3.06		Photo #: 100_1055	Date: 9/24/2007	Segment ID: T3.06		Photo #: 100_1056	Date: 9/24/2007
View: US	Description: Bottom of reach (braiding, islands)			View: US	Description: Mouth of Bickford Hollow Brook at reach break		
							
Segment ID: T3.06		Photo #: 100_1058	Date: 9/24/2007	Segment ID: T3.06		Photo #: 100_1059	Date: 9/24/2007
View: US	Description: Steep riffle and large deposition			View: DS	Description: Top of characteristic dry side channel		
							

Segment ID: T3.06		Photo #: 100_1060	Date: 9/24/2007	Segment ID: T3.06		Photo #: 100_1061	Date: 9/24/2007
View: DS	Description: Incising section with right bank erosion			View: DS	Description: Debris jam blocking side channel above x-section		
							
Segment ID: T3.06		Photo #: 100_1062	Date: 9/24/2007	Segment ID: T3.06		Photo #: 100_1064	Date: 9/24/2007
View: US	Description: Bottom of reach T3.07			View: US	Description: Cross section		
							

Segment ID: T3.06	Photo #: 100_1066	Date: 9/24/2007
View: DS	Description: Cross section	

A photograph of a small, rocky stream flowing through a dense forest. The water is clear and shallow, with many rocks visible. The banks are covered in green foliage and trees. A large, dark tree trunk leans over the stream on the right side.


Appendix G: Bridge and Culvert Assessment Photographs

Segment ID: S1.01A		Photo #: 100_0873		Date: 9/11/2007	
View: DS		Description: Inlet of Harbor Rd. bridge			
					
Segment ID: S1.01A		Photo #: 100_0871		Date: 9/11/2007	
View: US		Description: Upstream of Harbor Rd. bridge			
					


Segment ID: S1.01A		Photo #: 100_0874		Date: 9/11/2007	
View: US		Description: Outlet of Harbor Rd. bridge			
					
Segment ID: S1.01A		Photo #: 100_0872		Date: 9/11/2007	
View: DS		Description: Downstream of Harbor Rd. bridge			
					

Segment ID: S1.02A		Photo #: 100_0919		Date: 9/12/2007	
View: DS		Description: Inlet of Rt. 9 bridge			
					
Segment ID: S1.02A		Photo #: 100_0918		Date: 9/12/2007	
View: US		Description: Outlet of Rt. 9 bridge			
					
Segment ID: S1.02A		Photo #: 100_0920		Date: 9/12/2007	
View: US		Description: Upstream of Rt. 9 bridge			
					
Segment ID: S1.02A		Photo #: 100_0921		Date: 9/18/2007	
View: DS		Description: Downstream of Rt. 9 bridge (reach break)			
					

Segment ID: S1.03		Photo #: 100_0927		Date: 9/12/2007		Segment ID: S1.03		Photo #: 100_0926		Date: 9/12/2007	
View: DS		Description: Inlet of arch on City Stream Rd.				View: US		Description: Outlet of arch on City Stream Rd.			
											
Segment ID: S1.03		Photo #: 100_0922		Date: 9/12/2007		Segment ID: S1.03		Photo #: 100_0924		Date: 9/12/2007	
View: US		Description: Upstream of arch on City Stream Rd.				View: DS		Description: Downstream of arch on City Stream Rd.			
											

Segment ID: S1.04A		Photo #: 100_0931	Date: 9/12/2007	Segment ID: S1.04A		Photo #: 100_0932	Date: 9/12/2007
View: DS		Description: Inlet of bridge on driveway off City Stream Rd.		View: US		Description: Outlet of bridge on driveway off City Stream Rd.	
							
Segment ID: S1.04A		Photo #: 100_0928	Date: 9/12/2007	Segment ID: S1.03		Photo #: 100_0929	Date: 9/12/2007
View: US		Description: Upstream of bridge off City Stream Rd.		View: DS		Description: Downstream of bridge off City Stream Rd.	
							

Segment ID: S1.04D		Photo #: 100_0917	Date: 9/12/2007	Segment ID: S1.04C		Photo #: 100_0916	Date: 9/12/2007
View: DS	Description: Inlet of culvert on driveway to Prospect Mt.			View: US	Description: Outlet of culvert on driveway to Prospect Mt.		
							
Segment ID: S1.04D		Photo #: 100_0916	Date: 9/12/2007	Segment ID: S1.04C		Photo #: 100_0914	Date: 9/12/2007
View: US	Description: Upstream of culvert on driveway to Prospect Mt.			View: DS	Description: Downstream of culvert on driveway to Prospect Mt.		
							

Segment ID: S1.04D		Photo #: 100_0912		Date: 9/12/2007	
View: DS		Description: Inlet of culvert below Bugbee Mill Pond			
					
Segment ID: S1.04D		Photo #: 100_0913		Date: 9/12/2007	
View: US		Description: Outlet of culvert below Bugbee Mill Pond			
					
Segment ID: S1.04D		Photo #: 100_0910		Date: 9/12/2007	
View: US		Description: Upstream of culvert below Bugbee Mill Pond			
					
Segment ID: S1.04D		Photo #: 100_0911		Date: 9/12/2007	
View: DS		Description: Downstream of culvert below Bugbee Mill Pond			
					

Segment ID: S1.06		Photo #: 100_0909	Date: 9/12/2007	Segment ID: S1.06		Photo #: 100_0908	Date: 9/12/2007
View: DS	Description: Inlet of bridge on driveway off Rt. 9			View: US	Description: Outlet of bridge on driveway off Rt. 9		
							
Segment ID: S1.06		Photo #: 100_0906	Date: 9/12/2007	Segment ID: S1.06		Photo #: 100_0907	Date: 9/12/2007
View: US	Description: Upstream of bridge on driveway off Rt. 9			View: DS	Description: Downstream of bridge on driveway off Rt. 9		
							

Segment ID: S1.06		Photo #: 100_0903		Date: 9/12/2007	
View: DS		Description: Inlet of snowmobile bridge			
					
Segment ID: S1.06		Photo #: 100_0900		Date: 9/12/2007	
View: US		Description: Upstream of snowmobile bridge			
					

Segment ID: S1.06		Photo #: 100_0902		Date: 9/12/2007	
View: US		Description: Outlet of snowmobile bridge			
					
Segment ID: S1.06		Photo #: 100_0901		Date: 9/12/2007	
View: DS		Description: Downstream of snowmobile bridge			
					

Segment ID: S1.06		Photo #: 100_0897		Date: 9/12/2007	
View: DS		Description: Inlet of culvert across Rt. 9			
					

Segment ID: S1.06		Photo #: 100_0899		Date: 9/12/2007	
View: US		Description: Outlet of culvert across Rt. 9			
					

Segment ID: S1.06		Photo #: 100_0896		Date: 9/12/2007	
View: US		Description: Upstream of culvert across Rt. 9			
					

Segment ID: S1.06		Photo #: 100_0896		Date: 9/12/2007	
View: DS		Description: Downstream of culvert across Rt. 9			
					

Segment ID: S1.06		Photo #: 100_0895		Date: 9/12/2007	
View: DS		Description: Inlet of culvert below Big Pond			
					

Segment ID: S1.06		Photo #: 100_0894		Date: 9/12/2007	
View: US		Description: Outlet of culvert below Big Pond			
					

Segment ID: S1.06		Photo #: 100_0893		Date: 9/12/2007	
View: US		Description: Upstream of culvert below Big Pond			
					

Segment ID: S1.06		Photo #: 100_0892		Date: 9/12/2007	
View: DS		Description: Downstream of culvert below Big Pond			
					


Segment ID: T3.05		Photo #: 100_0890		Date: 9/11/2007	
View: DS		Description: Inlet of 1 st Bolles Brook bridge on Harbor Rd.			
					

Segment ID: T3.05		Photo #: 100_0891		Date: 9/11/2007	
View: US		Description: Outlet of 1 st Bolles Brook bridge on Harbor Rd.			
					

Segment ID: T3.05		Photo #: 100_0888		Date: 9/11/2007	
View: US		Description: Upstream of 1 st Bolles Br. bridge on Harbor Rd.			
					

Segment ID: T3.05		Photo #: 100_0889		Date: 9/11/2007	
View: DS		Description: Downstream of 1 st Bolles Br. bridge on Harbor Rd.			
					

Segment ID: T3.05		Photo #: 100_0884		Date: 9/11/2007	
View: DS		Description: Inlet of bridge above dam on Harbor Rd.			
					
Segment ID: T3.05		Photo #: 100_0886		Date: 9/11/2007	
View: US		Description: Outlet of bridge above dam on Harbor Rd.			
					
Segment ID: T3.05		Photo #: 100_0882		Date: 9/11/2007	
View: US		Description: Upstream of bridge above dam on Harbor Rd.			
					
Segment ID: T3.05		Photo #: 100_0883		Date: 9/11/2007	
View: DS		Description: Downstream of bridge above dam on Harbor Rd.			
					

Segment ID: T3.06		Photo #: 100_0880		Date: 9/11/2007	
View: DS		Description: Inlet of bridge on National Forest road			
					
Segment ID: T3.06		Photo #: 100_0881		Date: 9/11/2007	
View: US		Description: Outlet of bridge on National Forest road			
					
Segment ID: T3.06		Photo #: 100_0878		Date: 9/11/2007	
View: US		Description: Upstream of bridge on National Forest road			
					
Segment ID: T3.06		Photo #: 100_0879		Date: 9/11/2007	
View: DS		Description: Downstream of bridge on National Forest road			
					

Appendix H: Standard Phase 2 Database Output Reports

Stream Geometry Data

Walloomsac Woodford

Reach	Seg- ment	Phase 2 Stream Type			Phase 1 Data		Phase 2 Channel Data														RGA		
		Stream Type	Bed Material	Bedform	Subcl. Slope	Sub Rch?	Channel Slope	Channel width	Bankfull width	Max. depth	Mean depth	Floodpr. width	Abandn FldPln	W/D Ratio	Entrench- ment	Incision Ratio	StageEvol.	Evol. Model.	Cond.	RHA	QC Stf Aut		
M6T3.05	A	B	Cobble	Step-Pool	None	No	6.85	64.28	48.0	3.0	2.18	86.6	3.04	22.02	1.80	1.01	III	F	Fair	Good	F	P	
M6T3.05	B	B	Cobble	Step-Pool	c	No	6.24	64.28	55.52	2.88	1.87	87.3	5.18	29.69	1.57	1.80	IV	F	Fair	Good	F	P	
M6T3.05	C	B	Cobble	Step-Pool	c	No	12.03	64.28	32.0	4.22	2.62	59.2		12.21	1.85		II	F	Fair	Good	F	P	
M6T3.05S1.01	A	B	Cobble	Step-Pool	None	No	9.26	46.27	62.0	2.92	1.98	99.6	6.97	31.31	1.61	2.39	III	F	Fair	Good	F	P	
M6T3.05S1.01	B	F	Cobble	Step-Pool	None	No	16.34	46.27	56.66	3.07	2.11	65.0	7.36	26.85	1.15	2.40	III	F	Poor	Good	F	P	
M6T3.05S1.01	C	B	Cobble	Step-Pool	None	No	5.61	46.27	54.0	3.25	2.19	88.5	4.51	24.66	1.64	1.39	III	F	Fair	Good	F	P	
M6T3.05S1.02	A	F	Cobble	Step-Pool	None	No	6.99	43.96	60.64	2.94	1.7	67.7		35.67	1.12		III	F	Fair	Fair	F	P	
M6T3.05S1.02	B	B	Cobble	Step-Pool	a	No	8.34	43.96	52.0	3.35	1.97	63.0	6.16	26.40	1.21	1.84	II	F	Fair	Good	F	P	
M6T3.05S1.03	0					No	6.18	24.65													F	F	
M6T3.05S1.04	A					No	13.65	20.33													F	F	
M6T3.05S1.04	B	F	Gravel	Riffle-Pool	None	No	6.38	20.33	23.38	1.74	0.89	30.3	3.49	26.27	1.30	2.01	II	F	Fair	Good	F	P	
M6T3.05S1.04	C					No	16.03	20.33													F	F	
M6T3.05S1.04	D	F	Gravel	Riffle-Pool	None	No	3.63	20.33	16.0	1.43	1.09	21.0	3.23	14.68	1.31	2.26	II	F	Fair	Good	F	P	
M6T3.05S1.06	0	D	Gravel	Braided	b	No	3.32	14.59	16.0	1.39	0.97	34.8	2.22	16.49	2.17	1.60	IV	F	Good	Good	F	P	
M6T3.06	0	D	Cobble	Braided	b	No	3.40	39.13	29.0	2.8	1.76	115.0	5.55	16.48	3.97	1.98	IV	F	Good	Good	F	P	

Rapid Geomorphic Assessment

Walloomsac Woodford

Reach	Seg- ment	Sub- Rch?	Degradation			Aggradation			Widening		Planform		Geo. Score	Geo. Condition	Evol. Stage	Confin- ement Type	Sens- itivity	QC	
			Score	STD	Historic	Score	STD	Historic	Score	Historic	Score	Historic						Stf	Aut
M6T3.05	A	No	5	None	No	14	None	No	9	No	12	No	0.50	Fair	III	BD	High	F	P
M6T3.05	B	No	5	None	Yes	13	None	No	10	No	17	No	0.56	Fair	IV	BD	High	F	P
M6T3.05	C	No	5	None	No	15	None	No	14	No	14	No	0.60	Fair	II	VB	High	F	P
M6T3.05S1.01	A	No	10	C to B	No	14	None	No	11	No	13	No	0.60	Fair	III	SC	High	F	P
M6T3.05S1.01	B	No	5	C to F	Yes	15	None	No	10	No	11	No	0.51	Poor	III	NC	Extreme	F	P
M6T3.05S1.01	C	No	8	C to B	Yes	12	None	No	9	No	9	No	0.48	Fair	III	NW	High	F	P
M6T3.05S1.02	A	No	5	B to F	Yes	10	None	No	8	No	11	No	0.43	Fair	III	NC	Extreme	F	P
M6T3.05S1.02	B	No	5	None	No	13	None	No	11	No	12	No	0.51	Fair	II	NW	Extreme	F	P
M6T3.05S1.03	0	No											0.00					F	F
M6T3.05S1.04	A	No											0.00					F	F
M6T3.05S1.04	B	No	5	C to F	No	16	None	No	12	No	18	No	0.64	Fair	II	VB	Extreme	F	P
M6T3.05S1.04	C	No											0.00					F	F
M6T3.05S1.04	D	No	5	C to F	No	13	None	No	13	No	16	No	0.59	Fair	II	VB	Extreme	F	P
M6T3.05S1.06	0	No	14	None	No	15	None	No	13	No	16	No	0.73	Good	IV	VB	Extreme	F	P
M6T3.06	0	No	13	None	No	16	None	No	12	No	13	No	0.68	Good	IV	VB	Extreme	F	P

Project: Walloomsac Woodford

Stream: City Stream

Organization: Bennington County NRCD

Segment Length (ft): 2,377

Phase 2 Segment Summary

page 1 of 2

November 27, 2007 SGAT Version: 4.56

Reach # M6T3.05S1.01

Segment: A

Completion Date: September 17, 2007

Observers: Jason George and Jill Winton

Why Not assessed:

Rain: Yes

Segment Location: From confluence with Bolles Brook upstream to old logging road stream ford.

QC Status - Staff: Provisional Consultant: Provisional Step 2. (Contued)

Step 1. Valley and Floodplain

1.1 Segmentation Valley Width

1.2 Alluvial Fan None

1.3 Corridor Encroachments

Length (ft)	One	Both
Berms	1,228	0
height	0	0
Roads	675	0
height	0	0
Railroads	0	0
height	0	0
Improved Paths	0	0
height	0	0
Development	834	0

2.5 Aband. Floodpln 6.97 ft.

Human Elev Floodpln 11.62 ft.

2.6 Width/Depth Ratio 31.31

2.7 Entrenchment Ratio 1.61

2.8 Incision Ratio 2.39

Human Elevated Inc Rat 3.98

2.9 Sinuosity Low

2.10 Riffles Type Complete

2.11 Riffle/Step Spacing (ft) 70

2.12 Substrate Composition

Bedrock 0%

Boulder 29%

Cobble 44%

Coarse Gravel 19%

Fine Gravel 7%

Sand 1%

Silt and smaller 0%

Silt/Clay Present? No

Detritus 3 %

Large Woody 18

2.13 Average Largest Particle on

Bed 36.0 inches

Bar 15.0 inches

Step 3. Riparian Features

3.1 Stream Banks

Typical Bank Slope Steep

Bank Texture Left Right

Upper

Material Type Boulder/Cobbl Mix

Consistency Non-cohesive Cohesive

Lower

Material Type Boulder/Cobbl Boulder/Cobbl

Consistency Non-cohesive Non-cohesive

Bank Erosion Left Right

Erosion Length (ft) 110 0

Erosion Height (ft) 6.00 0.00

Revetmt. Type None Rip-Rap

Revetmt. Length (ft) 0 10

Near Bank Veg. Type Left Right

Dominant Shrubs/Saplin Coniferous

Sub-dominant Invasives Deciduous

Bank Canopy Left Right

Canopy % 26-50 76-100

Mid-Channel Canopy Open

3.2 Riparian Buffer

Buffer Width Left Right

Dominant 51-100 >100

Sub-dominant 0-25 None

W less than 25 33 181

Buffer Veg. Type Left Right

Dominant Mixed Trees Mixed Trees

Sub-dominant Shrubs/Saplin Shrubs/Saplin

3.3 Riparian Corridor

Corridor Land Left Right

Dominant Forest Forest

Sub-dominant Residential None

Mass Failures 0 0

Height 0 0

Gullies 0 0

Height 0 0

Step 4. Flow & Flow Modifiers

4.1 Springs / Seeps Minimal

4.2 Adjacent Wetlands None

4.3 Flow Status Moderate

4.4 # of Debris Jams 0

4.5 Flow Regulation Type None

Flow Regulation Use

Impoundments None

Impoundmt. Location

4.6 Up/Down strm flow reg None

(old) Upstrm Flow Reg None

4.7 StormwaterInputs

Field Ditch 0 Road Ditch 0

Other 0 Tile Drain 0

Overland Flow 0 Urb Strm Wtr Pipe 0

4.9 # of Beaver Dams 0

Affected Length (ft) 0

Step 5. Channel Bed and Planform Changes

5.1 Bar Types

Mid Point Side

0 1 1

Diagonal Delta Island

0 0 1

5.2 Other Features Braiding

Flood Neck Cutoff Avulsion 2

2 0 0

5.3 Steep Riffles and Head Cuts

Steep Riffles Head Cuts Trib Rejuv.

1 1 No

5.4 Stream Ford or Animal Yes

5.5 Straightening Straightening

Straightening Length: 126

5.5 Dredging Dredging

Project: Walloomsac Woodford	Phase 2 Segment Summary	page 2 of 2	November 27, 2007
Stream: City Stream	Reach # M6T3.05S1.01	Segment: A	Completion Date: September 17,
Organization: Bennington County NRCD	Observers: Jason George and Jill Winton		Rain: Yes
Segment Length (ft): 2,377	Segment Location: From confluence with Bolles Brook upstream to old logging road stream ford.		

1.6 Grade Controls		None			
Type	Location	Total	Total Height Above Water	Photo Taken	GPSTaken

4.8 Channel Constrictions					
Type	Width	Photo Taken?	GPS Taken?	Channel Constriction?	Floodprone Constriction?
Bridge	90.0	Yes	Yes	No	Yes
Problem		Deposition Below			

Narrative:
Degradation

Step 7. Rapid Geomorphic Assessment Data			
Confinement Type		Confined	
	Score	STD	Historic
7.1 Channel Degradation	10	C to B	No
7.2 Channel Aggradation	14	None	No
7.3 Widening Channel	11		No
7.4 Change in Planform	13		No
Total Score	48		
Geomorphic Rating	0.6		
Channel Evolution Model	F		
Channel Evolution Stage	III		
Geomorphic Condition	Fair		
Stream Sensitivity	High		

Step 6. Rapid Habitat Assessment Data	
Stream Gradient Type	High
	Score
6.1 Epifaunal Substrate - Available Cover	15
6.2 Embeddedness	18
6.3 Velocity/Depth Patterns	15
6.4 Sediment Deposition	10
6.5 Channel Flow Status	14
6.6 Channel Alteration	10
6.7 Frequency of Riffles/Steps	18
6.8 Bank Stability	Left: 8 Right: 9
6.9 Bank Vegetation Protection	Left: 7 Right: 9
6.10 Riparian Vegetation Zone Width	Left: 5 Right: 10
Total Score	148
Habitat Rating	0.74
Habitat Stream Condition	Good

Project: Walloomsac Woodford

Stream: City Stream

Organization: Bennington County NRCD

Segment Length (ft): 1,346

Phase 2 Segment Summary

page 1 of 2

Reach # M6T3.05S1.01

Segment: B

Observers: Jason George and Jill Winton

Why Not assessed:

November 27, 2007 SGAT Version: 4.56

Completion Date: September 18, 2007

Rain: Yes

Segment Location: From old logging road stream ford upstream to just above bedrock constriction (straight,

QC Status - Staff: Provisional Consultant: Provisional Step 2. (Contued)

Step 1. Valley and Floodplain

1.1 Segmentation Valley Width

1.2 Alluvial Fan None

1.3 Corridor Encroachments

Length (ft)	One	Both
Berms	434	0
height	0	0
Roads	1,346	0
height	0	0
Railroads	0	0
height	0	0
Improved Paths	0	0
height	0	0
Development	0	0

1.4 Adjacent Side Left Right

Hillside Slope	Very Steep	Extremely
Continuous w/	Never	Sometimes
W/in 1 Bankfill	Never	Always
Texture	Not Evalua	Mixed

1.5 Valley Features

Valley Width (ft)	82
Width Determination	Measured
Confinement Type	Narrowly
Rock Gorge?	No

Human-caused Change? Yes

Step 2. Stream Channel

2.1 Bankfull Width	57
2.2 Max Depth (ft)	3.07
2.3 Mean Depth (ft)	2.11
2.4 Floodprone Width (ft)	65

Notes:

Berms constructed of dredged material.

2.5 Aband. Floodpln	7.36 ft.
Human Elev Floodpln	0.00 ft.
2.6 Width/Depth Ratio	26.85
2.7 Entrenchment Ratio	1.15
2.8 Incision Ratio	2.40
Human Elevated Inc Rat	0.00
2.9 Sinuosity	Low
2.10 Riffles Type	Eroded
2.11 Riffle/Step Spacing (ft)	35
2.12 Substrate Composition	
Bedrock	0%
Boulder	27%
Cobble	45%
Coarse Gravel	17%
Fine Gravel	7%
Sand	4%
Silt and smaller	0%

Silt/Clay Present?	No
Detritus	5 %
# Large Woody	10
2.13 Average Largest Particle on	
Bed	48.0 inches
Bar	18.0 inches

2.14 Stream Type

Stream Type:	F
Bed Material:	Cobble
Subclass Slope:	None
Bed Form:	Step-Pool
Field Measured Slope:	1.5

2.15 Reference Stream Type
(if different from Phase 1)

3.3 old	Amount	Mean Height
Failures	None	0.00
Gullies	None	0.00

Step 3. Riparian Features

3.1 Stream Banks

Typical Bank Slope Undercut

Bank Texture Left Right

Upper

Material Type Boulder/Cobbl Boulder/Cobbl

Consistency Non-cohesive Non-cohesive

Lower

Material Type Boulder/Cobbl Boulder/Cobbl

Consistency Non-cohesive Non-cohesive

Bank Erosion Left Right

Erosion Length (ft) 222 0

Erosion Height (ft) 5.00 0.00

Revetmt. Type Rip-Rap None

Revetmt. Length (ft) 303 0

Near Bank Veg. Type Left Right

Dominant Herbaceous Coniferous

Sub-dominant Shrubs/Saplin Deciduous

Bank Canopy Left Right

Canopy % 1-25 51-75

Mid-Channel Canopy Open

3.2 Riparian Buffer

Buffer Width Left Right

Dominant 0-25 >100

Sub-dominant 26-50 None

W less than 25 0 0

Buffer Veg. Type Left Right

Dominant Herbaceous Mixed Trees

Sub-dominant Shrubs/Saplin Shrubs/Saplin

3.3 Riparian Corridor

Corridor Land Left Right

Dominant Bare Forest

Sub-dominant Shrubs/Saplin Shrubs/Saplin

Mass Failures 0 0

Height 0 0

Gullies 0 0

Height 0 0

Step 4. Flow & Flow Modifiers

4.1 Springs / Seeps None

4.2 Adjacent Wetlands None

4.3 Flow Status Moderate

4.4 # of Debris Jams 0

4.5 Flow Regulation Type None

Flow Regulation Use

Impoundments None

Impoundmt. Location

4.6 Up/Down strm flow reg None

(old) Upstrm Flow Reg None

4.7 StormwaterInputs

Field Ditch 0 Road Ditch 0

Other 0 Tile Drain 0

Overland Flow 0 Urb Strm Wtr Pipe 0

4.9 # of Beaver Dams 0

Affected Length (ft) 0

Step 5. Channel Bed and Planform Changes

5.1 Bar Types

Mid Point Side

0 0 0

Diagonal Delta Island

0 0 0

5.2 Other Features Braiding

Flood Neck Cutoff Avulsion 0

0 0 0

5.3 Steep Riffles and Head Cuts

Steep Riffles Head Cuts Trib Rejuv.

0 1 No

5.4 Stream Ford or Animal No

5.5 Straightening Straightening

Straightening Length: 1,346

5.5 Dredging Dredging

Note: Step 1.6 - Grade Controls

and Step 4.8 - Channel Constrictions

are on The second page of this

report - with Steps 6 through 7.

Project: Walloomsac Woodford	Phase 2 Segment Summary	page 2 of 2	November 27, 2007
Stream: City Stream	Reach # M6T3.05S1.01	Segment: B	Completion Date: September 18,
Organization: Bennington County NRCD	Observers: Jason George and Jill Winton		Rain: Yes
Segment Length (ft): 1,346	Segment Location: From old logging road stream ford upstream to just above bedrock constriction (straight,		

1.6 Grade Controls **None**

Type	Location	Total	Total Height Above Water	Photo Taken	GPSTaken
------	----------	-------	--------------------------	-------------	----------

4.8 Channel Constrictions

Type	Width	Photo Taken?	GPS Taken?	Channel Constriction?	Floodprone Constriction?
Bedrock Problem	15.0	Yes	Yes	Yes	No

Step 7. Rapid Geomorphic Assessment Data

Confinement Type **Confined**

	Score	STD	Historic
7.1 Channel Degradation	5	C to F	Yes
7.2 Channel Aggradation	15	None	No
7.3 Widening Channel	10		No
7.4 Change in Planform	11		No

Total Score **41**

Geomorphic Rating **0.5125**

Channel Evolution Model **F**

Channel Evolution Stage **III**

Geomorphic Condition **Poor**

Stream Sensitivity **Extreme**

Step 6. Rapid Habitat Assessment Data

Stream Gradient Type **High**

	Score
6.1 Epifaunal Substrate - Available Cover	10
6.2 Embeddedness	16
6.3 Velocity/Depth Patterns	13
6.4 Sediment Deposition	18
6.5 Channel Flow Status	10
6.6 Channel Alteration	10
6.7 Frequency of Riffles/Steps	13
6.8 Bank Stability	Left: 5 Right: 9
6.9 Bank Vegetation Protection	Left: 5 Right: 10
6.10 Riparian Vegetation Zone Width	Left: 3 Right: 10

Total Score **132**

Habitat Rating **0.66**

Habitat Stream Condition **Good**

Narrative:

Degradation and widening.

Modified from "Fair" to "Poor" condition due to departure from "C" to "F" stream type.

Project: Walloomsac Woodford

Stream: City Stream

Organization: Bennington County NRCD

Segment Length (ft): 3,924

Phase 2 Segment Summary

page 1 of 2

November 27, 2007 SGAT Version: 4.56

Reach # M6T3.05S1.01

Segment: C

Completion Date: September 18, 2007

Observers: Jason George and Jill Winton

Why Not assessed:

Rain: Yes

Segment Location: From just above bedrock constriction to just below Route 9 bridge.

QC Status - Staff: Provisional Consultant: Provisional Step 2. (Contued)

Step 1. Valley and Floodplain

1.1 Segmentation Valley Width

1.2 Alluvial Fan None

1.3 Corridor Encroachments

Length (ft)	One	Both
Berms	2,617	0
height	0	0
Roads	1,758	0
height	0	0
Railroads	0	0
height	0	0
Improved Paths	0	0
height	0	0
Development	522	0

1.4 Adjacent Side Left Right

Hillside Slope	Very Steep	Extremely
Continuous w/	Never	Sometimes
W/in 1 Bankfill	Never	Sometimes
Texture	Not Evalua	Mixed

1.5 Valley Features

Valley Width (ft)	240
Width Determination	Measured
Confinement Type	Narrow
Rock Gorge?	No
Human-caused Change?	Yes

Step 2. Stream Channel

2.1 Bankfull Width	54
2.2 Max Depth (ft)	3.25
2.3 Mean Depth (ft)	2.19
2.4 Floodprone Width (ft)	89

Notes:

Berms constructed of dredged material.

2.5 Aband. Floodpln	4.51 ft.
Human Elev Floodpln	13.62 ft.
2.6 Width/Depth Ratio	24.66
2.7 Entrenchment Ratio	1.64
2.8 Incision Ratio	1.39
Human Elevated Inc Rat	4.19
2.9 Sinuosity	Low
2.10 Riffles Type	Complete
2.11 Riffle/Step Spacing (ft)	0
2.12 Substrate Composition	
Bedrock	1%
Boulder	28%
Cobble	47%
Coarse Gravel	15%
Fine Gravel	7%
Sand	2%
Silt and smaller	0%

Silt/Clay Present?	No
Detritus	5 %
# Large Woody	13
2.13 Average Largest Particle on	
Bed	48.0 inches
Bar	18.0 inches

2.14 Stream Type

Stream Type:	B
Bed Material:	Cobble
Subclass Slope:	None
Bed Form:	Step-Pool
Field Measured Slope:	3.1

2.15 Reference Stream Type
(if different from Phase 1)

3.3 old	Amount	Mean Height
Failures	None	0.00
Gullies	None	0.00

Step 3. Riparian Features

3.1 Stream Banks

Typical Bank Slope Steep

Bank Texture Left Right

Upper

Material Type Boulder/Cobbl Boulder/Cobbl

Consistency Non-cohesive Non-cohesive

Lower

Material Type Boulder/Cobbl Boulder/Cobbl

Consistency Non-cohesive Non-cohesive

Bank Erosion Left Right

Erosion Length (ft) 551 319

Erosion Height (ft) 5.17 6.67

Revetmt. Type Rip-Rap None

Revetmt. Length (ft) 279 0

Near Bank Veg. Type Left Right

Dominant Deciduous Coniferous

Sub-dominant Shrubs/Saplin Deciduous

Bank Canopy Left Right

Canopy % 51-75 51-75

Mid-Channel Canopy Open

3.2 Riparian Buffer

Buffer Width Left Right

Dominant 51-100 >100

Sub-dominant 26-50 None

W less than 25 0 0

Buffer Veg. Type Left Right

Dominant Mixed Trees Mixed Trees

Sub-dominant Shrubs/Saplin Shrubs/Saplin

3.3 Riparian Corridor

Corridor Land Left Right

Dominant Forest Forest

Sub-dominant Residential None

Mass Failures 0 43

Height 0 20

Gullies 0 0

Height 0 0

Step 4. Flow & Flow Modifiers

4.1 Springs / Seeps Minimal

4.2 Adjacent Wetlands None

4.3 Flow Status Moderate

4.4 # of Debris Jams 0

4.5 Flow Regulation Type None

Flow Regulation Use

Impoundments None

Impoundmt. Location

4.6 Up/Down strm flow reg None

(old) Upstrm Flow Reg None

4.7 StormwaterInputs

Field Ditch 0 Road Ditch 3

Other 0 Tile Drain 0

Overland Flow 0 Urb Strm Wtr Pipe 0

4.9 # of Beaver Dams 0

Affected Length (ft) 0

Step 5. Channel Bed and Planform Changes

5.1 Bar Types

Mid Point Side

1 3 4

Diagonal Delta Island

1 0 0

5.2 Other Features Braiding

Flood Neck Cutoff Avulsion 0

1 0 0

5.3 Steep Riffles and Head Cuts

Steep Riffles Head Cuts Trib Rejuv.

1 0 No

5.4 Stream Ford or Animal No

5.5 Straightening Straightening

Straightening Length: 3,911

5.5 Dredging Dredging

Note: Step 1.6 - Grade Controls

and Step 4.8 - Channel Constrictions

are on The second page of this

report - with Steps 6 through 7.

Phase 2 Segment Summary page 2 of 2
 Reach # **M6T3.05S1.01** Segment: **C** Completion: **100%**
 Observers: **Jason George and Jill Winton**
 Segment Location: **From just above bedrock constriction to just below Route 9 bridge.**

Completion Date: **September 18,**
Rain: **Yes**

[illegible]

Total Score	38
Geomorphic Rating	0.475
Channel Evolution Model	F
Channel Evolution Stage	III
Geomorphic Condition	Fair
Stream Sensitivity	High

Step 6. Rapid Habitat Assessment Data

Stream Gradient Type	High
----------------------	-------------

	Score
6.1 Epifaunal Substrate - Available Cover	13
6.2 Embeddedness	18
6.3 Velocity/Depth Patterns	16
6.4 Sediment Deposition	10
6.5 Channel Flow Status	12
6.6 Channel Alteration	10
6.7 Frequency of Riffles/Steps	16
6.8 Bank Stability	Left: 4 Right: 6
6.9 Bank Vegetation Protection	Left: 5 Right: 9
6.10 Riparian Vegetation Zone Width	Left: 7 Right: 10
Total Score	136
Habitat Rating	0.68
Habitat Stream Condition	Good

Narrative:
Degradation, widening, and planform.
Used confined RGA form even though confinement ratio at cross-section was 4.44.

Project: Walloomsac Woodford

Stream: City Stream

Organization: Bennington County NRCD

Segment Length (ft): 1,073

Phase 2 Segment Summary

page 1 of 2

Reach # M6T3.05S1.02

Segment: A

Observers: Jason George and Jill Winton

Why Not assessed:

November 27, 2007 SGAT Version: 4.56

Completion Date: September 19, 2007

Rain: Yes

Segment Location: From just below Route 9 bridge upstream to sharp increase in slope/substrate size.

QC Status - Staff: Provisional Consultant: Provisional Step 2. (Contued)

Step 1. Valley and Floodplain

1.1 Segmentation Planform and Scope

1.2 Alluvial Fan None

1.3 Corridor Encroachments

Length (ft)	One	Both
Berms	0	0
height	0	0
Roads	655	353
height	0	0
Railroads	0	0
height	0	0
Improved Paths	0	0
height	0	0
Development	0	0
1.4 Adjacent Side	Left	Right
Hillside Slope	Extremely	Extremely
Continuous w/	Always	Always
W/in 1 Bankfill	Always	Always
Texture	Mixed	Mixed

1.5 Valley Features

Valley Width (ft)	72
Width Determination	Measured
Confinement Type	Narrowly
Rock Gorge?	No
Human-caused Change?	Yes

Step 2. Stream Channel

2.1 Bankfull Width	61
2.2 Max Depth (ft)	2.94
2.3 Mean Depth (ft)	1.70
2.4 Floodprone Width (ft)	68

Notes:

2.5 Aband. Floodpln	0.00 ft.
Human Elev Floodpln	22.06 ft.
2.6 Width/Depth Ratio	35.67
2.7 Entrenchment Ratio	1.12
2.8 Incision Ratio	0.00
Human Elevated Inc Rat	7.50
2.9 Sinuosity	Low
2.10 Riffles Type	Sedimented
2.11 Riffle/Step Spacing (ft)	65
2.12 Substrate Composition	
Bedrock	0%
Boulder	20%
Cobble	47%
Coarse Gravel	20%
Fine Gravel	10%
Sand	3%
Silt and smaller	0%

Silt/Clay Present?	No
Detritus	1 %
# Large Woody	5
2.13 Average Largest Particle on	
Bed	36.0 inches
Bar	30.0 inches

2.14 Stream Type

Stream Type:	F
Bed Material:	Cobble
Subclass Slope:	None
Bed Form:	Step-Pool
Field Measured Slope:	1.9

2.15 Reference Stream Type
(if different from Phase 1)

3.3 old	Amount	Mean Height
Failures	None	0.00
Gullies	None	0.00

Step 3. Riparian Features

3.1 Stream Banks

Typical Bank Slope Steep

Bank Texture Left Right

Upper

Material Type Boulder/Cobbl Boulder/Cobbl

Consistency Non-cohesive Non-cohesive

Lower

Material Type Boulder/Cobbl Boulder/Cobbl

Consistency Non-cohesive Non-cohesive

Bank Erosion Left Right

Erosion Length (ft) 75 58

Erosion Height (ft) 8.00 8.00

Revetmt. Type Multiple Rip-Rap

Revetmt. Length (ft) 845 393

Near Bank Veg. Type Left Right

Dominant Herbaceous Herbaceous

Sub-dominant Shrubs/Saplin Shrubs/Saplin

Bank Canopy Left Right

Canopy % 1-25 1-25

Mid-Channel Canopy Open

3.2 Riparian Buffer

Buffer Width Left Right

Dominant 26-50 51-100

Sub-dominant 0-25 0-25

W less than 25 0 0

Buffer Veg. Type Left Right

Dominant Shrubs/Saplin Shrubs/Saplin

Sub-dominant Herbaceous Mixed Trees

3.3 Riparian Corridor

Corridor Land Left Right

Dominant Shrubs/Saplin Forest

Sub-dominant Bare Bare

Mass Failures 0 0

Height 0 0

Gullies 0 0

Height 0 0

Step 4. Flow & Flow Modifiers

4.1 Springs / Seeps None

4.2 Adjacent Wetlands None

4.3 Flow Status Moderate

4.4 # of Debris Jams 0

4.5 Flow Regulation Type None

Flow Regulation Use

Impoundments None

Impoundmt. Location

4.6 Up/Down strm flow reg None

(old) Upstrm Flow Reg None

4.7 StormwaterInputs

Field Ditch 0 Road Ditch 3

Other 0 Tile Drain 0

Overland Flow 0 Urb Strm Wtr Pipe 0

4.9 # of Beaver Dams 0

Affected Length (ft) 0

Step 5. Channel Bed and Planform Changes

5.1 Bar Types

Mid Point Side

1 1 1

Diagonal Delta Island

0 0 0

5.2 Other Features Braiding

Flood Neck Cutoff Avulsion 0

0 0 0

5.3 Steep Riffles and Head Cuts

Steep Riffles Head Cuts Trib Rejuv.

1 0 No

5.4 Stream Ford or Animal No

5.5 Straightening Straightening

Straightening Length: 1,049

5.5 Dredging None

Note: Step 1.6 - Grade Controls

and Step 4.8 - Channel Constrictions

are on The second page of this

report - with Steps 6 through 7.

Completion Date: **September 19,**
Rain: **Yes**

Habitat Stream Condition **Fair**

Project: Walloomsac Woodford

Stream: City Stream

Organization: Bennington County NRCD

Segment Length (ft): 899

Phase 2 Segment Summary

page 1 of 2

Reach # M6T3.05S1.02

Segment: B

Observers: Jason George and Jill Winton

Why Not assessed:

November 27, 2007 SGAT Version: 4.56

Completion Date: September 19, 2007

Rain: Yes

Segment Location: From sharp increase in slope/substrate size to confluence with Stamford Stream

QC Status - Staff: Provisional Consultant: Provisional Step 2. (Contued)

Step 1. Valley and Floodplain

1.1 Segmentation Planform and Scope

1.2 Alluvial Fan None

1.3 Corridor Encroachments

Length (ft)	One	Both
Berms	127	0
height	0	0
Roads	899	0
height	0	0
Railroads	0	0
height	0	0
Improved Paths	0	0
height	0	0
Development	42	0
1.4 Adjacent Side	Left	Right
Hillside Slope	Extremely	Extremely
Continuous w/	Always	Sometimes
W/in 1 Bankfill	Always	Always
Texture	Mixed	Mixed

1.5 Valley Features

Valley Width (ft)	267
Width Determination	Measured
Confinement Type	Narrow
Rock Gorge?	No
Human-caused Change?	Yes

Step 2. Stream Channel

2.1 Bankfull Width	52
2.2 Max Depth (ft)	3.35
2.3 Mean Depth (ft)	1.97
2.4 Floodprone Width (ft)	63

Notes:

Pile of dredged material on left bank.

2.5 Aband. Floodpln	6.16 ft.
Human Elev Floodpln	0.00 ft.
2.6 Width/Depth Ratio	26.40
2.7 Entrenchment Ratio	1.21
2.8 Incision Ratio	1.84
Human Elevated Inc Rat	0.00
2.9 Sinuosity	Low
2.10 Riffles Type	Complete
2.11 Riffle/Step Spacing (ft)	60
2.12 Substrate Composition	
Bedrock	0%
Boulder	27%
Cobble	47%
Coarse Gravel	19%
Fine Gravel	6%
Sand	1%
Silt and smaller	0%
Silt/Clay Present?	No
Detritus	3 %
# Large Woody	9

2.13 Average Largest Particle on

Bed	60.0	inches
Bar	24.0	inches

2.14 Stream Type

Stream Type:	B
Bed Material:	Cobble
Subclass Slope:	a
Bed Form:	Step-Pool
Field Measured Slope:	4.4

2.15 Reference Stream Type

(if different from Phase 1)

3.3 old	Amount	Mean Height
Failures	None	0.00
Gullies	None	0.00

Step 3. Riparian Features

3.1 Stream Banks

Typical Bank Slope Steep

Bank Texture Left Right

Upper

Material Type Mix Boulder/Cobbl

Consistency Cohesive Non-cohesive

Lower

Material Type Boulder/Cobbl Boulder/Cobbl

Consistency Non-cohesive Non-cohesive

Bank Erosion Left Right

Erosion Length (ft) 321 172

Erosion Height (ft) 3.00 6.00

Revetmt. Type Hard Bank None

Revetmt. Length (ft) 70 0

Near Bank Veg. Type Left Right

Dominant Shrubs/Saplin Shrubs/Saplin

Sub-dominant Deciduous Deciduous

Bank Canopy Left Right

Canopy % 26-50 26-50

Mid-Channel Canopy Open

3.2 Riparian Buffer

Buffer Width Left Right

Dominant 51-100 >100

Sub-dominant 26-50 None

W less than 25 0 0

Buffer Veg. Type Left Right

Dominant Deciduous Deciduous

Sub-dominant Herbaceous Shrubs/Saplin

3.3 Riparian Corridor

Corridor Land Left Right

Dominant Forest Forest

Sub-dominant Shrubs/Saplin Shrubs/Saplin

Mass Failures 0 0

Height 0 0

Gullies 0 0

Height 0 0

Step 4. Flow & Flow Modifiers

4.1 Springs / Seeps None

4.2 Adjacent Wetlands None

4.3 Flow Status Moderate

4.4 # of Debris Jams 0

4.5 Flow Regulation Type None

Flow Regulation Use

Impoundments None

Impoundmt. Location

4.6 Up/Down strm flow reg None

(old) Upstrm Flow Reg None

4.7 StormwaterInputs

Field Ditch 0 Road Ditch 0

Other 0 Tile Drain 0

Overland Flow 0 Urb Strm Wtr Pipe 0

4.9 # of Beaver Dams 0

Affected Length (ft) 0

Step 5. Channel Bed and Planform Changes

5.1 Bar Types

Mid	Point	Side
1	1	1
Diagonal	Delta	Island
0	0	0

5.2 Other Features Braiding

Flood Neck Cutoff Avulsion 0

0 0 0

5.3 Steep Riffles and Head Cuts

Steep Riffles Head Cuts Trib Rejuv.

0 0 No

5.4 Stream Ford or Animal No

5.5 Straightening Straightening

Straightening Length: 838

5.5 Dredging Dredging

Note: Step 1.6 - Grade Controls

and Step 4.8 - Channel Constrictions

are on The second page of this

report - with Steps 6 through 7.

Completion Date: **September 19,**
Rain: **Yes**

Narrative:
Degradation.
Used confined RGA form even though confinement ratio at cross-section was 5.13.

Project: Walloomsac Woodford

Stream: City Stream

Organization: Bennington County NRCD

Segment Length (ft): 10,443

Phase 2 Segment Summary

page 1 of 2

November 27, 2007 SGAT Version: 4.56

Reach # M6T3.05S1.03

Segment: 0

Completion Date:

Observers:

Why Not assessed: Other (to be explained in Rain:

Segment Location: From confluence with Stamford Stream upstream to bridge on driveway off of City Stream

QC Status - Staff: Provisional Consultant: Provisional Step 2. (Contued)

Step 1. Valley and Floodplain

1.1 Segmentation

1.2 Alluvial Fan None

1.3 Corridor Encroachments

Length (ft)	One	Both
Berms	0	0
height	0	0
Roads	7,249	62
height	0	0
Railroads	0	0
height	0	0
Improved Paths	0	0
height	0	0
Development	1,089	0

1.4 Adjacent Side Left Right

Hillside Slope

Continuous w/

W/in 1 Bankfill

Texture

1.5 Valley Features

Valley Width (ft) 0

Width Determination

Confinement Type

Rock Gorge?

Human-caused Change?

Step 2. Stream Channel

2.1 Bankfull Width 0

2.2 Max Depth (ft) 0.00

2.3 Mean Depth (ft) 0.00

2.4 Floodprone Width (ft) 0

Notes:

Reach not assessed due to extreme confinement between Route 9 and valley wall.

2.5 Aband. Floodpln 0.00 ft.

Human Elev Floodpln 0.00 ft.

2.6 Width/Depth Ratio 0.00

2.7 Entrenchment Ratio 0.00

2.8 Incision Ratio 0.00

Human Elevated Inc Rat 0.00

2.9 Sinuosity

2.10 Riffles Type

2.11 Riffle/Step Spacing (ft) 0

2.12 Substrate Composition

Silt/Clay Present?

Detritus 0 %

Large Woody 0

2.13 Average Largest Particle on

Bed 0.0

Bar 0.0

2.14 Stream Type

Stream Type:

Bed Material:

Subclass Slope:

Bed Form:

Field Measured Slope:

2.15 Reference Stream Type

(if different from Phase 1)

3.3 old	Amount	Mean Height
Failures	None	0.00
Gullies	None	0.00

Step 3. Riparian Features

3.1 Stream Banks

Typical Bank Slope

Bank Texture Left Right

Upper

Material Type

Consistency

Lower

Material Type

Consistency

Bank Erosion Left Right

Erosion Length (ft) 0 0

Erosion Height (ft) 0.00 0.00

Revetmt. Type None None

Revetmt. Length (ft) 0 0

Near Bank Veg. Type Left Right

Dominant

Sub-dominant

Bank Canopy Left Right

Canopy %

Mid-Channel Canopy

3.2 Riparian Buffer

Buffer Width Left Right

Dominant

Sub-dominant

W less than 25 147 3,884

Buffer Veg. Type Left Right

Dominant

Sub-dominant

3.3 Riparian Corridor

Corridor Land Left Right

Dominant

Sub-dominant

Mass Failures 0 0

Height 0 0

Gullies 0 0

Height 0 0

Step 4. Flow & Flow Modifiers

4.1 Springs / Seeps

4.2 Adjacent Wetlands

4.3 Flow Status

4.4 # of Debris Jams 0

4.5 Flow Regulation Type None

Flow Regulation Use

Impoundments

Impoundmt. Location

4.6 Up/Down strm flow reg None

(old) Upstrm Flow Reg

4.7 StormwaterInputs

Field Ditch 0 Road Ditch 0

Other 0 Tile Drain 0

Overland Flow 0 Urb Strm Wtr Pipe 0

4.9 # of Beaver Dams 0

Affected Length (ft) 0

Step 5. Channel Bed and Planform Changes

5.1 Bar Types

Mid	Point	Side
0	0	0

Diagonal	Delta	Island
0	0	0

5.2 Other Features Braiding

Flood Neck Cutoff Avulsion 0

5.3 Steep Riffles and Head Cuts

Steep Riffles Head Cuts Trib Rejuv.

0 0

5.4 Stream Ford or Animal No

5.5 Straightening None

Straightening Length: 0

5.5 Dredging None

Note: Step 1.6 - Grade Controls and Step 4.8 - Channel Constrictions are on The second page of this report - with Steps 6 through 7.

1.6 Grade Controls					
Type	Location	Total	Total Height Above Water	Photo Taken	GPSTaken
Ledge	Mid-segment	0.00	0.00	Yes	

4.8 Channel Constrictions					
Type	Width	Photo Taken?	GPS Taken?	Channel Constriction?	Floodprone Constriction?
Bridge	16.0	Yes	Yes	Yes	Yes
	Problem	None			

Narrative:

Step 7. Rapid Geomorphic Assessment Data					
Confinement Type					

are on The second page of this

<u>1.6 Grade Controls</u>					<u>Step 7. Rapid Geomorphic Assessment Data</u>				
Type	Location	Total	Total Height Above Water	Photo Taken	GPSTaken	Confinement Type			
Waterfall	Mid-segment	6.00	5.00	Yes					
Ledge	Mid-segment	1.00	0.00	Yes					
						Channel Evolution Model			
						Channel Evolution Stage			
						Geomorphic Condition			
						Stream Sensitivity			
<u>4.8 Channel Constrictions</u>						<u>Step 6. Rapid Habitat Assessment Data</u>			
Type	Width	Photo Taken?	GPS Taken?	Channel Constriction?	Floodprone Constriction?	Stream Gradient Type			

Project: Walloomsac Woodford

Stream: City Stream

Organization: Bennington County NRCD

Segment Length (ft): 1,112

Phase 2 Segment Summary

page 1 of 2

November 27, 2007 SGAT Version: 4.56

Reach # M6T3.05S1.04

Segment: B

Completion Date: September 14, 2007

Observers: Jason George and Jill Winton

Why Not assessed:

Rain: Yes

Segment Location: From sharp right bend above bedrock gorge upstream to beaver dam below culvert across

QC Status - Staff: Provisional Consultant: Provisional Step 2. (Contued)

Step 1. Valley and Floodplain

1.1 Segmentation Planform and Scope

1.2 Alluvial Fan None

1.3 Corridor Encroachments

Length (ft)	One	Both
Berms	0	0
height	0	0
Roads	0	0
height	0	0
Railroads	0	0
height	0	0
Improved Paths	301	0
height	0	0
Development	0	0

2.5 Aband. Floodpln 3.49 ft.

Human Elev Floodpln 0.00 ft.

2.6 Width/Depth Ratio 26.27

2.7 Entrenchment Ratio 1.30

2.8 Incision Ratio 2.01

Human Elevated Inc Rat 0.00

2.9 Sinuosity Low

2.10 Riffles Type Complete

2.11 Riffle/Step Spacing (ft) 41

2.12 Substrate Composition

Bedrock 0%

Boulder 8%

Cobble 21%

Coarse Gravel 42%

Fine Gravel 16%

Sand 10%

Silt and smaller 3%

Silt/Clay Present? No

Detritus 5 %

Large Woody 6

2.13 Average Largest Particle on

Bed 12.0 inches

Bar 3.0 inches

Step 3. Riparian Features

3.1 Stream Banks

Typical Bank Slope Moderate

Bank Texture Left Right

Upper

Material Type Mix Mix

Consistency Cohesive Cohesive

Lower

Material Type Mix Mix

Consistency Cohesive Cohesive

Bank Erosion Left Right

Erosion Length (ft) 0 0

Erosion Height (ft) 0.00 0.00

Revetmt. Type None None

Revetmt. Length (ft) 0 0

Near Bank Veg. Type Left Right

Dominant Shrubs/Saplin Herbaceous

Sub-dominant Coniferous Shrubs/Saplin

Bank Canopy Left Right

Canopy % 0 0

Mid-Channel Canopy Open

Step 4. Flow & Flow Modifiers

4.1 Springs / Seeps Minimal

4.2 Adjacent Wetlands Abundant

4.3 Flow Status Moderate

4.4 # of Debris Jams 0

4.5 Flow Regulation Type None

Flow Regulation Use

Impoundments None

Impoundmt. Location

4.6 Up/Down strm flow reg None

(old) Upstrm Flow Reg None

4.7 StormwaterInputs

Field Ditch 0 Road Ditch 0

Other 0 Tile Drain 0

Overland Flow 0 Urb Strm Wtr Pipe 0

4.9 # of Beaver Dams 0

Affected Length (ft) 0

Step 5. Channel Bed and Planform Changes

5.1 Bar Types

Mid Point Side

0 5 4

Diagonal Delta Island

0 0 0

Note: Step 1.6 - Grade Controls and Step 4.8 - Channel Constrictions are on The second page of this report - with Steps 6 through 7.

Project: Walloomsac Woodford	Phase 2 Segment Summary	page 2 of 2	November 27, 2007
Stream: City Stream	Reach # M6T3.05S1.04	Segment: B	Completion Date: September 14,
Organization: Bennington County NRCD	Observers: Jason George and Jill Winton		Rain: Yes
Segment Length (ft): 1,112	Segment Location: From sharp right bend above bedrock gorge upstream to beaver dam below culvert across		

1.6 Grade Controls

Type	Location	Total	Total Height Above Water	Photo Taken	GPSTaken
Ledge	Mid-segment	2.00	1.00	Yes	
Ledge	Mid-segment	1.00	1.00	Yes	

4.8 Channel Constrictions **None**

Type	Width	Photo Taken?	GPS Taken?	Channel Constriction?	Floodprone Constriction?
------	-------	--------------	------------	-----------------------	--------------------------

Narrative:
Degradation.

Step 7. Rapid Geomorphic Assessment Data

Confinement Type **Unconfined**

	Score	STD	Historic
7.1 Channel Degradation	5	C to F	No
7.2 Channel Aggradation	16	None	No
7.3 Widening Channel	12		No
7.4 Change in Planform	18		No

Total Score **51**

Geomorphic Rating **0.6375**

Channel Evolution Model

F

Channel Evolution Stage

II

Geomorphic Condition

Fair

Stream Sensitivity

Extreme

Step 6. Rapid Habitat Assessment Data

Stream Gradient Type **High**

	Score
6.1 Epifaunal Substrate - Available Cover	17
6.2 Embeddedness	15
6.3 Velocity/Depth Patterns	16
6.4 Sediment Deposition	15
6.5 Channel Flow Status	17
6.6 Channel Alteration	17
6.7 Frequency of Riffles/Steps	15
6.8 Bank Stability	Left: 9 Right: 9
6.9 Bank Vegetation Protection	Left: 9 Right: 9
6.10 Riparian Vegetation Zone Width	Left: 9 Right: 9
Total Score	166
Habitat Rating	0.83
Habitat Stream Condition	Good

Project: Walloomsac Woodford

Stream: City Stream

Organization: Bennington County NRCD

Segment Length (ft): 443

Phase 2 Segment Summary page 1 of 2

Reach # M6T3.05S1.04

Observers:

Segment: C

November 27, 2007 SGAT Version: 4.56

Completion Date:

Why Not assessed: impounded

Rain:

Segment Location: From beaver dam below culvert across Prospect Mt. driveway upstream to culvert.

QC Status - Staff: Provisional Consultant: Provisional *Step 2. (Contued)***Step 1. Valley and Floodplain**

1.1 Segmentation

1.2 Alluvial Fan

1.3 Corridor Encroachments

Length (ft)	One	Both
Berms	0	0
height	0	0
Roads	60	0
height	0	0
Railroads	0	0
height	0	0
Improved Paths	0	0
height	0	0
Development	0	263

1.4 Adjacent Side Left Right

Hillside Slope
Continuous w/
W/in 1 Bankfill
Texture

1.5 Valley Features

Valley Width (ft) 0

Width Determination

Confinement Type

Rock Gorge?

Human-caused Change?

Step 2. Stream Channel

2.1 Bankfull Width 0

2.2 Max Depth (ft) 0.00

2.3 Mean Depth (ft) 0.00

2.4 Floodprone Width (ft) 0

Notes:

2.5 Aband. Floodpln 0.00 ft.

Human Elev Floodpln 0.00 ft.

2.6 Width/Depth Ratio 0.00

2.7 Entrenchment Ratio 0.00

2.8 Incision Ratio 0.00

Human Elevated Inc Rat 0.00

2.9 Sinuosity

2.10 Riffles Type

2.11 Riffle/Step Spacing (ft) 0

2.12 Substrate Composition

Silt/Clay Present?

Detritus 0 %

Large Woody 0

2.13 Average Largest Particle on

Bed 0.0

Bar 0.0

2.14 Stream Type

Stream Type:

Bed Material:

Subclass Slope:

Bed Form:

Field Measured Slope:

2.15 Reference Stream Type

(if different from Phase 1)

3.3 old Amount Mean Height

Failures None 0.00

Gullies None 0.00

Step 3. Riparian Features

3.1 Stream Banks

Typical Bank Slope

Bank Texture Left Right

Upper

Material Type

Consistency

Lower

Material Type

Consistency

Bank Erosion Left Right

Erosion Length (ft) 0 0

Erosion Height (ft) 0.00 0.00

Revetmt. Type Rip-Rap Rip-Rap

Revetmt. Length (ft) 23 15

Near Bank Veg. Type Left Right

Dominant

Sub-dominant

Bank Canopy Left Right

Canopy %

Mid-Channel Canopy

3.2 Riparian Buffer

Buffer Width Left Right

Dominant

Sub-dominant

W less than 25 0 0

Buffer Veg. Type Left Right

Dominant

Sub-dominant

3.3 Riparian Corridor

Corridor Land Left Right

Dominant

Sub-dominant

Mass Failures 0 0

Height 0 0

Gullies 0 0

Height 0 0

Step 4. Flow & Flow Modifiers

4.1 Springs / Seeps

4.2 Adjacent Wetlands

4.3 Flow Status

4.4 # of Debris Jams 0

4.5 Flow Regulation Type None

Flow Regulation Use

Impoundments

Impoundmt. Location

4.6 Up/Down strm flow reg None

(old) Upstrm Flow Reg

4.7 StormwaterInputs

Field Ditch 0 Road Ditch 0

Other 0 Tile Drain 0

Overland Flow 0 Urb Strm Wtr Pipe 0

4.9 # of Beaver Dams 1

Affected Length (ft) 420

Step 5. Channel Bed and Planform Changes

5.1 Bar Types

Mid Point Side

0 0 0

Diagonal Delta Island

0 0 0

5.2 Other Features Braiding

Flood Neck Cutoff Avulsion 0

0 0 0

5.3 Steep Riffles and Head Cuts

Steep Riffles Head Cuts Trib Rejuv.

0 0

5.4 Stream Ford or Animal No

5.5 Straightening Straightening

Straightening Length: 254

5.5 Dredging None

Note: Step 1.6 - Grade Controls
and Step 4.8 - Channel Constrictions
are on The second page of this
report - with Steps 6 through 7.

<u>1.6 Grade Controls</u>					
Type	Location	Total	Total Height Above Water	Photo Taken	GPSTaken

Project: Walloomsac Woodford

Stream: City Stream

Organization: Bennington County NRCD

Segment Length (ft): 1,957

Phase 2 Segment Summary

page 1 of 2

November 27, 2007 SGAT Version: 4.56

Reach # M6T3.05S1.04

Segment: D

Completion Date: September 14, 2007

Observers: Jason George and Jill Winton

Why Not assessed:

Rain: Yes

Segment Location: From culvert across Prospect Mt. driveway upstream to Bugbee Mill Pond dam.

QC Status - Staff: Provisional Consultant: Provisional Step 2. (Contued)

Step 1. Valley and Floodplain

1.1 Segmentation Other Reason

1.2 Alluvial Fan None

1.3 Corridor Encroachments

Length (ft)	One	Both
Berms	0	0
height	0	0
Roads	786	0
height	0	0
Railroads	0	0
height	0	0
Improved Paths	501	0
height	0	0
Development	244	227
1.4 Adjacent Side	Left	Right
Hillside Slope	Flat	Flat
Continuous w/	Always	Always
W/in 1 Bankfill	Always	Always
Texture	Silt/Clay	Silt/Clay

1.5 Valley Features

Valley Width (ft)	1,028
Width Determination	Measured
Confinement Type	Very Broad
Rock Gorge?	No
Human-caused Change?	No

Step 2. Stream Channel

2.1 Bankfull Width	16
2.2 Max Depth (ft)	1.43
2.3 Mean Depth (ft)	1.09
2.4 Floodprone Width (ft)	21

Notes:

2.5 Aband. Floodpln	3.23 ft.
Human Elev Floodpln	0.00 ft.
2.6 Width/Depth Ratio	14.68
2.7 Entrenchment Ratio	1.31
2.8 Incision Ratio	2.26
Human Elevated Inc Rat	0.00
2.9 Sinuosity	Low
2.10 Riffles Type	Eroded
2.11 Riffle/Step Spacing (ft)	0
2.12 Substrate Composition	
Bedrock	0%
Boulder	0%
Cobble	0%
Coarse Gravel	33%
Fine Gravel	35%
Sand	9%
Silt and smaller	23%
Silt/Clay Present?	No
Detritus	10 %
# Large Woody	1
2.13 Average Largest Particle on	
Bed	6.0 inches
Bar	N/A inches

2.14 Stream Type

Stream Type:	F
Bed Material:	Gravel
Subclass Slope:	None
Bed Form:	Riffle-Pool
Field Measured Slope:	0.8

2.15 Reference Stream Type
(if different from Phase 1)

3.3 old	Amount	Mean Height
Failures	None	0.00
Gullies	None	0.00

Step 3. Riparian Features

3.1 Stream Banks		
Typical Bank Slope	Steep	
Bank Texture	Left	Right
Upper		
Material Type	Silt	Silt
Consistency	Cohesive	Cohesive
Lower		
Material Type	Silt	Silt
Consistency	Cohesive	Cohesive
Bank Erosion	Left	Right
Erosion Length (ft)	0	0
Erosion Height (ft)	0.00	0.00
Revetmt. Type	None	Rip-Rap
Revetmt. Length (ft)	0	187
Near Bank Veg. Type	Left	Right
Dominant	Herbaceous	Herbaceous
Sub-dominant	Shrubs/Saplin	Shrubs/Saplin
Bank Canopy	Left	Right
Canopy %	0	0
Mid-Channel Canopy		Open
3.2 Riparian Buffer		
Buffer Width	Left	Right
Dominant	>100	>100
Sub-dominant	26-50	0-25
W less than 25	0	509
Buffer Veg. Type	Left	Right
Dominant	Herbaceous	Herbaceous
Sub-dominant	Shrubs/Saplin	Shrubs/Saplin
3.3 Riparian Corridor		
Corridor Land	Left	Right
Dominant	Shrubs/Saplin	Shrubs/Saplin
Sub-dominant	None	Residential
Mass Failures	0	0
Height	0	0
Gullies	0	0
Height	0	0

Step 4. Flow & Flow Modifiers

4.1 Springs / Seeps	Minimal		
4.2 Adjacent Wetlands	Abundant		
4.3 Flow Status	Moderate		
4.4 # of Debris Jams	0		
4.5 Flow Regulation Type	None		
Flow Regulation Use			
Impoundments			
Impoundmt. Location			
4.6 Up/Down strm flow reg	None		
(old) Upstrm Flow Reg			
4.7 StormwaterInputs			
Field Ditch	0	Road Ditch	0
Other	0	Tile Drain	0
Overland Flow	0	Urb Strm Wtr Pipe	0
4.9 # of Beaver Dams	1		
Affected Length (ft)	150		

Step 5. Channel Bed and Planform Changes

5.1 Bar Types

Mid	Point	Side
1	2	0
Diagonal	Delta	Island
0	0	0

5.2 Other Features

Flood	Neck Cutoff	Avulsion	Braiding
0	0	0	0

5.3 Steep Riffles and Head Cuts

Steep Riffles	Head Cuts	Trib Rejuv.
0	0	No

5.4 Stream Ford or Animal

5.5 Straightening

Straightening Length:	1,032
5.5 Dredging	None

Note: Step 1.6 - Grade Controls and Step 4.8 - Channel Constrictions are on The second page of this report - with Steps 6 through 7.

Completion Date: **September 14,**
Rain: **Yes**

Narrative:
Degradation.

Project: Walloomsac Woodford	Phase 2 Segment Summary	page 2 of 2	November 27, 2007
Stream: City Stream	Reach # M6T3.05S1.06	Segment: 0	Completion Date: September 12,
Organization: Bennington County NRCD	Observers: Jason George and Jill Winton		Rain: Yes
Segment Length (ft): 2,260	Segment Location: From top of wetland area above Bugbee Mill Pond to small dam above culvert across Route		

1.6 Grade Controls

Type	Location	Total	Total Height Above Water	Photo Taken	GPSTaken
Ledge	Mid-segment	1.00	1.00	Yes	
Ledge	Mid-segment	2.00	1.00	Yes	

4.8 Channel Constrictions

Type	Width	Photo Taken?	GPS Taken?	Channel Constriction?	Floodprone Constriction?
Bridge	14.5	Yes	Yes	Yes	Yes
	Problem	None			
Culvert	3.20	Yes	Yes	Yes	Yes
	Problem	None			
Old	8.00	Yes	Yes	Yes	Yes
	Problem	Deposition Above			
Old	12.0	Yes	Yes	No	No
	Problem	Deposition Above,Scour Above			

Narrative:
Planform.

Step 7. Rapid Geomorphic Assessment Data

Confinement Type **Unconfined**

	Score	STD	Historic
7.1 Channel Degradation	14	None	No
7.2 Channel Aggradation	15	None	No
7.3 Widening Channel	13		No
7.4 Change in Planform	16		No

Total Score **58**

Geomorphic Rating **0.725**

Channel Evolution Model

F

Channel Evolution Stage

IV

Geomorphic Condition

Good

Stream Sensitivity

Extreme

Step 6. Rapid Habitat Assessment Data

Stream Gradient Type **High**

	Score
6.1 Epifaunal Substrate - Available Cover	18
6.2 Embeddedness	16
6.3 Velocity/Depth Patterns	18
6.4 Sediment Deposition	15
6.5 Channel Flow Status	16
6.6 Channel Alteration	15
6.7 Frequency of Riffles/Steps	19
6.8 Bank Stability	Left: 9 Right: 9
6.9 Bank Vegetation Protection	Left: 8 Right: 7
6.10 Riparian Vegetation Zone Width	Left: 9 Right: 8

Total Score **167**

Habitat Rating **0.835**

Habitat Stream Condition **Good**

Project: **Walloomsac Woodford** Phase 2 Segment Summary page 1 of 2 November 27, 2007 SGAT Version: 4.56
Stream: **Bolles Brook** Reach # **M6T3.05** Segment: **A** Completion Date: **September 25, 2007**
Organization: **Bennington County NRCD** Observers: **Jason George and Jill Winton** Why Not assessed: Rain: **No**
Segment Length (ft): **2,042** Segment Location: **From confluence with City Stream upstream to tributary just below second bridge on Harbor**

QC Status - Staff: Provisional Consultant: Provisional *Step 2. (Contued)*

Step 1. Valley and Floodplain

1.1 Segmentation **Corridor Encroachment**

1.2 Alluvial Fan **None**

1.3 Corridor Encroachments

Length (ft)	One	Both
Berms	0	0
height	0	0
Roads	882	0
height	0	0
Railroads	0	0
height	0	0
Improved Paths	0	0
height	0	0
Development	1,775	0
1.4 Adjacent Side	Left	Right
Hillside Slope	Very Steep	Extremely
Continuous w/	Never	Sometimes
W/in 1 Bankfill	Never	Always
Texture	Mixed	Mixed

1.5 Valley Features

Valley Width (ft)	445
Width Determination	Measured
Confinement Type	Broad
Rock Gorge?	No
Human-caused Change?	Yes

Step 2. Stream Channel

2.1 Bankfull Width	48
2.2 Max Depth (ft)	3.00
2.3 Mean Depth (ft)	2.18
2.4 Floodprone Width (ft)	87

Notes:

No evidence of dredging observed in the field.

2.5 Aband. Floodpln	3.04	ft.
Human Elev Floodpln	0.00	ft.
2.6 Width/Depth Ratio	22.02	
2.7 Entrenchment Ratio	1.80	
2.8 Incision Ratio	1.01	
Human Elevated Inc Rat	0.00	
2.9 Sinuosity	Low	
2.10 Riffles Type	Eroded	
2.11 Riffle/Step Spacing (ft)	115	
2.12 Substrate Composition		
Bedrock	0%	
Boulder	27%	
Cobble	46%	
Coarse Gravel	15%	
Fine Gravel	9%	
Sand	3%	
Silt and smaller	0%	
Silt/Clay Present?	No	
Detritus	5 %	
# Large Woody	12	
2.13 Average Largest Particle on		
Bed	30.0	inches
Bar	21.0	inches

2.14 Stream Type

Stream Type:	B
Bed Material:	Cobble
Subclass Slope:	None
Bed Form:	Step-Pool
Field Measured Slope:	2

2.15 Reference Stream Type
(if different from Phase 1)

3.3 old	Amount	Mean Height
Failures	None	0.00
Gullies	None	0.00

Step 3. Riparian Features

3.1 Stream Banks

Typical Bank Slope **Steep**

Bank Texture Left Right

Upper

Material Type **Boulder/Cobbl Boulder/Cobbl**

Consistency **Non-cohesive Non-cohesive**

Lower

Material Type **Boulder/Cobbl Boulder/Cobbl**

Consistency **Non-cohesive Non-cohesive**

Bank Erosion Left Right

Erosion Length (ft) **138** **182**

Erosion Height (ft) **7.00** **4.00**

Revetmt. Type **None** **None**

Revetmt. Length (ft) **0** **0**

Near Bank Veg. Type Left Right

Dominant **Shrubs/Saplin Deciduous**

Sub-dominant **Herbaceous Shrubs/Saplin**

Bank Canopy Left Right

Canopy % **26-50** **51-75**

Mid-Channel Canopy **Open**

3.2 Riparian Buffer

Buffer Width Left Right

Dominant **26-50** **>100**

Sub-dominant **0-25** **None**

W less than 25 **698** **185**

Buffer Veg. Type Left Right

Dominant **Shrubs/Saplin Mixed Trees**

Sub-dominant **Mixed Trees Shrubs/Saplin**

3.3 Riparian Corridor

Corridor Land Left Right

Dominant **Residential Forest**

Sub-dominant **Forest** **None**

Mass Failures **0** **148**

Height **0** **20**

Gullies **0** **0**

Height **0** **0**

Step 4. Flow & Flow Modifiers

4.1 Springs / Seeps **None**

4.2 Adjacent Wetlands **None**

4.3 Flow Status **Low**

4.4 # of Debris Jams **0**

4.5 Flow Regulation Type **None**

Flow Regulation Use

Impoundments **None**

Impoundmt. Location

4.6 Up/Down strm flow reg **None**

(old) Upstrm Flow Reg **None**

4.7 StormwaterInputs

Field Ditch **0** Road Ditch **0**

Other **0** Tile Drain **0**

Overland Flow **0** Urb Strm Wtr Pipe **0**

4.9 # of Beaver Dams **0**

Affected Length (ft) **0**

Step 5. Channel Bed and Planform Changes

5.1 Bar Types

Mid	Point	Side
1	1	2
Diagonal	Delta	Island
1	0	1

5.2 Other Features

Flood	Neck Cutoff	Avulsion	Braiding
1	0	0	1

5.3 Steep Riffles and Head Cuts

Steep Riffles	Head Cuts	Trib Rejuv.
0	2	No

5.4 Stream Ford or Animal

5.5 Straightening **Straightening**

Straightening Length: **1,727**

5.5 Dredging **None**

Note: Step 1.6 - Grade Controls and Step 4.8 - Channel Constrictions are on The second page of this report - with Steps 6 through 7.

Completion Date: **September 25,**
Rain: **No**

Step 7. Rapid Geomorphic Assessment Data			
Confinement Type	Unconfined		
	Score	STD	Historic
Channel Degradation	5	None	No
Channel Aggradation	14	None	No
Shifting Channel	9		No
Change in Planform	12		No
Total Score	40		
Geomorphic Rating	0.5		
Channel Evolution Model	F		
Channel Evolution Stage	III		
Geomorphic Condition	Fair		
Stream Sensitivity	High		

Step 6. Rapid Habitat Assessment Data		
Stream Gradient Type	High	
	Score	
6.1 Epifaunal Substrate - Available Cover	12	
6.2 Embeddedness	14	
6.3 Velocity/Depth Patterns	15	
6.4 Sediment Deposition	14	
6.5 Channel Flow Status	12	
6.6 Channel Alteration	11	
6.7 Frequency of Riffles/Steps	16	
6.8 Bank Stability	Left: 5	Right: 5
6.9 Bank Vegetation Protection	Left: 5	Right: 7
6.10 Riparian Vegetation Zone Width	Left: 4	Right: 9
Total Score	129	
Habitat Rating	0.645	
Habitat Stream Condition	Good	

Narrative:
Degradation and widening.

Project: Walloomsac Woodford

Stream: Bolles Brook

Organization: Bennington County NRCD

Segment Length (ft): 2,242

Phase 2 Segment Summary

page 1 of 2

Reach # M6T3.05

Segment: B

Observers: Jason George and Jill Winton

Why Not assessed:

November 27, 2007 SGAT Version: 4.56

Completion Date: September 25, 2007

Rain: No

Segment Location: From tributary just below second bridge on Harbor Road to sharp right bend before straight,

QC Status - Staff: Provisional Consultant: Provisional Step 2. (Contued)

Step 1. Valley and Floodplain

1.1 Segmentation Corridor Encroachment

1.2 Alluvial Fan None

1.3 Corridor Encroachments

Length (ft)	One	Both
Berms	0	0
height	0	0
Roads	1,664	0
height	0	0
Railroads	0	0
height	0	0
Improved Paths	0	0
height	0	0
Development	647	0

1.4 Adjacent Side Left Right

Hillside Slope Extremely Steep

Continuous w/Sometimes Never

W/in 1 Bankfill Sometimes Never

Texture Bedrock Not Evalua

1.5 Valley Features

Valley Width (ft) 535

Width Determination Measured

Confinement Type Broad

Rock Gorge? No

Human-caused Change? No

Step 2. Stream Channel

2.1 Bankfull Width 56

2.2 Max Depth (ft) 2.88

2.3 Mean Depth (ft) 1.87

2.4 Floodprone Width (ft) 87

Notes:

2.5 Aband. Floodpln 5.18 ft.

Human Elev Floodpln 0.00 ft.

2.6 Width/Depth Ratio 29.69

2.7 Entrenchment Ratio 1.57

2.8 Incision Ratio 1.80

Human Elevated Inc Rat 0.00

2.9 Sinuosity Low

2.10 Riffles Type Complete

2.11 Riffle/Step Spacing (ft) 45

2.12 Substrate Composition

Bedrock 0%

Boulder 26%

Cobble 55%

Coarse Gravel 12%

Fine Gravel 6%

Sand 1%

Silt and smaller 0%

Silt/Clay Present? No

Detritus 5 %

Large Woody 19

2.13 Average Largest Particle on

Bed 40.0 inches

Bar 26.0 inches

2.14 Stream Type

Stream Type: B

Bed Material: Cobble

Subclass Slope: c

Bed Form: Step-Pool

Field Measured Slope: 1.8

2.15 Reference Stream Type

(if different from Phase 1)

3.3 old Amount Mean Height

Failures None 0.00

Gullies None 0.00

Step 3. Riparian Features

3.1 Stream Banks

Typical Bank Slope Moderate

Bank Texture Left Right

Upper

Material Type Boulder/Cobbl Boulder/Cobbl

Consistency Non-cohesive Non-cohesive

Lower

Material Type Boulder/Cobbl Boulder/Cobbl

Consistency Non-cohesive Non-cohesive

Bank Erosion Left Right

Erosion Length (ft) 236 95

Erosion Height (ft) 8.00 4.00

Revetmt. Type Multiple Rip-Rap

Revetmt. Length (ft) 151 62

Near Bank Veg. Type Left Right

Dominant Coniferous Shrubs/Saplin

Sub-dominant Shrubs/Saplin Deciduous

Bank Canopy Left Right

Canopy % 76-100 76-100

Mid-Channel Canopy Open

3.2 Riparian Buffer

Buffer Width Left Right

Dominant >100 >100

Sub-dominant None 51-100

W less than 25 0 136

Buffer Veg. Type Left Right

Dominant Mixed Trees Mixed Trees

Sub-dominant Shrubs/Saplin Shrubs/Saplin

3.3 Riparian Corridor

Corridor Land Left Right

Dominant Forest Forest

Sub-dominant None Residential

Mass Failures 0 0

Height 0 0

Gullies 0 0

Height 0 0

Step 4. Flow & Flow Modifiers

4.1 Springs / Seeps Minimal

4.2 Adjacent Wetlands None

4.3 Flow Status Low

4.4 # of Debris Jams 0

4.5 Flow Regulation Type None

Flow Regulation Use

Impoundments None

Impoundmt. Location

4.6 Up/Down strm flow reg None

(old) Upstrm Flow Reg

4.7 StormwaterInputs

Field Ditch 0 Road Ditch 0

Other 0 Tile Drain 0

Overland Flow 0 Urb Strm Wtr Pipe 0

4.9 # of Beaver Dams 0

Affected Length (ft) 0

Step 5. Channel Bed and Planform Changes

5.1 Bar Types

Mid	Point	Side
0	1	1
Diagonal	Delta	Island
0	0	11

5.2 Other Features Braiding

Flood Neck Cutoff Avulsion 1

2 0 0

5.3 Steep Riffles and Head Cuts

Steep Riffles Head Cuts Trib Rejuv.

3 0 No

5.4 Stream Ford or Animal No

5.5 Straightening Straightening

Straightening Length: 1,519

5.5 Dredging None

Note: Step 1.6 - Grade Controls and Step 4.8 - Channel Constrictions are on The second page of this report - with Steps 6 through 7.

Project: Walloomsac Woodford	Phase 2 Segment Summary	page 2 of 2	November 27, 2007
Stream: Bolles Brook	Reach # M6T3.05	Segment: B	Completion Date: September 25,
Organization: Bennington County NRCD	Observers: Jason George and Jill Winton		Rain: No
Segment Length (ft): 2,242	Segment Location: From tributary just below second bridge on Harbor Road to sharp right bend before straight,		

1.6 Grade Controls

Type	Location	Total	Total Height Above Water	Photo Taken	GPSTaken
Ledge	Mid-segment	3.00	2.00	Yes	
Ledge	Mid-segment	5.00	4.00	Yes	

4.8 Channel Constrictions

Type	Width	Photo Taken?	GPS Taken?	Channel Constriction?	Floodprone Constriction?
Bridge	75.0	Yes	Yes	No	Yes
Problem Deposition Below					

Narrative:
Widening and Aggradation.

Step 7. Rapid Geomorphic Assessment Data

Confinement Type **Unconfined**

	Score	STD	Historic
7.1 Channel Degradation	5	None	Yes
7.2 Channel Aggradation	13	None	No
7.3 Widening Channel	10		No
7.4 Change in Planform	17		No

Total Score **45**

Geomorphic Rating **0.5625**

Channel Evolution Model

F

Channel Evolution Stage

IV

Geomorphic Condition

Fair

Stream Sensitivity

High

Step 6. Rapid Habitat Assessment Data

Stream Gradient Type **High**

	Score
6.1 Epifaunal Substrate - Available Cover	17
6.2 Embeddedness	16
6.3 Velocity/Depth Patterns	16
6.4 Sediment Deposition	15
6.5 Channel Flow Status	13
6.6 Channel Alteration	18
6.7 Frequency of Riffles/Steps	16
6.8 Bank Stability	Left: 8 Right: 9
6.9 Bank Vegetation Protection	Left: 9 Right: 9
6.10 Riparian Vegetation Zone Width	Left: 9 Right: 8

Total Score **163**

Habitat Rating **0.815**

Habitat Stream Condition **Good**

Project: **Walloomsac Woodford**Stream: **Bolles Brook**Organization: **Bennington County NRCD**Segment Length (ft): **1,163****Phase 2 Segment Summary**

page 1 of 2

Reach # **M6T3.05**Segment: **C**Observers: **Jason George and Jill Winton**

Why Not assessed:

November 27, 2007 SGAT Version: 4.56

Completion Date: **September 25, 2007**Rain: **No**Segment Location: **From sharp right bend below straight, channelized section upstream to confluence with****QC Status - Staff: Provisional Consultant: Provisional** *Step 2. (Contued)***Step 1. Valley and Floodplain**1.1 Segmentation **Corridor Encroachment**1.2 Alluvial Fan **None**

1.3 Corridor Encroachments

Length (ft)	One	Both
Berms	0	0
height	0	0
Roads	961	172
height	0	0
Railroads	0	0
height	0	0
Improved Paths	0	0
height	0	0
Development	1,150	0

2.5 Aband. Floodpln **0.00** ft.Human Elev Floodpln **12.20** ft.2.6 Width/Depth Ratio **12.21**2.7 Entrenchment Ratio **1.85**2.8 Incision Ratio **0.00**Human Elevated Inc Rat **2.89**2.9 Sinuosity **Low**2.10 Riffles Type **Eroded**2.11 Riffle/Step Spacing (ft) **90**

2.12 Substrate Composition

Bedrock **10%**Boulder **38%**Cobble **31%**Coarse Gravel **3%**Fine Gravel **12%**Sand **6%**Silt and smaller **0%**Silt/Clay Present? **No**Detritus **5 %**# Large Woody **1**

2.13 Average Largest Particle on

Bed **24.0** inchesBar **N/A** inches

2.14 Stream Type

Stream Type: **B**Bed Material: **Cobble**Subclass Slope: **c**Bed Form: **Step-Pool**Field Measured Slope: **1.7**

2.15 Reference Stream Type

(if different from Phase 1)

3.3 old Amount Mean Height

Failures **None** **0.00**Gullies **None** **0.00****Step 3. Riparian Features**

3.1 Stream Banks

Typical Bank Slope **Steep**Bank Texture **Left** **Right**

Upper

Material Type **Boulder/Cobbl** **Boulder/Cobbl**Consistency **Non-cohesive** **Non-cohesive**

Lower

Material Type **Boulder/Cobbl** **Boulder/Cobbl**Consistency **Non-cohesive** **Non-cohesive**Bank Erosion **Left** **Right**Erosion Length (ft) **0** **0**Erosion Height (ft) **0.00** **0.00**Revetmt. Type **None** **Rip-Rap**Revetmt. Length (ft) **0** **637**Near Bank Veg. Type **Left** **Right**Dominant **Coniferous** **Herbaceous**Sub-dominant **Deciduous** **Shrubs/Saplin**Bank Canopy **Left** **Right**Canopy % **51-75** **1-25**Mid-Channel Canopy **Open**

3.2 Riparian Buffer

Buffer Width **Left** **Right**Dominant **51-100** **26-50**Sub-dominant **26-50** **0-25**W less than 25 **91** **889**Buffer Veg. Type **Left** **Right**Dominant **Coniferous** **Shrubs/Saplin**Sub-dominant **Deciduous** **Herbaceous**

3.3 Riparian Corridor

Corridor Land **Left** **Right**Dominant **Forest** **Residential**Sub-dominant **Residential** **Shrubs/Saplin**Mass Failures **0** **0**Height **0** **0**Gullies **0** **0**Height **0** **0****Step 4. Flow & Flow Modifiers**4.1 Springs / Seeps **None**4.2 Adjacent Wetlands **None**4.3 Flow Status **Low**4.4 # of Debris Jams **0**4.5 Flow Regulation Type **Small Bypass**Flow Regulation Use **Drinking**

Impoundments

Impoundmt. Location

4.6 Up/Down strm flow reg **None**

(old) Upstrm Flow Reg

4.7 StormwaterInputs

Field Ditch **0** Road Ditch **0**Other **0** Tile Drain **0**Overland Flow **0** Urb Strm Wtr Pipe **0**4.9 # of Beaver Dams **0**Affected Length (ft) **0****Step 5. Channel Bed and Planform Changes**

5.1 Bar Types

Mid	Point	Side
0	0	0

Diagonal	Delta	Island
0	0	0

5.2 Other Features

Flood	Neck Cutoff	Avulsion	Braiding
0	0	0	0

5.3 Steep Riffles and Head Cuts

Steep Riffles	Head Cuts	Trib Rejuv.
0	0	No

5.4 Stream Ford or Animal **No**5.5 Straightening **Straightening**Straightening Length: **871**5.5 Dredging **Dredging**

Project: Walloomsac Woodford	Phase 2 Segment Summary	page 2 of 2	November 27, 2007
Stream: Bolles Brook	Reach # M6T3.05	Segment: C	Completion Date: September 25,
Organization: Bennington County NRCD	Observers: Jason George and Jill Winton		Rain: No
Segment Length (ft): 1,163	Segment Location: From sharp right bend below straight, channelized section upstream to confluence with		

1.6 Grade Controls

Type	Location	Total	Total Height Above Water	Photo Taken	GPSTaken
Dam	Mid-segment	8.00	5.00	Yes	

4.8 Channel Constrictions

Type	Width	Photo Taken?	GPS Taken?	Channel Constriction?	Floodprone Constriction?
Bridge	80.0	Yes	Yes	No	Yes
Problem	None				

Narrative:
Degradation

Step 7. Rapid Geomorphic Assessment Data

Confinement Type **Unconfined**

	Score	STD	Historic
7.1 Channel Degradation	5	None	No
7.2 Channel Aggradation	15	None	No
7.3 Widening Channel	14		No
7.4 Change in Planform	14		No

Total Score **48**

Geomorphic Rating **0.6**

Channel Evolution Model **F**

Channel Evolution Stage **II**

Geomorphic Condition **Fair**

Stream Sensitivity **High**

Step 6. Rapid Habitat Assessment Data

Stream Gradient Type **High**

	Score
6.1 Epifaunal Substrate - Available Cover	10
6.2 Embeddedness	13
6.3 Velocity/Depth Patterns	14
6.4 Sediment Deposition	14
6.5 Channel Flow Status	15
6.6 Channel Alteration	10
6.7 Frequency of Riffles/Steps	16
6.8 Bank Stability	Left: 8 Right: 6
6.9 Bank Vegetation Protection	Left: 9 Right: 2
6.10 Riparian Vegetation Zone Width	Left: 9 Right: 3

Total Score **129**

Habitat Rating **0.645**

Habitat Stream Condition **Good**

Project: **Waloomsac Woodford**Stream: **Bolles Brook**Organization: **Bennington County NRCD**Segment Length (ft): **5,734****Phase 2 Segment Summary**

page 1 of 2

Reach # **M6T3.06**Segment: **0**Observers: **Jason George and Jill Winton**

Why Not assessed:

November 27, 2007 SGAT Version: 4.56

Completion Date: **September 24, 2007**Rain: **No**Segment Location: **From confluence with Bickford Hollow Brook to intersection with National Forest Road 278.****QC Status - Staff: Provisional Consultant: Provisional** *Step 2. (Contued)***Step 1. Valley and Floodplain**1.1 Segmentation **None**1.2 Alluvial Fan **None**

1.3 Corridor Encroachments

Length (ft)	One	Both
Berms	345	0
height	0	0
Roads	1,947	0
height	0	0
Railroads	0	0
height	0	0
Improved Paths	0	0
height	0	0
Development	481	0

2.5 Aband. Floodpln **5.55 ft.**Human Elev Floodpln **0.00 ft.**2.6 Width/Depth Ratio **16.48**2.7 Entrenchment Ratio **3.97**2.8 Incision Ratio **1.98**Human Elevated Inc Rat **0.00**2.9 Sinuosity **Low**2.10 Riffles Type **Complete**2.11 Riffle/Step Spacing (ft) **45**

2.12 Substrate Composition

Bedrock **0%**Boulder **18%**Cobble **56%**Coarse Gravel **13%**Fine Gravel **12%**Sand **1%**Silt and smaller **0%**Silt/Clay Present? **No**Detritus **5 %**# Large Woody **55**

2.13 Average Largest Particle on

Bed **48.0 inches**Bar **22.0 inches**

2.14 Stream Type

Stream Type: **D**Bed Material: **Cobble**Subclass Slope: **b**Bed Form: **Braided**Field Measured Slope: **3.4**

2.15 Reference Stream Type

(if different from Phase 1)

3.3 old Amount Mean Height

Failures **None 0.00**Gullies **None 0.00****Step 3. Riparian Features**

3.1 Stream Banks

Typical Bank Slope **Moderate**Bank Texture **Left Right**

Upper

Material Type **Boulder/Cobbl Boulder/Cobbl**Consistency **Non-cohesive Non-cohesive**

Lower

Material Type **Boulder/Cobbl Boulder/Cobbl**Consistency **Non-cohesive Non-cohesive**Bank Erosion **Left Right**Erosion Length (ft) **101 108**Erosion Height (ft) **8.00 6.00**Revetmt. Type **None None**Revetmt. Length (ft) **0 0**Near Bank Veg. Type **Left Right**Dominant **Deciduous Deciduous**Sub-dominant **Shrubs/Saplin Shrubs/Saplin**Bank Canopy **Left Right**Canopy % **76-100 76-100**Mid-Channel Canopy **Closed**

3.2 Riparian Buffer

Buffer Width **Left Right**Dominant **>100 >100**Sub-dominant **26-50 None**W less than 25 **339 0**Buffer Veg. Type **Left Right**Dominant **Deciduous Deciduous**Sub-dominant **Coniferous Coniferous**

3.3 Riparian Corridor

Corridor Land **Left Right**Dominant **Forest Forest**Sub-dominant **Pasture None**Mass Failures **0 0**Height **0 0**Gullies **0 0**Height **0 0****Step 4. Flow & Flow Modifiers**4.1 Springs / Seeps **Abundant**4.2 Adjacent Wetlands **None**4.3 Flow Status **Low**4.4 # of Debris Jams **0**4.5 Flow Regulation Type **None**

Flow Regulation Use

Impoundments **None**

Impoundmt. Location

4.6 Up/Down strm flow reg **None**

(old) Upstrm Flow Reg

4.7 StormwaterInputs

Field Ditch **0** Road Ditch **0**Other **0** Tile Drain **0**Overland Flow **0** Urb Strm Wtr Pipe **0**4.9 # of Beaver Dams **0**Affected Length (ft) **0****Step 5. Channel Bed and Planform Changes**

5.1 Bar Types

Mid	Point	Side
1	2	2
Diagonal	Delta	Island
0	0	12

5.2 Other Features **Braiding**Flood **10** Neck Cutoff **0** Avulsion **0**

5.3 Steep Riffles and Head Cuts

Steep Riffles **0** Head Cuts **0** Trib Rejuv. **No**5.4 Stream Ford or Animal **No**5.5 Straightening **None**Straightening Length: **0**5.5 Dredging **None**

Note: Step 1.6 - Grade Controls

and Step 4.8 - Channel Constrictions

are on The second page of this

report - with Steps 6 through 7.

Completion Date: **September 24,**
Rain: **No**

Habitat Stream Condition	Good
--------------------------	------

Narrative:
Planform.