

Phase 2 Stream Geomorphic Assessment

**East Creek Watershed
Towns of Rutland, East Pittsford, and Chittenden
Rutland County, Vermont**

March 2007



**Prepared for:
Rutland Regional Planning Commission
The Opera House
P.O. Box 965, 67 Merchant's Row
Rutland, VT 05737**

March 22, 2007

Mr. Steve Schild
Rutland Regional Planning Commission
The Opera House
P.O. Box 965, 67 Merchant's Row
Rutland, VT 05737

Re: Phase 2 Stream Geomorphic Assessment
East Creek Watershed
Rutland County, Vermont
JCO Project No. 1-1872-5


Dear Mr. Schild:

The Johnson Company is pleased to present the following Phase 2 Stream Geomorphic Assessment report to the Rutland Regional Planning Commission. This report includes the results of Phase 2 Geomorphic Assessments performed in accordance with the Vermont Agency of Natural Resources (VTANR) Stream Geomorphic Assessment Protocols on 5 reaches of the East Creek mainstem.

Should you have any questions or require additional assistance, please do not hesitate to contact me at (802) 229-4600. Thank you for the opportunity to be of assistance to the RRPC on this project.

Sincerely,

THE JOHNSON COMPANY, INC.

By: 
Noelia Báez Rodríguez
Staff Scientist

C: Shannon Pytlik, VTANR

EXECUTIVE SUMMARY

The Johnson Company was retained by Rutland Regional Planning Commission to perform Phase 2 Geomorphic Assessments on five reaches of the East Creek mainstem (M04, M06, M08, M09, and M10) during the summer of 2006. Due to difficulties with landowner access, the geomorphic assessments of M08 and M10 were incomplete. Bridge and Culvert Assessments were conducted on all structures within all five reaches. All of the Phase 2 Assessments were conducted in accordance with the 2006 Vermont Agency of Natural Resources (VT ANR) Stream Geomorphic Assessment Protocols (VT ANR 2006) Steps 1-7. All of the collected data were recorded on the VT ANR Phase 2 data sheets and entered into the VT ANR Stream Geomorphic Assessment Web Based Data Management System (DMS). A thorough internal QA review was performed by The Johnson Company in November, 2006. An independent QA review was performed by VT ANR in January 2007 and the Phase 1 and 2 DMS were updated in March, 2007. Goals and Objectives for the project included the following:

- Determine the existing stream type for each targeted reach and field verify the previously collected Phase 1 assessments;
- Conduct geomorphic condition evaluations for each reach which detail the current condition and sensitivity to existing and future natural and anthropogenic stressors;
- Collect and interpret the Phase 2 data to assess which reaches are responding to anthropogenic and natural modifications, and help prioritize which reaches warrant further study and/or restoration activities.

Individual narratives for each assessed reach are included as Appendix A. Based on the field measurements taken during the Phase 2 Assessments, the evolution stages of the assessed reaches are as follows: M04 – Stage IV –planform adjustment; M06 – Stage II –degradation; M09A – Stage I – equilibrium; and M09B – Stage II-degradation. A description of the different channel evolution stages can be found in the VT ANR Stream Geomorphic Assessment Protocols, which may be found online at: http://www.anr.state.vt.us/dec/waterq/rivers/htm/rv_geoassess.htm.

Stream types for the assessed reaches were: M04 C riffle-pool; M06 C riffle-pool; M09A – C riffle-pool; and M09B – B step-pool. Departures from the reference stream type were noted in segment M09B which departed from reference type C to B. The dominant sediment regime for the watershed is aggradation. The sensitivity ratings for M06 and M09B were very high and for M04 were high, indicating the potential for future degradation in these reaches. Sensitivity for M09A was rated as moderate, and since the segment was in evolution Stage I, this segment was at low risk for future degradation. The reaches were generally well buffered with most segments having buffer widths wider than 50 feet. Debris jams, which acted as channel constrictions, were common throughout the assessed reaches.

The bridge and culvert assessment found undersized bridges in M04, M06, M08, and M09B. One undersized culvert was noted in M08 and five undersized culverts were noted in M10. During future bridge and culvert replacement projects the collected data should be used to ensure that the new bridges are correctly sized.

Based on the results of the Phase 2 Assessments and visual observations, potential restoration/corridor protection projects identified within the watershed are described below. Figures 3 through 5 depict the project locations. Photos of some of the project areas are shown in Appendix A.

- M04 – While this reach is generally well buffered, inadequate buffer widths were noted adjacent to fields in agricultural use. Buffer installation on these fields is recommended.
- M06 – Removal of the berms which are corridor encroachments in this reach is recommended. Also, this reach is relatively undeveloped and contains some riparian wetlands, so a Corridor Protection Plan is also recommended.
- M09B – Since this segment is constricted by a significant berm on the right side, removal of part or all of this berm is recommended. Further study of the site is necessary to assess potential for negative impacts on adjacent property from berm removal. The removal of the stone wall that acts as a revetment is also recommended.

There are federal programs which could potentially provide funding in support of these projects such as the Conservation Reserve Enhancement Program (CREP), and Environmental Quality Improvement Program (EQIP), which compensates landowners for the loss of cropland to enhance riparian buffers. Funds from the Vermont River Management Program (RMP) may also be available for projects not eligible for the federal programs.

TABLE OF CONTENTS

1.0 PROJECT OVERVIEW	1
2.0 BACKGROUND INFORMATION	2
2.1 GEOGRAPHIC SETTING	2
2.2 GEOLOGIC SETTING.....	2
2.3 GEOMORPHIC SETTING.....	2
2.4 HYDROLOGY	3
2.5 ECOLOGICAL SETTING.....	3
3.0 METHODOLOGY	4
3.1 FLUVIAL GEOMORPHIC ASSESSMENT PROTOCOLS.....	4
3.2 QUALITY ASSURANCE AND QUALITY CONTROL	4
4.0 RESULTS	5
4.1 WATERSHED SCALE STRESSORS.....	5
4.1.1 Hydrologic Alterations.....	5
4.1.2 Dams	5
4.1.3 Sediment Load Indicators	5
4.2 REACH SCALE STRESSORS – BOUNDARY CONDITIONS	6
4.2.1 Channel Bed Modifiers.....	6
4.2.2 Bank and Riparian Vegetation Modifiers	6
4.3 REACH SCALE STRESSORS – ENERGY GRADE	7
4.3.1 Slope Modifiers.....	7
4.3.2 Floodplain Modifiers	8
4.4 BRIDGE AND CULVERT ASSESSMENTS	8
5.0 PRELIMINARY PROJECT IDENTIFICATION.....	8
5.1 DEPARTURE ANALYSIS – CHANNEL EVOLUTION STAGE	8
5.2 SENSITIVITY ANALYSIS – DOMINANT ADJUSTMENT PROCESS.....	9
5.3 POTENTIAL PROJECT AREAS	9
6.0 REFERENCES.....	11

LIST OF FIGURES

- Figure 1 Site locations of the studied reaches M04 and M06, along the East Creek River, Rutland County, VT.
- Figure 2 Site locations of the studied reaches M08, M09 and M10, along the East Creek River, Rutland County, VT.
- Figure 3 Proposed buffer installation on the right side of Reach M04
- Figure 4 Potential for a berm removal project in Reach M06
- Figure 5 Segmentation of Reach M09 and potential sites for berm and stone wall removal
- Figure 6 Adjacent properties to the berm removal project on the right side of M09.

LIST OF APPENDICES

- Appendix A Individual Reach Narratives
- Appendix B Phase 2 Data Management System Reports

1.0 PROJECT OVERVIEW

The Johnson Company was retained by Rutland Regional Planning Commission to perform Phase 2 Geomorphic Assessments on five reaches of the East Creek mainstem (M04, M06, M08, M09, and M10) during the summer of 2006 (Figure 1 through 2). Due to difficulties with landowner access, the geomorphic assessments of M08 and M10 were incomplete. Bridge and Culvert Assessments were conducted on all structures within all five reaches. Funding for the project was provided by the Vermont Agency of Natural Resources (VT ANR) Rivers Management Section. Quality Assurance responsibilities were coordinated between The Johnson Company and the Vermont Agency of Natural Resources (VT ANR). Phase 1 Geomorphic Assessments of the watershed were completed by Rutland Regional Planning Commission in 2006.

The East Creek watershed encompasses approximately 61 square miles within the towns of Chittenden, East Pittsford, Mendon, Rutland Town and Rutland City, and is a major tributary of the Otter Creek. The study area included most of the mainstem of the East Creek from Rutland Town to its head waters at Chittenden Reservoir. The study area for East Creek included the five most upstream stream reaches, except M05 and M07 which were not included as part of the assessment.

Goals and Objectives for the project included the following:

- Determine the existing stream type for each targeted reach and field verify the previously collected Phase 1 assessments;
- Conduct geomorphic condition evaluations for each reach which detail the current condition and sensitivity to existing and future natural and anthropogenic stressors;
- Collect and interpret the Phase 2 data to assess which reaches are responding to anthropogenic and natural modifications, and help prioritize which reaches warrant further study and/or restoration activities;

2.0 BACKGROUND INFORMATION

2.1 GEOGRAPHIC SETTING

The East Creek watershed encompasses approximately 61 square miles within the towns of Chittenden, East Pittsford, Mendon, Rutland Town and Rutland City, and is a major tributary of the Otter Creek which flows into Lake Champlain. The watershed elevation ranges from approximately 615 feet above mean sea level at Rutland Town and more than 1,465 feet at the upstream end of its tributaries. Figure 1 and 2 shows the geographic setting for the watershed.

Much of the watershed is located in the Green Mountain National Forest and the Rutland City Forest, so the upper reaches of the watershed are forested. The watershed also encompasses the Chittenden Reservoir and the village of Chittenden. The lower reaches of the watershed extend into more developed areas in Rutland Town and Rutland City. The reaches in this assessment were shown in Figure 1 and 2.

2.2 GEOLOGIC SETTING

Much of the East Creek watershed is located in the Green Mountain National Forest. Like other areas within Vermont, the area has been periodically covered by glaciers, the most recent of which occurred from approximately 10,000 to 30,000 years ago. Bedrock in the study area is dominated by a combination of the Holly Complex, Hoosic, Dalton, and Dunham Formations which are comprised of various types of quartzite, schist, and calcite and dolomite marbles (Doll 1961). The surficial geology is comprised of glaciofluvial gravel and terminal moraine and littoral gravels and sands (Doll 1970) (Stewart and MacClintock 1970). Soils in the study area are dominated by loam, silt loam, and loamy sands predominantly associated with the following series; Turnbridge Berkshire Complex, Berkshire-Colton Association, Udifluvents and fluvaquents near level, and Udipsamment nearly level (USDA SCS 1985).

2.3 GEOMORPHIC SETTING

The locations of the assessed reaches are shown on Figures 1 and 2. The study area included the mainstem of the East Creek (M04 to M10) from Rutland Town to its head waters at

the Chittenden Reservoir with the exception of two short reaches (M05 and M07). However, due to problems with landowner permission for access, M08 and M10 were not fully assessed.

The channel slopes for the study area ranged from 0.89% to 3.11% within the East Creek (Rutland Regional Planning Commission 2006). Bedrock grade controls were noted in all the reaches.

Based on the Phase 1 data, all five reaches within the study have a C as reference stream type characterized by slopes of less than 4% with substrate ranging from gravel to cobble. The valley types for all assessed reaches range from broad to very broad. The calculated valley widths ranged from 366 feet in M10 to nearly 3,458 feet in M04 (Rutland Regional Planning Commission 2006).

2.4 HYDROLOGY

No stream gages are located on East Creek. The nearest USGS gage for the study area is on the Otter Creek at its outlet in Rutland Center downstream from of the study area, and in Rutland. A significant flood occurred in 1947 after heavy rains and a malfunction of the dam at the Chittenden Reservoir. The hydrology of the study area is influenced by the dam at the Chittenden Reservoir, upstream of M10, and the Glen Dam in M05, a reach that was not assessed in this study.

2.5 ECOLOGICAL SETTING

The study area includes a variety of aquatic and upland habitat types which range from forest, agricultural crop and pasture land to beaver ponds. The majority of the aquatic habitat consists of a riffle-pool community which has been affected by some amount of aggradation causing filling of pools and embedding of riffle substrates (M04, M06, and M08). The majority of the riparian zone in the East Creek consists of hardwood and softwood forests. Several beaver ponds and alder wetlands (M06, M08, and M09) were noted, and residential and agricultural areas were also present in M04 and M09.

3.0 METHODOLOGY

3.1 FLUVIAL GEOMORPHIC ASSESSMENT PROTOCOLS

All of the Phase 2 Assessments were conducted in accordance with the 2006 Vermont Agency of Natural Resources (VT ANR) Stream Geomorphic Assessment Protocols (VT ANR 2006) Steps 1-7. All of the collected data were recorded on the VT ANR Phase 2 data sheets and entered into the VT ANR Stream Geomorphic Assessment Web Based Data Management System (DMS). Copies of the DMS Reports are provided in Appendix B. Following a thorough quality assurance (QA) review, the previously collected Phase 1 data were updated based on the findings of the Phase 2 Assessments. Bridge and Culvert Assessments were conducted in all five reaches, and the collected data was recorded on the appropriate VT ANR Bridge and Culvert Data Sheets and later entered into the VT ANR Bridge and Culvert Database.

In accordance with the protocols each of the assessed reaches was walked in its entirety prior to collecting any measurements to allow for reach segmentation where appropriate and identification of potential bankfull identifiers and cross section locations. A detailed Site Sketch Map was created for each of the assessed reaches documenting the locations of cross sections, photo points, pebble counts, bank erosion and revetments, grade controls, debris jams, depositional features, channel cut-offs and avulsions, and other important features. Cross sections were measured at representative locations within each reach using a staff gage and measuring tape.

3.2 QUALITY ASSURANCE AND QUALITY CONTROL

A thorough internal QA review was performed by The Johnson Company in November 2006. An independent QA review was performed by VT ANR in January 2007 and the Phase 1 and 2 DMS were updated in March, 2007. All of the collected data are stored in the DMS and original copies of the data sheets may be found at The Johnson Company's office in Montpelier, VT.

4.0 RESULTS

4.1 WATERSHED SCALE STRESSORS

Figures 3 through 6 depict the geomorphic features identified on the East Creek during the Phase 2 Assessments.

4.1.1 *Hydrologic Alterations*

The East Creek watershed is dominated by forest land and rural residential development. As shown in Figures 3 through 6, most of the riparian corridor is forest land with some residential development near the floodplain boundaries. Based on field observations and historic maps, it does not appear that a significant amount of wetland loss has occurred in the watershed in the recent past. Two hydroelectric dams with impoundments and five beaver dams were located in the study area (See Section 4.1.2).

4.1.2 *Dams*

There are two active dams located in the study area, the Glen Dam in M05, and the Chittenden Reservoir Dam at the upstream end of M10 (Figure 1 through 2). Both dams are used for hydropower generation. M05 was not assessed during this study, but the downstream effects from both dams were noted (See Appendix A). An old dam is located in mid-reach on M10 which acts as a grade control. Beaver dams were noted in M06, M08, and M09.

4.1.3 *Sediment Load Indicators*

As previously stated, a majority of the study area is dominated by forest land, mostly hardwood and erosion was not a widespread problem. More areas of erosion were observed in M04, M06, and M08 where more of the floodplain has been developed. Areas of bank erosion are located along poorly buffered sections of the riparian corridor. Areas of erosion in the individual reaches are discussed in Appendix A. No mass failures were observed.

The lowest reach assessed within the study area, M04 contained multiple steep riffles, and enlarged bars, signs of the aggradational process. Other depositional features which were common include point bars, diagonal bars, delta bars, side bars, mid bars and islands. Flood chutes were noted in all of the reaches. Four channel avulsions were identified: one in M08;

two in M09—one in each segment; and one in M10. A few braided channels were observed in four of the reaches M04, M06, M08 and M09, though all of them were associated with beaver activity where dams have blown out and the large slug of water and sediment formed a short braided section immediately downstream or within the former dam.

4.2 REACH SCALE STRESSORS – BOUNDARY CONDITIONS

Individual narratives for each assessed reach are included as Appendix A. Below is a summary of the dominant reach scale stressors observed throughout the watershed. Figures 3 through 6 depict the geomorphic features identified on the East Creek during the Phase 2 Assessments.

4.2.1 Channel Bed Modifiers

The measured incision ratios in M04, M06, and M09A were less than 1.4 and the entrenchment ratios were greater than 2.2, so while some incision has taken place, the stream still access to its floodplain. The incision ratio for M09B was 3.5 and the entrenchment ratio was 2.3. Thus the stream is highly incised and moderately entrenched. Evidence of gravel mining on point bars was present in M04.

4.2.2 Bank and Riparian Vegetation Modifiers

Figures 3 through 6 show the locations of bank armoring and active erosion. Relatively short areas of rip-rap were noted in M04, M08, M09A, and M10. More extensive rip-rap and other revetments were noted in M09B.

Since most of the reaches had buffer widths greater than 50 feet, lack of riparian buffer and woody vegetation is a minor stressor to the East Creek watershed. Riparian buffers serve many functions. They help to stabilize stream banks and prevent erosion, provide shade and cover for aquatic species, and serve as natural filters to help remove excess nutrients and organic matter from the system.

4.3 REACH SCALE STRESSORS – ENERGY GRADE

4.3.1 *Slope Modifiers*

While some channelization was noted in all the assessed reaches, it was not a significant stressor except in M09B, where approximately one-third of the reach had been straightened. Straightening increases the channel slope and power and velocity of the water within the stream. This can lead to degradation and increased stream bank erosion.

Both natural constrictions and human made ones, such as bridges and dams were observed. Naturally occurring bedrock channel constrictions were found in the following reaches: M04, M09A and M09B. Bridges were found on all study segments and culverts were observed in M08, and M10. One undersized bridge was found in M04, M06 and M09. Undersized culverts were noted in M08 and M10. The effect of these constrictions was limited to the immediate area upstream and downstream of the constriction and was principally the accumulation of excess sediment above the constriction and scour and deposition downstream of the constriction.

There are two dams located in the study area, one in M05 immediately upstream of M04, and one at the upstream end of M10 (Figures 1 through 2). Both dams are used for hydropower generation. M05 was not assessed during this study. Downstream effects from both dams were noted (See Appendix A). In M04, the segment immediately downstream of the dam had less fine sediment and was slightly more incised than at the cross section (incision ratio 1.2 compared to 1.1 for the cross section), but this difference was not significant enough to segment the reach. One possible reason for the lack of degradation directly downstream of the dam is the amount of water that bypasses the channel through the diversion structure. Since M10 was not fully assessed, the influence of the Chittenden Reservoir Dam directly downstream of the dam was not measured. An old dam is located in mid-reach on M08 which acts as a grade control. The beaver dams in M06, M08, and M09, and the debris jams in M06, M08, M09, and M10 act as slope modifiers.

4.3.2 *Floodplain Modifiers*

No active head cuts were observed. All of the assessed reaches had incision ratios greater than 1.0 indicating that some incision had occurred. However, the entrenchment ratios in for all of the assessed reaches were greater than 2.2 indicating floodplain access at 2 times maximum depth. In reach M09, segment B, the incision ratio was 3.5 and the entrenchment ratio was 2.3 suggesting that further incision would reduce floodplain access in this reach also.

While there were some documented river corridor encroachments within the watershed, they were not as substantial as what would be expected in a more developed setting. Roads have encroached upon portions of M04, M06, M09, and M10. Berm constructions were also observed in M04, M06, M09 and M10. The berm in M09 has had a significant impact on the loss of floodplain access in this reach.

4.4 BRIDGE AND CULVERT ASSESSMENTS

Bridge and Culvert Assessments were completed in all of the study reaches because they were all located where access was possible. Summary reports from the VT ANR DMS are included in Appendix B. None of the assessed bridges were found to be threatened by nearby bank erosion or undermining abutments. Several bridges are slightly undersized and act as local channel and floodplain constrictions, though none of the identified problem areas are directly associated with a particular bridge. The culverts in M10 are undersized and act as channel constrictions. During future bridge and culvert replacement projects the collected data should be used to ensure that the new bridges and culverts are correctly sized.

5.0 PRELIMINARY PROJECT IDENTIFICATION

5.1 DEPARTURE ANALYSIS – CHANNEL EVOLUTION STAGE

Based on the field measurements taken during the Phase 2 Assessments, one reach, M09 segment A, is in equilibrium, Stage I. M06 and M09B are in evolution Stage II (degradation), and M04 is in Stage IV (aggradation). The basic evolution model has five stages. In Stage I the stream is in equilibrium condition. In Stage II stream degradation is triggered by some stressor whereby the stream bed elevation is lowered and the stream no longer has adequate access to its

floodplain. Without floodplain access, which dissipates the energy during high flow events, the stream banks erode and the channel widens (Stage III). The widened channel does not have the force to move all of the sediment through the system so sediment buildup and aggradation occur and a new floodplain begins to form at a lower elevation (Stage IV). Once the new floodplain is fully developed the stream is back in equilibrium (Stage V). Further information regarding stream evolution models can be found at

http://www.anr.state.vt.us/dec/waterq/rivers/htm/rv_geoassess.htm. Stream type departures were observed in M09B. M09B departed from the reference type C to a B type channel due to historic degradation and anthropogenic factors. The sediment regime for the studied reaches, overall, is dominated by aggradation, but signs of degradation were noted in M06 and M09.

5.2 SENSITIVITY ANALYSIS – DOMINANT ADJUSTMENT PROCESS

The dominant adjustment process for the overall watershed appears to be aggradation, although as noted above degradation is a significant stressor in Reach M09B and a portion of M06. The other assessed reaches are evolution Stages II and IV. Reach M09A is in Stage I, equilibrium. Based on the evolution stage and stream type, reaches M06 and M09B have a very high sensitivity rating, and M04 has a high sensitivity rating. Thus these three reaches can be expected to continue to widen.

5.3 POTENTIAL PROJECT AREAS

Based on the results of the Phase 2 Assessments and visual observations, potential restoration/corridor protection projects identified within the watershed are described below. Figures 3 through 7 depict the project locations.

- M04 – While this reach is generally well buffered, inadequate buffer widths were noted adjacent to fields in agricultural use. Buffer installation on these fields is recommended.
- M06 – Removal of the berms which are corridor encroachments in this reach is recommended. Also, this reach is relatively undeveloped and contains some riparian wetlands, so a Corridor Protection Plan is also recommended.
- M09B – Since this segment is constricted by a significant berm on the right side, removal of part or all of this berm is recommended. Further study of the site is necessary to assess

potential for negative impacts on adjacent property from berm removal. The removal of the stone wall that acts as a revetment is also recommended.

There are federal programs which could potentially provide funding in support of these projects such as the Conservation Reserve Enhancement Program (CREP), and Environmental Quality Improvement Program (EQIP), which compensates landowners for the loss of cropland to enhance riparian buffers. Funds from the Vermont River Management Program (RMP) may also be available for projects not eligible for the federal programs.

6.0 REFERENCES

Doll, Charles, Centennial Geologic Map of Vermont, State of Vermont Geologists Office, 1961.

Doll, Charles, Surficial Geologic Map of Vermont, State of Vermont Geologists Office, 1970.

http://www.anr.state.vt.us/dec/waterq/rivers/htm/rv_geoassess.htm

Rutland Regional Planning Commission, Phase 1 Geomorphic Assessment of the East Creek Watershed, 2006.

Stewart, D.P. and MacClintock, P., Surficial Geologic Map of Vermont; State of Vermont, 1970.

United States Department of Agriculture Soil Conservation Service, Soil Survey of Rutland County, Vermont, 1985.

Vermont Agency of Natural Resources, Vermont Stream Geomorphic Assessment Phase 2 Handbook and Appendices, 2005.

FIGURES




Figure 1 Site locations of the studied reaches M04 and M06 along the East Creek River, Rutland County, VT.




Figure 2 Site locations of the studied reaches M08, M09 and M10 along the East Creek River, Rutland County, VT.

APPENDIX A

INDIVIDUAL REACH NARRATIVES

East Creek – M04

M04 is the most downstream reach in the East Creek assessment area. It extends from approximately 30 feet from the Route 7 intersection with East Pittsford Road to approximately 100 feet downstream of the Glen Dam. This reach was in regime with its reference stream type C. The stream in this reach is slightly incised, incision ratio of 1.1, and still has access to its floodplain at bankfull stage, entrenchment ratio of 5.8. It was found to be in Stage IV of evolution with a sensitivity rating of high. Active channel migration was evidenced by flood chutes. The bedform is riffle-pool. Limited areas of erosion were noted on both right and left banks (approximately 5 feet high and 100 feet long).

Given the meander pattern in the reach and the presence of the dam upstream, we assume that it was straightened in the past, but the 1893 USGS map of the stream shows it in essentially the same place as it is now. We also expected to see highly eroded banks and degradation in this reach, but the assessment did not confirm this expectation. The segment immediately downstream of the dam did have less fine sediment and was slightly more incised (incision ratio 1.2 compared to 1.1 for the cross section) but this difference was not significant enough to segment the reach. One possible reason for the lack of degradation directly downstream of the dam is the amount of water that bypasses the channel through the diversion structure. The observed bankfull width, 52 feet, was narrower than the 75 foot width estimated in the Phase I assessment. This narrow bankfull width is further evidence of the impact of the dam and diversion structure.

The reach is well buffered by trees on both sides with buffer widths ranging from 51 feet to more than 100 feet. The geomorphic assessment rating was “good”, 0.7, and the habitat assessment rating was also “good”, 0.7. This is a high gradient stream showing evidence of aggradation by the number of mid, point, and side bars and steep riffles. Some scalping of gravel from a point bar was noted. Effects of the Glen Dam can be observed at the upstream end of the reach.

Two bridges were located in this reach which showed deposition above and below and evidence of scour. While not forming channel constrictions, these bridges were flood prone constrictions.

While this reach is generally well buffered, inadequate buffer widths were noted adjacent to fields in agricultural use. Buffer installation on these fields is recommended.




Figure 3 Proposed buffer installations on the right side of Reach M04

East Creek – M06

M06 extends from approximately 400 feet upstream from the confluence of the Mendon Brook with the East Creek to approximately 700 feet upstream from the bridge at East Pittsford. This reach was in regime with its reference stream type C. The stream is slightly incised, incision ratio 1.2, but not entrenched (entrenchment ratio 11.8), so it still has floodplain access at high flows. It was found to be in Stage II of evolution with a very high sensitivity rating, which indicates that the stream is currently incised. Active channel migration was evidenced by flood chutes. A ledge provided bedrock grade control within the reach. Berms were noted on both sides of the downstream portion of the reach, limiting the floodplain access.

The reach was well buffered by trees on both sides, with buffers generally in excess of 100 feet wide. This is a high gradient stream and a large amount of woody debris was noted in this reach. The geomorphic assessment rating was “fair” but the habitat rating was “good”. Two beaver dams and one debris jam were located on the lower to mid-portion of the reach acting as grade control and channel constriction. One bridge was located in this reach which acted as a channel constriction.

Removal of the berms which are corridor encroachments in this reach is recommended. Also, this reach is relatively undeveloped and contains some riparian wetlands, so a Corridor Protection Plan is also recommended.




Figure 4 Potential for a berm removal project in Reach M06

East Creek – M08

M08 extends downstream approximately 4,800 from Sangaman Hill Road and upstream approximately 1,500 feet from Barstow School. This reach was not fully assessed due to lack of landowner permission to access the stream, so geomorphic and habitat assessment data are not available. One channel avulsion was noted mid-way in this reach. The bridge and culvert survey was conducted for this reach and some areas of erosion and riprap were recorded. Three beaver dams were located on mid and two lower portions of the reach. Two bridges were assessed. The bridge located on a driveway off of Power House Road acted as a channel constriction causing deposition upstream and downstream of the constriction. The second bridge on Power House Road did not appear to be a constriction, but deposition was noted below the bridge.

East Creek – M09

Reach M09 is located in the village of Chittenden, and was segmented into M09A and M09B due to corridor encroachment.

M09A extends from the confluence of the East Creek with an unnamed tributary located approximately 1,500 downstream from the Bridge at Holden Road to approximately 100 feet downstream from the bridge at Holden Road. The reach was in regime with its reference type C stream and was found to be in channel evolution Stage I, equilibrium. Stream sensitivity was moderate. One channel avulsion was noted in the lower portion of the segment. One beaver dam and one debris jam acted as grade control and channel constriction. Active channel migration was evidenced by flood chutes. The segment was well buffered with trees. Both the geomorphic and habitat assessment ratings for this segment were “good”.

M09B extends from approximately 100 feet downstream from the Holden Road bridge to approximately 400 feet downstream from the culvert at the Fox Creek Inn. This segment had departed from its reference stream type C to a type B. The stream is highly incised (incision ratio 3.5 and entrenchment ratio 2.3) and was found to be in channel evolution Stage II, with a very high sensitivity rating. Active channel migration was evidenced by flood chutes. One debris jam acted as channel constriction. The stream has lost access to its historic floodplain and is now confined by a terrace on the left side and a berm on the right side that is continuous along almost all of the right side of the segment. The distance from the top of the terrace to the valley wall is less than 50 feet and the distance from the top of the berm to the valley wall are approximately 100 feet. Both the geomorphic and habitat assessment ratings for this segment were “fair.” The bridge at Holden Road in Chittenden Village was undersized and showed evidence of scour both above and below.

The areas of erosion noted were limited, but the reach was armored with rip-rap and stone walls. One channel avulsion was noted near on the upstream end of M09B. Historic evidence of straightening was found. The right side of this reach was not well buffered.

Since M09B is constricted by a significant berm on the right side, removal of part or all of this berm is recommended. Further study of the site is necessary to assess potential for negative impacts on adjacent property from berm removal. The removal of the stone wall that acts as a revetment is also recommended.




Figure 5 Segmentation of Reach M09 and potential sites for berm and stone wall removal



Figure 6 Adjacent properties to the berm removal project on the right side of M09.

East Creek – M10

M10 extends from approximately 400 feet downstream from the culvert at the Fox Creek Inn to the Chittenden Reservoir. This reach was not fully assessed due to lack of landowner permission for access so geomorphic and habitat assessment data are not available. The dam at the Chittenden reservoir creates an impoundment upstream of M10. An old dam which created a grade control was noted in mid-reach. Active channel migration was evidenced by flood chutes. Two debris jams are acting as constrictions. One bridge and five culvert assessments were performed for this reach. All the culverts that were noted provided channel constructions. The culverts were mostly located on private property driveways and deposition and scour were noted upstream of the constrictions.

APPENDIX B
PHASE 2 DATA MANAGEMENT SYSTEM REPORTS

Project: Otter Creek - East Creek Trib
 Stream: East Creek
 Organization: Johnson Company
 Segment Length (ft): 15,164

Phase 2 Segment Summary page 1 of 2
 Reach # M04
 Observers: Noelia Báez Rodríguez, Adam Rutland Town
 Segment: 0
 Why Not assessed:

March 9, 2007
 Completion Date: September 11, 2006
 FIT: Yes
 Rain: Yes

Step 1. Valley and Floodplain		Step 2. Stream Channel		Step 3. Riparian Features		Step 4. Flow & Flow Modifiers	
1.1 Segmentation	None	2.1 Bankfull Width	52	3.1 Stream Banks		4.1 Springs / Seeps	Some
1.2 Alluvial Fan	No	2.2 Max Depth (ft)	3.40	Typical Bank Slope	Steep	4.2 Adjacent Wetlands	Some
1.3 Corridor Encroachments		2.3 Mean Depth (ft)	2.40	Bank Texture	Left	4.3 Flow Status	Low
Length (ft)	One	2.4 Floodprone Width (ft)	300	Upper		4.4 # of Debris Jams	0
Berns	281	2.5 Aband. Floodpin	3.70	Material Type	Gravel	4.5 Impoundments	Large
Roads	1,077	2.6 Width/Depth Ratio	21.54	Consistency	Non-cohesive	Impoundmt. Location	Upstream
Railroads	0	2.7 Entrenchment Ratio	5.80	Lower		4.6 # of Stormwater Inputs	0
Improved Paths	0	2.8 Incision Ratio	1.09	Material Type	Boulder/Cobb/Boulder/Cobb	4.7 Upstream Flow	Store-release
Development	2,774	2.9 Sinuosity	Moderate	Consistency	Non-cohesive	4.9 # of Beaver Dams	0
1.4 Adjacent Side	Left	2.10 Riffles Type	Sedimented	Bank Erosion	Left	Affected Length (ft)	0
Hillside Slope	Very Steep	2.11 Riffle/Step Spacing (ft)	200	Erosion Length (ft)	849	Step 5. Channel Bed and Planform Changes	
Continuous w/Sometimes	Sometimes	2.12 Substrate Composition		Erosion Height (ft)	4.83	5.1 Bar Types	
W/in 1 Bankfill	Sometimes	Bedrock	0 %	Revetmt. Type	Rip-Rap	Mid	Point
Texture	Bedrock	Boulder	1 %	Revetmt. Length (ft)	585	13	22
1.5 Valley Features	Bedrock	Cobble	37 %	Near Bank Veg. Type	Left	Diagonal	Delta
Valley Width (ft)	1,000	Coarse Gravel	42 %	Dominant	Herbaceous	2	2
Width Determination	Estimated	Fine Gravel	15 %	Sub-dominant	Shrubs/Saplin	5.2 Other Features	
Confinement Type	Very Broad	Sand	5 %	Bank Canopy	Left	Flood Neck Cutoff	Avulsion
Rock Gorge?	No	Silt/Clay Present?	No	Canopy %	51-75	10	0
Human-caused changed valley width?	no	# Large Woody	36	Mid-Channel Canopy	Open	5.3 Steep Riffles and Head Cuts	
Notes:		2.13 Average Largest Particle on		3.2 Riparian Buffer		Steep Riffles	Head Cuts
Historic Straightening.		Bed	200.0 mm	Buffer Width	Left	15	0
Landowner working on a rip-rap on the left bank and scalping on a point bar.		Bar	150.0 mm	Dominant	51-100	Trib Rejuv.	
		# Large Woody	36	Sub-dominant	>100	5.4 Stream Ford or Animal	
		2.13 Average Largest Particle on		Buffer Veg. Type	Left	5.5 Straightening	
		Bed	200.0 mm	Dominant	Coniferous	Straightening Length:	
		Bar	150.0 mm	Sub-dominant	Shrubs/Saplin	2,051	
		Stream Type	C	3.3 Riparian Corridor		5.5 Dredging	
		Bed Material:	Gravel	Corridor Land	Left	Gravel Mining	
		Subclass Slope:	None	Dominant	Forest		
		Bed Form:	Riffle-Pool	Sub-dominant	Crop		
		2.15 Reference Stream Type	(if different from Phase 1)	Mass Failures	Amount		
				Gullies	Mean Height		
					None	0.00	
					None	0.00	

Note:
 Step 1.6 - Grade Controls and
 Step 4.8 - Channel Constrictions
 are on The second page of this
 report - Steps 6 through 7.

Project: **Otter Creek - East Creek Trib** Reach # **M04** Phase 2 Reach Summary page 2 of 2 March 9, 2007
 Stream: **East Creek** Observers: **Noelia Báez Rodríguez, Adam Robtoy** Segment: **0** Completion Date: **September 11,**
 Organization: **Johnson Company** Segment Location: **Rutland Town** Rain: **Yes**
 Segment Length (ft): **15,164**

1.6 Grade Controls None

Type	Location	Total	Total Height Above Water	Photo Taken	GPSTaken

Step 7. Rapid Geomorphic Assessment Data

Confinement Type	Unconfined	Score	STD	Historic
7.1 Channel Degradation		16	None	Yes
7.2 Channel Aggradation		11	None	Yes
7.3 Widening Channel		14		
7.4 Change in Planform		15		
Total Score		56		
Geomorphic Rating		0.7		
Channel Evolution Model		F		
Channel Evolution Stage		IV		
Geomorphic Condition		Good		
Stream Sensitivity		High		

Step 6. Rapid Habitat Assessment Data

Stream Gradient Type	High	Score
6.1 Epifaunal Substrate - Available Cover		14
6.2 Embeddedness		8
6.3 Velocity/Depth Patterns		15
6.4 Sediment Deposition		13
6.5 Channel Flow Status		8
6.6 Channel Alteration		12
6.7 Frequency of Riffles/Steps		15
6.8 Bank Stability	Left: 8 Right: 8	
6.9 Bank Vegetation Protection	Left: 8 Right: 8	
6.10 Riparian Vegetation Zone Width	Left: 8 Right: 8	
Total Score		133
Habitat Rating		0.665
Habitat Stream Condition		Good

4.8 Channel Constrictions

Type	Width	Photo Taken?	GPS Taken?	Channel Constriction?	Floodprone Constriction?
Bridge 135.	Yes	Yes	No	Yes	Yes
Problem	Deposition Above, Deposition Below, Scour				
Bridge 126.	Yes	Yes	No	Yes	Yes
Problem	Deposition Above, Deposition Below, Scour				

Narrative:
 Evidence of aggradation showing by the abundance of steep riffles.

Project: **Otter Creek - East Creek Trib** Phase 2 Reach Summary page 2 of 2 March 9, 2007
 Stream: **East Creek** Reach # **M06** Segment: **0**
 Organization: **Johnson Company** Observers: **Noelia Báez Rodríguez, Adam Robtoy** Completion Date: **September 18,**
 Segment Length (ft): **8,719** Segment Location: **Pittsford, Rutland Town** Rain: **No**

1.6 Grade Controls

Type	Location	Total	Total Height Above Water	Photo Taken	GPSTaken
Ledge	Upstream	2.00	1.00		

Step 7. Rapid Geomorphic Assessment Data

Confinement Type	Unconfined	Score	STD	Historic
7.1 Channel Degradation		11	None	Yes
7.2 Channel Aggradation		13	None	Yes
7.3 Widening Channel		14		No
7.4 Change in Planform		13		No
Total Score		51		
Geomorphic Rating		0.6375		
Channel Evolution Model		F		
Channel Evolution Stage		II		
Geomorphic Condition		Fair		
Stream Sensitivity		Very High		

Step 6. Rapid Habitat Assessment Data

Stream Gradient Type	High	Score
6.1 Epifaunal Substrate - Available Cover		13
6.2 Embeddedness		8
6.3 Velocity/Depth Patterns		12
6.4 Sediment Deposition		15
6.5 Channel Flow Status		14
6.6 Channel Alteration		17
6.7 Frequency of Riffles/Steps		13
6.8 Bank Stability		Left: 9 Right: 9
6.9 Bank Vegetation Protection		Left: 9 Right: 9
6.10 Riparian Vegetation Zone Width		Left: 9 Right: 9
Total Score		146
Habitat Rating		0.73

Habitat Stream Condition **Good**

4.8 Channel Constrictions

Type	Width	Photo Taken?	GPS Taken?	Channel Constriction?	Floodprone Constriction?
Bridge	24.0	Yes	Yes	Yes	Yes

Problem **Deposition Below, Scour Below**

Narrative:
 Changes in planform

Project: Otter Creek - East Creek Trib
 Stream: East Creek
 Organization: Johnson Company
 Segment Length (ft): 13,147

Phase 2 Segment Summary page 1 of 2
 Reach # M08
 Observers: Noelia Báez Rodríguez, Dan Chittenden, Pittsford
 Segment: 0
 Why Not assessed:

March 9, 2007
 Completion Date: September 28, 2006
 FIT: Yes
 Rain: No

Step 1. Valley and Floodplain		Step 2. Stream Channel		Step 3. Riparian Features		Step 4. Flow & Flow Modifiers	
1.1 Segmentation	Substrate Size	2.1 Bankfull Width	2.2 Max Depth (ft)	3.1 Stream Banks	4.1 Springs / Seeps	4.2 Adjacent Wetlands	Some
Alluvial Fan	No	0	0.00	Typical Bank Slope	Steep	Some	Some
Corridor Encroachments		0	0.00	Bank Texture	Left	Low	Low
Length (ft)	One	Both	2.4 Floodprone Width (ft)	Upper	Right	5	5
Berm	0	0	2.5 Aband. Floodpin	Material Type	Sand	Small	Small
Road	0	0	2.6 Width/Depth Ratio	Consistency	Non-cohesive	In Reach	In Reach
Railroad	0	0	2.7 Entrenchment Ratio	Lower	Non-cohesive	0	0
Improved Paths	0	0	2.8 Incision Ratio	Material Type	Gravel	Run-of-river	Run-of-river
Development	1,654	344	2.9 Sinuosity	Consistency	Cohesive	3	3
1.4 Adjacent Side	Left	Right	2.10 Riffles Type	Bank Erosion	Left	170	170
Hillside Slope	Very Steep	Steep	2.11 Riffle/Step Spacing (ft)	Erosion Length (ft)	304		
Continuous w/	Sometimes	Sometimes	2.12 Substrate Composition	Erosion Height (ft)	5.67		
Win 1 Bankfill	Sometimes	Sometimes		Revetmt. Type	Rip-Rap		
Texture	Not Evalua	Not Evalua		Revetmt. Length (ft)	80		
1.5 Valley Features				Near Bank Veg. Type	Left		
Valley Width (ft)	2,146			Dominant	Shrubs/Saplin		
Width Determination	Estimated			Sub-dominant	Herbaceous		
Confinement Type	Very Broad			Bank Canopy	Left		
Rock Gorge?	No			Canopy %	26-50		
Human-caused changed valley width?	No			Mid-Channel Canopy	Open		
Notes:				3.2 Riparian Buffer			
Approximately 3,300 ft of the stream section was not cover in the survey. The SGA was not complete due to land owner access. The reach assessment implies segmentation based on substrate size and/or flow status on the lower section.				Buffer Width	Left		
				Dominant	51-100		
				Sub-dominant	26-50		
				Buffer Veg. Type	Left		
				Dominant	Deciduous		
				Sub-dominant	Shrubs/Saplin		
				3.3 Riparian Corridor			
				Corridor Land	Left		
				Dominant	Forest		
				Sub-dominant	Residential		
				Mass Failures	None		
				Gullies	None		
				2.14 Stream Type			
				Stream Type:			
				Bed Material:			
				Subclass Slope:			
				Bed Form:			
				2.15 Reference Stream Type			
				(if different from Phase 1)			
				Slit/Clay Present?	Yes		
				Detritus	0 %		
				# Large Woody	0		
				2.13 Average Largest Particle on			
				Bed	0.0		
				Bar	0.0		
				Not Evaluated			
				5.2 Other Features			
				Flood Neck Cutoff	Avulsion		
				2	1		
				5.3 Steep Riffles and Head Cuts			
				Steep Riffles	Head Cuts		
				1	0		
				5.4 Stream Ford or Animal			
				2	2		
				5.5 Straightening			
				2	1		
				5.5 Straightening Length:			
				4	1		
				5.5 Dredging			
				1	0		
				5.4 Stream Ford or Animal			
				2	2		
				5.5 Straightening			
				2	1		
				5.5 Straightening Length:			
				4	1		
				5.5 Dredging			
				1	0		
				5.4 Stream Ford or Animal			
				2	2		
				5.5 Straightening			
				2	1		
				5.5 Straightening Length:			
				4	1		
				5.5 Dredging			
				1	0		
				5.4 Stream Ford or Animal			
				2	2		
				5.5 Straightening			
				2	1		
				5.5 Straightening Length:			
				4	1		
				5.5 Dredging			
				1	0		
				5.4 Stream Ford or Animal			
				2	2		
				5.5 Straightening			
				2	1		
				5.5 Straightening Length:			
				4	1		
				5.5 Dredging			
				1	0		
				5.4 Stream Ford or Animal			
				2	2		
				5.5 Straightening			
				2	1		
				5.5 Straightening Length:			
				4	1		
				5.5 Dredging			
				1	0		
				5.4 Stream Ford or Animal			
				2	2		
				5.5 Straightening			
				2	1		
				5.5 Straightening Length:			
				4	1		
				5.5 Dredging			
				1	0		
				5.4 Stream Ford or Animal			
				2	2		
				5.5 Straightening			
				2	1		
				5.5 Straightening Length:			
				4	1		
				5.5 Dredging			
				1	0		
				5.4 Stream Ford or Animal			
				2	2		
				5.5 Straightening			
				2	1		
				5.5 Straightening Length:			
				4	1		
				5.5 Dredging			
				1	0		
				5.4 Stream Ford or Animal			
				2	2		
				5.5 Straightening			
				2	1		
				5.5 Straightening Length:			
				4	1		
				5.5 Dredging			
				1	0		
				5.4 Stream Ford or Animal			
				2	2		
				5.5 Straightening			
				2	1		
				5.5 Straightening Length:			
				4	1		
				5.5 Dredging			
				1	0		
				5.4 Stream Ford or Animal			
				2	2		
				5.5 Straightening			
				2	1		
				5.5 Straightening Length:			
				4	1		
				5.5 Dredging			
				1	0		
				5.4 Stream Ford or Animal			
				2	2		
				5.5 Straightening			
				2	1		
				5.5 Straightening Length:			
				4	1		
				5.5 Dredging			
				1	0		
				5.4 Stream Ford or Animal			
				2	2		
				5.5 Straightening			
				2	1		
				5.5 Straightening Length:			
				4	1		
				5.5 Dredging			
				1	0		
				5.4 Stream Ford or Animal			
				2	2		
				5.5 Straightening			
				2	1		
				5.5 Straightening Length:			
				4	1		
				5.5 Dredging			
				1	0		
				5.4 Stream Ford or Animal			
				2	2		
				5.5 Straightening			
				2	1		
				5.5 Straightening Length:			
				4	1		
				5.5 Dredging			
				1	0		
				5.4 Stream Ford or Animal			
				2	2		
				5.5 Straightening			
				2	1		
				5.5 Straightening Length:			
				4	1		
				5.5 Dredging			
				1	0		
				5.4 Stream Ford or Animal			
				2	2		
				5.5 Straightening			
				2	1		
				5.5 Straightening Length:			
				4	1		
				5.5 Dredging			
				1	0		
				5.4 Stream Ford or Animal			
				2	2		
				5.5 Straightening			
				2	1		
				5.5 Straightening Length:			
				4	1		
				5.5 Dredging			
				1	0		
				5.4 Stream Ford or Animal			
				2	2		
				5.5 Straightening			
				2	1		
				5.5 Straightening Length:			
				4	1		
				5.5 Dredging			
				1	0		
				5.4 Stream Ford or Animal			
				2	2		
				5.5 Straightening			
				2	1		
				5.5 Straightening Length:			
				4	1		
				5.5 Dredging			

Project: **Otter Creek - East Creek Trib** Phase 2 Reach Summary page 2 of 2 March 9, 2007
 Stream: **East Creek** Reach # **M08** Segment: **0** Completion Date: **September 28,**
 Organization: **Johnson Company** Observers: **Noelia Báez Rodríguez, Dan Smith** Rain: **No**
 Segment Length (ft): **13,147** Segment Location: **Chittenden, Pittsford**

1.6 Grade Controls

Type	Location	Total	Total Height Above Water	Photo Taken	GPSTaken
Dam	Mid-Segment	2.00	1.00		

Step 7. Rapid Geomorphic Assessment Data

Confinement Type

Channel Evolution Model
 Channel Evolution Stage
 Geomorphic Condition
 Stream Sensitivity

4.8 Channel Constrictions

Type	Width	Photo Taken?	GPS Taken?	Channel Constriction?	Floodprone Constriction?
Instream	12.4	Yes	Yes	Yes	No
Problem Deposition Above, Scour Below					
Bridge	12.0	Yes	Yes	Yes	No
Problem Deposition Above, Deposition Below					
Bridge	13.0	Yes	Yes	No	No
Problem Deposition Below					

Step 6. Rapid Habitat Assessment Data

Stream Gradient Type

Habitat Stream Condition

Narrative:

Project: **Otter Creek - East Creek Trib**
 Stream: **East Creek**
 Organization: **Johnson Company**
 Segment Length (ft): **1,400**

Reach # **M09**
 Observers: **Noelia Báez Rodríguez**
 Segment Location: **Chittenden**
 Why Not assessed:

March 9, 2007
 Completion Date: **September 20, 2006**
 FIT: **Yes**
 Rain: **No**

Step 1. Valley and Floodplain		Step 2. Stream Channel		Step 3. Riparian Features		Step 4. Flow & Flow Modifiers	
1.1 Segmentation	Corridor Encroachment	2.1 Bankfull Width	21	3.1 Stream Banks		4.1 Springs / Seeps	Some
1.2 Alluvial Fan	No	2.2 Max Depth (ft)	2.80	Typical Bank Slope	Moderate	4.2 Adjacent Wetlands	Some
1.3 Corridor Encroachments		2.3 Mean Depth (ft)	1.50	Bank Texture	Left	4.3 Flow Status	Low
		2.4 Floodprone Width (ft)	471	Upper		4.4 # of Debris Jams	1
		2.5 Aband. Floodpin	3.70	Material Type	Sand	4.5 Impoundments	Large
		2.6 Width/Depth Ratio	14.00	Consistency	Non-cohesive	Impoundmt. Location	Upstream
		2.7 Entrenchment Ratio	22.43	Lower		4.6 # of Stormwater Inputs	0
		2.8 Incision Ratio	1.32	Material Type	Gravel	4.7 Upstream Flow	Store-release
		2.9 Sinuosity	Moderate	Consistency	Non-cohesive	4.9 # of Beaver Dams	1
1.4 Adjacent Side	Left	2.10 Riffles Type	Eroded	Bank Erosion	Left	Affected Length (ft)	250
Hillslope Slope	Very Steep	2.11 Riffle/Step Spacing (ft)	0	Erosion Length (ft)	18	Step 5. Channel Bed and Planform Changes	
Continuous w/Sometimes	Sometimes	2.12 Substrate Composition		Erosion Height (ft)	6.00	5.1 Bar Types	
W/in 1 Bankfill	Sometimes	Bedrock	0 %	Revetmt. Type	None	Mid	Point
Texture	Not Evalua	Boulder	9 %	Revetmt. Length (ft)	0	1	2
Not Evalua	Not Evalua	Cobble	42 %	Near Bank Veg. Type	Left	Diagonal	Delta
1.5 Valley Features		Coarse Gravel	16 %	Dominant	Deciduous	1	0
Valley Width (ft)	715	Fine Gravel	10 %	Sub-dominant	Herbaceous	Flood Neck Cutoff	Avulsion
Width Determination	Estimated	Sand	23 %	Bank Canopy	Left	1	0
Confinement Type	Very Broad	Silt/Clay Present?	No	Canopy %	76-100	5.2 Other Features	Braiding
Rock Gorge?	No	Detritus	12 %	Mid-Channel Canopy	Open	Flood Neck Cutoff	Avulsion
Human-caused changed valley width?	no	# Large Woody	20	3.2 Riparian Buffer		5.3 Steep Riffles and Head Cuts	Head Cuts
		2.13 Average Largest Particle on		Buffer Width	Left	Steep Riffles	Trib Rejuv.
		Bed	200.0	Dominant	51-100	0	0
		Bar	64.0	Sub-dominant	>100	5.4 Stream Ford or Animal	No
		2.14 Stream Type		Buffer Veg. Type	Left	5.5 Straightening	Yes
		Stream Type:	C	Dominant	Mixed Trees	Straightening Length:	181
		Bed Material:	Cobble	Sub-dominant	Deciduous	5.5 Dredging	None
		Subclass Slope:	b	3.3 Riparian Corridor	Deciduous Shrubs/Saplin		
		Bed Form:	Riffle-Pool	Corridor Land	Left		
		2.15 Reference Stream Type		Dominant	Forest		
		(if different from Phase 1)		Sub-dominant	Residential		
				Mass Failures	Amount		
				Gullies	Mean Height		
					None		
					0.00		
					0.00		

Note:
 Step 1.6 - Grade Controls and
 Step 4.8 - Channel Constrictions
 are on The second page of this
 report - Steps 6 through 7.

Project: **Otter Creek - East Creek Trib** Phase 2 Reach Summary page 2 of 2 March 9, 2007
 Stream: **East Creek** Reach # **M09** Segment: **A** Completion Date: **September 20,**
 Organization: **Johnson Company** Observers: **Noelia Báez Rodríguez** Rain: **No**
 Segment Length (ft): **1,400** Segment Location: **Chittenden**

1.6 Grade Controls **None**

Type	Location	Total	Total Height Above Water	Photo Taken	GPSTaken
7.1 Channel Degradation					
7.2 Channel Aggradation					
7.3 Widening Channel					
7.4 Change in Planform					

Step 7. Rapid Geomorphic Assessment Data

Confinement Type	Unconfined	Score	STD	Historic
7.1 Channel Degradation		12	None	
7.2 Channel Aggradation		14	None	No
7.3 Widening Channel		14		
7.4 Change in Planform		15		
Total Score		55		
Geomorphic Rating		0.6875		
Channel Evolution Model		F		
Channel Evolution Stage		I		
Geomorphic Condition		Good		
Stream Sensitivity		Moderate		

Step 6. Rapid Habitat Assessment Data

Stream Gradient Type	High	Score
6.1 Epifaunal Substrate - Available Cover		13
6.2 Embeddedness		15
6.3 Velocity/Depth Patterns		13
6.4 Sediment Deposition		11
6.5 Channel Flow Status		15
6.6 Channel Alteration		13
6.7 Frequency of Riffles/Steps		16
6.8 Bank Stability	Left: 8 Right: 9	
6.9 Bank Vegetation Protection	Left: 8 Right: 8	
6.10 Riparian Vegetation Zone Width	Left: 5 Right: 6	
Total Score		140
Habitat Rating		0.7
Habitat Stream Condition		Good

4.8 Channel Constrictions **None**

Type	Width	Photo Taken?	GPS Taken?	Channel Constriction?	Floodprone Constriction?

Narrative:
Channel Degradation

Project: **Otter Creek - East Creek Trib** Reach # **M09** Phase 2 Reach Summary page 2 of 2 March 9, 2007
 Stream: **East Creek** Observers: **Noelia Báez Rodríguez** Completion Date: **September 20,**
 Organization: **Johnson Company** Segment Location: **Chittenden** Rain: **No**
 Segment Length (ft): **2,142**

1.6 Grade Controls **None**

Type	Location	Total	Total Height Above Water	Photo Taken	GPSTaken

Step 7. Rapid Geomorphic Assessment Data

Confinement Type	Unconfined	Score	STD	Historic
7.1 Channel Degradation		5	C to B	Yes
7.2 Channel Aggradation		13	None	Yes
7.3 Widening Channel		11		
7.4 Change in Planform		12		
Total Score		41		
Geomorphic Rating		0.5125		
Channel Evolution Model		F		
Channel Evolution Stage		II		
Geomorphic Condition		Fair		
Stream Sensitivity		Very High		

4.8 Channel Constrictions

Type	Width	Photo Taken?	GPS Taken?	Channel Constriction?	Floodprone Constriction?
Bridge	54.0	Yes	Yes	No	Yes
Problem	None				
Other	90.0	Yes	Yes	Yes	Yes
Problem	Scour Above, Scour Below, Alignment				

Step 6. Rapid Habitat Assessment Data

Stream Gradient Type	High	Score
6.1 Epifaunal Substrate - Available Cover		10
6.2 Embeddedness		13
6.3 Velocity/Depth Patterns		11
6.4 Sediment Deposition		16
6.5 Channel Flow Status		15
6.6 Channel Alteration		6
6.7 Frequency of Riffles/Steps		16
6.8 Bank Stability		Left: 6 Right: 8
6.9 Bank Vegetation Protection		Left: 8 Right: 5
6.10 Riparian Vegetation Zone Width		Left: 5 Right: 6
Total Score		125
Habitat Rating		0.625
Habitat Stream Condition		Fair

Narrative: Degradation

Project: **Otter Creek - East Creek Trib**
 Stream: **East Creek**
 Organization: **Johnson Company**
 Segment Length (ft): **10,364**

Phase 2 Segment Summary page 1 of 2
 Reach # **M10**
 Observers: **Noelia Báez Rodriguez**
 Segment Location: **Chittenden**
 Why Not assessed:

March 9, 2007 **FIT: Yes**
 Completion Date: **October 2, 2006**
 Rain: **No**

Step 1. Valley and Floodplain		Step 2. Stream Channel		Step 3. Riparian Features		Step 4. Flow & Flow Modifiers	
1.1 Segmentation	None	18	18	3.1 Stream Banks		4.1 Springs / Seeps	Abundant
1.2 Alluvial Fan	No	0.00	0.00	Typical Bank Slope	Steep	4.2 Adjacent Wetlands	Some
1.3 Corridor Encroachments		0.00	0.00	Bank Texture	Left	4.3 Flow Status	Moderate
Length (ft)	One	0	0	Upper		4.4 # of Debris Jams	2
Berm	809	0.00	0.00	Material Type	Gravel	4.5 Impoundments	Large
Roads	9,868	0.00	0.00	Consistency	Non-cohesive	Impoundmt. Location	Upstream
Railroads	0	0.00	0.00	Lower		4.6 # of Stormwater Inputs	3
Improved Paths	0	0.00	0.00	Material Type	Boulder/Cobb/Boulder/Cobb	4.7 Upstream Flow	Store-release
Development	3,649	Low	Low	Consistency	Non-cohesive	4.9 # of Beaver Dams	0
1.4 Adjacent Side	Left	Not Applicable	0	Bank Erosion	Left	Affected Length (ft)	0
Hillslope Slope	Very Steep	Extremely	0	Erosion Length (ft)	21		
Continuous w/	Sometimes	Sometimes	0.00	Erosion Height (ft)	5.00		
W/in 1 Bankfill	Sometimes	Sometimes	0.00	Revetmt. Type	None		
Texture	Not Evalua	Not Evalua	0.00	Revetmt. Length (ft)	0		
1.5 Valley Features				Near Bank Veg. Type	Left		
Valley Width (ft)	366			Dominant	Deciduous		
Width Determination	Estimated			Sub-dominant	Coniferous		
Confinement Type	Very Broad			Bank Canopy	Left		
Rock Gorge?	No			Canopy %	51-75		
Human-caused changed valley width?	No			Mid-Channel Canopy	Open		
Notes:				3.2 Riparian Buffer			
Approximately 4800ft of the stream was not cover during the field work. The assessment was not complete due to land owner access. The Rapid Habitat Assessment or Rapid Geomorph Assessment and a cross section was not complete.				Buffer Width	Left		
				Dominant	26-50		
				Sub-dominant	5-25		
				Buffer Veg. Type	Left		
				Dominant	Deciduous		
				Sub-dominant	Mixed Trees		
				3.3 Riparian Corridor			
				Corridor Land	Left		
				Dominant	Residential		
				Sub-dominant	Forest Shrubs/Saplin		
				Mass Failures	None		
				Gullies	None		
				2.14 Stream Type			
				Stream Type:			
				Bed Material:			
				Subclass Slope:			
				Bed Form:			
				2.15 Reference Stream Type			
				(if different from Phase 1)			
				5.1 Bar Types			
				Mid	Point	Side	
				1	4	4	
				Diagonal	Delta	Island	
				0	0	1	
				5.2 Other Features			
				Flood Neck Cutoff	Avulsion	Braiding	
				2	0	1	0
				5.3 Steep Riffles and Head Cuts			
				Steep Riffles	Head Cuts	Trib Rejuv.	
				0	0	No	
				5.4 Stream Ford or Animal			
				5.5 Straightening			
				Straightening Length:			
				2,893			
				5.5 Dredging			
				None			

Note:
 Step 1.6 - Grade Controls and
 Step 4.8 - Channel Constrictions
 are on The second page of this
 report - Steps 6 through 7.

Project: **Otter Creek - East Creek Trib** Phase 2 Reach Summary page 2 of 2 March 9, 2007
 Stream: **East Creek** Reach # **M10** Segment: **0**
 Organization: **Johnson Company** Observers: **Noelia Báez Rodríguez** Completion Date: **October 2, 2006**
 Segment Length (ft): **10,364** Segment Location: **Chittenden** Rain: **No**

Step 7. Rapid Geomorphic Assessment Data

Confinement Type
Channel Evolution Model
Channel Evolution Stage
Geomorphic Condition
Stream Sensitivity

1.6 Grade Controls

Type	Location	Total	Total Height Above Water	Photo Taken	GPSTaken
Dam	Mid-Segment	3.00	3.00		

4.8 Channel Constrictions

Type	Width	Photo Taken?	GPS Taken?	Channel Constriction?	Floodprone Constriction?
Instream	12.0	Yes	Yes	Yes	No
Problem	Scour Above				
Instream	8.00	Yes	Yes	Yes	Yes
Problem	Deposition Above, Scour Above				
Instream	8.00	Yes	Yes	Yes	No
Problem	None				
Instream	10.0	Yes	Yes	Yes	No
Problem	None				
Instream	11.0	Yes	Yes	Yes	No
Problem	None				

Step 6. Rapid Habitat Assessment Data

Stream Gradient Type	Habitat Stream Condition
	Habitat Stream Condition

Narrative:
 Minor degradation process acting based on observations.

Stream Geomorphic Assessment

VT DEC

Bridge Summary Report

General Information			
VTrans Structure ID	vtrans-700001001211043	Local Structure ID	---
Assessment Date	09/25/2006	Observers	Noelia Báez Rodríguez
Town	Chittenden		
Location	Drive way 133, intersect with Dam Rd		
Latitude	43.71	Longitude	-72.92
Road Name	---	Road Type	---
Stream Name	East Creek		
Channel width	24 ft. (Measured)	High flow stage	No
Bridge/Arch Information			
Material	Timber	Number of bridge piers/arches	1
Bridge Width	10 ft.	Skewed to roadway?	Yes
Bridge Clearance	7 ft.		
Bridge/Arch Span	36 ft.		
Geomorphic Information			
Floodplain filled by roadway approaches		Not Significant	
Structure is located at significant break in valley slope		No	
Obstructions at the opening of the structure		---	
Steep riffle present immediately upstream of structure		No	
If channel avulses, stream will		Follow Road	
Estimated distance avulsion would follow road		120 ft.	
Angle of stream flow approaching structure		Sharp Bend	
Pool present immediately downstream of structure		No	
Downstream bank heights are substantially higher than upstream bank heights		No	
Stepped footers		No	
More Geomorphic Information			
	Upstream	Downstream	In Structure
Dominant Bed Material	Boulder	Boulder	Cobble
Bedrock Present	No	No	No
Type of Sediment Deposits	---	---	---
Elevation of sediment deposits greater than 1/2 bankfull	No	No	No
Bank Erosion	Low	None	
Hard Bank Armoring	None	Intact	
Stream bed scour causing undermining around or under structure	---	---	
Beaver Dam near Structure	No	No	
Beaver Dam distance (ft.)	---	---	
Vegetation			
	Upstream	Downstream	In Structure
Dominant Vegetation Type - Left	Deciduous Forest	Deciduous Forest	
Dominant Vegetation Type - Right	Deciduous Forest	Deciduous Forest	
Does a band of shrub/forest vegetation 50 ft. wide start within 25 ft. of the structure and extend at least 500 ft. up/downstream?			
Vegetation Band - Left	Yes	Yes	
Vegetation Band - Right	Yes	Yes	
Wildlife			
	Roadkill	Outside Structure	Inside Structure
Species	---	---	---

Other Information			
Spatial location data collected with GPS?	Yes	Photos taken?	Yes
Comments	---		

VT DEC • 103 South Main Street • Waterbury, VT 05671

Vermont Department of Environmental Conservation

A Vermont Government Website Copyright © 2004-2006 State of Vermont - All rights reserved



Stream Geomorphic Assessment

VT DEC

Culvert Summary Report

General Information			
VTrans Structure ID	vtrans-700001001311043	Local Structure ID	---
Assessment Date	09/25/2006	Observers	Noelia Báez Rodríguez
Town	Chittenden		
Location	Dirt road that intersect with Route 2, where acueduct run over East Creek.		
Latitude	43.72	Longitude	-72.92
Road Name	---	Road Type	Gravel
Stream Name	East Creek		
Channel width	15 ft. (Measured)	High flow stage	No
Culvert Information			
Material	Steel Corrugated	Number of culverts	1
Culvert Length	12 ft.	Skewed to roadway?	No
Culvert Height	68 inches (5.7 ft.)	Culvert Overflow Pipe	No
Culvert Width	96 inches (8.0 ft.)		
Geomorphic Information			
Floodplain filled by roadway approaches		Partially	
Structure is located at significant break in valley slope		Yes	
Obstructions at the opening of the structure		---	
Culvert slope as compared with channel slope is significantly		Same	
Steep riffle present immediately upstream of structure		No	
If channel avulses, stream will		Cross Road	
Estimated distance avulsion would follow road		--- ft.	
Angle of stream flow approaching structure		Sharp Bend	
Culvert outlet invert		At Grade	
Outlet drop (invert to water surface)		--- ft.	
Water depth in culvert (at outlet)		--- ft.	
Pool present immediately downstream of structure		Yes	
Downstream bank heights are substantially higher than upstream bank heights		No	
More Geomorphic Information			
	Upstream	Downstream	In Structure
Dominant Bed Material	Gravel	Cobble	None
Bedrock Present	No	No	
Material Present throughout			No
Type of Sediment Deposits	---	---	---
Elevation of sediment deposits greater than 1/2 bankfull	No	No	No
Bank Erosion	Low	None	
Hard Bank Armoring	Intact	Intact	
Stream bed scour causing undermining around or under structure	---	---	
Beaver Dam near Structure	No	No	
Beaver Dam distance (ft.)	---	---	
Vegetation			
	Upstream	Downstream	In Structure
Dominant Vegetation Type - Left	Shrub/Sapling	Herbaceous/Grass	
Dominant Vegetation Type - Right	Shrub/Sapling	Shrub/Sapling	
Does a band of shrub/forest vegetation 50 ft. wide start within 25 ft. of the structure and extend at least 500 ft. up/downstream?			
Vegetation Band - Left	No	No	
Vegetation Band - Right	No	No	

Wildlife

	Roadkill	Outside Structure	Inside Structure
Species	---	---	---

Other Information

Spatial location data collected with GPS?	Yes	Photos taken?	Yes
Comments	---		

VT DEC • 103 South Main Street • Waterbury, VT 05671

Vermont Department of Environmental Conservation

A Vermont Government Website Copyright © 2004-2006 State of Vermont - All rights reserved



Stream Geomorphic Assessment

VT DEC

Culvert Summary Report

General Information			
VTrans Structure ID	vtrans-700001001411043	Local Structure ID	---
Assessment Date	09/25/2006	Observers	Noelia Báez Rodriguez
Town	Chittenden		
Location	O'Neil drive way 193, intersect Dam Road		
Latitude	43.72	Longitude	-72.92
Road Name	---	Road Type	Gravel
Stream Name	East Creek		
Channel width	15 ft. (Measured)	High flow stage	No
Culvert Information			
Material	Aluminum Corrugated	Number of culverts	1
Culvert Length	21 ft.	Skewed to roadway?	No
Culvert Height	48 inches (4.0 ft.)	Culvert Overflow Pipe	No
Culvert Width	96 inches (8.0 ft.)		
Geomorphic Information			
Floodplain filled by roadway approaches		Partially	
Structure is located at significant break in valley slope		No	
Obstructions at the opening of the structure		---	
Culvert slope as compared with channel slope is significantly		Same	
Steep riffle present immediately upstream of structure		No	
If channel avulses, stream will		Cross Road	
Estimated distance avulsion would follow road		--- ft.	
Angle of stream flow approaching structure		Mild Bend	
Culvert outlet invert		At Grade	
Outlet drop (invert to water surface)		--- ft.	
Water depth in culvert (at outlet)		--- ft.	
Pool present immediately downstream of structure		No	
Downstream bank heights are substantially higher than upstream bank heights		No	
More Geomorphic Information			
	Upstream	Downstream	In Structure
Dominant Bed Material	Cobble	Cobble	None
Bedrock Present	---	---	
Material Present throughout			---
Type of Sediment Deposits	---	---	---
Elevation of sediment deposits greater than 1/2 bankfull	No	No	No
Bank Erosion	None	None	
Hard Bank Armoring	Intact	Intact	
Stream bed scour causing undermining around or under structure	---	---	
Beaver Dam near Structure	No	No	
Beaver Dam distance (ft.)	---	---	
Vegetation			
	Upstream	Downstream	In Structure
Dominant Vegetation Type - Left	Shrub/Sapling	Shrub/Sapling	
Dominant Vegetation Type - Right	Shrub/Sapling	Shrub/Sapling	
Does a band of shrub/forest vegetation 50 ft. wide start within 25 ft. of the structure and extend at least 500 ft. up/downstream?			
Vegetation Band - Left	No	No	
Vegetation Band - Right	No	No	

Wildlife

	Roadkill	Outside Structure	Inside Structure
Species	---	---	---

Other Information

Spatial location data collected with GPS?	Yes	Photos taken?	Yes
Comments	---		

VT DEC • 103 South Main Street • Waterbury, VT 05671

Vermont Department of Environmental Conservation

A Vermont Government Website Copyright © 2004-2006 State of Vermont - All rights reserved



Stream Geomorphic Assessment

VT DEC

Culvert Summary Report

General Information			
VTrans Structure ID	vtrans-700001003211043	Local Structure ID	---
Assessment Date	09/25/2006	Observers	Noelia Báez Rodríguez
Town	Chittenden		
Location	Drive way 125, intersect Dam Rd		
Latitude	43.71	Longitude	-72.93
Road Name	---	Road Type	Gravel
Stream Name	East Creek		
Channel width	13 ft. (Measured)	High flow stage	No
Culvert Information			
Material	Aluminum Corrugated	Number of culverts	2
Culvert Length	15 ft.	Skewed to roadway?	No
Culvert Height	62 inches (5.2 ft.)	Culvert Overflow Pipe	No
Culvert Width	60 inches (5.0 ft.)		
Geomorphic Information			
Floodplain filled by roadway approaches		Entirely	
Structure is located at significant break in valley slope		No	
Obstructions at the opening of the structure		---	
Culvert slope as compared with channel slope is significantly		Lower	
Steep riffle present immediately upstream of structure		Yes	
If channel avulses, stream will		Cross Road	
Estimated distance avulsion would follow road		--- ft.	
Angle of stream flow approaching structure		Mild Bend	
Culvert outlet invert		At Grade	
Outlet drop (invert to water surface)		--- ft.	
Water depth in culvert (at outlet)		--- ft.	
Pool present immediately downstream of structure		Yes	
Downstream bank heights are substantially higher than upstream bank heights		Yes	
More Geomorphic Information			
	Upstream	Downstream	In Structure
Dominant Bed Material	Cobble	Boulder	None
Bedrock Present	No	No	
Material Present throughout			No
Type of Sediment Deposits	---	---	---
Elevation of sediment deposits greater than 1/2 bankfull	No	No	No
Bank Erosion	None	None	
Hard Bank Armoring	Intact	Intact	
Stream bed scour causing undermining around or under structure	---	---	
Beaver Dam near Structure	No	No	
Beaver Dam distance (ft.)	---	---	
Vegetation			
	Upstream	Downstream	In Structure
Dominant Vegetation Type - Left	Coniferous Forest	Deciduous Forest	
Dominant Vegetation Type - Right	Shrub/Sapling	Deciduous Forest	
Does a band of shrub/forest vegetation 50 ft. wide start within 25 ft. of the structure and extend at least 500 ft. up/downstream?			
Vegetation Band - Left	No	Yes	
Vegetation Band - Right	No	Yes	

Wildlife

	Roadkill	Outside Structure	Inside Structure
Species	---	---	---

Other Information

Spatial location data collected with GPS?	Yes	Photos taken?	Yes
Comments	---		

VT DEC • 103 South Main Street • Waterbury, VT 05671

Vermont Department of Environmental Conservation

A Vermont Government Website Copyright © 2004-2006 State of Vermont - All rights reserved



Stream Geomorphic Assessment

VT DEC

Culvert Summary Report

General Information			
VTrans Structure ID	vtrans-700001003911043	Local Structure ID	---
Assessment Date	10/02/2006	Observers	Noelia Báez Rodriguez
Town	Chittenden		
Location	Drive way to Fox Creek Inn, intersect with Dam Rd.		
Latitude	43.71	Longitude	-72.94
Road Name	---	Road Type	Gravel
Stream Name	East Creek		
Channel width	21 ft. (Measured)	High flow stage	No
Culvert Information			
Material	Aluminum Corrugated	Number of culverts	2
Culvert Length	30 ft.	Skewed to roadway?	No
Culvert Height	72 inches (6.0 ft.)	Culvert Overflow Pipe	No
Culvert Width	66 inches (5.5 ft.)		
Geomorphic Information			
Floodplain filled by roadway approaches		Partially	
Structure is located at significant break in valley slope		No	
Obstructions at the opening of the structure		---	
Culvert slope as compared with channel slope is significantly		Higher	
Steep riffle present immediately upstream of structure		No	
If channel avulses, stream will		Cross Road	
Estimated distance avulsion would follow road		---	ft.
Angle of stream flow approaching structure		Channelized Straight	
Culvert outlet invert		Free Fall	
Outlet drop (invert to water surface)		0.8 ft.	
Water depth in culvert (at outlet)		2.0 ft.	
Pool present immediately downstream of structure		Yes	
Downstream bank heights are substantially higher than upstream bank heights		No	
More Geomorphic Information			
	Upstream	Downstream	In Structure
Dominant Bed Material	Cobble	Cobble	None
Bedrock Present	No	No	
Material Present throughout			No
Type of Sediment Deposits	---	---	---
Elevation of sediment deposits greater than 1/2 bankfull	No	No	No
Bank Erosion	None	None	
Hard Bank Armoring	Intact	Intact	
Stream bed scour causing undermining around or under structure	---	---	
Beaver Dam near Structure	No	No	
Beaver Dam distance (ft.)	---	---	
Vegetation			
	Upstream	Downstream	In Structure
Dominant Vegetation Type - Left	Deciduous Forest	Shrub/Sapling	
Dominant Vegetation Type - Right	Shrub/Sapling	Deciduous Forest	
Does a band of shrub/forest vegetation 50 ft. wide start within 25 ft. of the structure and extend at least 500 ft. up/downstream?			
Vegetation Band - Left	Yes	No	
Vegetation Band - Right	No	Yes	

Wildlife

	Roadkill	Outside Structure	Inside Structure
Species	---	---	---

Other Information

Spatial location data collected with GPS?	Yes	Photos taken?	Yes
Comments	---		

VT DEC • 103 South Main Street • Waterbury, VT 05671

Vermont Department of Environmental Conservation

A Vermont Government Website Copyright © 2004-2006 State of Vermont - All rights reserved



Stream Geomorphic Assessment

VT DEC

Bridge Summary Report

General Information			
VTrans Structure ID	vtrans-700002005511043	Local Structure ID	---
Assessment Date	09/28/2006	Observers	Noelia Báez Rodríguez
Town	Chittenden		
Location	Drive way, intersect with Dam Rd.		
Latitude	43.69	Longitude	-72.96
Road Name	---	Road Type	Gravel
Stream Name	East Creek		
Channel width	21 ft. (Measured)	High flow stage	No
Bridge/Arch Information			
Material	Timber	Number of bridge piers/arches	0
Bridge Width	12 ft.	Skewed to roadway?	No
Bridge Clearance	5 ft.		
Bridge/Arch Span	13 ft.		
Geomorphic Information			
Floodplain filled by roadway approaches		Entirely	
Structure is located at significant break in valley slope		No	
Obstructions at the opening of the structure		---	
Steep riffle present immediately upstream of structure		No	
If channel avulses, stream will		Follow Road	
Estimated distance avulsion would follow road		300 ft.	
Angle of stream flow approaching structure		Naturally Straight	
Pool present immediately downstream of structure		Yes	
Downstream bank heights are substantially higher than upstream bank heights		No	
Stepped footers		No	
More Geomorphic Information			
	Upstream	Downstream	In Structure
Dominant Bed Material	Cobble	Cobble	Gravel
Bedrock Present	No	No	No
Type of Sediment Deposits	---	---	---
Elevation of sediment deposits greater than 1/2 bankfull	No	No	No
Bank Erosion	None	None	
Hard Bank Armoring	Failing	Intact	
Stream bed scour causing undermining around or under structure	---	---	
Beaver Dam near Structure	No	No	
Beaver Dam distance (ft.)	---	---	
Vegetation			
	Upstream	Downstream	In Structure
Dominant Vegetation Type - Left	Shrub/Sapling	Herbaceous/Grass	
Dominant Vegetation Type - Right	Shrub/Sapling	Herbaceous/Grass	
Does a band of shrub/forest vegetation 50 ft. wide start within 25 ft. of the structure and extend at least 500 ft. up/downstream?			
Vegetation Band - Left	No	Yes	
Vegetation Band - Right	No	Yes	
Wildlife			
	Roadkill	Outside Structure	Inside Structure
Species	---	---	---

Other Information			
Spatial location data collected with GPS?	Yes	Photos taken?	Yes
Comments	---		

VT DEC • 103 South Main Street • Waterbury, VT 05671

Vermont Department of Environmental Conservation

A Vermont Government Website Copyright © 2004-2006 State of Vermont - All rights reserved



Stream Geomorphic Assessment

VT DEC

Culvert Summary Report

General Information			
VTrans Structure ID	vtrans-700001001111043	Local Structure ID	---
Assessment Date	09/25/2006	Observers	Noelia Báez Rodríguez
Town	Chittenden		
Location	Chittenden Reservoir at Dam Rd		
Latitude	43.72	Longitude	-72.92
Road Name	DAM RD	Road Type	Paved
Stream Name	East Creek		
Channel width	20 ft. (Measured)	High flow stage	No
Culvert Information			
Material	Aluminum Corrugated	Number of culverts	1
Culvert Length	100 ft.	Skewed to roadway?	No
Culvert Height	144 inches (12.0 ft.)	Culvert Overflow Pipe	No
Culvert Width	144 inches (12.0 ft.)		
Geomorphic Information			
Floodplain filled by roadway approaches		Entirely	
Structure is located at significant break in valley slope		No	
Obstructions at the opening of the structure		---	
Culvert slope as compared with channel slope is significantly		Lower	
Steep riffle present immediately upstream of structure		No	
If channel avulses, stream will		Cross Road	
Estimated distance avulsion would follow road		--- ft.	
Angle of stream flow approaching structure		Channelized Straight	
Culvert outlet invert		At Grade	
Outlet drop (invert to water surface)		0.5 ft.	
Water depth in culvert (at outlet)		0.8 ft.	
Pool present immediately downstream of structure		No	
Downstream bank heights are substantially higher than upstream bank heights		No	
More Geomorphic Information			
	Upstream	Downstream	In Structure
Dominant Bed Material	Unknown	Gravel	None
Bedrock Present	No	No	
Material Present throughout			No
Type of Sediment Deposits	---	---	---
Elevation of sediment deposits greater than 1/2 bankfull	No	No	No
Bank Erosion	None	None	
Hard Bank Armoring	None	None	
Stream bed scour causing undermining around or under structure	---	---	
Beaver Dam near Structure	No	No	
Beaver Dam distance (ft.)	---	---	
Vegetation			
	Upstream	Downstream	In Structure
Dominant Vegetation Type - Left	Herbaceous/Grass	Shrub/Sapling	
Dominant Vegetation Type - Right	Herbaceous/Grass	Shrub/Sapling	
Does a band of shrub/forest vegetation 50 ft. wide start within 25 ft. of the structure and extend at least 500 ft. up/downstream?			
Vegetation Band - Left	No	No	
Vegetation Band - Right	No	No	

Wildlife

	Roadkill	Outside Structure	Inside Structure
Species	---	---	---

Other Information

Spatial location data collected with GPS?	Yes	Photos taken?	Yes
Comments	Low flow coming from the outlet of the dam. Wetland complex at the base of the outlet.		

VT DEC • 103 South Main Street • Waterbury, VT 05671

Vermont Department of Environmental Conservation

A Vermont Government Website Copyright © 2004-2006 State of Vermont - All rights reserved



Stream Geomorphic Assessment

VT DEC

Bridge Summary Report

General Information			
VTrans Structure ID	vtrans-700001004411043	Local Structure ID	---
Assessment Date	09/20/2006	Observers	Noelia Báez Rodríguez
Town	Chittenden		
Location	Intersection between Haiden Rd and Dam Rd		
Latitude	43.71	Longitude	-72.95
Road Name	HOLDEN RD	Road Type	Paved
Stream Name	East Creek		
Channel width	18 ft. (Measured)	High flow stage	No
Bridge/Arch Information			
Material	Concrete	Number of bridge piers/arches	0
Bridge Width	30 ft.	Skewed to roadway?	No
Bridge Clearance	10 ft.		
Bridge/Arch Span	54 ft.		
Geomorphic Information			
Floodplain filled by roadway approaches		Partially	
Structure is located at significant break in valley slope		No	
Obstructions at the opening of the structure		---	
Steep riffle present immediately upstream of structure		No	
If channel avulses, stream will		Cross Road	
Estimated distance avulsion would follow road		--- ft.	
Angle of stream flow approaching structure		Channelized Straight	
Pool present immediately downstream of structure		No	
Downstream bank heights are substantially higher than upstream bank heights		No	
Stepped footers		Yes	
More Geomorphic Information			
	Upstream	Downstream	In Structure
Dominant Bed Material	Boulder	Cobble	Cobble
Bedrock Present	No	No	No
Type of Sediment Deposits	---	---	---
Elevation of sediment deposits greater than 1/2 bankfull	No	No	No
Bank Erosion	None	None	
Hard Bank Armoring	Intact	Intact	
Stream bed scour causing undermining around or under structure	---	---	
Beaver Dam near Structure	No	No	
Beaver Dam distance (ft.)	---	---	
Vegetation			
	Upstream	Downstream	In Structure
Dominant Vegetation Type - Left	Shrub/Sapling	Shrub/Sapling	
Dominant Vegetation Type - Right	Shrub/Sapling	Shrub/Sapling	
Does a band of shrub/forest vegetation 50 ft. wide start within 25 ft. of the structure and extend at least 500 ft. up/downstream?			
Vegetation Band - Left	No	No	
Vegetation Band - Right	No	No	
Wildlife			
	Roadkill	Outside Structure	Inside Structure
Species	---	---	---

Other Information

Spatial location data collected with GPS?	Yes	Photos taken?	Yes
---	-----	---------------	-----

Comments	---
----------	-----

VT DEC • 103 South Main Street • Waterbury, VT 05671

Vermont Department of Environmental Conservation

A Vermont Government Website Copyright © 2004-2006 State of Vermont - All rights reserved



Stream Geomorphic Assessment

VT DEC

Bridge Summary Report

General Information			
VTrans Structure ID	vtrans-700002005411043	Local Structure ID	---
Assessment Date	09/25/2006	Observers	Noelia Báez Rodríguez
Town	Chittenden		
Location	Power House Rd		
Latitude	43.70	Longitude	-72.96
Road Name	POWERHOUSE RD	Road Type	Paved
Stream Name	East Creek		
Channel width	24 ft. (Measured)	High flow stage	No
Bridge/Arch Information			
Material	Concrete	Number of bridge piers/arches	0
Bridge Width	44 ft.	Skewed to roadway?	No
Bridge Clearance	4 ft.		
Bridge/Arch Span	12 ft.		
Geomorphic Information			
Floodplain filled by roadway approaches		Partially	
Structure is located at significant break in valley slope		Unsure	
Obstructions at the opening of the structure		---	
Steep riffle present immediately upstream of structure		Yes	
If channel avulses, stream will		Cross Road	
Estimated distance avulsion would follow road		--- ft.	
Angle of stream flow approaching structure		Sharp Bend	
Pool present immediately downstream of structure		Yes	
Downstream bank heights are substantially higher than upstream bank heights		No	
Stepped footers		No	
More Geomorphic Information			
	Upstream	Downstream	In Structure
Dominant Bed Material	Gravel	Gravel	Sand
Bedrock Present	Yes	No	No
Type of Sediment Deposits	---	---	---
Elevation of sediment deposits greater than 1/2 bankfull	No	No	No
Bank Erosion	None	None	
Hard Bank Armoring	Intact	Intact	
Stream bed scour causing undermining around or under structure	---	---	
Beaver Dam near Structure	No	No	
Beaver Dam distance (ft.)	---	---	
Vegetation			
	Upstream	Downstream	In Structure
Dominant Vegetation Type - Left	Shrub/Sapling	Herbaceous/Grass	
Dominant Vegetation Type - Right	Herbaceous/Grass	Herbaceous/Grass	
Does a band of shrub/forest vegetation 50 ft. wide start within 25 ft. of the structure and extend at least 500 ft. up/downstream?			
Vegetation Band - Left	No	No	
Vegetation Band - Right	No	No	
Wildlife			
	Roadkill	Outside Structure	Inside Structure
Species	---	---	---

Other Information			
Spatial location data collected with GPS?	Yes	Photos taken?	Yes
Comments	---		

VT DEC • 103 South Main Street • Waterbury, VT 05671

Vermont Department of Environmental Conservation

A Vermont Government Website Copyright © 2004-2006 State of Vermont - All rights reserved



Stream Geomorphic Assessment

VT DEC

Culvert Summary Report

General Information			
VTrans Structure ID	vtrans-700001002911043	Local Structure ID	---
Assessment Date	09/28/2006	Observers	Noelia Báez Rodriguez
Town	Chittenden		
Location	Sangamon Road		
Latitude	43.69	Longitude	-72.96
Road Name	SANGAMON RD	Road Type	Paved
Stream Name	East Creek		
Channel width	18 ft. (Measured)	High flow stage	No
Culvert Information			
Material	Aluminum Corrugated	Number of culverts	2
Culvert Length	42 ft.	Skewed to roadway?	No
Culvert Height	72 inches (6.0 ft.)	Culvert Overflow Pipe	No
Culvert Width	74 inches (6.2 ft.)		
Geomorphic Information			
Floodplain filled by roadway approaches		Partially	
Structure is located at significant break in valley slope		No	
Obstructions at the opening of the structure		---	
Culvert slope as compared with channel slope is significantly		Same	
Steep riffle present immediately upstream of structure		No	
If channel avulses, stream will		Follow Road	
Estimated distance avulsion would follow road		210 ft.	
Angle of stream flow approaching structure		Naturally Straight	
Culvert outlet invert		At Grade	
Outlet drop (invert to water surface)		--- ft.	
Water depth in culvert (at outlet)		--- ft.	
Pool present immediately downstream of structure		Yes	
Downstream bank heights are substantially higher than upstream bank heights		No	
More Geomorphic Information			
	Upstream	Downstream	In Structure
Dominant Bed Material	Gravel	Cobble	None
Bedrock Present	No	No	
Material Present throughout			---
Type of Sediment Deposits	---	---	---
Elevation of sediment deposits greater than 1/2 bankfull	No	No	No
Bank Erosion	None	Low	
Hard Bank Armoring	Intact	Intact	
Stream bed scour causing undermining around or under structure	---	---	
Beaver Dam near Structure	No	No	
Beaver Dam distance (ft.)	---	---	
Vegetation			
	Upstream	Downstream	In Structure
Dominant Vegetation Type - Left	Shrub/Sapling	Herbaceous/Grass	
Dominant Vegetation Type - Right	Deciduous Forest	Shrub/Sapling	
Does a band of shrub/forest vegetation 50 ft. wide start within 25 ft. of the structure and extend at least 500 ft. up/downstream?			
Vegetation Band - Left	No	No	
Vegetation Band - Right	Yes	No	

Wildlife

	Roadkill	Outside Structure	Inside Structure
Species	---	---	---

Other Information

Spatial location data collected with GPS?	Yes	Photos taken?	Yes
Comments	---		

VT DEC • 103 South Main Street • Waterbury, VT 05671

Vermont Department of Environmental Conservation

A Vermont Government Website Copyright © 2004-2006 State of Vermont - All rights reserved



Stream Geomorphic Assessment

VT DEC

Bridge Summary Report

General Information			
VTrans Structure ID	vttrans-700026024511043	Local Structure ID	---
Assessment Date	09/18/2006	Observers	Noelia Báez Rodríguez
Town	Rutland Town		
Location	E. Pittsford road		
Latitude	43.67	Longitude	-72.94
Road Name	E PITTSFORD RD	Road Type	Paved
Stream Name	East Creek		
Channel width	24 ft. (Measured)	High flow stage	No
Bridge/Arch Information			
Material	Concrete	Number of bridge piers/arches	0
Bridge Width	70 ft.	Skewed to roadway?	No
Bridge Clearance	15 ft.		
Bridge/Arch Span	24 ft.		
Geomorphic Information			
Floodplain filled by roadway approaches		Entirely	
Structure is located at significant break in valley slope		No	
Obstructions at the opening of the structure		---	
Steep riffle present immediately upstream of structure		No	
If channel avulses, stream will		Cross Road	
Estimated distance avulsion would follow road		--- ft.	
Angle of stream flow approaching structure		Mild Bend	
Pool present immediately downstream of structure		Yes	
Downstream bank heights are substantially higher than upstream bank heights		No	
Stepped footers		Yes	
More Geomorphic Information			
	Upstream	Downstream	In Structure
Dominant Bed Material	Cobble	Cobble	Unknown
Bedrock Present	No	No	No
Type of Sediment Deposits	---	---	---
Elevation of sediment deposits greater than 1/2 bankfull	No	No	No
Bank Erosion	None	None	
Hard Bank Armoring	Intact	Intact	
Stream bed scour causing undermining around or under structure	---	---	
Beaver Dam near Structure	No	No	
Beaver Dam distance (ft.)	---	---	
Vegetation			
	Upstream	Downstream	In Structure
Dominant Vegetation Type - Left	Deciduous Forest	Herbaceous/Grass	
Dominant Vegetation Type - Right	Deciduous Forest	Herbaceous/Grass	
Does a band of shrub/forest vegetation 50 ft. wide start within 25 ft. of the structure and extend at least 500 ft. up/downstream?			
Vegetation Band - Left	Yes	Yes	
Vegetation Band - Right	Yes	Yes	
Wildlife			
	Roadkill	Outside Structure	Inside Structure
Species	---	---	---

Other Information

Spatial location data collected with
GPS?

Yes

Photos taken?

Yes

Comments

VT DEC • 103 South Main Street • Waterbury, VT 05671

Vermont Department of Environmental Conservation

A Vermont Government Website Copyright © 2004-2006 State of Vermont - All rights reserved



Stream Geomorphic Assessment

VT DEC

Bridge Summary Report

General Information			
VTrans Structure ID	vtrans-700073046611203	Local Structure ID	---
Assessment Date	09/11/2006	Observers	Noelia Báez Rodriguez.
Town	Rutland Town		
Location	E. Pittsford Road south of 1881 corn farm		
Latitude	43.65	Longitude	-72.97
Road Name	E PITTSFORD RD	Road Type	Paved
Stream Name	East Creek		
Channel width	70 ft. (Measured)	High flow stage	No
Bridge/Arch Information			
Material	Concrete	Number of bridge piers/arches	0
Bridge Width	30 ft.	Skewed to roadway?	No
Bridge Clearance	10 ft.		
Bridge/Arch Span	126 ft.		
Geomorphic Information			
Floodplain filled by roadway approaches		Not Significant	
Structure is located at significant break in valley slope		No	
Obstructions at the opening of the structure		---	
Steep riffle present immediately upstream of structure		No	
If channel avulses, stream will		Cross Road	
Estimated distance avulsion would follow road		--- ft.	
Angle of stream flow approaching structure		Naturally Straight	
Pool present immediately downstream of structure		No	
Downstream bank heights are substantially higher than upstream bank heights		No	
Stepped footers		No	
More Geomorphic Information			
	Upstream	Downstream	In Structure
Dominant Bed Material	Cobble	Cobble	Cobble
Bedrock Present	No	No	No
Type of Sediment Deposits	---	---	---
Elevation of sediment deposits greater than 1/2 bankfull	Yes	No	No
Bank Erosion	None	Low	
Hard Bank Armoring	Intact	Intact	
Stream bed scour causing undermining around or under structure	---	---	
Beaver Dam near Structure	No	No	
Beaver Dam distance (ft.)	---	---	
Vegetation			
	Upstream	Downstream	In Structure
Dominant Vegetation Type - Left	Herbaceous/Grass	Herbaceous/Grass	
Dominant Vegetation Type - Right	Herbaceous/Grass	Herbaceous/Grass	
Does a band of shrub/forest vegetation 50 ft. wide start within 25 ft. of the structure and extend at least 500 ft. up/downstream?			
Vegetation Band - Left	No	No	
Vegetation Band - Right	No	No	
Wildlife			
	Roadkill	Outside Structure	Inside Structure
Species	---	---	---

Other Information

Spatial location data collected with GPS?	Yes	Photos taken?	Yes
Comments	---		

VT DEC • 103 South Main Street • Waterbury, VT 05671

Vermont Department of Environmental Conservation

A Vermont Government Website Copyright © 2004-2006 State of Vermont - All rights reserved



Stream Geomorphic Assessment

VT DEC

Bridge Summary Report

General Information			
VTrans Structure ID	vtrans-700004006811203	Local Structure ID	---
Assessment Date	09/11/2006	Observers	Noelia Báez Rodríguez
Town	Rutland Town		
Location	Route 7		
Latitude	43.65	Longitude	-72.99
Road Name	Route 7	Road Type	Paved
Stream Name	East Creek		
Channel width	39 ft. (Measured)	High flow stage	No
Bridge/Arch Information			
Material	Concrete	Number of bridge piers/arches	2
Bridge Width	40 ft.	Skewed to roadway?	No
Bridge Clearance	30 ft.		
Bridge/Arch Span	135 ft.		
Geomorphic Information			
Floodplain filled by roadway approaches		Not Significant	
Structure is located at significant break in valley slope		No	
Obstructions at the opening of the structure		---	
Steep riffle present immediately upstream of structure		No	
If channel avulses, stream will		Cross Road	
Estimated distance avulsion would follow road		--- ft.	
Angle of stream flow approaching structure		Naturally Straight	
Pool present immediately downstream of structure		Yes	
Downstream bank heights are substantially higher than upstream bank heights		No	
Stepped footers		No	
More Geomorphic Information			
	Upstream	Downstream	In Structure
Dominant Bed Material	Gravel	Gravel	Gravel
Bedrock Present	No	No	No
Type of Sediment Deposits	---	---	---
Elevation of sediment deposits greater than 1/2 bankfull	No	No	No
Bank Erosion	Low	Low	
Hard Bank Armoring	Intact	Intact	
Stream bed scour causing undermining around or under structure	---	---	
Beaver Dam near Structure	No	No	
Beaver Dam distance (ft.)	---	---	
Vegetation			
	Upstream	Downstream	In Structure
Dominant Vegetation Type - Left	Shrub/Sapling	Herbaceous/Grass	
Dominant Vegetation Type - Right	Shrub/Sapling	Shrub/Sapling	
Does a band of shrub/forest vegetation 50 ft. wide start within 25 ft. of the structure and extend at least 500 ft. up/downstream?			
Vegetation Band - Left	No	No	
Vegetation Band - Right	No	No	
Wildlife			
	Roadkill	Outside Structure	Inside Structure
Species	---	---	---

Other Information			
Spatial location data collected with GPS?	Yes	Photos taken?	Yes
Comments	---		

VT DEC • 103 South Main Street • Waterbury, VT 05671

Vermont Department of Environmental Conservation

A Vermont Government Website Copyright © 2004-2006 State of Vermont - All rights reserved

