

SEP 03 1991

ENVIRONMENTAL SITE ASSESSMENT - PHASE II
MT. HOLLY COUNTRY STORE
MT. HOLLY, VERMONT

Prepared for:

Dartmouth Bank
Manchester, New Hampshire

Prepared by:

Nobis Engineering, Inc.
Concord, New Hampshire

July 1991
File No. 91-310

NOBIS
ENGINEERING, INC.

HYDROGEOLOGIC & ENVIRONMENTAL CONSULTING

July 25, 1991
File No. 91-310

Dartmouth Bank
156 Hanover Street
Manchester, New Hampshire 03101

Attention: Mr. Wayne F. Jean

Re: Environmental Site Assessment - Phase II
Mt. Holly Country Store
State Aid Highway 1
Mt. Holly, Vermont


Dear Mr. Jean:

Nobis Engineering, Inc. is pleased to submit this report of an environmental assessment of the above-referenced site. This work was performed in accordance with our discussions with Mr. Frederick Kelley and our contract dated May 1, 1991. Following your review of this assessment, this report should be submitted to the Vermont Agency of Natural Resources, Department of Environmental Conservation for their review and comment.

Thank you for the opportunity to be of service to Dartmouth Bank. If you have any questions, please do not hesitate to call us at your convenience.

Very truly yours,

NOBIS ENGINEERING, INC.


Roger B. Keilig, P.E.
Project Manager


Nannu Nobis, P. E.
Principal

NN/dd

TABLE OF CONTENTS

	Page
1.00 INTRODUCTION	1
2.00 SITE LOCATION AND ENVIRONS	1
2.10 Site Location and Abutters	1
2.20 Local Surface Drainage Area	1
3.00 SITE DESCRIPTION	2
3.10 Store Structure Interiors	2
3.20 Site Exterior	3
4.00 REVIEW OF STATE AND MUNICIPAL AGENCY RECORDS.....	3
4.10 Review of Municipal Agency Records.....	3
4.20 Review of State Records	3
5.00 UST STATUS SUMMARY	4
6.00 FIELD EXPLORATIONS	5
6.10 Soil Test Boring/Monitoring Well Installations.....	5
6.20 Soil Sample Screening.....	5
6.30 Well Elevation Survey	6
7.00 SUBSURFACE CONDITIONS	6
7.10 Soil Conditions	6
7.20 Groundwater Levels and Flow Directions.....	6
8.00 SAMPLING AND ANALYSIS	6
9.00 RESULTS OF ANALYSES	7
9.10 Soil Screening Results.....	7
9.20 Groundwater Analyses	7
10.00 CONCLUSIONS.....	7
11.00 RECOMMENDATIONS	9

TABLES

- TABLE 1 - SUMMARY OF GROUNDWATER ELEVATIONS
- TABLE 2 - SUMMARY OF OVM SCREENING OF SOILS
- TABLE 3 - SUMMARY OF ANALYSES FOR VOLATILE ORGANIC COMPOUNDS
IN GROUNDWATER AND SURFACE WATER
- TABLE 4 - SUMMARY OF FIELD TESTING OF GROUNDWATER

FIGURES

- FIGURE 1 - LOCUS PLAN
- FIGURE 2 - SUBSURFACE EXPLORATION LOCATION PLAN
- FIGURE 3 - STORE BASEMENT PLAN
- FIGURE 4 - GROUNDWATER ELEVATION CONTOUR PLAN

APPENDICES

- APPENDIX A - LIMITATIONS
- APPENDIX B - VERMONT DEPT. OF ENVIRONMENTAL CONSERVATION
INFORMATION
- APPENDIX C - FIELD PROCEDURES
- APPENDIX D - TEST BORING/WELL INSTALLATION LOGS
- APPENDIX E - ANALYTICAL LABORATORY REPORTS

1.00 INTRODUCTION

This report presents the results of an environmental site assessment of the Mt. Holly Country Store located off State Aid Highway 1 in Mt. Holly, Vermont. This work was performed in accordance with our contract dated May 1, 1991. The objective of this assessment was to assess the site for the presence of hazardous wastes within the context of Vermont Statutes Annotated Chapter 159. This report is subject to the limitations in Appendix A.

To meet this objective, Nobis Engineering, Inc. (1) reviewed available records with the Town of Mt. Holly; (2) reviewed available records of the Vermont Agency of Natural Resources, Department of Environmental Conservation; (3) performed a site visit and building walk-through to observe general conditions at the site and adjacent environs; (4) performed four soil test borings with monitoring well installations at the site; (5) collected groundwater samples from the four monitoring wells and one surface water sample from the brook adjacent to the site and submitted the samples for laboratory analyses; and (6) prepared this report summarizing our opinion as to the possible presence of hazardous wastes at the subject site. This study did not include an assessment for the presence of lead paint, pesticides, radon, urea-formaldehyde, asbestos or any air quality monitoring.

2.00 SITE LOCATION AND ENVIRONS

2.10 Site Location and Abutters

The site is located on the eastern side of and adjacent to State Aid Highway 1 (SA-1) approximately 200± feet to the south of Route 103 in Mt. Holly, Vermont. The site includes a 2-story wood-frame building that has recently included a general store with gasoline refueling pumps, the Mt. Holly Post Office, the owner's residential quarters and two one-bedroom apartments. The size of the site parcel is not known (no surveys available) but the latest deed (Book 41, Page 209) indicates the parcel to be "a triangular piece of land [that] contains two acres more or less". A locus plan showing the approximate location of the site is presented as Figure 1.

The site is abutted to the north by land of the State of Vermont that is currently occupied by a Green Mountain Railroad track, and to the east by undeveloped wooded land. An unnamed westerly flowing brook abuts the site to the south and an undeveloped wet area is located across SA-1 to the west of the site. There is a single-family house on a property with a private well (apparently in bedrock) located immediately to the south of the unnamed brook about 100 feet to the south of the site.

2.20 Local Surface Drainage Area

The local site upgradient drainage area (i.e., the tributary land area from which surface runoff may flow on to the subject site) was approximately delineated to aid in the assessment of the potential for drainage from nearby properties impacting the site. For the purposes of this assessment, the local site upgradient drainage area is approximately determined to within a distance of 1,000± feet of the site boundaries through site observations and review of a USGS topographic map of the site area. The approximate site upgradient drainage area is shown on Figure 1. There are only residential dwellings within the site drainage area upgradient of the site.

Surface flow from nearby properties within the local upgradient surface drainage area may flow on to the subject site. The approximate delineation of the local site upgradient drainage area provides only a general indication of overburden groundwater flow patterns and is not appropriate for evaluation of groundwater flow conditions in bedrock. The evaluation of bedrock groundwater

July 25, 1991

flow patterns is beyond the scope of this assessment. Observed groundwater flow directions in the vicinity of the four monitoring wells installed for this study are discussed later in this report.

3.00 SITE DESCRIPTION

On June 7, 1991, Mr. Kenneth R. Koornneef of Nobis Engineering, Inc. visited the site to observe surficial conditions at the site and in portions of abutting properties for evidence which may indicate the possible presence of hazardous wastes at the site. Observations made during the site visit are summarized below. General site features are shown on Figure 2 and a plan of the store building basement is presented as Figure 3. Selected photographs of site features are shown on Figure 5.

3.10 Store Structure Interiors

Nobis Engineering, Inc. did not visit the interiors of the private living spaces (apartments and owner residence) within the building on-site. In the basement, which had a concrete floor, the following observations were made:

- The basement was observed to have a concrete floor throughout except for the southwestern portion, which had a soil floor. The concrete portion of the soil floor appeared to be, in general, in poor condition. There were no seals around pipes (e.g., sewer discharge) that exited through the concrete floor.
- There were two steel fuel oil tanks located adjacent to the mid-section of the north basement wall. These tanks appeared to be in good condition and no evidence of significant leakage was observed on the concrete floor in their vicinity.
- A New Yorker oil-fired boiler (for heat) and a Ford 50-gallon oil-fired boiler (for hot water) were present in the basement. No evidence of significant fuel oil leakage was observed in their vicinity.
- There is a concrete cistern for the site water supply, in the central portion of the basement. A continuous flow of water into and out of the cistern was observed. The overflow discharge appears to be to the unnamed brook via an underground iron pipe.
- The building's sewer discharge pipe (one pipe) was noted to exit the building through the basement floor in the direction of the unnamed brook.
- A partially full 55-gallon steel drum of apparent used motor oil was observed in the southeastern portion of the basement. This drum did not appear to be leaking.
- The metal garbage container of used oil filters was observed adjacent to the 55-gallon drum. The garbage container appeared to be leaking as was evident from surficial staining around it on the concrete floor.

3.20 Site Exterior

The site includes paved areas to the west (along SA-1) and to the north of the store building. A gravel surface driveway loops around the building. The remainder of the site consists of unlandscaped wooded, scrub brush and open areas.

And island for two apparent former gasoline pumps is located to the west of the building adjacent to SA-1. Two loosely covered fillers for apparent underground storage tanks (USTs) were located within the island. A flush-mounted filler for another apparent UST was observed in the paved area to the north of the western half of the building. Two UST vent pipes were observed adjacent to the northwestern portion of the building at the edge of a porch walkway. Filler pipes for two basement installation fuel oil tanks were observed along the mid-section of the porch. No significant surficial staining was observed in the vicinity of the above-mentioned fillers and vents.

Nothing of apparent hazardous waste concern was observed along the western and southern (garage access) perimeters of the building or within the undeveloped remainder of the site. A small wood-frame barn, that was observed to be empty, was located within a wooded area to the east of the store building and the gravel access driveway. No surficial evidence of the presence of hazardous wastes was observed in the vicinity of the barn and the undeveloped areas of the site including the bank of the unnamed brook. An iron pipe believed to be the inlet pipe for the site water supply cistern was observed in the stream to the southeast of the store building.

4.00 REVIEW OF STATE AND MUNICIPAL AGENCY RECORDS

4.10 Review of Municipal Agency Records

On June 14, 1991, Nobis Engineering, Inc. made telephone contact with officials at the Mt. Holly Assessor's Office and Selectmen's Office. Mr. Warren Cole, Town Selectman (Chairman) and Road Commissioner, indicated that the property had been a general store and gasoline station dating back to at least the 1940s. Ms. Susan Covalla, Town Clerk, indicated further that the Town of Mt. Holly has not yet assigned tax map and lot numbers to the properties within the town.

Concerning USTs, Mr. Cole indicated that the only UST facilities that he was aware of near the subject site was the "Town Garage" located across the unnamed brook about 300 feet to the south of the subject site and the Mt. Holly Elementary School located across the unnamed brook about 500 feet to the southeast of the site. Mr. Cole indicated that the UST installations (gasoline and fuel oil) at the Town Garage and the Mt. Holly Elementary School are in good order to his present knowledge.

Information from the Mt. Holly Assessor's Office indicated that the properties located in the vicinity of the subject site are serviced by private water supply wells and septic systems. The subject site is reported to receive water supply from a spring located on the Mt. Holly Elementary School property about 500 feet to the southeast of the site.

4.20 Review of State Records

On June 19, 1991, Nobis Engineering, Inc. reviewed files made available by the Vermont Agency of Natural Resources, Department of Environmental Conservation (VTDEC).

The VTDEC files did not contain any information indicating hazardous waste related environmental concerns or Resource Conservation and Recovery Act (RCRA) regulated facilities within approximately 1,000 feet of the site. VTDEC records indicated that there are several USTs at the Mt. Holly Public Works (Town Garage) facility, and one fuel oil UST at the above-mentioned Mt. Holly Elementary School. Both the Mt. Holly Public Works facility and the Mt. Holly Elementary School do not appear to be situated hydraulically upgradient (i.e., not located within the site upgradient drainage area), based on site area observations and review of USGS topographic and drainage data and, therefore, are not likely to impact the subject site environment. VTDEC records

did not contain any reports of leakage or spill incidents associated with these two nearby UST facilities. Pertaining to the subject site, VTDEC records indicated the following:

- An above-ground (basement installation) kerosene tank in the store building developed a leak on December 15, 1987. About 400 gallons of kerosene were estimated to have leaked in an area where the basement had a soil floor. VTDEC records indicate that the site owner at the time (Sherman V. Allen, Inc. of Rutland, Vermont) was required to clean up the spilled kerosene through soil excavation, the installation of recovery sumps in the soil floor portion of the basement and the installation of absorbent booms in the brook. A VTDEC correspondence to Sherman V. Allen, Inc. dated January 12, 1989, indicates that the VTDEC closed the site stating:

"All of the recoverable free floating kerosene that could be recovered had been recovered"; and "Monitoring in the store basement and in the stream behind the store has shown that remediation efforts at the store have been successful."
- Two 2,000-gallon gasoline USTs at the site were registered with the VTDEC in December 12, 1985. These USTs were reported to be 3 and 12 years in age at that time.
- A VTDEC "Incident Report" dated February 5, 1988 indicates that the older 2,000-gallon UST (designated UST No. 2) failed a tightness test. The site owner at that time had reported no evidence of product loss in the two 2,000-gallon USTs. This UST was removed from the site on February 22, 1988 and not replaced. The VTDEC report on the removal indicated that the removed UST was in "poor condition" and that "some sheen" was present on the groundwater in the UST removal excavation. The February 22, 1988, VTDEC UST removal report also indicated that two unregistered permanently-out-of-use USTs (size not known) were located at the site under the pump island in front of and to the west of the store building.
- A June 4, 1991, VTDEC correspondence to Dartmouth Bank stated that the remaining 2,000-gallon gasoline UST was required to be closed and removed from the site as it had been out of service for at least one year.

Copies of the above-referenced VTDEC information are enclosed in Appendix B.

5.00 UST STATUS SUMMARY

Based on our site observations and review of readily available local and state information pertaining to the site, the status of past and present on-site USTs is summarized as follows:

- There are apparently two out-of-use gasoline USTs (ages and sizes not known) located generally beneath the former pump island. These USTs appear to be partially filled with sand. Based on our June 26, 1991, telephone conversation with Mr. Theodore (Ted) Unkles of the VTDEC Hazardous Materials Management Division, it is understood that these two USTs must be "closed out" in accordance with Vermont UST regulations¹. Mr. Unkles indicated that further evaluation of the present contents of these USTs would be required prior to determining an appropriate closure method. Mr. Unkles also indicated that proper closure of these two USTs could possibly consist of completely filling them

¹ Refer to "Underground Storage Tank Regulations" issued by the Vermont Agency of Natural Resources, Department of Environmental Conservation, dated February 1, 1991.

with an inert material (e.g., clean sand) and leaving them in place rather than removing them which would likely result in disturbance to State Aid Highway 1.

- A 9± year old 2,000-gallon gasoline UST that has been out-of-use for more than one year is located in the northwestern portion of the site. A June 4, 1991, VTDEC correspondence to Dartmouth Bank stated that this UST was required to be closed and removed from the site as it had been out of service for more that one year.
- A 2,000-gallon gasoline UST (reported to be 12 years old) that had reportedly failed a tightness test in February 1988 was removed from the site in February 1988. Only minor contamination was reported to have been observed by the VTDEC in the UST removal excavation and no further site evaluation work was required subsequent to the removal of that UST.

6.00 FIELD EXPLORATIONS

6.10 Soil Test Boring/Monitoring Well Installations

On June 7, 1991, six soil test borings were performed at the site by New Hampshire Boring, Inc. of Derry, New Hampshire, under the observation of Nobis Engineering, Inc. personnel. Groundwater monitoring wells (designated MW-1 through MW-4) were installed in four of the test borings. Monitoring wells consisted of 2-inch diameter PVC pipe with machine slotted screen sections. The approximate locations of the test borings and monitoring wells are shown on Figure 2. The borings were advanced to depths ranging from approximately 5 to 13.5 feet using 4-1/4-inch I.D. hollow-stem auger drilling techniques. A description of the test boring/monitoring well installation procedures is included in Appendix C. Logs of the test boring/monitoring well installations are included in Appendix D.

Boring B-2A and boring MW-3 encountered auger refusal at depths of 5 and 13.5 feet respectively. Auger refusal is defined herein as the inability to further advance the boring under increased down-pressure and torque due to the presence of large or tightly-nested boulders. Boring B-2B encountered and punctured the top of an out-of-use UST (the northernmost of two old out-of-use USTs located beneath the pump island) at a depth of about 3 feet. This UST was observed to be partially filled with soil to a depth of about 5 feet below the ground surface.

6.20 Soil Sample Screening

Soil samples collected from the test borings were screened for total concentrations of volatile organic compounds (VOCs) using a Photovac MicroTIP organic vapor meter (OVM) equipped with a photoionization detector (10.6 eV lamp). The MicroTIP OVM responds readily to most VOCs but does not register methane or natural components of air such as oxygen, nitrogen or carbon dioxide. The MicroTIP OVM detection limit is approximately one part per million (ppm) by volume, referenced to an isobutylene-in-air standard. Results of OVM screening of test boring soil samples are discussed later in this report.

6.30 Well Elevation Survey

A well elevation survey was performed on June 9, 1991 by Nobis Engineering, Inc. personnel using a laser level. Well elevations were obtained for the top of the PVC riser pipe of each well referenced to an assumed benchmark elevation of 100.00 feet established at the top of the PVC pipe for MW-1. Well elevation data are included in Table 1.

July 25, 1991

7.00 SUBSURFACE CONDITIONS

7.10 Soil Conditions

The soil samples obtained from test borings MW-1 through MW-4 and boring B-2A were visually classified in the field in accordance with the Burmister Classification System, a summary of which is included in Appendix D.

In general, overburden soils typically encountered in the test borings included about 3 to 8 feet of fine granular soil fills underlain by dense to very dense natural glacial till consisting generally of sands with varying amounts of silt, clayey-silt, gravel, cobbles, and boulders. A 6± foot thick layer of very dense sand and gravel was encountered beneath surficial fills and above the glacial till from the 3 to 9-foot depth interval in test boring MW-4.

7.20 Groundwater Levels and Flow Directions

Groundwater levels measured during the groundwater sampling round on June 9, 1991 ranged from about 2 to 7 feet below the existing ground surface. Groundwater elevation data are summarized in Table 1 and a groundwater surface elevation contour plan is presented as Figure 4.

Based on the observed static water table elevations, groundwater in the western portion of the site appears to flow in a general southerly direction toward the unnamed brook that abuts the site. Available data suggests that the stream may serve as a discharge area for groundwater flowing beneath the site. Fluctuations in groundwater levels will occur due to variations in rainfall, surface runoff, temperature, and other factors. Local groundwater flow anomalies may also exist due to the influence of paved areas, underground utilities and localized topography. Additional monitoring wells and long-term groundwater level monitoring would be necessary to establish groundwater flow directions more definitively.

8.00 SAMPLING AND ANALYSIS

Groundwater samples were collected on June 9, 1991 by Nobis Engineering, Inc. personnel from the four groundwater monitoring wells. A surface water sample was also obtained from the brook at the southwestern portion of the site. The groundwater samples were field tested for pH and specific conductance by Nobis Engineering, Inc. Nobis Engineering, Inc. also checked each of the samples for floating product or a sheen at the time of sampling. No floating product or sheen was evident in the four groundwater samples and one surface water sample collected. The samples were subsequently submitted to Aquarian Analytical, Inc. in Canterbury, New Hampshire analyses for Hazardous Substance List (HSL) VOCs analysis by EPA Method 624. Copies of the analytical laboratory reports are included in Appendix E.

9.00 RESULTS OF ANALYSES

9.10 Soil Screening Results

OVM screening results of the test boring soil samples ranged from approximately 10 to 310 ppm on the MicroTIP. The highest reading (310 ppm) was observed in the soil sample obtained from near the ground surface and groundwater table in boring MW-4, located to the south edge of the building and gravel surface driveway. The other OVM readings were slightly elevated

July 25, 1991

(approximately 10 to 22 ppm) and are likely indicative of the presence of some VOCs at those locations. A summary of OVM screening of soil samples is presented on Table 2.

9.20 Groundwater Analyses

A summary of laboratory analyses of groundwater and surface water samples is presented in Table 3. Results of laboratory analyses of the water samples indicated that gasoline-related VOCs were present above analytical detection method limits in the groundwater samples obtained from wells MW-2 through MW-4. VOCs detected in each of these three wells included benzene, ethylbenzene, toluene and xylenes (collectively referred to as BTEX). Another gasoline-related VOC, methyl t-butyl ether (MTBE), which is typically an additive to unleaded gasoline, was also detected in well MW-3.

The observed concentrations of benzene in wells MW-2 through MW-4 were 87, 85, and 6 parts per billion (ppb), respectively. These concentrations exceed the current "Primary Ground Water Quality Enforcement Standard"² of 5 ppb for benzene established by the VTDEC. The observed concentrations of xylenes (MW-1: 590 ppb, MW-2: 335 ppb, MW-3: 813 ppb) also generally exceed the current VTDEC Enforcement Standard of 400 ppb. The observed concentrations of toluene (MW-1: 129 ppb, MW-2: 56 ppb, MW-3: 4 ppb), and ethylbenzene (MW-1: 50 ppb, MW-2: 47 ppb, MW-3: 59 ppb), while elevated, do not exceed the current VTDEC Enforcement Standard criteria for these compounds of 2,420 and 680 ppb. MTBE was detected in MW-3 only at a concentration of 3 ppb. Enforcement Standard criteria for MTBE are currently not available. The laboratory analyses indicated that other gasoline-related petroleum hydrocarbons not specifically identifiable as HSL VOCs were also present in the samples from wells MW-2 through MW-4. The concentrations of these petroleum hydrocarbons were not determined. Only xylenes at a relatively low concentration of 1 ppb were detected in the surface water sample obtained from the unnamed brook.

The pH of the groundwater and surface water samples ranged from 6.5 to 7.1. The pH values are within the range of values typically observed in Vermont groundwater and surface water in lightly developed areas. The specific conductance of the groundwater samples ranged from 710 microSiemens per centimeter (uS/cm) to 890 uS/cm. The observed groundwater specific conductance values were generally above the range of values typically observed in Vermont groundwater in lightly developed areas. The observed specific conductance value of 140 us/cm for the surface water sample from the unnamed brook was within the range of values typically observed in Vermont surface water in lightly developed areas.

10.00 CONCLUSIONS

On the basis of this environmental assessment performed at in Mt. Holly Country Store on State Aid Highway 1, Mt. Holly, Vermont, the following conclusions are presented:

1. The site contains a small village store with a gasoline refueling station. The site has reportedly included a gasoline refueling station since the 1940s. The site, with a reported land area of 2± acres, is situated in a lightly developed setting adjacent to an unnamed brook. There are no industrial facilities, petroleum storage facilities, or other commercial facilities on the same side of the brook within 1,000 feet of the site.

² Refer to Chapter 12 - "Ground Water Protection Rule and Strategy" issued by the Vermont Agency of Natural Resources, Department of Environmental Conservation, dated September 19, 1988.

July 25, 1991

2. The site and the properties within the general site vicinity have on-site private sewage disposal systems. The site water supply is reportedly from a spring located at the Mt. Holly Elementary School about 500 feet to the southeast of the site (on a hillside across the unnamed brook). A cistern in the store building basement is fed continuously by the spring with overflow discharge to the unnamed brook that forms the site's southern boundary. The location of the cistern feed and discharge lines, their existence or condition, were not verified as part of this assessment.
3. Groundwater and surface water elevation data obtained during this study indicate that groundwater flow in the western portion of the site is generally to the south toward the adjacent unnamed brook. Available data suggests that groundwater from beneath the site discharges, at least in part, into the brook. Based on our site observations and review of a USGS topographic map of the site area, groundwater flow in the remainder of the 2± acre site is also likely to be in a southerly direction.
4. VTDEC files indicate that a 2,000-gallon gasoline UST that has been out-of-use for more than one year is located to the north of the western portion of the store building. Current VTDEC UST regulations require appropriate closure of USTs that have been out-of-use for more than one year.
5. VTDEC files indicate that another 2,000-gallon UST that was previously situated adjacent to the existing 2,000-gallon UST, was removed from the site on February 22, 1988, following failure of a tightness test on February 5, 1988. The site owner at that time had reported no evidence of product loss associated with the removed UST. VTDEC records, however, indicated that the removed UST was in "poor condition" and that "some sheen" was present on the groundwater in the UST removal excavation.
6. Our site observations and VTDEC records indicate that two old out-of-use USTs of undetermined size are located beneath the pump island adjacent to the western end of the store building. One of these (the northernmost of the two) USTs was observed to be partially full of soil. Collapse of the empty portion of the UST(s) could result in potentially dangerous subsidence of the ground along State Aid Highway 1. While no evidence of product was observed within the UST, the presence of contamination within the soil was not determined. Current VTDEC UST regulations also require proper closure of these two older out-of-use USTs. Because of the proximity of these two USTs to State Aid Highway 1, acceptable closure of these two USTs could possibly consist of completely filling them with clean sand and leaving them in-place. Further evaluation of the contents (apparently sand) of these USTs would be required to provide the VTDEC with sufficient information to designate an acceptable closure method for these USTs.
7. VTDEC records indicate that a basement installation 500-gallon kerosene tank (for the building heating system) developed a leak in December 1987 resulting in a 400± gallon spill. The kerosene spill resulted in contamination of the basement soil floor and of soil and groundwater between the building and the unnamed brook. A VTDEC correspondence to Sherman V. Allen, Inc. (a previous site owner) dated January 23, 1989 indicates that the remediation of the contamination associated with the kerosene spill had been completed to the satisfaction of the VTDEC. The 500-gallon tank was replaced with two 275-gallon steel tanks in December 1987.
8. VTDEC information did not indicate any reported hazardous waste problems on properties situated hydraulically upgradient of the site within 1,000± feet of the site boundaries.

9. The store building utilized two oil-fired boilers. Fuel oil is stored in two 275-gallon steel tanks located in the basement. The fuel oil tanks and the two boilers appeared to be in good condition with no evidence of leakage observed on June 7, 1991.
10. Laboratory analyses of four groundwater samples from monitoring wells indicated that elevated concentrations of four gasoline-related VOCs (benzene, ethylbenzene, toluene and xylenes) were present in the three wells (MW-2 through MW-4) that were installed hydraulically downgradient of on-site USTs. The observed concentrations of benzene in wells MW-2 through MW-4 and of xylenes in wells MW-2 and MW-4 exceeded current VTDEC Primary Groundwater Quality Enforcement Standards criteria. Unquantified concentrations of gasoline-related petroleum hydrocarbons were also present in the groundwater samples from wells MW-2 through MW-4. Methyl t-butyl ether (MTBE), a HSL VOC typically present in unleaded gasoline, was detected only in well MW-3 at a relatively low concentration. Evidence of floating product was not observed in monitoring wells MW-1 through MW-4 during field operations on June 7 and 9, 1991. The former and present on-site USTs are the likely source of the observed VOC contamination of groundwater.
11. No HSL VOCs were detected in upgradient well MW-1. One HSL VOC (xylene) was observed in the surface water sample obtained from a downgradient location of the adjacent unnamed brook at the relatively low concentration of 1 ppb.
12. There is a single-family residence with a private water supply well on the property associated with the residence located across the unnamed brook approximately 100 feet to the south of the site. Though it appears to be a bedrock well, information on the construction of this well was not available for this assessment. Laboratory analyses of a water sample from this well would be necessary to determine if the on-site gasoline-related contamination has impacted this nearby well.

11.00 RECOMMENDATIONS

Based on the results of this assessment, the following recommendations are offered:

- 1) The 2,000 gallon gasoline UST (and appurtenances) to the north of the western portion of the store building should be removed per VTDEC requirements as it has been out-of-use for more than 1 year.
- 2) Further evaluation of the contents of the two old out-of-use USTs (and appurtenances) beneath the pump island should be performed toward the determination of an acceptable closure method for this USTs per VTDEC requirements.

Due to the presence of observed VOC contamination of groundwater at the site, Nobis Engineering, Inc. recommends that this report be submitted to the VTDEC to assess what further evaluation, if any, may be required. VTDEC Rules Chapter 12 "Ground Water Protection Rule and Strategy", Subchapter 12-709, require all instances of exceedance of Primary Ground Water Quality Enforcement Standards to be reported immediately to the VTDEC by the site owner or operator.

**T
A
B
L
E
S**

TABLE 1
SUMMARY OF GROUNDWATER ELEVATIONS
91-310

WELL No.	REFERENCE ELEVATION (FT)	DEPTH TO GROUNDWATER (FT)	WATER ELEVATION (FT)
MW-1	100.00	2.4	97.6
MW-2	97.03	6.6	90.4
MW-3	98.78	6.5	92.3
MW-4	91.46	3.6	87.9
STREAM	86.40	-	86.4

NOTES:

1. Well elevations are referenced to an arbitrary datum of 100.00 feet established on the top of PVC at well MW-1. Elevations were determined by Nobis Engineering Inc. personnel on June 9, 1991 using a laser level.
2. Groundwater level measurements were obtained by Nobis Engineering, Inc. personnel on June 9, 1991 using a Solinst electronic water level indicator.

TABLE 2
SUMMARY OF OVM SCREENING OF SOILS
91-310

SAMPLE NUMBER	DEPTH (ft.)	OVM READING (ppm)
<u>MW-1</u>		
A-1	0-2	21
S-1	5-7	15
S-2	10-12	21
<u>B-2A</u>		
A-1	0-2	10
<u>B-2B</u>		
A-1	0-2	8
<u>MW-2</u>		
A-1	0-2	10
S-1	5-7	--
S-2	10-12	22
<u>MW-3</u>		
A-1	0-2	13
S-1	5-7	18
S-2	10-12	11
<u>MW-4</u>		
A-1	0-2	310
S-1	5-7	14
S-2	10-12	16

NOTES:

1. Organic vapor meter (OVM) readings obtained by Nobis Engineering, Inc. personnel in the field using a Photovac MicroTIP meter equipped with a photoionization detector (PID).
2. OVM readings are in parts per million (ppm) referenced to an isobutylene-in-air standard. "--" indicates no sample obtained (no split-spoon sample recovery).
3. OVM readings obtained from the head-space of 8-ounce jars filled with soil obtained from the test borings performed on June 7, 1991.

TABLE 3
SUMMARY OF ANALYSES FOR VOLATILE ORGANIC COMPOUNDS IN GROUNDWATER AND
SURFACE WATER
91-310

PARAMETER	DRINKING WATER STANDARD	MW-1	MW-2	MW-3	MW-4	STREAM
Benzene	5	-	87	85	6	-
Toluene	2420	-	129	56	4	-
Ethylbenzene	680	-	50	47	59	-
Xylenes	400	-	590	335	813	1
Methyl t-butyl ether	N/A	-	-	3	-	-
Unknowns	N/A	-	P	P	P	-

NOTES:

1. All concentrations reported in parts per billion (ppb).
2. Only detected parameters are listed.
3. "-" indicates that parameter was not present above analytical detection limit.
"P" indicates parameter present but not quantified.
"N/A" indicates "Not applicable."
4. Sampling was performed on June 9, 1991 by Nobis Engineering, Inc. personnel.
5. All analyses performed by Aquarian Analytical Inc. of Canterbury, New Hampshire. VOC analyses were performed using EPA Method 624.
6. Drinking Water Standards represent "Primary Ground Water Quality Standards - Enforcement Standard" referenced in Vermont Agency of Natural Resources, Department of Environmental Conservation Rules Chapter 12 "Ground Water Protection Rule and Strategy": dated September 19, 1988.


TABLE 4
SUMMARY OF FIELD TESTING OF GROUNDWATER
91-310

WELL No.	pH (Standard Units)	SPECIFIC CONDUCTANCE (uS/cm)
MW-1	6.5	710
MW-2	6.5	830
MW-3	6.5	890
MW-4	7.1	720
STREAM	7.0	140

NOTES:

1. Sampling and field testing of groundwater performed by Nobis Engineering, Inc. personnel on June 9, 1991.
2. Measurements of pH were made with Hanna Instruments Model 0624-00 pH Electronic Paper. Measurements of specific conductance were made with a Hanna Instruments Model 0661-30 Dissolved Solids Tester.

F I G U R E S



FILE No. 91-310 © 1991 NOBIS ENGINEERING, INC.



**USGS TOPOGRAPHIC MAP
MOUNT HOLLY, VERMONT
QUADRANGLE
1986**

**APPROXIMATE SCALE:
1 INCH = 2,000 FEET**


**NOBIS
ENGINEERING, INC.**
CONCORD • NEW HAMPSHIRE


**ENVIRONMENTAL SITE ASSESSMENT
PHASE II
MOUNT HOLLY COUNTRY STORE
STATE AID HIGHWAY 1
MOUNT HOLLY, VERMONT**

LOCUS PLAN

JULY 1991

FIGURE 1





NOTES:

- 1) See Figure 2 notes and legend.

APPROXIMATE SCALE



FILE No. 91-310 © 1991 NOBIS ENGINEERING, INC.


NOBIS
ENGINEERING, INC.
CONCORD • NEW HAMPSHIRE

ENVIRONMENTAL SITE ASSESSMENT
PHASE II
MOUNT HOLLY COUNTRY STORE
STATE AID HIGHWAY 1
MOUNT HOLLY, VERMONT

STORE BASEMENT PLAN

JULY 1991

FIGURE 3




NOTES:

- 1) Groundwater elevations are based on groundwater level measurements obtained by Nobis Engineering, Inc. on June 9, 1991. The groundwater elevation contours presented herein represent one interpretation of flow conditions. Other interpretations are possible.
- 2) See Figure 2 for additional notes and legend.

LEGEND:

- MW-1 Monitoring Well (97.6) Groundwater elevation observed on June 9, 1991.
- 90 Estimated groundwater elevation contour.
- Estimated direction of groundwater flow.
- X SW-1 Surface water sampling location and description.



<p>NOBIS ENGINEERING, INC. CONCORD - NEW HAMPSHIRE</p>	<p>ENVIRONMENTAL SITE ASSESSMENT PHASE II MOUNT HOLLY COUNTRY STORE STATE AID HIGHWAY 1 MOUNT HOLLY, VERMONT</p>	<p>GROUNDWATER ELEVATION CONTOUR PLAN-JUNE 9, 1991</p> <p>JULY 1991 FIGURE 4</p>
--	--	---

**A
P
P
E
N
D
I
X

A**

APPENDIX A

LIMITATIONS

- 1) This Phase II environmental assessment was performed in accordance with generally accepted practices of other consultants undertaking similar assessments at the same time and in the same geographical area. The results of this preliminary assessment are based on our professional judgement and are not scientific certainties. Specifically, Nobis Engineering, Inc. does not and cannot represent that the site contains no hazardous wastes, oil or other latent conditions beyond those observed during this assessment. No other warranty, express or implied, is made.
- 2) The observations and conclusions presented in this report were made solely on the basis of conditions described in the report and not on scientific tasks or procedures beyond the scope of described services or the budgetary and time constraints imposed by the client. The work described in this report was performed in accordance with the terms and conditions of our agreement dated May 1, 1991. No other warranty, express or implied, is made.
- 3) Observations were made of the site as indicated in this report. Where access to portions of the site were unavailable or limited, Nobis Engineering, Inc. renders no opinion as to the presence of hazardous wastes or the presence of indirect evidence of hazardous wastes in that portion of the site.
- 4) No property boundary, site feature or topographic surveys of the site were performed by Nobis Engineering, Inc.
- 5) No sampling or testing was performed for the presence of pesticides, herbicides, radon, lead paint, urea-formaldehyde, asbestos or polychlorinated biphenyls (PCBs) at the site.
- 6) The purpose of this assessment was to assess the physical characteristics of the subject site with respect to the presence of hazardous wastes in the environment within the meaning of Vermont Statutes Annotated, Chapter 159. No attempt was made to check the compliance of present or past owners of the site with federal, state or local laws.
- 7) The conclusions and recommendations contained in this report are based in part upon data obtained from widely spaced subsurface explorations. The nature and extent of variations between these explorations may not become evident until further exploration. If variations or other latent conditions then appear evident, it will be necessary to reevaluate the conclusions and recommendations of this report.
- 8) Water level readings have been made in the test borings/monitoring wells at the times and under the conditions stated in this report. Fluctuations in groundwater levels will occur due to variations in rainfall and other factors different from those prevailing at the time measurements were made.
- 9) Except as noted within the text of the report, no quantitative laboratory testing was performed as part of the site assessment. Where such analyses have been conducted by an outside laboratory, Nobis Engineering, Inc. has relied upon the data provided and has not conducted an independent evaluation of the reliability of these data.
- 10) Chemical analyses have been performed for specific parameters during this site assessment, as described in the text of the report. Additional chemical constituents not searched for during the current study may be present in soil and/or groundwater at the site.
- 11) This assessment has been prepared for the exclusive use of Dartmouth Bank solely for use in an environmental evaluation of the site. This report shall not, in whole or in part, be conveyed to any other party without prior written consent of Nobis Engineering, Inc. However, Nobis Engineering, Inc. acknowledges and agrees that the report may be conveyed by Dartmouth Bank to others associated with the proximate transaction of the site.

**A
P
P
E
N
D
I
X

B**

**VERMONT
DEPARTMENT OF ENVIRONMENTAL CONSERVATION
INFORMATION**

RECEIVED JUN 21 1991

Mount Holly Country Store

1. Spill Incident Report, 12/15/87
2. Trip Report, Greg Leech, 12/22/87
3. Trip Report, Greg Leech, 1/4/88
4. Letter from Dan Poalino, Sherman Allen, 1/15/87
5. Spill Incident Report, 2/5/88
6. Trip Report, Richard Spiese, 2/11/88
7. 1283 Tank Pull Order, 2/18/88 (Never sent)
8. Tank pull form, notification form
9. Trip Report, Richard Spiese, 2/24/88
10. Letter from Dan Poalino, Sherman Allen, 3/7/88
11. Trip Report, RFS, 3/24/88

CASE # 239-87

Department of Water Resources and Environmental Engineering

Incident Report

Date/Time: 12/15 3:00pm Person taking report RATD

Location: Town/City: Mt Holly Store
Road, Street, Highway: TRK 103
Address/Mile Marker: FLASHING LIGHT

Person Making Report

Name/Organization: Maria JOHNSON, Store Owner
Telephone #: 259-2368
Address: TRK 103

Is this an emergency? NO
Nature of Incident: Kerosene leak from skin tank patch
Date/Time of Incident: on-going
Type of Contaminant: Kerosene
Quantity of Contaminant: unknown
Responsible Parties: (Sherman P. Lewis)
owner/operator: Elroy Hill - VT Feraco 975-6628
shipper/consignee: _____
carrier/facility: _____
Other Information: _____

Case Assigned to Which Section: _____

Priority: High, Medium, Low

Actions Taken: Absorbents put down to remove oil from river. Soils to be removed and stored on plastic. Site's person will screen soils.

cc to:

- Dept of Health
- Dept of Motor Vehicles
- Dept of Agriculture
- Dept of Labor & Industry
- Emergency Management
- Dept of Fish & Wildlife
- U.S. EPA

Case Closed: Date: _____

State of Vermont

Department of Fish and Wildlife
Department of Forests, Parks and Recreation
Department of Environmental Conservation
State Geologist
Natural Resources Conservation Council



AGENCY OF NATURAL RESOURCES
103 SOUTH MAIN STREET
Waterbury, Vermont 05676

Department of Environmental Conservation

MEMORANDUM

TO: Spill File #239-87
THRU: John Amadon, ERMS *[Signature]*
FROM: Greg Leech, ERMS *[Signature]*
RE: Mount Holly General Store, #239-87
Rte. 103, Mount Holly
DATE: December 22, 1987

I stopped by the General Store to take a look at the spill that occurred on December 15, 1987. Sherman Allen representative Elroy Hill was on site with two other people cleaning up the estimated 400 gallons of kerosene. Elroy estimates that approximately 175 gallons have been recovered so far from the use of sorbents.

The tank that failed was an above ground tank that was in the basement of the store. The store has a dirt basement, so product has soaked through the soil and stopped at the water table. The water table is approximately 18-24" below the floor. Elroy dug a hole approximately four feet square by two feet deep. The soil will be taken to the main office of Sherman Allen in Fair Haven. The two yards of soil will be stockpiled under plastic until the spring. In the spring the soils should be screened using Photovac TIP or HNU.

Mill River is the immediate receptor of the release and there is a very slight sheen getting away from the sorbent booms. Pads are also being used in the river.

The excavation will be filled when recovery attempts prove fruitless. Elroy will put a slotted piece of culvert in the hole so further mopping up may take place in the future.

Site should be checked from time to time.

GML/kb#91

cc: Ken Rota, Hazardous Waste Management Program
Bill Barry, ERMS

Bill

3

To: Spill File #239-87
From: Greg Leech, ERMS *gml*
Re: Mount Holly update
Date: January 4, 1988

I talked to Elroy Hill of Sherman V. Allen and got a verbable update on the situation in Mount Holly. Elroy makes frequent trips to the site to check on the excavation and to mop up the kerosene. In the past few days, only about a quart a day is being recovered by the use of sorbents. The boom is still in the river. There is no obvious sheen on the river.

The soil has been moved to 100 Acedemy Street in Fair Haven and should remain there until HNU readings have taken place. The spring time would be the best time to do this.

When in the area, the site should be checked.



Sherman V. Allen, Inc.
Distributor of Petroleum Products

JAN 20 1987 (4)
802 775 6720
EXECUTIVE OFFICES

253 South Main Street • Rutland, VT 05701

January 15, 1987

Mr. Greg Leach
Waste Management
State of Vermont
103 S. Main St.
Waterbury, VT 05676

Re: Above Ground Storage Leak
Mt. Holly Country Store

Dear Mr. Leach:


In the late afternoon of December 15th, our fuel manager, Jack Hennessey received a phone call from Marie Johnson (owner of Mt. Holly Country Store) in regards to a leak from an above ground kerosene tank. That afternoon Mr. Hennessey visited the site and noticed a stress fracture where the skid connected with the storage tank. The tank was empty with the exception of a gallon or so of product. (Note, the remaining kerosene was below the fracture point, therefore, not leaking). The following morning, I dispatched Mr. Hennessey and Elroy Hill, our senior tank and pump technician, to the site. Water Resources, as well as Fire Prevention Departments, were notified and we immediately undertook recovery procedures. The skid tank was removed on the 16th and returned to our plant. A recovery well was excavated and collection procedures were initiated immediately. On the 17th, a second recovery well was excavated. Additionally, a third recovery well was excavated on the 22nd. Each day thereafter, our tank and pump technicians continued recovery procedures until December 25th. Starting the 26th, our technician proceeded to monitor the recovery wells and by the 28th the total daily recovery was approximately a quart of product. As of January 15th, amounts of kerosene detected had been reduced to pint measurements.

Besides the recovery procedures conducted, a stream running along side the Mt. Holly Country Store property is being monitored and no trace of product has been observed escaping into the stream. I am unable to determine the actual product loss because of poor record keeping by the store, however, our total recovery amount as of this writing is approximately 207 gallons.

Presently, I believe the situation has been addressed and we will continue to periodically monitor the site and will advise upon any further changes. I might add that a complete inspection has been conducted on all above ground storage tanks installed by our company (there are only three other sites) and I have personally sent a letter to these individuals instructing them on the procedures for monitoring inventory and what to do in the case of an emergency leak situation (see attached).

If I may provide any further information, please contact me at 775-6628.

Sincerely,



Daniel S. Poalino
Vice President/General Manager
SHERMAN V. ALLEN, INC.

DSP/st
cc: Sherman V. Allen
Peter J. Shambo



Sherman V. Allen, Inc.

Distributor of Petroleum Products

802 775 6720
EXECUTIVE OFFICES

253 South Main Street • Rutland, VT 05701

January 4, 1988

Dear Customer:

I wish to remind you of the following safety and notification procedures regarding the above ground storage of petroleum at your business.

As you may well know, it is the law to monitor all underground storage tanks which are used for resale. This protects the environment and you from potential underground leaks which may be difficult to determine without constant monitoring.

In regards to above ground storage, there are no specific monitoring requirements at this time. A good rule of thumb would be to verify your purchases to your sales and take into consideration the inventory in the storage tank. In the event there is a discrepancy, you should notify Jack Hennessey from Vermont Texaco Sherman V. Allen, Inc. immediately. Another idea may be to dike around the tank. In the event there is a leak, the product would be contained and you could visually see it.

It makes sense to monitor your product occasionally to insure safety to you, the environment and Sherman V. Allen, Inc.

If you have any questions, you may contact Jack Hennessey, Fuel Manager, Vermont Texaco, Sherman V. Allen, Inc., 126-128 Post St., Rutland, VT. 05701 (telephone 775-6628).

Sincerely,

Daniel S. Poalino
Vice President/General Manager
SHERMAN V. ALLEN, INC.

DSP/st

5

CASE # _____

Department of Water Resources and Environmental Engineering

Incident Report

Date/Time: 2/5/88 7:00 Person taking report Peter Reed
Location: Town/City: Mt Holly Country Store
Road, Street, Highway: _____
Address/Mile Marker: _____

Person Making Report

Name/Organization: John Scott S P Headquarters
Telephone #: 244-8727
Address: _____

Is this an emergency? NO
Nature of Incident: Leaking underground tank
Date/Time of Incident: 2/5/88
Type of Contaminant: gasoline
Quantity of Contaminant: unk.
Responsible Parties
owner/operator: Marie Johnson 259-2368
shipper/consignee: _____
carrier/facility: _____

Other Information: Inventory shows no loss - tanks failed tank test. Atlantic did test earlier in week and store filled with fumes. Wymans called S.P.

Case Assigned to Which Section: Loss / EAMS

Priority: High, Medium, Low

Actions Taken:

cc to:

- Dept of Health
- Dept of Motor Vehicles
- Dept of Agriculture
- Dept of Labor & Industry
- Emergency Management
- Dept of Fish & Wildlife
- U.S. EPA

Case Closed: Date: _____

MEMORANDUM

TO: Mount Holly Store File

THRU: John Amadon, Soils Scientist

FROM: Richard F. Spiese, LUST Technician *RFS*

DATE: February 11, 1988

RE: Mount Holly Trip Report

On Wednesday, February 10, 1988, I visited the Mount Holly Store in Mount Holy. The purpose of this trip was to ascertain the status of the store's underground storage tank (UST). A secondary purpose was to evaluate the store's basement recovery system.


On February 5, 1988, Peter Reed (spill response) received a call informing the state that the Mount Holly Store had two USTs which failed tank tests (see spill file #239-87). The unleaded tank failed the tank test because of a faulty fill pipe. This pipe has since been replaced and the UST is currently believed to not be leaking. The regular tank is a known LUST. Wyman's tested the tank with the piping disconnected and they detected a leak in the tenths of a gallon per hour. I have heard that the leak ranges from 1/10 gallon per hour to 3/10 gallon per hour. *as of 2/17/88 known to leak - 3/4 gal/hr.*

I went to the site and spoke with the Mayos (the store's current owners) and the Johnsons (the store's previous owners). I was informed that the Mayos have a written agreement with the Johnsons which states that any problems associated with this LUSTs removal is the Johnson's responsibility. Because the tank is still exposed and is a known leaker, I informed the Johnsons that they would have to have the tank removed ASAP. I also informed them that I had to be on site during the tank's removal.

The recovery system is located in the back corner of the store basement (see map). This system consists of a 36" slotted culvert inserted into a hand dug hole. About a dozen petroleum sorbents have been inserted into the well to absorb any free product. I was informed that Elroy Hill, Sherman Allen's field representative, comes every day and removes the product from the well by wringing the product out of these pads and into 55 gallon drums. On the day of my visit I noted that the pads in the recovery well were only slight saturated. I did not notice any free product in the well. HNU readings were quite low. Ambient readings in the store and basement were non detect. Five feet from the recovery well readings were 2 ppm PID. In the well itself readings were 10 ppm PID. The only Class I receptor impacted is the store basement.

From my visit I have concluded that the Johnsons must have the LUST removed and the holes backfilled as soon as possible. I have also concluded that the skid tank kerosene clean up has been well managed and well executed. I do not foresee any future problems from this leak.

Mount Holly St. E



Parking Lot

Regular Tank

Unleaded Tank


Post Office
Mount Holly Store

Road

Bridge


Mill Stream

Floor plan to Mount Holly Store Basement



Storage

hole where
recovery system
is located



Location
where
Kerosene
Tank
was
located



Stairs

State of Vermont

Department of Fish and Wildlife
Department of Forests, Parks and Recreation
Department of Environmental Conservation
State Geologist
Natural Resources Conservation Council



AGENCY OF NATURAL RESOURCES
103 SOUTH MAIN STREET
Waterbury, Vermont 05676

Department of Environmental Conservation

MEMORANDUM

TO: Patrick A. Parenteau, Commissioner, Department of
Environmental Conservation

THRU: John A. Malter, Director, Hazardous Materials
Management Division
Cedric Sanborn, Chief, ERMS

FROM: Richard F. Spiese, Environmental Technician *RFS*

DATE: February 18, 1988

RE: Tank Removal Order at the Mount Holly Country Store

This memo will serve to inform you of my findings at the Mount Holly Country Store and to request that you sign this Order so that it can be mailed.

I have investigated the Mount Holly Country Store site and have determined the following:

1. Mr. and Mrs. Tom Mayo are the current owners of the Mount Holly Country Store.
2. Wyman's Meter and Tank Equipment, Incorporated conducted a tightness test on February 5, 1988, and determined that the regular 2,000 gallon underground storage tank leaked at a rate of .314 gallons per hour.
3. Gasoline contamination from a leak of this magnitude may pose a threat to the persons in the Mount Holly General Store as well as to the environment. The only way to determine this is by removing the tank and observing the surrounding soils.
4. Mr. and Mrs. Tom Mayo, as owners of the store and the tank, are responsible for the removal of this tank.

I hope that this memorandum briefs you as to the need for this Order. If you have any questions, please do not hesitate to contact me.

RFS/bi-h

Tank removed before letter sent, so letter not sent. RFS 1/22/88

State of Vermont



AGENCY OF NATURAL RESOURCES
103 SOUTH MAIN STREET
Waterbury, Vermont 05676

Department of Fish and Wildlife
Department of Forests, Parks and Recreation
Department of Environmental Conservation
State Geologist
Natural Resources Conservation Council

Department of Environmental Conservation

February 17, 1988

CERTIFIED MAIL

Mr. and Mrs. Tom Mayo
Mount Holly Country Store
P.O. Box 72
Mount Holly, Vermont 05758

RE: Underground Storage Tank Removal at the Mount Holly Country Store

Dear Mr. and Mrs. Mayo:

The Mount Holly Country Store has two 2,000 gallon underground storage tanks on the north side of the store. On February 5, 1988, Wyman's Meter and Tank Equipment, Incorporated conducted a tightness test at the Mount Holly Country Store on these two tanks. The results of the second tightness test on the regular underground storage tank (the second test is performed on a tank with all associated piping disconnected when the first test has shown the tank and piping together to be leaking) indicated a leak of .314 gallons per hour. This leak may have released significant quantities of gasoline to the environment. This gasoline may pose a potential hazard to the health of persons in the Mount Holly Country Store as well as to the environment.

Based on these findings, the Secretary of the Agency of Natural Resources ("Secretary") has concluded, pursuant to 10 V.S.A., Section 1932, that this underground storage tank must be removed from the ground. This tank must be removed in accordance with Section 505.2 in the Vermont Underground Storage Tank Regulations. The Secretary has further concluded, pursuant to 10 V.S.A., Section 1922.4.A, that Mr. and Mrs. Tom Mayo are the owners of this tank and as such are responsible for the removal of this tank.

Please advise this office, in writing, within ten (10) days of receipt of this notice, whether you intend to perform this work. If you decline to do so, the Secretary may expend state funds to have this work done. If he does so, he will move, pursuant to 10 V.S.A., Section 1283, to have you reimburse the state of Vermont for the costs of this work.

If you agree to perform this work, you are required to initiate this action within ten (10) days of receipt of this notice. Failure to initiate these actions by this date may result in expenditure of state funds to perform this work.

Sincerely,

Patrick A. Parenteau, Commissioner
Department of Environmental Conservation

PAP/bl-h

2/8/88 Property being sold - (Forms mailed to attorney Paul Kuli...
 APR 20 1987 X X APR 21 1987 APR 14 1987
 Paul Kuli...
 Rutland, PAGE 1
 0570

VERMONT NOTIFICATION FOR UNDERGROUND STORAGE TANKS

- READ INSTRUCTION PAGE CAREFULLY BEFORE COMPLETING THIS FORM -

PLEASE TYPE OR PRINT IN INK ALL ITEMS EXCEPT "SIGNATURE" IN SECTION VI ON PAGE 2.
 SEPARATE NOTIFICATION MUST BE FILED FOR TANKS OWNED AT A DIFFERENT LOCATION.
 FOR ADDITIONAL INFORMATION, CALL THE VERMONT UNDERGROUND STORAGE TANK PROGRAM AT (802) 828-3395.

I. OWNERSHIP OF TANKS

NAME (CORPORATION, INDIVIDUAL, PUBLIC AGENCY OR OTHER ENTITY)
Johnson Properties Inc.

STREET ADDRESS
P.O. Box 72

TOWN OR CITY COUNTY
Mt. Holly Rutland

STATE ZIP CODE AREA CODE PHONE NUMBER
Vt. 05758 (802) 259-2368

III. SITE LEAK HISTORY (COMPLETE THIS SECTION ONLY IF APPLICABLE)

YEAR OF LEAK ESTIMATE OF QUANTITY
 LEAKED IN GALLONS _____

SUBSTANCE LEAKED _____

SOURCE OF LEAK (CHECK ALL THAT APPLY)

TANK PUMP OVERFILL
 PIPING TRANSFER OTHER _____

CONTAMINATION (CHECK ALL THAT APPLY)

	YES	NO	DON'T KNOW
SOIL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
GROUNDWATER	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
SURFACE WATER	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

CORRECTIVE ACTION (CHECK ALL THAT APPLY)

PRODUCT RECOVERY WELLS INSTALLED
 SURFACE WATER CONTAINMENT USED
 CONTAMINATED SOIL EXCAVATED
 TANK REPLACED
 PIPING REPLACED
 NO ACTION TAKEN
 OTHER (SPECIFY) _____

II. CONTACT PERSON (PERSON RESPONSIBLE FOR DAY-TO-DAY OPERATION OF TANKS)

NAME (IF SAME AS IN SECTION I, CHECK BOX HERE)
Donald or Marie Johnson

JOB TITLE AREA CODE PHONE NUMBER
Owner (802) 259-2368

MAILING ADDRESS (IF DIFFERENT FROM SECTION I)
 STREET ADDRESS
P.O. Box 72

TOWN OR CITY
Mt. Holly

COUNTY STATE ZIP CODE
Rutland Vt. 05758

IV. LOCATION OF TANKS

FACILITY NAME OR OTHER SITE IDENTIFIER, AS APPLICABLE
Mt. Holly Country Store

STREET ADDRESS, STATE ROAD, R.R. #, AS APPLICABLE
Belmont Rd.

TOWN OR CITY COUNTY
Mt. Holly Rutland


STATE ZIP CODE NUMBER OF TANKS AT THIS LOCATION
Vt. 05758 2

NAME OF LANDOWNER
Donald & Marie Johnson

TYPE OF FACILITY (CHECK ONE)

INSTITUTIONAL RETAIL/CONVENIENCE STORE
 BULK PLANT INDUSTRIAL/COMMERCIAL
 STATE RESIDENTIAL
 TOWN SERVICE STATION
 FARM
 FEDERAL (GIVE FACILITY I.D. NO. _____)
 OTHER (SPECIFY) _____

USE THIS SPACE TO SKETCH AND/OR VERBALLY DESCRIBE FACILITY LOCATION. INCLUDE ESTIMATED DISTANCES TO CENTER LINE OF ROADS, BUILDINGS, STREAMS AND OTHER LANDMARKS. USE DIRECTIONAL DESCRIPTORS (NORTH, SOUTH, ETC.) WHERE APPLICABLE.



LOCAL USE ONLY

FACILITY I.D. NO. 0001312 WAS RECORDED ON April 28, 1987 IN BOOK NO. 40, PAGE 121

FILE Mount Holly LAND RECORDS. (TOWN)

Susan C. Corallo
 SIGNATURE OF TOWN OR CITY OFFICER

STATE USE ONLY

FIRST AMENDED

FACILITY IDENTIFICATION NUMBER
0001312

DATE RECEIVED 4/14/87 APPROVED 4/24/87

RECEIVED BY *Shirley B. Miller*

V. TANK INFORMATION (COMPLETE FOR EACH TANK AT THIS LOCATION)

NUMBER TANKS SEQUENTIALLY (START WITH TANK CLOSEST TO BUILDING, IF POSSIBLE)	TANK NO.	TANK NO.	TANK NO.	TANK NO.	TANK NO.
	<u>1</u>	<u>2</u>			
1. STATUS OF TANK (CHECK ONE)	CURRENTLY IN USE	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	TEMPORARILY OUT OF USE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	PERMANENTLY OUT OF USE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. ESTIMATED AGE IN YEARS	<u>3</u>	12			
3. TOTAL CAPACITY (GALLONS)	2,000	2,000			
4. MATERIAL OF CONSTRUCTION (CHECK ONE)	STEEL	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	CONCRETE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	FIBERGLASS REINFORCED PLASTIC	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	OTHER (SPECIFY)				
	UNKNOWN	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. INTERNAL PROTECTION (CHECK ALL THAT APPLY)	LINING (E.G. EPOXY RESINS)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	OTHER (SPECIFY)				
	NONE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	UNKNOWN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. EXTERNAL PROTECTION (CHECK ALL THAT APPLY)	CATHODIC PROTECTION	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	PAINTED COATING (E.G. ASPHALTIC)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	FIBERGLASS REINFORCED PLASTIC COATED	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	OTHER (SPECIFY)				
	NONE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
UNKNOWN	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
7. SECONDARY CONTAINMENT (CHECK ONE)	DOUBLE-WALL TANK	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	CONCRETE VAULT	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	IMPERVIOUS LINER	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	OTHER (SPECIFY)				
	NONE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
UNKNOWN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
8. LEAK DETECTION (CHECK ALL THAT APPLY)	DAILY INVENTORY CONTROL	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	CONTINUOUS SENSOR	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	ELECTRONIC IN-TANK SYSTEM	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	GROUNDWATER MONITORING WELL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	* PRECISION TEST (ENTER MO./YR. IF WITHIN LAST 5 YRS.)	<input type="checkbox"/> /	<input type="checkbox"/> /	<input type="checkbox"/> /	<input type="checkbox"/> /
* A PRECISION TEST IS NOT AN AIR PRESSURE TEST. BY DEFINITION, A PRECISION TEST IS ACCURATE TO .06 GAL./HR.	OTHER (SPECIFY)				
	NONE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	UNKNOWN	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. PIPING (CHECK ALL THAT APPLY)	BARE STEEL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	GALVANIZED STEEL	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	BLACK IRON	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	FIBERGLASS REINFORCED PLASTIC	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	CATHODICALLY PROTECTED	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	OTHER (SPECIFY)				
UNKNOWN	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
10. SUBSTANCE CURRENTLY OR LAST STORED IN GREATEST QUANTITY BY VOLUME (CHECK ALL THAT APPLY)	GASOLINE (INCL. ALCOHOL BLENDS)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	DIESEL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	NOS. 2 OR 4 FUEL OIL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	NOS. 5 OR 6 FUEL OIL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	AVIATION FUEL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	KEROSENE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	USED OIL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	OTHER PETROLEUM SUBSTANCE (SPECIFY)				
	HAZARDOUS SUBSTANCE (GIVE NAME OR CAS NO.)				
	MIXTURE OF SUBSTANCES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
UNKNOWN	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
11. ADDITIONAL INFORMATION FOR TANKS TAKEN PERMA- NENTLY OUT OF SERVICE	(A) ESTIMATED DATE LAST USED (MO./YR.)	<u>/</u>	<u>/</u>	<u>/</u>	<u>/</u>
	(B) ESTIMATED QUANTITY LEFT STORED (GAL.)				

VI. SIGNATURE I CERTIFY UNDER PENALTY OF LAW THAT THE INFORMATION PROVIDED ON THIS FORM AND ALL ATTACHED DOCUMENTS IS TRUE, ACCURATE AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF.

Donald G. Johnson

President

PRINTED NAME AND OFFICIAL TITLE OF OWNER OR OWNER'S AUTHORIZED REPRESENTATIVE

Donald G. Johnson

SIGNATURE

12-23-85

DATE SIGNED

TODAYS DATE: FEB 22, 1988

DATE OF REMOVAL: SAME

INSPECTOR: G. LEECH

BUSINESS NAME: MT. HOLLY GENERAL STORE

RUTLAND COUNTY

ADDRESS OF BUSINESS: RT. 103 - MT. ~~ROCK~~ HOLLY (VERMONT RD.)

OWNER OF TANKS: DONALD AND MARIE JOHNSON

ADDRESS OF OWNER: PO BOX 72, MT. HOLLY

TANK#	PRODUCT	SIZE	CONDITION
1	GAS	2000	POOR - LUST(?)
2			
3			
4			
5			
6			
7			
8			

REPLACEMENTS? NO

MONITOR WELLS OR OTHER REMEDIATION INSTALLED? NO

CONTAMINATED SOILS: NO AMOUNT: -

MOVED TO: USED AS FILL

DEGREE OF CONTAMINATION (PHOTONAL TIP) 1-5 PPM

FREE PHASE PRODUCT ENCOUNTERED: SOME SHEEN ON THE GROUND WATER

COMMENTS: ~~COARSE~~ COARSE SANDS

see here

2 - POOLS AT THIS LOCATION
 RIGHT UNDER THE ISLAND
 THESE 2 TANKS ARE NOT ON
 THE NOTIFICATION FORM

MEMORANDUM

TO: Mount Holly Store File
 THRU: John Amadon, Soils Scientist
 FROM: Richard F. Spiese, LUST Technician *RFS*
 DATE: February 24, 1988
 RE: Mount Holly Trip Report

On Monday, February 22, 1988, Greg Leech and I visited the Mount Holly Country Store in Mount Holly. The purpose of this trip was to ascertain the degree of soil contamination around a know LUST. A secondary purpose was to evaluate the store's basement recovery system.

The gasoline LUST was pulled with only minimal delays. Soils from the excavation and in the hole showed evidence of only mild contamination. Readings on the photovac TIP ranged from 1 - 5 ppm PID. The groundwater in the hole had a slight sheen on it. The soils in the area are coarse sands with gravel lenses.

Based on these findings I instructed the excavator to put the soils back into the hole. I do not foresee any problems at the site from this LUST.

The recovery system in the basement is still recovering product. The sorbent pads in the well were mostly saturated. Water under these pads had a slight sheen on it. Based on these observations I determined that Sherman Allen, Incorporated should continue to recover product from this well.

RFS/bl-h

DANIEL S. POALINO
VICE PRESIDENT-GENERAL MANAGER

Sherman V. Allen, Inc.
Distributor of Petroleum Products

126-128 Post St., Rutland, VT 05701 802-775-6828



Sherman V. Allen, Inc.
Distributor of Petroleum Products

253 South Main Street • Rutland, VT 05701

MAR 10 1988

802 775 6720
EXECUTIVE OFFICES

10

March 7, 1988

Mr. Richard Spiese
Agency of Natural Resources
Hazardous Materials
State of Vermont
103 S. Main St.
Waterbury, VT 05676

Re: Mt. Holly Country Store

Dear Mr. Spiese:

Pursuant to our conversation, enclosed is a copy of a sample analysis done on the above mentioned location. Total recovery of liquid from January 15, 1988 to March 2, 1988 is approximately Nineteen (19) gallons. Per day collection amount between one and one-half (1 1/2) pints presently. No discharge observed in the nearby stream.

Will continue observations and inspections and contact your office of any variation. Otherwise, I will speak with you in the coming weeks.

Sincerely,

Daniel S. Poalino
Vice President/General Manager
SHERMAN V. ALLEN, INC.

DSP/st

Enc.

cc: Peter J. Shambo, Chief Financial Officer



aquatec INC. ENVIRONMENTAL SERVICES

75 GREEN MOUNTAIN DRIVE, SOUTH BURLINGTON, VERMONT 05403, TELEPHONE (802) 658-1074

March 1, 1988

Mr. Peter Shambo
Sherman V. Allen, Inc.
253 South Main Street
Rutland, VT 05701

Re: Aquatec Project No. 88400, ETR No. 12890

Dear Mr. Shambo:

Enclosed is the result of a lead analysis performed on the top layer of a bi-layered liquid sample received at Aquatec on February 11, 1988.

It was determined that 3.2 mg/kg of lead was present in the top fuel layer. The fuel had a characteristic kerosene odor. Assuming that leaded gasoline was responsible for the lead content present, the data indicates that the gasoline concentration present in the fuel would be less than one percent.

Sincerely,

Joseph K. Comeau, Ph.D.
Laboratory Director

JKC/lam

Enclosure



aquatec

ENVIRONMENTAL SERVICES

75 Green Mountain Drive, So. Burlington, VT 05403
TEL. 802/658-1074

ANALYTICAL REPORT

Sherman Allen, Inc.
253 South Main St.
Rutland, VT 05701

Date: 2 March 1988
Project No: 88400
ETR No: 12890
Sample(s) Received On: 2/11/88
Page 1 of 1

Standard analyses were performed in accordance with Methods for Analysis of Water and Wastes, EPA-600/4/79-020, Test Methods for Evaluating Solid Waste, SW-846, or Standard Methods for the Examination of Water and Wastewater. All results are in mg/l unless otherwise noted.

Parameter	80010							
Lead in Fuel (mg/Kg)	3.2							

Lab No.	Sample Description
80010.	Fuel/liquid sample received 2/11/88.

Submitted By: *R. J. Hanson Miller* Aquatec Inc.

725-6628

(11) (82)

MEMORANDUM

TO: Mt. Holly Store site (file #182)

THRU: John Amadon, Soils Scientist *John F. Amadon*

FROM: Richard Spiese, LUST Technician *RJS*

DATE: March 29, 1988

RE: Trip Report

On March 24, 1988, I visited with Elroy Hill of Sherman V. Allen, Incorporated at the Mt. Holly County Store. The purpose of this visit was to discuss Sherman Allen's product recovery efforts.

The product recovery efforts at this site consist of a 24" slotted culvert placed in a hole in the basement of the store's floor. Product sorbent pads are placed in this hole and a representative of Sherman Allen would wring out the pads into a 55 gallon drum. To date, this process was being done daily. I discussed the recovery system and timetable with Elroy Hill and we decided the following schedule be followed:

<u>week of</u>	<u>Number of visits to store</u>
3/28 - 4/ 1	3
4/ 4 - 4/ 8	2
4/11 - 4/15	1

At the end of each week Elroy Hill will call me to discuss whether or not this recovery schedule should be modified.

We also checked the sorbent sausage boom in the stream behind the store. The sausage boom was completely saturated with product. Elroy Hill said he would change the boom and discard it with the six to eight saturated sorbent pads which we removed from the stream.

RFS/bl-h

JAN 19 1989



STATE OF VERMONT
AGENCY OF NATURAL RESOURCES
DEPARTMENT OF ENVIRONMENTAL
CONSERVATION

RICHARD F. SPIESE
ENVIRONMENTAL TECHNICIAN

PETROLEUM MANAGEMENT SECTION
HAZARDOUS MATERIALS MANAGEMENT DIVISION
103 SOUTH MAIN STREET, WEST BUILDING
WATERBURY, VERMONT 05676 (802) 244-8702



aquatec INC. ENVIRONMENTAL SERVICES

75 GREEN MOUNTAIN DRIVE, SOUTH BURLINGTON, VERMONT 05403, TELEPHONE (802) 658-1074

March 1, 1988

Mr. Peter Shambo
Sherman V. Allen, Inc.
253 South Main Street
Rutland, VT 05701

Re: Aquatec Project No. 88400, ETR No. 12890

Dear Mr. Shambo:

Enclosed is the result of a lead analysis performed on the top layer of a bi-layered liquid sample received at Aquatec on February 11, 1988.

It was determined that 3.2 mg/kg of lead was present in the top fuel layer. The fuel had a characteristic kerosene odor. Assuming that leaded gasoline was responsible for the lead content present, the data indicates that the gasoline concentration present in the fuel would be less than one percent.

Sincerely,

Joseph K. Comeau, Ph.D.
Laboratory Director

JKC/lam

Enclosure



aquatec

ENVIRONMENTAL SERVICES

75 Green Mountain Drive, So. Burlington, VT 05403
TEL. 802/658-1074

ANALYTICAL REPORT

Sherman Allen, Inc.
253 South Main St.
Rutland, VT 05701

M.A. Holly

Date: 2 March 1988
Project No: 88400
ETR No: 12890
Sample(s) Received On: 2/11/88
Page 1 of 1

Standard analyses were performed in accordance with Methods for Analysis of Water and Wastes, EPA-800/4/79-020, Test Methods for Evaluating Solid Waste, SW-846, or Standard Methods for the Examination of Water and Wastewater. All results are in mg/l unless otherwise noted.

Parameter	80010							
Lead in Fuel (mg/Kg)	3.2							

Lab No. Sample Description

010. Fuel/liquid sample received 2/11/88.

Submitted By:

R. Marion Miller

Aquatec Inc.



Getty

Sherman V. Allen, Inc.

Distributor of Petroleum Products

Box 100, Academy St., Fair Haven, VT 05743

A. P. ANDY BOISVERT
MARKETING REPRESENTATIVE

802-775-6628

OCT 11 1988



Industrial & Environmental Analysts, Inc.
P.O. Box 626 • Essex Junction, Vermont 05453 • 802-878-5138

LAB RESULTS

10/3/88

Sherman Y. Allen, Inc
Box 865, 126-128 Post Street
Rutland, Vermont 05701

IEA#: 245263
Date Received: 9/19/88 Date Collected: 9/19/88
Total Samples Received: 1 Total Parameters Requested: 1

Reviewed & Approved by: Ruben W. Walden

Attention: Andy Boisvert
Sa# Sample I.D.

Parameter Studied Results Comments

1 S. Allen Water GC Petroleum Hydrocarbons 5400ug/L

Test results from Mt Holly Country Store.

State of Vermont

Department of Fish and Wildlife
Department of Forests, Parks and Recreation
Department of Environmental Conservation
State Geologist
Natural Resources Conservation Council



AGENCY OF NATURAL RESOURCES
103 SOUTH MAIN STREET
Waterbury, Vermont 05676

Department of Environmental Conservation

January 23, 1989

Mr. Daniel S. Poalino
Sherman V. Allen, Inc.
126-128 Post Street
Rutland, Vermont 05701

Dear Mr. Poalino:

Subject: Closure of Mt. Holly Country Store Site

I am writing this letter to inform you that the Department of Environmental Conservation (DEC) feels that Sherman V. Allen has adhered to the understanding it had with the state of Vermont concerning the Mt. Holly Country Store. This means that the DEC has determined the following:

1. All of the recoverable free floating kerosene that could be recovered has been recovered.
2. Monitoring in the store basement and in the stream behind the store has shown that remediation efforts at the store have been successful.

Based on these findings, the DEC is closing this site. The closure of this site doesn't release Sherman V. Allen from any past or future liability which may arise from the petroleum contamination which originated from the leaking storage tank. The closure does mean that the DEC isn't requiring any additional work be performed at this site in response to the December 1987, leak. The DEC does recommend that, in the spirit of a good working relationship with its clients, Sherman V. Allen fill in the culvert in the basement of the Mt. Holly Country Store.

Please feel free to contact either myself or Richard Spiese with any further questions or concerns you may have (244-8702.)

Sincerely,

A handwritten signature in cursive script, appearing to read "Cedric Sanborn".

Cedric Sanborn, Chief
Petroleum Management Section

CS/RFS:bgc536

cc: Mr. and Mrs. Tom Mayo

STATE OF VERMONT

~~OFFICE MEMO~~

TO: Robin Monjea

FROM: June M. Doleta UST Program

DATE: 6/4/91

SUBJECT: Mt Holly STORGE

- | | | |
|---|--|--|
| <input type="checkbox"/> APPROVAL | <input type="checkbox"/> NOTE AND SEE ME | <input checked="" type="checkbox"/> PER CONVERSATION |
| <input type="checkbox"/> SIGNATURE | <input type="checkbox"/> NOTE AND RETURN | <input type="checkbox"/> AS REQUESTED |
| <input type="checkbox"/> COMMENT | <input type="checkbox"/> NOTE AND FILE | <input type="checkbox"/> NECESSARY ACTION |
| <input type="checkbox"/> REVIEW | <input type="checkbox"/> FOR YOUR INFORMATION | <input type="checkbox"/> GIVE ME THE FACTS |
| <input type="checkbox"/> PREPARE REPLY FOR MY SIGNATURE | <input type="checkbox"/> SUGGESTIONS REQUESTED | |
| <input type="checkbox"/> YOUR ACTION REQUESTED BY THIS DATE | | |

REMARKS:

Here are the copies as requested.

Sorry do not have copy of test results. We (the state) only required them as from 3/1/89 for tanks ten years of age or older. See forms for reference to tests done.

State has a site file # 880182 which refers to the gas tank failure (test done by Wynman of Montpelier now out of business)

and also to a kerosene leak from an aboveground tank.

SITE FILE IS NOW CLOSED

Copies of incident reports enclosed.

CASE # _____

Department of Water Resources and Environmental Engineering

Incident Report

Date/Time: 2/5/88 7:00 Person taking report Peter Reed

Location: Town/City: Mt Holly Country Store
Road, Street, Highway: _____
Address/Mile Marker: _____

Person Making Report

Name/Organization: John Scott - S P Headquarters
Telephone #: 244-8727
Address: _____

Is this an emergency? NO
Nature of Incident: leaking underground tank
Date/Time of Incident: 2/5/88
Type of Contaminant: gasoline
Quantity of Contaminant: unknown
Responsible Parties
owner/operator: Marie Johnson 259-2168
shipper/consignee: _____
carrier/facility: _____

Other Information:

Inventory shows no loss - tanks failed tank test. Atlantic did test earlier in week and store filled with fumes. Wymans called S.P.

Case Assigned to Which Section: Last / EAMS

Priority: High, Medium, Low

Actions Taken:

cc to:

- Dept of Health
- Dept of Motor Vehicles
- Dept of Agriculture
- Dept of Labor & Industry
- Emergency Management
- Dept of Fish & Wildlife
- U.S. EPA

Case Closed: Date: _____

CASE # 739-87

Department of Water Resources and
Environmental Engineering

Incident Report

Date/Time: 12/15 3:00pm Person taking report RTP

Location: Town/City: Mt Holly Str
Road, Street, Highway: 7th 103
Address/Mile Marker: FLASHING LIGHT

Person Making Report

Name/Organization: Marie Johnson, Storeowner
Telephone #: 259-2368
Address: 7th 103

Is this an emergency? NO
Nature of Incident: Kerosene leak from skin tank patch
Date/Time of Incident: on-going
Type of Contaminant: Kerosene
Quantity of Contaminant: unknown
Responsible Parties
owner/operator: Elroy Hill - VT Texaco 975-4289 (Sherman Ptlw)
shipper/consignee: _____
carrier/facility: _____
Other Information: _____

Case Assigned to Which Section: _____

Priority: High Medium, Low

Actions Taken: Absorbents put down to remove oil from river
soils to be removed and stored on plastic.
Site's person will screen soils.

cc to:

- Dept of Health
- Dept of Motor Vehicles
- Dept of Agriculture
- Dept of Labor & Industry
- Emergency Management
- Dept of Fish & Wildlife
- U.S. EPA

Case Closed: Date: _____

RECEIVED JUN - 7 1991



State of Vermont

Department of Fish and Wildlife
Department of Forests, Parks and Recreation
Department of Environmental Conservation
State Geologist
Natural Resources Conservation Council

AGENCY OF NATURAL RESOURCES
Department of Environmental Conservation

Hazardous Materials Management Division
103 S. Main Street, West Building
Waterbury, Vermont 05671-0404

June 4, 1991

Fred Kelly
Dartmouth Bank
40 South Main
Hanover, NH 03755

Dear Mr. Kelly:

re: T & S Enterprises, Ltd.
dba Mount Holly Country Store, Mount Holly, VT
ID# 0001312-1211

I refer to previous correspondence between the Bank and the Department of Environmental Conservation concerning the above underground storage tank facility. A form letter regarding the annual testing requirement was recently mailed to all tank owners who have chosen that method for release detection.

A review of the facility file has brought to my attention the fact that the tank has now been out of service for one year. The permit to operate said tank issued by the Department on February 9, 1989, must be cancelled.

Pursuant to Section 8-605(2)(b) of the Vermont UST Regulations, the owner of an underground storage tank which has not been used for a period not to exceed one year shall permanently close the UST by removing all liquid and sludge, purging the tank, and removing it from the ground. A site assessment performed by a qualified consultants is required to be performed.

Should you have questions, please do not hesitate to contact me at (802) 244-8702.

Sincerely,

A handwritten signature in cursive script that reads "June Middleton".

June Middleton
UST Permit Administrator

STATE OF VERMONT
AGENCY OF NATURAL RESOURCES
DEPARTMENT OF ENVIRONMENTAL CONSERVATION

UNDERGROUND STORAGE TANK PERMIT

PART I — FACILITY PERMIT PAGE — PLEASE TYPE OR PRINT IN INK.

TANK OWNER

NAME T + S ENTERPRISES LTD. PHONE (802) 254-2367
MAILING ADDRESS 150 Mt Holly Country Store Route 103 P.O. Box 50
CITY Mt Holly STATE VT ZIP CODE 05758

TANK LOCATION

NAME SAME AS ABOVE PHONE (802) 254-2367
MAILING ADDRESS 20 Mount Road
CITY Mt Holly STATE VT ZIP CODE

OPERATOR

NAME SAME AS ABOVE - Tankowner PHONE ()
MAILING ADDRESS 150 Mt Holly Country Store
CITY STATE ZIP CODE

CONTACT PERSON

NAME Thomas Mayo PHONE ()
MAILING ADDRESS SAME AS ABOVE
CITY STATE ZIP CODE

BACK-UP CONTACT

NAME SHARON MAYO PHONE ()
MAILING ADDRESS SAME AS ABOVE
CITY STATE ZIP CODE

TO REPORT A RELEASE:

CALL (802) 244-8702 MON.-FRI. 7:30 A.M. TO 4:30 P.M. OR 1-(800)-641-5005 MON.-FRI. 4:30 P.M. TO 7:30 A.M. AND WEEK-
ENDS AND HOLIDAYS. (THIS NUMBER IS ONLY TO BE USED WHEN THE AGENCY OF NATURAL RESOURCES IS CLOSED
AND ONLY FOR REPORTING RELEASES. DO NOT USE THIS NUMBER FOR GENERAL INFORMATION.)

TO REPORT A RELEASE:

CERTIFICATION: I CERTIFY UNDER PENALTY OF LAW THAT THE INFORMATION PROVIDED ON THIS FORM AND ALL
ATTACHED DOCUMENTS IS TRUE, ACCURATE AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF.

T + S Enterprises Ltd. PRINTED NAME TITLE President
Thomas S. Mayo SIGNATURE DATE 11/4/89

STATE USE ONLY

DATE PERMIT RECEIVED 1-5-1989 DATE PERMIT ISSUED 2.9.1989
DATE PERMIT EXPIRES 1-5-1994 NUMBER OF CATEGORY ONE TANKS ONE
APPROVED BY William E. O'Leary ID # 0001312 - 1211
CHECK # 1071 RECEIPT # 4656 AMOUNT PAID 25 + 100

UNDERGROUND STORAGE TANK PERMIT

FACILITY ID# 2000-1-1

PART 2 — TANK INFORMATION PAGE

TANK # 1

THIS PERMIT APPLICATION IS FOR AN EXISTING UST.
THIS FORM IS TO BE USED FOR RECORDING THE INFORMATION FOR ONE UST ONLY.
FILL OUT ADDITIONAL FORMS FOR EACH CATEGORY ONE UST AT THE FACILITY.

1. TANK AGE 1983 (YEAR INSTALLED)
PIPING AGE 1983 (YEAR INSTALLED)

2. TANK SIZE 2000 (U.S. GALLONS)

3. MATERIAL OF CONSTRUCTION

	TANK	PIPE
FIBERGLASS	<input type="checkbox"/>	<input type="checkbox"/>
STEEL	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
STEEL WITH NONCORROSIVE CLADDING	<input type="checkbox"/>	<input type="checkbox"/>
OTHER (SPECIFY)	<input type="checkbox"/>	<input type="checkbox"/>
UNKNOWN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

4. CATHODIC PROTECTION

(Metal Tanks and Pipes Only)

TANK	PIPES
STI-P3	<input type="checkbox"/>
IMPRESSED CURRENT	<input type="checkbox"/>
NONE	<input type="checkbox"/>
UNKNOWN	<input checked="" type="checkbox"/>

5. SECONDARY CONTAINMENT

	TANK	PIPE
DOUBLE WALL	<input type="checkbox"/>	<input type="checkbox"/>
CUT OFF BARRIER	<input type="checkbox"/>	<input type="checkbox"/>
ALTERNATIVE SYSTEM	<input type="checkbox"/>	<input type="checkbox"/>

	TANK	PIPE
IMPERVIOUS LINER	<input type="checkbox"/>	<input type="checkbox"/>
VAULT	<input type="checkbox"/>	<input type="checkbox"/>
SUCTION PUMP WITH VERTICAL CHECK VALVE	NA	<input type="checkbox"/>

6. PRODUCT BEING STORED: GAS COLOR CODE: _____

7. OVERFILL AND SPILL PREVENTION:

BALL FLOAT VALVE (on gravity systems only)

HIGH LIQUID LEVEL ALARM

AUTOMATIC SHUT OFF DEVICE AT FILL PIPE

CONTAINMENT MANHOLE

OTHER (SPECIFY) _____

8. ADDITIONAL MONITORING SYSTEM: THIS ONLY APPLIES TO EXISTING UST THAT

A. IS 10 YEARS OLD OR GREATER, AND,
B. DOES NOT MEET NEW CONSTRUCTION STANDARDS
PERMITTEE HAS UNTIL MARCH 1, 1989 TO CHOOSE ONE OF THE FOLLOWING SYSTEMS.
CHECK IF ANY CURRENTLY APPLY.

I. IN-TANK ELECTRONIC MONITOR _____
(specify manufacturer and model)

II. EXTERNAL MONITOR WELLS _____
(submit site plan showing location)

III. PRECISION TEST SCHEDULE MAY 1988
(name of testing company)

b. If total gallonage sold is less than an average of 40,000 gallons/month (480,000 gallons/year), but more than an average of 20,000 gallons/month (240,000 gallons/year) the annual fee is \$100.00 per tank.

c. If total gallonage sold is less than an average of 20,000 gallons per month (240,000 gallons/year) the fee is \$100.00 per tank, but not more than \$200.00 per facility.

Total Gallonage sold per month at this facility? _____

5. Determination of Tank Assessment Fee

Number of Category One tanks x Appropriate fee (Section 2, 3 or 4 above) = Assessment due

1 Tanks x \$ 100 Fee/Tank = \$ 100

ck
1071
4657

The amount shown in section 5 above is due to the state of Vermont and must be submitted to the state no later than November 15, 1988. Failure to pay the required fee by this date, will result in the above facility being shut down until proper evidence of financial responsibility is submitted to the state.

Checks should be made payable to:

Treasurer, State of Vermont

And send to:

State of Vermont
Agency of Natural Resources
Underground Storage Tank Program
103 South Main Street, West Building
Waterbury, Vermont 05676

For assistance in completing the above form, please contact the Underground Storage Tank Program at 244-8702.

PAYMENT OF ASSESSMENT FEE ENTITLES TANK OWNERS WHO ARE NOT IN SIGNIFICANT VIOLATION OF THEIR UST PERMIT ACCESS TO PETROLEUM CLEANUP FUND IN THE EVENT OF A RELEASE SUCH THAT THE FUND WOULD PAY:

(a) All uninsured corrective action costs, after the first \$10,000 has been paid by the tank owner, up to \$1 million per occurrence; and (b) All of the allowable third party bodily injury and property damage claims, again up to \$1 million per occurrence.

AMENDED - NEW OIL TANK #2 PULLED

VERMONT NOTIFICATION FOR UNDERGROUND STORAGE TANKS

- READ INSTRUCTION PAGE CAREFULLY BEFORE COMPLETING THIS FORM -

PLEASE TYPE OR PRINT IN INK ALL ITEMS EXCEPT "SIGNATURE" IN SECTION VI ON PAGE 2. SEPARATE NOTIFICATION MUST BE FILED FOR TANKS OWNED AT A DIFFERENT LOCATION. FOR ADDITIONAL INFORMATION, CALL THE VERMONT UNDERGROUND STORAGE TANK PROGRAM AT (802) 828-3395.


I. OWNERSHIP OF TANKS				III. SITE LEAK HISTORY (COMPLETE THIS SECTION ONLY IF APPLICABLE)			
NAME (CORPORATION, INDIVIDUAL, PUBLIC AGENCY OR OTHER ENTITY) T. + S. ENTERPRISES LTD. INC.				YEAR OF LEAK 1988		ESTIMATE OF QUANTITY LEAKED IN GALLONS _____	
STREET ADDRESS P.O. BOX 50				SUBSTANCE LEAKED GASOLINE			
TOWN OR CITY MT. HOLLY		COUNTY RUTLAND		SOURCE OF LEAK (CHECK ALL THAT APPLY)			
STATE VT.	ZIP CODE 05758	AREA CODE (802)	PHONE NUMBER 259-2368	<input checked="" type="checkbox"/> TANK		<input type="checkbox"/> PUMP	
				<input type="checkbox"/> PIPING		<input type="checkbox"/> OVERFILL	
				<input type="checkbox"/> TRANSFER		<input type="checkbox"/> OTHER _____	
II. CONTACT PERSON (PERSON RESPONSIBLE FOR DAY-TO-DAY OPERATION OF TANKS)				CONTAMINATION (CHECK ALL THAT APPLY)			
NAME (IF SAME AS IN SECTION I, CHECK BOX HERE <input type="checkbox"/>) THOMAS OR SHARON MAYO				SOIL <input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> DON'T KNOW			
JOB TITLE OWNER		AREA CODE PHONE NUMBER (802) 259-2368		GROUNDWATER <input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> DON'T KNOW			
MAILING ADDRESS (IF DIFFERENT FROM SECTION I)				SURFACE WATER <input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> DON'T KNOW			
STREET ADDRESS P.O. BOX 50				CORRECTIVE ACTION (CHECK ALL THAT APPLY)			
TOWN OR CITY MT. HOLLY		COUNTY RUTLAND		<input type="checkbox"/> PRODUCT RECOVERY WELLS INSTALLED			
STATE VT.	ZIP CODE 05758			<input type="checkbox"/> SURFACE WATER CONTAINMENT USED			
				<input type="checkbox"/> CONTAMINATED SOIL EXCAVATED			
				<input type="checkbox"/> TANK REPLACED			
				<input type="checkbox"/> PIPING REPLACED			
				<input type="checkbox"/> NO ACTION TAKEN			
				<input type="checkbox"/> OTHER (SPECIFY) TANK LOST TO BE REMOVED ASAP			

SITE FILE # 80188

IV. LOCATION OF TANKS

FACILITY NAME OR OTHER SITE IDENTIFIER, AS APPLICABLE MT. HOLLY COUNTRY STORE				TYPE OF FACILITY (CHECK ONE)			
STREET ADDRESS, STATE ROAD, R.R. #, AS APPLICABLE BELMONT RD.				<input type="checkbox"/> INSTITUTIONAL		<input checked="" type="checkbox"/> RETAIL/CONVENIENCE STORE	
TOWN OR CITY MT. HOLLY		COUNTY RUTLAND		<input type="checkbox"/> BULK PLANT		<input type="checkbox"/> INDUSTRIAL/COMMERCIAL	
STATE VT.	ZIP CODE 05758	NUMBER OF TANKS AT THIS LOCATION 2		<input type="checkbox"/> STATE		<input type="checkbox"/> RESIDENTIAL	
NAME OF LANDOWNER THOMAS + SHARON MAYO				<input type="checkbox"/> TOWN		<input type="checkbox"/> SERVICE STATION	
				<input type="checkbox"/> FARM			
				<input type="checkbox"/> FEDERAL (GIVE FACILITY I.D. NO. _____)			
				<input type="checkbox"/> OTHER (SPECIFY) _____			

USE THIS SPACE TO SKETCH AND/OR VERBALLY DESCRIBE FACILITY LOCATION. INCLUDE ESTIMATED DISTANCES TO CENTER LINE OF ROADS, BUILDINGS, STREAMS AND OTHER LANDMARKS. USE DIRECTIONAL DESCRIPTORS (NORTH, SOUTH, ETC.) WHERE APPLICABLE.



LOCAL USE ONLY		STATE USE ONLY	
FACILITY I.D. NO. <u>0001312</u> WAS		<input type="checkbox"/> FIRST <input checked="" type="checkbox"/> AMENDED	
RECORDED ON <u>Feb. 26, 1988</u> IN		FACILITY IDENTIFICATION NUMBER <u>0001312</u>	
BOOK NO. <u>41</u> , PAGE <u>271-272</u>		DATE RECEIVED <u>3-11-88</u> APPROVED <u>3/24/88</u>	
OF THE <u>Mount Holly</u> LAND RECORDS.		RECEIVED BY <u>Susan Alexander</u>	
 SIGNATURE OF TOWN OR CITY OFFICER			

V. TANK INFORMATION (COMPLETE FOR EACH TANK AT THIS LOCATION)

NUMBER TANKS SEQUENTIALLY (START WITH TANK CLOSEST TO BUILDING, IF POSSIBLE)	TANK NO.	TANK NO.	TANK NO.	TANK NO.	TANK NO.
1. STATUS OF TANK (CHECK ONE)	1	2			
CURRENTLY IN USE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
TEMPORARILY OUT OF USE	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
PERMANENTLY OUT OF USE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. ESTIMATED AGE IN YEARS	6?	12?			
3. TOTAL CAPACITY (GALLONS)	2000	2000			
4. MATERIAL OF CONSTRUCTION (CHECK ONE)	STEEL	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	CONCRETE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	FIBERGLASS REINFORCED PLASTIC	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	OTHER (SPECIFY)				
	UNKNOWN	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. INTERNAL PROTECTION (CHECK ALL THAT APPLY)	LINING (E.G. EPOXY RESINS)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	OTHER (SPECIFY)				
	NONE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	UNKNOWN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. EXTERNAL PROTECTION (CHECK ALL THAT APPLY)	CATHODIC PROTECTION	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	PAINTED COATING (E.G. ASPHALTIC)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	FIBERGLASS REINFORCED PLASTIC COATED	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	OTHER (SPECIFY)				
	UNKNOWN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. SECONDARY CONTAINMENT (CHECK ONE)	DOUBLE-WALL TANK	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	CONCRETE VAULT	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	IMPERVIOUS LINER	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	OTHER (SPECIFY)				
	NONE	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. LEAK DETECTION (CHECK ALL THAT APPLY)	DAILY INVENTORY CONTROL	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	CONTINUOUS SENSOR	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	ELECTRONIC IN-TANK SYSTEM	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	GROUNDWATER MONITORING WELL	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	* PRECISION TEST (ENTER NO./YR. IF WITHIN LAST 5 YRS.)	<input checked="" type="checkbox"/> 1/88	<input checked="" type="checkbox"/> 1/88	<input type="checkbox"/>	<input type="checkbox"/>
	OTHER (SPECIFY)				
9. PIPING (CHECK ALL THAT APPLY)	BARE STEEL	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	GALVANIZED STEEL	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	BLACK IRON	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	FIBERGLASS REINFORCED PLASTIC	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	CATHODICALLY PROTECTED	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	OTHER (SPECIFY)				
10. SUBSTANCE CURRENTLY OR LAST STORED IN GREATEST QUANTITY BY VOLUME (CHECK ALL THAT APPLY)	GASOLINE (INCL. ALCOHOL BLENDS)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	DIESEL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	NOS. 2 OR 4 FUEL OIL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	NOS. 5 OR 6 FUEL OIL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	AVIATION FUEL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	KEROSENE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	USED OIL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	OTHER PETROLEUM SUBSTANCE (SPECIFY)				
	HAZARDOUS SUBSTANCE (GIVE NAME OR CAS NO.)				
	MIXTURE OF SUBSTANCES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
UNKNOWN	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
11. ADDITIONAL INFORMATION FOR TANKS TAKEN PERMANENTLY OUT OF SERVICE	(A) ESTIMATED DATE LAST USED (MO./YR.)	1	12/87	1	1
	(B) ESTIMATED QUANTITY LEFT STORED (GAL.)		1?		

VI. SIGNATURE I CERTIFY UNDER PENALTY OF LAW THAT THE INFORMATION PROVIDED ON THIS FORM AND ALL ATTACHED DOCUMENTS IS TRUE, ACCURATE AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF.

THOMAS S. MAYO PRES. + TREAS.

PRINTED NAME AND OFFICIAL TITLE OF OWNER OR OWNER'S AUTHORIZED REPRESENTATIVE

Thomas S. Mayo
SIGNATURE

2/18/88
DATE SIGNED

TANK FULL FORM

TODAYS DATE: FEB 22, 1988

DATE OF REMOVAL: SAME

INSPECTOR: G. LEECH

BUSINESS NAME: MT. HOLLY GENERAL STORE

RUTLAND COUNTY

ADDRESS OF BUSINESS: RT. 103 - MT. ~~ROCK~~ HOLLY (BERMONT RD.)

OWNER OF TANKS: DONALD AND MARIE JOHNSON

ADDRESS OF OWNER: PO BOX 72, MT. HOLLY

TANK#	PRODUCT	SIZE	CONDITION
1	GAS	2000	POOR - LUST(?)
2			
3			
4			
5			
6			
7			
8			

REPLACEMENTS? NO

MONITOR WELLS OR OTHER REMEDIATION INSTALLED? NO

CONTAMINATED SOILS: NO AMOUNT: -

MOVED TO: USED AS FILL

DEGREE OF CONTAMINATION (PHOTONAL TIP) 1-5 ppm

FREE PHASE PRODUCT ENCOUNTERED: SOME SHEEN ON THE GROUND WATER

COMMENTS: ~~COARSE~~ COARSE SANDS

ex. Richard

2 - POOLS AT THIS LOCATION
RIGHT UNDER THE ISLAND
THESE 2 TANKS ARE NOT ON
THE NOTIFICATION FORM

Handwritten notes and signatures in the bottom left corner.

Handwritten notes and signatures in the bottom right corner.

V. TANK INFORMATION (COMPLETE FOR EACH TANK AT THIS LOCATION)

NUMBER TANKS SEQUENTIALLY (START WITH TANK CLOSEST TO BUILDING, IF POSSIBLE)	TANK NO.	TANK NO.	TANK NO.	TANK NO.	TANK NO.
	<u>1</u>	<u>2</u>			
1. STATUS OF TANK (CHECK ONE)	CURRENTLY IN USE	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	TEMPORARILY OUT OF USE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	PERMANENTLY OUT OF USE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. ESTIMATED AGE IN YEARS	<u>3</u>	<u>12</u>			
3. TOTAL CAPACITY (GALLONS)	<u>2,000</u>	<u>2,000</u>			
4. MATERIAL OF CONSTRUCTION (CHECK ONE)	STEEL	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	CONCRETE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	FIBERGLASS REINFORCED PLASTIC	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	OTHER (SPECIFY)				
	UNKNOWN	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. INTERNAL PROTECTION (CHECK ALL THAT APPLY)	LINING (E.G. EPOXY RESINS)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	OTHER (SPECIFY)				
	NONE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	UNKNOWN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. EXTERNAL PROTECTION (CHECK ALL THAT APPLY)	CATHODIC PROTECTION	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	PAINTED COATING (E.G. ASPHALTIC)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	FIBERGLASS REINFORCED PLASTIC COATED	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	OTHER (SPECIFY)				
	UNKNOWN	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. SECONDARY CONTAINMENT (CHECK ONE)	DOUBLE-WALL TANK	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	CONCRETE VAULT	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	IMPERVIOUS LINER	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	OTHER (SPECIFY)				
	UNKNOWN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. LEAK DETECTION (CHECK ALL THAT APPLY)	DAILY INVENTORY CONTROL	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	CONTINUOUS SENSOR	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	ELECTRONIC IN-TANK SYSTEM	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	GROUNDWATER MONITORING WELL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	* PRECISION TEST (ENTER MO./YR. IF WITHIN LAST 5 YRS.)	<input type="checkbox"/> / /	<input type="checkbox"/> / /	<input type="checkbox"/> / /	<input type="checkbox"/> / /
	OTHER (SPECIFY)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. PIPING (CHECK ALL THAT APPLY)	BARE STEEL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	GALVANIZED STEEL	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	BLACK IRON	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	FIBERGLASS REINFORCED PLASTIC	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	CATHODICALLY PROTECTED	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	UNKNOWN	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. SUBSTANCE CURRENTLY OR LAST STORED IN GREATEST QUANTITY BY VOLUME (CHECK ALL THAT APPLY)	GASOLINE (INCL. ALCOHOL BLENDS)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	DIESEL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	NOS. 2 OR 4 FUEL OIL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	NOS. 5 OR 6 FUEL OIL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	AVIATION FUEL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	KEROSENE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	USED OIL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	OTHER PETROLEUM SUBSTANCE (SPECIFY)				
	HAZARDOUS SUBSTANCE (GIVE NAME OR CAS. NO.)				
	MIXTURE OF SUBSTANCES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
UNKNOWN	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
11. ADDITIONAL INFORMATION FOR TANKS TAKEN PERMA- NENTLY OUT OF SERVICE	(A) ESTIMATED DATE LAST USED (MO./YR.)	<u>/</u>	<u>/</u>	<u>/</u>	<u>/</u>
	(B) ESTIMATED QUANTITY LEFT STORED (GAL.)				

VI. SIGNATURE I CERTIFY UNDER PENALTY OF LAW THAT THE INFORMATION PROVIDED ON THIS FORM AND ALL ATTACHED DOCUMENTS IS TRUE, ACCURATE AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF.

Donald G. Johnson President
PRINTED NAME AND OFFICIAL TITLE OF OWNER OR OWNER'S AUTHORIZED REPRESENTATIVE

Donald G. Johnson
SIGNATURE

12-23-85
DATE SIGNED

A
P
P
E
N
D
I
X

C

APPENDIX C

FIELD PROCEDURES

Test borings

The test borings were generally performed in accordance with ASTM method D1452 using 4-1/4-inch I.D. hollow-stem auger drilling techniques with no water or drilling fluid being introduced into the borehole during drilling. The soil samples were generally obtained in accordance with ASTM method D1586 at 5-foot intervals using a 24-inch split spoon sampler driven by a 140-pound hammer free-falling a distance of approximately 30 inches. The number of blows required to drive the sampler each 6-inch increment over the 24-inch interval was recorded. The sum of the blows for the interval from 6 to 18 inches is referred to as the Standard Penetration Test (SPT) N-value and gives an indication of the density of the soil. The soil samples collected during drilling were placed in glass jars with Teflon-lined caps for future reference.

Field Screening of Soils

The soil samples collected during drilling were screened for total concentrations of volatile organic compounds (VOCs) using a MicroTIP organic vapor meter (OVM) equipped with a photoionization detector. The tightly-capped soil samples were allowed to equilibrate to room temperature. Immediately prior to screening, the jar sample was shaken vigorously for approximately 30 seconds. A measurement of the total VOCs within the headspace of the jar sample was then obtained by loosening the cap, slightly lifting one side of the cap, and inserting the OVM probe tip between the lip of the jar and the cap. The maximum OVM reading was recorded and the cap was placed back on the jar.

Groundwater Monitoring Well Installations

Groundwater monitoring wells were installed in selected test borings upon completion of the borings. The wells consisted of 2-inch I.D. Schedule 40 PVC well screen and riser pipe. The well screen consisted of 0.010-inch machine-slotted sections of PVC pipe. The threaded PVC well sections were joined without the use of cement or glue. A clean filter sand was placed surrounding the well screen. An approximately one-foot thick bentonite seal was placed above the filter sand to limit the potential infiltration of water along the well. Formation material was then backfilled into the borehole to the ground surface. Each well was completed with a steel curb box to protect the well from tampering and vandalism. A concrete surface seal was placed around each well installation upon completion. Details of the monitoring well construction are included on the boring logs included in this report.

Water Sampling Procedures

Groundwater levels were measured in each well prior to sampling using a Solinst electronic water level indicator. The wells were purged of at least three times the standing volume of water in the wells using a centrifugal pump. After purging the wells, groundwater samples were collected using pre-cleaned high density polyethylene (HDPE) disposable bailers. Separate bailers were used for each well to limit the potential for cross-contamination. The first bailer volume was observed for the possible presence of a floating product layer. No floating product layer was observed in any of the wells. The water samples were placed in appropriate sample containers supplied by the laboratory and placed in an ice-filled cooler for delivery to the laboratory.

A
P
P
E
N
D
I
X

D

 <p>CONCORD • NEW HAMPSHIRE</p>	<p>PROJECT</p> <p>Mt. Holly Country Store Mt. Holly, Vermont</p>	<p>BORING NO. <u>MW-1</u></p> <p>SHEET <u>1</u> of <u>1</u></p> <p>FILE NO. <u>91-310</u></p> <p>CHKD. BY <u>RBK</u></p>																				
<p>BORING Co. <u>New Hampshire Boring, Inc.</u></p> <p>DRILLER <u>J. Michaud</u></p> <p>ENGINEER <u>K. Koornneef</u></p>		<p>BORING LOCATION <u>See Exploration Location Plan</u></p> <p>GROUND SURFACE ELEV. _____ DATUM _____</p> <p>DATE START <u>6/7/91</u> DATE END <u>6/7/91</u></p>																				
<p>Sampler: Unless otherwise noted, sampler consists of a 2-inch split spoon driven by a 140-lb. hammer free-falling 30".</p> <p>Casing: Unless otherwise noted, casing driven using a 300-lb. hammer falling 24".</p> <p>Casing Size: Other: <u>4-1/4-inch I.D. hollow-stem auger</u></p>		<p style="text-align: center;">Groundwater Readings</p> <table border="1" style="width:100%; border-collapse: collapse;"> <thead> <tr> <th>Date</th> <th>Time</th> <th>Depth</th> <th>Casing</th> <th>Stabilization Time</th> </tr> </thead> <tbody> <tr> <td>6/9</td> <td>--</td> <td>2.4'</td> <td>well</td> <td>2 days</td> </tr> <tr> <td> </td> <td> </td> <td> </td> <td> </td> <td> </td> </tr> <tr> <td> </td> <td> </td> <td> </td> <td> </td> <td> </td> </tr> </tbody> </table>	Date	Time	Depth	Casing	Stabilization Time	6/9	--	2.4'	well	2 days										
Date	Time	Depth	Casing	Stabilization Time																		
6/9	--	2.4'	well	2 days																		
DEPTH	SAMPLE	SAMPLE DESCRIPTION BURMISTER / (USCS) CLASSIFICATION	STRATUM DESC.	WELL INSTALLATION	REMARKS																	
No.	PEN/ REC.	DEPTH (ft.)	BLOWS / 6"																			
5	A-1 --	0-2	--	FILL 3'	Curb Box Bentonite Seal 2'																	
10	S-1 24/10	5-7	21-28 15-17	TILL	2' PVC well screen Filter sand																	
15	S-2 24/10	10-12	7-16 22-23	12'	12'																	
20																						
25																						
30																						
35																						
<p>REMARKS:</p> <p>1) Groundwater first noted at approximately 4.5 feet.</p>																						
<p>NOTES:</p> <p>1) Stratification lines represent approximate boundaries between soil types; Actual transitions may be gradual and varied.</p> <p>2) Fluctuations in water levels will occur due to conditions different from those present at the time these measurements were made.</p>																						



CONCORD • NEW HAMPSHIRE

PROJECT

Mt. Holly Country Store
Mt. Holly, Vermont

BORING NO. B-2A
SHEET 1 of 1
FILE NO. 91-310
CHKD. BY RBK

BORING Co. New Hampshire Boring, Inc.
DRILLER J. Michaud
ENGINEER K. Koomneef

BORING LOCATION See Exploration Location Plan
GROUND SURFACE ELEV. _____ DATUM _____
DATE START 6/7/91 DATE END 6/7/91

Sampler: Unless otherwise noted, sampler consists of a 2-inch split spoon driven by a 140-lb. hammer free-falling 30".
Casing: Unless otherwise noted, casing driven using a 300-lb. hammer falling 24".
Casing Size: Other: 4-1/4-inch I.D. hollow-stem auger

Groundwater Readings				
Date	Time	Depth	Casing	Stabilization Time
6/9	--	dry	5'	none

DEPTH	SAMPLE				SAMPLE DESCRIPTION BURMISTER / (USCS) CLASSIFICATION	STRATUM DESC.	WELL INSTALLATION	REMARKS
	No.	PEN/ REC.	DEPTH (ft.)	BLOWS / 6"				
5	A-1	--	0-2	--	Grey, fine to medium SAND, little Gravel, trace Silt. (Auger cuttings sample)	FILL		
	S-2	6/0	4-4.5	100				
10					No recovery. Auger refusal at 5'; boring terminated.	5'		
15								
20								
25								
30								
35								

REMARKS:

NOTES:
1) Stratification lines represent approximate boundaries between soil types; Actual transitions may be gradual and varied.
2) Fluctuations in water levels will occur due to conditions different from those present at the time these measurements were made.

PROJECT

Mt. Holly Country Store
 Mt. Holly, Vermont

BORING NO. B-2B
 SHEET 1 of 1
 FILE NO. 91-310
 CHKD. BY RBK

BORING Co. New Hampshire Boring, Inc.
 DRILLER J. Michaud
 ENGINEER K. Koornneef

BORING LOCATION See Exploration Location Plan
 GROUND SURFACE ELEV. _____ DATUM _____
 DATE START 6/7/91 DATE END 6/7/91

Sampler: Unless otherwise noted, sampler consists of a 2-inch split spoon driven by a 140-lb. hammer free-falling 30".
 Casing: Unless otherwise noted, casing driven using a 300-lb. hammer falling 24".
 Casing Size: Other: 4-1/4-inch I.D. hollow-stem auger

Groundwater Readings				
Date	Time	Depth	Casing	Stabilization Time

DEPTH	SAMPLE				SAMPLE DESCRIPTION BURMISTER / (USCS) CLASSIFICATION	STRATUM DESC.	WELL INSTALLATION	REMARKS
	No.	PEN/REC.	DEPTH (ft.)	BLOWS / 6"				
	A-1	--	0-2	--	Grey, fine to medium SAND, little Gravel, trace Silt. (Auger cuttings sample)	FILL 3'		1
					Boring terminated at 3'. See notes below.			2
10								
15								
20								
25								
30								
35								

REMARKS:
 1) Encountered and punctured apparent UST at 3 feet.
 2) The apparent UST appeared to contain soil fill to a depth of 5 feet below the ground surface. No liquid product was observed.
 3) A temporary cover was placed over the puncture and the borehole was backfilled. An asphalt seal was placed at the ground surface.

NOTES:
 1) Stratification lines represent approximate boundaries between soil types; Actual transitions may be gradual and varied.
 2) Fluctuations in water levels will occur due to conditions different from those present at the time these measurements were made.

PROJECT

Mt. Holly Country Store
 Mt. Holly, Vermont

BORING NO. B-2C, MW-2
 SHEET 1 of 1
 FILE NO. 91-310
 CHKD. BY RBK

BORING Co. New Hampshire Boring, Inc.
 DRILLER J. Michaud
 ENGINEER K. Koornneef

BORING LOCATION See Exploration Location Plan
 GROUND SURFACE ELEV. _____ DATUM _____
 DATE START 6/7/91 DATE END 6/7/91

Sampler: Unless otherwise noted, sampler consists of a 2-inch split spoon driven by a 140-lb. hammer free-falling 30".
 Casing: Unless otherwise noted, casing driven using a 300-lb. hammer falling 24".
 Casing Size: Other: 4-1/4-inch I.D. hollow-stem auger

Groundwater Readings				
Date	Time	Depth	Casing	Stabilization Time
6/9	--	6.6'	well	2 days

DEPTH	SAMPLE				SAMPLE DESCRIPTION BURMISTER / (USCS) CLASSIFICATION	STRATUM DESC.	WELL		REMARKS
	No.	PEN/REC.	DEPTH (ft.)	BLOWS / 6'			INSTALLATION		
0	A-1	--	0-2	--	Grey, fine SAND, some Gravel, trace Silt. (auger cuttings sample)	FILL	2'	Curb Box Bentonite seal	1
5	S-1	6/0	4-4.5	100					
10							Filter sand		
10	S-2	24/12	10-12	8-25 46-16	Very dense, olive-brown, fine SAND, some Gravel, some Clayey-Silt.	12'	12'		
15									
20									
25									
30									
35									

REMARKS:
 1) Groundwater first noted at approximately 5 feet.

NOTES:
 1) Stratification lines represent approximate boundaries between soil types; Actual transitions may be gradual and varied.
 2) Fluctuations in water levels will occur due to conditions different from those present at the time these measurements were made.



CONCORD • NEW HAMPSHIRE

PROJECT

Mt. Holly Country Store
Mt. Holly, Vermont

BORING NO. MW-3
SHEET 1 of 1
FILE NO. 91-310
CHKD. BY RBK

BORING Co. New Hampshire Boring, Inc.
DRILLER J. Michaud
ENGINEER K. Koomneef

BORING LOCATION See Exploration Location Plan
GROUND SURFACE ELEV. _____ DATUM _____
DATE START 6/7/91 DATE END 6/7/91

Sampler: Unless otherwise noted, sampler consists of a 2-inch split spoon driven by a 140-lb. hammer free-falling 30".
Casing: Unless otherwise noted, casing driven using a 300-lb. hammer falling 24".
Casing Size: Other: 4-1/4-inch I.D. hollow-stem auger

Groundwater Readings				
Date	Time	Depth	Casing	Stabilization Time
6/9	--	6.5'	well	2 days

DEPTH	SAMPLE				SAMPLE DESCRIPTION BURMISTER / (USCS) CLASSIFICATION	STRATUM DESC.	WELL		REMARKS
	No.	PEN/REC.	DEPTH (ft.)	BLOWS / 6"			INSTALLATION		
5	A-1	--	0-2	--	Grey-grown, fine to medium SAND, little Gravel, trace Silt. (auger cuttings sample)	FILL		3.5'	Curb Box Bentonite seal Solid PVC riser
10	S-1	24/6	5-7	4-4 4-4	Loose, grey, fine SAND, little Gravel, little Silt.	8'		2' PVC well screen	Filter sand
15	S-2	24/12	10-12	15-17 14-14	Dense, olive-brown, fine SAND, some Clayey-Silt, some Gravel.	TILL 13.5'		13.5'	Filter sand
20					Auger refusal at 13.5' Boring terminated at 13.5'				
25									
30									
35									

REMARKS:
1) Groundwater first noted at approximately 7 feet.

NOTES:
1) Stratification lines represent approximate boundaries between soil types; Actual transitions may be gradual and varied.
2) Fluctuations in water levels will occur due to conditions different from those present at the time these measurements were made.

A
P
P
E
N
D
I
X

E



AQUARIAN ANALYTICAL INC.

Laboratory Services

P.O. Box 186

Canterbury, N.H. 03224

603-783-9097

June 13, 1991

Mr. Roger Keilig
Nobis Engineering, Inc.
6 Chenell Dr. Suite 200
Concord, N.H. 03301

Dear Mr. Keilig:

Enclosed you will find the reports and the bills for the samples that we received on June 10th from the Mt. Holly Vermont site, file number 91-310.

Three of the samples contained BTEX and/or MTBE compounds at moderate levels, they also contained other 'petroleum hydrocarbons' typical of gasoline contamination. No chlorinateds were seen. The one stream sample contained only a trace of m&p Xylene, and o-Xylene at less than 1 ppb, which was not reported.

If you have any questions about the results or the bills, please give us a call. Thank you for your patronage.

Sincerely,

Kathleen S. Rice



AQUARIAN ANALYTICAL INC.

Laboratory Services

P.O. Box 186

Canterbury, N.H. 03224

603-783-9097

Volatile Organic Report

06-12-91, 19:18

Sample 1696

Date Sampled = 06-09-91, 17:00
 Date Logged In = 06-10-91, 14:32
 Date of Analysis = 06-12-91

Sampler = R.K.
 Location = #91-310, MW-1
 Town = MT. HOLLY

Organic Compound	Result (ppb)	Det. Lim. (ppb)	MCL
Bromodichloromethane	BD	1	
Chlorodibromomethane	BD	1	
Bromoform	BD	1	-> 100
Chloroform	BD	1	Tot. THM
Carbon Tetrachloride	BD	1	
dichloromethane	BD	2	5
1,1-dichloroethane	BD	1	5
1,2-dichloroethane	BD	1	
1,1,1-trichloroethane	BD	1	5
1,1,2-trichloroethane	BD	1	200
1,1-dichloroethylene	BD	1	3
Trichloroethylene	BD	1	7
Tetrachloroethylene	BD	1	5
1,2-Dichloroethylene (c)	BD	1	5
1,2-Dichloroethylene (t)	BD	1	70c
Chloroethane	BD	1	100t
Vinylchloride	BD	1	
Bromomethane	BD	5	2
Chloromethane	BD	5	
Trichlorofluoromethane	BD	1	
Benzene	BD	1	5
Toluene	BD	1	
Ethylbenzene	BD	1	2000
m&p-Xylene	BD	1	700
o-Xylene	BD	1	10000
Chlorobenzene	BD	1	- Tot. (o+m+p)
1,2-dichlorobenzene	BD	2	100
1,3-dichlorobenzene	BD	2	600
1,4-dichlorobenzene	BD	2	
1,2,4-trichlorobenzene	BD	2	75
Styrene	BD	1	9
Acetone	BD	1	5
Tetrahydrofuran	BD	50	
Diethylether	BD	25	
Methyl t-butyl ether	BD	15	
Methyl isobutyl ketone	BD	3	
Methyl ethyl ketone	BD	25	
Carbon Disulfide	BD	25	
1,1,2-trichloro 1,2,2-	BD	2	
trifluoroethane	BD	1	

Comments:

Method of Analyses = EPA-624

Certified - N.H., Conn., Mass., Maine, EPA-624/524

BD = Below Detection Limit - The above analyses included compounds not listed on this page. Results are in parts per billion (ppb) unless noted.



AQUARIAN ANALYTICAL INC.

Laboratory Services

P.O. Box 186

Canterbury, N.H. 03224

603-783-9097

Volatile Organic Report

06-12-91, 19:18

Sample 1697

Date Sampled = 06-09-91, 17:00

Date Logged In = 06-10-91, 14:35

Date of Analysis = 06-12-91

Sampler = R.K.

Location = #91-310, MW-2

Town = MT. HOLLY

Organic Compound	Result (ppb)	Det. Lim. (ppb)	MCL
Bromodichloromethane	BD	50	
Chlorodibromomethane	BD	50	
Bromoform	BD	50	-> 100
Chloroform	BD	50	Tot. THM
Carbon Tetrachloride	BD	50	5
dichloromethane	BD	100	5
1,1-dichloroethane	BD	50	
1,2-dichloroethane	BD	50	5
1,1,1-trichloroethane	BD	50	200
1,1,2-trichloroethane	BD	50	5
1,1-dichloroethylene	BD	50	7
Trichloroethylene	BD	50	5
Tetrachloroethylene	BD	50	5
1,2-Dichloroethylene (c)	BD	50	70c
1,2-Dichloroethylene (t)	BD	50	100t
Chloroethane	BD	50	
Vinylchloride	BD	50	2
Bromomethane	BD	250	
Chloromethane	BD	250	
Trichlorofluoromethane	BD	50	
Benzene	87	50	5
Toluene	129	50	2000
Ethylbenzene	50	50	700
m&p-Xylene	383	50	- 10000
o-Xylene	207	50	- Tot. (o+m+p)
Chlorobenzene	BD	50	100
1,2-dichlorobenzene	BD	100	600
1,3-dichlorobenzene	BD	100	
1,4-dichlorobenzene	BD	100	
1,2,4-trichlorobenzene	BD	100	75
Styrene	BD	50	9
Acetone	BD	2500	5
Tetrahydrofuran	BD	1250	
Diethylether	BD	750	
Methyl t-butyl ether	BD	150	
Methyl isobutyl ketone	BD	1250	
Methyl ethyl ketone	BD	1250	
Carbon Disulfide	BD	100	
1,1,2-trichloro 1,2,2-trifluoroethane	BD	50	

Comments:

Other petroleum hydrocarbons were present.

Method of Analyses = EPA-624

Certified - N.H., Conn., Mass., Maine, EPA-624/524

BD = Below Detection Limit - The above analyses included compounds not listed on this page. Results are in parts per billion (ppb) unless noted.



AQUARIAN ANALYTICAL INC.

Laboratory Services

P.O. Box 186

Canterbury, N.H. 03224

603-783-9097

Volatile Organic Report

06-12-91, 19:18

Sample 1698

Date Sampled = 06-09-91, 17:00

Date Logged In = 06-10-91, 14:37

Date of Analysis = 06-12-91

Sampler = R.K.

Location = #91-310, MW-3

Town = MT. HOLLY

Organic Compound	Result (ppb)	Det.	Lim. (ppb)	MCL
Bromodichloromethane	BD	1	-	
Chlorodibromomethane	BD	1	-	-> 100
Bromoform	BD	1	-	Tot. THM
Chloroform	BD	1	-	
Carbon Tetrachloride	BD	1	-	5
dichloromethane	BD	2		5
1,1-dichloroethane	BD	1		
1,2-dichloroethane	BD	1		5
1,1,1-trichloroethane	BD	1		200
1,1,2-trichloroethane	BD	1		5
1,1-dichloroethylene	BD	1		7
Trichloroethylene	BD	1		5
Tetrachloroethylene	BD	1		5
1,2-Dichloroethylene (c)	BD	1		70c
1,2-Dichloroethylene (t)	BD	1		100t
Chloroethane	BD	1		
Vinylchloride	BD	1		2
Bromomethane	BD	5		
Chloromethane	BD	5		
Trichlorofluoromethane	BD	1		
Benzene	85	1		5
Toluene	56	1		2000
Ethylbenzene	47	1		700
m&p-Xylene	278	1		- 10000
o-Xylene	57	1		- Tot. (o+m+p)
Chlorobenzene	BD	1		100
1,2-dichlorobenzene	BD	2		600
1,3-dichlorobenzene	BD	2		
1,4-dichlorobenzene	BD	2		
1,2,4-trichlorobenzene	BD	2		75
Styrene	BD	2		9
Acetone	BD	1		5
Tetrahydrofuran	BD	50		
Diethylether	BD	25		
Methyl t-butyl ether	BD	15		
Methyl isobutyl ketone	3	3		
Methyl ethyl ketone	BD	25		
Carbon Disulfide	BD	25		
1,1,2-trichloro 1,2,2-trifluoroethane	BD	2		
		1		

Comments:

Other petroleum hydrocarbons were present.

Method of Analyses = EPA-624

Certified - N.H., Conn., Mass., Maine, EPA-624/524

BD = Below Detection Limit - The above analyses included compounds not listed on this page. Results are in parts per billion (ppb) unless noted.



AQUARIAN ANALYTICAL INC.

Laboratory Services

P.O. Box 186

Canterbury, N.H. 03224

603-783-9097

Volatile Organic Report

06-12-91, 19:18

Sample 1699

Date Sampled = 06-09-91, 17:00

Sampler = R.K.

Date Logged In = 06-10-91, 14:38

Location = #91-310, MW-4

Date of Analysis = 06-12-91

Town = MT. HOLLY

Organic Compound	Result (ppb)	Det. Lim. (ppb)	MCL
Bromodichloromethane	BD	1	-
Chlorodibromomethane	BD	1	-
Bromoform	BD	1	-> 100
Chloroform	BD	1	Tot. THM
Carbon Tetrachloride	BD	1	5
dichloromethane	BD	2	5
1,1-dichloroethane	BD	1	5
1,2-dichloroethane	BD	1	5
1,1,1-trichloroethane	BD	1	200
1,1,2-trichloroethane	BD	1	5
1,1-dichloroethylene	BD	1	7
Trichloroethylene	BD	1	5
Tetrachloroethylene	BD	1	5
1,2-Dichloroethylene (c)	BD	1	70c
1,2-Dichloroethylene (t)	BD	1	100t
Chloroethane	BD	1	
Vinylchloride	BD	1	2
Bromomethane	BD	5	
Chloromethane	BD	5	
Trichlorofluoromethane	BD	1	
Benzene	6	1	5
Toluene	4	1	2000
Ethylbenzene	59	1	700
m&p-Xylene	529	1	- 10000
o-Xylene	284	1	Tot. (o+m+p)
Chlorobenzene	BD	1	100
1,2-dichlorobenzene	BD	2	600
1,3-dichlorobenzene	BD	2	
1,4-dichlorobenzene	BD	2	75
1,2,4-trichlorobenzene	BD	2	9
Styrene	BD	1	5
Acetone	BD	50	
Tetrahydrofuran	BD	25	
Diethylether	BD	15	
Methyl t-butyl ether	BD	3	
Methyl isobutyl ketone	BD	25	
Methyl ethyl ketone	BD	25	
Carbon Disulfide	BD	2	
1,1,2-trichloro 1,2,2-trifluoroethane	BD	1	

Comments:

Other petroleum hydrocarbons were present.

Method of Analyses = EPA-624

Certified - N.H., Conn., Mass., Maine, EPA-624/524

BD = Below Detection Limit - The above analyses included compounds not listed on this page. Results are in parts per billion (ppb) unless noted.



AQUARIAN ANALYTICAL INC.

Laboratory Services

P.O. Box 186

Canterbury, N.H. 03224

603-783-9097

Volatile Organic Report

06-12-91, 19:18

Sample 1700

Date Sampled = 06-09-91, 17:00
Date Logged In = 06-10-91, 14:38
Date of Analysis = 06-12-91

Sampler = R.K.
Location = #91-310, STREAM
Town = MT. HOLLY

Table with 4 columns: Organic Compound, Result (ppb), Det. Lim. (ppb), MCL. Lists various compounds like Bromodichloromethane, Chlorodibromomethane, etc., with their respective results and limits.

Comments:

Method of Analyses = EPA-624

Certified - N.H., Conn., Mass., Maine, EPA-624/524

BD = Below Detection Limit - The above analyses included compounds not listed on this page. Results are in parts per billion (ppb) unless noted.

