

Phase 2 Stream Geomorphic Assessment

**Trout River Watershed
Towns of Berkshire, Enosburg, Richford, and Montgomery
Franklin County, Vermont**

April 2007



**Prepared for:
Missisquoi River Basin Association
2839 VT Route 105
East Berkshire, VT 05447**

April 27, 2007

Ms. Cynthia Scott
Missisquoi River Basin Association
2839 VT Route 105
East Berkshire, VT 05447

Re: Phase 2 Stream Geomorphic Assessment
Trout River Watershed
Franklin County, Vermont
JCO Project No. 3-1313-2

Dear Ms. Scott:

The Johnson Company is pleased to present the following Phase 2 Stream Geomorphic Assessment report to the Missisquoi River Basin Association (MRBA). This report includes the results of Phase 2 Geomorphic Assessments performed in accordance with the Vermont Agency of Natural Resources (VTANR) Stream Geomorphic Assessment Protocols on 20 reaches of the Trout River mainstem and its tributaries.

Should you have any questions or require additional assistance, please do not hesitate to contact me at (802) 229-4600. Thank you for the opportunity to be of assistance to the MRBA on this project.

Sincerely,

THE JOHNSON COMPANY, INC.

By: _____


Adam Robtoy
Project Scientist

C: Staci Pomeroy, VTANR

EXECUTIVE SUMMARY

The Johnson Company was retained by Missisquoi River Basin Association (MRBA) to perform Phase 2 Geomorphic Assessments on 20 reaches within the Trout River Watershed during the summer of 2006. In addition, Bridge and Culvert Assessments were conducted on all structures within the 20 reaches. All of the Phase 2 Assessments were conducted in accordance with the 2006 Vermont Agency of Natural Resources (VT ANR) Stream Geomorphic Assessment Protocols (VT ANR 2006) Steps 1-7. All of the collected data were recorded on the VT ANR Phase 2 data sheets and entered into the VT ANR Stream Geomorphic Assessment Web Based Data Management System (DMS). A thorough internal QA review was performed by The Johnson Company in December 2006. An independent QA review was performed by VT ANR in January 2007 and the Phase 1 and 2 DMS were updated on February 23 – 28, 2007. Goals and Objectives for the project included the following:

- Determine the existing stream type for each targeted reach and field verify the previously collected Phase 1 Assessments;
- Conduct geomorphic condition evaluations for each reach which detail the current condition and sensitivity to existing and future natural and anthropogenic stressors;
- Collect and interpret the Phase 2 data to assess which reaches are responding to anthropogenic and natural modifications, and help prioritize which reaches warrant further study and/or restoration activities;
- Identify potential restoration and or conservation projects within the study area to increase the sediment and nutrient retention potential within the watershed;
- Educate the public about the results of the study and the need for future work.

Individual narratives for each assessed reach are included in Section 4.2 and copies of the VT ANR Data Printouts are included in Appendix A. Based on the field measurements taken during the Phase 2 Assessments, it appears most of the assessed reaches in the watershed are in evolution stage II (degradation) or III (widening). A description of the different channel evolution stages can be found in the VT ANR Stream Geomorphic Assessment Protocols, which may be found online at: http://www.anr.state.vt.us/dec/waterq/rivers/htm/rv_geoassess.htm. Historic dredging, channelization and human encroachments are the likely cause of the observed adjustments occurring in the watershed. Several reaches have undergone a stream type departure in response to these changes and no longer have access to their historic floodplain.

Of the 23 structures assessed within the watershed three were identified as being undersized and/or at risk of structural damage during future flood events. These structures are described in Section 4.4 below. Many of the other bridges were identified as localized channel and floodplain constrictions and may be contributing to the adjustment processes observed. During future bridge replacement projects the collected data should be used to ensure that the new bridges are correctly sized.

Based on the results of the Phase 2 Assessments and visual observations, potential restoration/corridor protection projects identified within the watershed are described below. Photos of some of the project areas are shown in Section 4.2.

- **Reach M02** – Priorities for this reach include addressing the major erosion occurring just downstream of Longley Bridge. Given the proximity of Route 118 and Longley Bridge Road some form of bank stabilization will be needed to protect these assets. In addition to the stabilization measures, buffer enhancement and some form of corridor protection and/or floodplain restoration should also be implemented at this site to increase the sediment and nutrient retention potential of the reach and prevent future landowner conflicts.
- **Reach M03** – The restoration/conservation technique for this reach involves protection of the river corridor in Segment B, which is the alluvial fan portion of the reach. This area is inherently unstable and will likely undergo significant planform adjustments during future flood events. Protecting the corridor from development will allow this segment to continue to function as a sediment and nutrient storage area and prevent future conflicts both within the reach and in upstream and downstream reaches.
- **Reach T3-01** – Two major problems were identified in T3-01. One is an eroding bank and failed rip-rap in the middle of the reach which is threatening a nearby mobile home. Given the current level of residential development in this area the only valid restoration technique appears to be re-stabilization of the eroding bank to prevent future structural damage. The other area of concern in T3-01 is the downstream end of the reach which is on an alluvial fan. Currently a mobile home is located in the floodplain and may be damaged during future flood events. In order to retain this important sediment and nutrient storage asset, the ideal project would involve moving the mobile home to restore the area to its natural depositional role. If this cannot be accomplished, then more traditional flood prevention measures may be required.
- **Reach T4-01** – Reach T4-01 is an incised reach which runs through agricultural land and suffers from a lack of floodplain access and adequate riparian buffers. The preferred restoration/conservation strategy for this reach is to protect the river corridor to allow the expected widening and aggradational processes to proceed as the channel re-establishes floodplain connection. It is expected that if the channel is allowed to evolve, over time, floodplain connection and a more natural meander pattern will be established which will enhance the sediment and nutrient retention potential of the reach and reduce excess erosion both in this reach and in upstream and downstream reaches. A key part of any corridor protection plan should include re-establishment of adequate woody buffers to filter out excess nutrients, stabilize streambanks, and improve wildlife habitat.
- **Reach T4-03** – Given the observed planform adjustments which have been documented in T4-03, and the expected future adjustments, a corridor protection plan should be established for reach T4-03. The plan would limit channel management and encroachments to allow for the expected widening, aggradation, and planform adjustments to occur as the channel evolves toward geomorphic equilibrium. A key part

of any corridor protection plan should include re-establishment of adequate woody buffers to filter out excess nutrients, stabilize streambanks, and improve wildlife habitat.

- **Reach T4-04** – As with T4-01 and T4-03, the main restoration/conservation strategy for T4-04 involves re-establishment of adequate woody buffers and protection of the river corridor to allow the expected adjustments to occur which, over time, will bring the channel back toward equilibrium and enhance the nutrient and sediment storage capacity and reduce excess erosion.
- **Reach M1S1-01** – The main problem associated with this reach is the lack of riparian buffer and cattle access to the stream channel in the middle of the reach. The restoration strategy for M1S1-01 would involve fencing schemes to limit the cows' access to the stream channel and planting riparian buffers to prevent excess sediment and nutrients from entering the stream channel.

TABLE OF CONTENTS

1.0 PROJECT OVERVIEW	1
2.0 BACKGROUND INFORMATION	2
2.1 GEOGRAPHIC SETTING	2
2.2 GEOLOGIC SETTING.....	2
2.3 GEOMORPHIC SETTING	2
2.4 HYDROLOGY	3
2.5 ECOLOGICAL SETTING	4
3.0 METHODOLOGY	4
3.1 FLUVIAL GEOMORPHIC ASSESSMENT PROTOCOLS	4
3.2 QUALITY ASSURANCE AND QUALITY CONTROL.....	5
4.0 RESULTS	5
4.1 WATERSHED SCALE STRESSORS	5
4.1.1 <i>Trout River Mainstem and South Branch</i>	<i>5</i>
4.1.2 <i>Upper Watershed Tributaries</i>	<i>7</i>
4.2 REACH SCALE STRESSORS	7
4.2.1 <i>Reach M01</i>	<i>8</i>
4.2.2 <i>Reach M02</i>	<i>9</i>
4.2.3 <i>Reach M03</i>	<i>12</i>
4.2.4 <i>Reach M04</i>	<i>14</i>
4.2.5 <i>Reach M05</i>	<i>16</i>
4.2.6 <i>Reach T1-01</i>	<i>16</i>
4.2.7 <i>Reach T1-02</i>	<i>17</i>
4.2.8 <i>Reach T2-01</i>	<i>18</i>
4.2.9 <i>Reach T3-01</i>	<i>19</i>
4.2.10 <i>Reach T3-02</i>	<i>22</i>
4.2.11 <i>Reach T4-01</i>	<i>22</i>
4.2.12 <i>Reach T4-02</i>	<i>24</i>
4.2.13 <i>Reach T4-03</i>	<i>24</i>
4.2.14 <i>Reach T4-04</i>	<i>26</i>
4.2.15 <i>Reach T5-01</i>	<i>27</i>
4.2.16 <i>Reach T6-01</i>	<i>27</i>
4.2.17 <i>Reach T7-01</i>	<i>28</i>
4.2.18 <i>Reach M1S1.01</i>	<i>28</i>
4.2.19 <i>Reach M2S3.01</i>	<i>30</i>
4.2.20 <i>Reach M2S3.02</i>	<i>30</i>
4.3 BRIDGE AND CULVERT ASSESSMENTS	31
4.4 POTENTIAL PROJECT AREAS	33
5.0 REFERENCES.....	36

LIST OF FIGURES

Figure 1	M01 Cross-Section.....	9
Figure 2	M02 Areas of Extensive Bank Erosion.....	10
Figure 3	Bank Failure near Longley Bridge Road	11
Figure 4	Failed Riprap just Downstream of Longley Bridge.....	11
Figure 5	M03B and C.....	12
Figure 6	Alluvial Fan Portion of Reach M03.....	14
Figure 7	Reach M04 in village of Montgomery Center	15
Figure 8	Cross-Section location T1-01	17
Figure 9	Large Gravel Bar in T2-01A.....	19
Figure 10	T3-01A and B	20
Figure 11	Mobil Home in Floodplain T3-01A.....	21
Figure 12	Failed Riprap along T3-01B	22
Figure 13	Cross-Section T4-01 Showing High Incision	24
Figure 14	T4-03.....	25
Figure 15	Bank Failure and Debris along T4-03.....	26
Figure 16	Cross-Section Location Reach t7-01	28
Figure 17	M1S1-01	29
Figure 18	Barnyard located in M1S1.01	30
Figure 19	T1-01 Bridge.....	32
Figure 20	T2-01 Bridge Clogged with Sediment	32
Figure 21	T4-04 Bridge – South Branch Road.....	33

LIST OF APPENDICES

Appendix A	Phase 2 Data Management System Reports
Appendix B	Data Quality Assurance Summary Report
Appendix C	Reach Break Location Maps
Plate 1	Location of Reaches M01, M02, T1-02, T2-01, M1S1.01, M2 S3.02
Plate 2	Locations of Reaches M03, M04, T3-01, T3-02, and T5-01
Plate 3	Locations of Reaches Mo5, T4-01, T4-02, T4-03, T4-04

1.0 PROJECT OVERVIEW

The Johnson Company was retained by Missisquoi River Basin Association (MRBA) to perform Phase 2 Stream Geomorphic Assessments (SGAs) on 20 reaches of the Trout River mainstem and its associated tributaries during the summer of 2006 (Plates 1-3). Funding for the project was provided by the Vermont Agency of Natural Resources (VT ANR) Rivers Management Program. Assistants from MRBA aided The Johnson Company in the collection of field data, and notification of landowners within the study area. Quality Assurance responsibilities were coordinated between The Johnson Company and VT ANR. A Phase 1 SGA of the watershed was completed by Northwest Regional Planning Commission in 2004.

The Trout River watershed encompasses approximately 86 square miles within the towns of Berkshire, Enosburg, Richford, Montgomery, and Westfield and is a major tributary of the Missisquoi River. The study area included the entire mainstem of the Trout River from its confluence with the Missisquoi River to its head waters at the confluence of the South Branch and Jay Brook (reaches M01 through M05) in addition to one or more reaches on each of the seven major tributaries to the Trout River. The reaches were selected during a meeting between VT ANR, MRBA, and The Johnson Company in the spring of 2006.

Goals and Objectives for the project included the following:

- Determine the existing stream type for each targeted reach and field verify the previously collected Phase 1 Assessments;
- Conduct geomorphic condition evaluations for each reach which detail the current condition and sensitivity to existing and future natural and anthropogenic stressors;
- Collect and interpret the Phase 2 data to assess which reaches are responding to anthropogenic and natural modifications, and help prioritize which reaches warrant further study and/or restoration activities;
- Identify potential restoration and or conservation projects within the study area to increase the sediment and nutrient retention potential within the watershed;
- Educate the public about the results of the study and the need for future work.

2.0 BACKGROUND INFORMATION

2.1 GEOGRAPHIC SETTING

The Trout River watershed encompasses approximately 86 square miles within the towns of Berkshire, Enosburg, Richford, Montgomery, and Westfield and is a major tributary of the Missisquoi River which flows into Lake Champlain. The watershed elevation ranges from approximately 400 feet above mean sea level at the confluence with the Missisquoi to more than 3,000 feet at the upstream end of its tributaries. Plate 1 through 3 show the reaches which were studied as part of this assessment.

The watershed is and has historically been dominated by agricultural activities along the mainstem downstream of Montgomery Center and along most of the South Branch. The remainder of the watershed is dominated by forest land and residential properties. Residential development has grown substantially in the past few decades, though a majority of the land area is still sparsely populated by comparison to more urban areas.

2.2 GEOLOGIC SETTING

The Trout River watershed is located in the northernmost part of the Green Mountains. Like other areas within Vermont, the area has been periodically covered by glaciers, the most recent of which occurred from approximately 10,000 to 30,000 years ago. Bedrock in the study area is dominated by a combination of the Underhill and Hazen's Notch Formations which are comprised of various types of quartzite (Doll 1961). The surficial geology is comprised of predominantly glacial till above approximately 2,000 feet and kame gravels and lake bottom sediments (Stewart and MacClintock 1970). Soils in the study area are dominated by silt loam, and loamy sands predominantly associated with the following series; Ondawa silt loam, Rumney silt loam, Winooski silt loam, Hadley silt loam, Podunk silt loam, and Colton loamy sand (USDA SCS 1979).

2.3 GEOMORPHIC SETTING

The locations of the assessed reaches are shown on Figures 1 and 2. The study area included the entire mainstem of the Trout River from its confluence with the Missisquoi River to

its head waters at the confluence of the South Branch and Jay Brook (reaches M01 through M05) in addition to one or more reaches on each of the seven major tributaries to the Trout River including Alder Brook, West Hill Brook, Black Falls Brook, South Branch, Jay Brook, and Wade Brook.

The channel slopes for the study area ranged from 0.5% to more than 4% within the watershed. Shallower slopes were observed on the Trout River mainstem and lower reaches of the major tributaries and generally ranged from 0.5% to 1.5%. Based on the field observations and review of topographic maps, portions of three of the reaches assessed are located on alluvial fans (M03B, T2-01A, and T3-01A). Bedrock grade controls were noted in several reaches throughout the study area including; M04, M05, T1-02, T2-01, T3-01, T3-02, T4-01, T4-02, T4-04, T5-01, T6-01, T7-01, and M2S3-02. The relatively frequent occurrence of these bedrock grade controls has served to mediate the impacts which have resulted from human caused disturbances by limiting potential upstream movement of bed degradation

Based on the Phase 1 data, the 20 reaches within the study have reference stream types of B and C which vary primarily due to valley and slope characteristics. The C-type streams included reaches M01, M02, M03, M05, T1-01, T4-01, T4-03, T4-04 and are characterized by wide valleys with slopes of less than 2% and substrate ranging from gravel to cobble. The remaining reaches are B type streams and have narrower valleys and steeper slopes.

2.4 HYDROLOGY

The nearest USGS gage for the study area is on the Missisquoi River near its confluence with the Trout River in East Berkshire. Based on the USGS data several flood events greater than 25 year discharge have occurred over the last 30 years including the years 1976, 1982, 1992, and 1997. The 1997 flood was one of the most destructive events in the area since the 1927 flood and caused severe damage to multiple homes, bridges and roads in the town of Montgomery.

2.5 ECOLOGICAL SETTING

The study area includes a variety of aquatic and upland habitat types which range from agricultural crop and pasture land to mixed hardwood and softwood forests. The majority of the aquatic habitat consists of riffle-pool and step-pool communities which have been affected by historic channel management and ongoing fluvial adjustment processes. Historically, as its name suggests, the Trout River was known for its fishing opportunities though in recent years the quality of the fishery has diminished due to loss of stable morphology, bank vegetation, and increased sedimentation and water temperatures (VT DEC, 2001). The majority of the riparian zone in the Trout River mainstem and South Branch consists of agricultural pasture and cropland intermixed with hardwood and softwood forests. Most of the other major tributaries are located in steeper valleys surrounded by mixed forest with sparsely distributed residential properties.

3.0 METHODOLOGY

3.1 FLUVIAL GEOMORPHIC ASSESSMENT PROTOCOLS

All of the Phase 2 SGAs were conducted in accordance with the 2006 Vermont Agency of Natural Resources (VT ANR) Stream Geomorphic Assessment Protocols (VT ANR 2006) Steps 1-7. All of the collected data were recorded on the VT ANR Phase 2 data sheets and entered into the VT ANR Stream Geomorphic Assessment Web Based Data Management System (DMS) and Feature Index Tool (FIT). Copies of the DMS Reports are provided in Appendix A. Following a thorough quality assurance (QA) review, the previously collected Phase 1 data were updated based on the findings of the Phase 2 Assessments. Bridge and Culvert Assessments were also conducted throughout the study area and the collected data were recorded on the appropriate VT ANR Bridge and Culvert Data Sheets and later entered into the VT ANR Bridge and Culvert Database.

In accordance with the protocols each reach was walked in its entirety prior to collecting any measurements to allow for reach segmentation where appropriate and identification of potential bankfull identifiers and cross section locations. A detailed Site Sketch Map was created for each reach documenting the locations of cross sections, photo points, pebble counts,

bank erosion and revetments, grade controls, debris jams, depositional features, channel cut-offs and avulsions, and other important features. Cross sections were measured at representative locations within each reach using a staff gauge and measuring tape.

3.2 QUALITY ASSURANCE AND QUALITY CONTROL

A thorough internal QA review was performed by The Johnson Company in December 2006. An independent QA review was performed by VT ANR in January 2007 and the Phase 1 and 2 DMS were updated on February 23 – 28, 2007. Appendix B contains the QA summary for the Trout River Project. No major quality assurance issues were identified during the QA process. Some of the stream types and geomorphic assessment scores were modified from what was originally assigned, though overall the collected data was found to be useable with no major restrictions or qualifications. All of the collected data is stored in the DMS and original copies of the data sheets may be found at The Johnson Company's office in Montpelier, VT.

4.0 RESULTS

The following section presents the results of the Phase 2 SGA data for the Trout River watershed. Section 4.1 summarizes the watershed scale stressors on the physical stability and habitat conditions of the project area. Section 4.2 summarizes the Phase 2 data, discusses the reach scale stressors, and for applicable areas, describes potential restoration and conservation projects. The Phase 2 SGA data are summarized in Appendix A.

4.1 WATERSHED SCALE STRESSORS

The watershed scale stressors for the Trout River have been broken down into two watershed zones, the Trout River mainstem and South Branch, and the upper watershed tributaries. These two zones have distinctly different characteristics and stressors so separating them will allow for a more logical discussion of the adjustment processes taking place.

4.1.1 Trout River Mainstem and South Branch

This watershed area is characterized by those reaches with a C reference stream type including nearly the entire mainstem of the Trout River and South Branch. The area is located within a relatively wide valley with shallow channel slopes. Land use in this region is dominated by agricultural land and rural residential development including the villages of Montgomery and Montgomery Center.

4.1.1.1 Hydrologic Regime

The Trout River is one of the few large river networks in Vermont that is not currently dammed. Remnants of old dams, which have long since been removed, were noted in reaches T4-02, and T5-01, however both were constructed in naturally occurring bedrock gorges and were only large enough to provide a localized hydraulic alteration. Urban land use is present in two areas within the watershed, the villages of Montgomery and Montgomery Center; however the affects of these developed areas on the hydraulic regime of the watershed are relatively minimal. Very few direct stormwater inputs were observed and despite the relative high population density both towns still have a large amount of pervious land area to allow for infiltration. The more direct effects of these villages are the degree of channelization and sediment alterations related to them, which are discussed in Section 4.2 below.

4.1.1.2 Sediment Regime

As stated above, most of this region of the watershed is dominated by agricultural lands, particularly hay and corn fields. Several areas of erosion were noted, especially along those fields with little or no riparian buffer. Multiple large point bars and steep riffles were observed, an indication of the active widening and aggradational processes occurring in these lower reaches. Channel avulsions and braiding were also observed, particularly immediately downstream of Montgomery Center in the alluvial fan portion of M03. This area is inherently unstable as flows from the steeper tributaries upstream are funneled through the channelized portion of M04 and finally have space to dissipate their energy and sediment in the broad valley. As a whole this portion of the watershed is dominated by aggradational processes which are a

result of historic degradation which has caused loss of floodplain access. The channel is currently widening and aggrading to re-create this lost floodplain access.

4.1.2 Upper Watershed Tributaries

This area is characterized by the upper reaches of most of the major tributaries of the Trout River including Alder Brook, West Hill Brook, Black Falls Brook, Wade Brook, and Jay Brook. All of these streams run through relatively narrow v-shaped valleys with steeper slopes and are generally characterized as A and B-type streams. These steep narrow valleys have for the most part prevented large scale development in this area. The surrounding riparian corridor is dominated by mixed hardwood and softwood forest. Sparse residential properties are scattered throughout along with a network of roads and bridges but these developments have not adversely affected the hydraulic or sediment regimes of the area. Several mass failures were noted in this area, as the streams meander through the narrow valley and bump against the valley wall. Several bedrock gorges and grade controls are also present. In general, this portion of the watershed was found to be consistent with its historic hydraulic and sediment transport regime.

4.2 REACH SCALE STRESSORS

Below is a summary of the dominant reach scale stressors observed throughout the watershed organized for each reach. Each summary contains a description of the physical adjustment processes observed, the boundary conditions, and any potential restoration and/or conservation projects identified. Reference is made to the stage of channel evolution for each reach.

The basic evolution model has five stages. In Stage I the stream is in equilibrium condition. In Stage II stream degradation is triggered by some stressor whereby the stream bed elevation is lowered and the stream no longer has adequate access to its floodplain. Without floodplain access, which dissipates the energy during high flow events, the stream banks erode and the channel widens (Stage III). The widened channel does not have the force to move all of the sediment through the system so sediment buildup and aggradation occur and a new

floodplain begins to form at a lower elevation (Stage IV). Once the new floodplain is fully developed the stream is back in equilibrium (Stage V). Further information regarding stream evolution models can be found at

http://www.anr.state.vt.us/dec/waterq/rivers/htm/rv_geoassess.htm.

4.2.1 *Reach M01*

Reach M01 extends from the confluence with the Missisquoi River to the confluence with Alder Brook, approximately 2.5 miles upstream. The riparian corridor is dominated by agricultural land with buffer widths ranging from 5 to 50 feet. The reach was found to be in regime with its naturally occurring stream type of C-gravel riffle-pool. The major adjustment processes were found to be historic degradation and active minor aggradation and widening which placed the stream in evolution stage III nearing stage IV. The habitat and geomorphic assessment scores were 0.68 and 0.7, both in the “good” range. The sensitivity rating for M01 was high, meaning there is a high likelihood that further adjustments will occur in the future. The reach had an incision ratio of 1.3 and does have access to its floodplain during high flow events. Historic dredging was noted during the Phase 1 SGA, though no evidence of active dredging was observed. Some minor bar scalping was observed in the middle of the reach. This historic dredging is likely the cause of the degradation which has occurred. The active widening and aggradation are a response by the stream to regain connection to its floodplain. Extensive channel management work was done in this reach within the last few years during replacement of the Route 118 bridge. This work involved planform adjustments, bank stabilization with rip-rap, and tree planting. Several large areas of rip-rap were also observed downstream of the bridge.

Given the current adjustment processes and boundary conditions, no large scale restoration projects have been identified within this reach. It is likely that the reach may continue to widen slightly in some areas, and the aggradational processes will continue to re-establish floodplain connection. Attempts should be made to limit channel management in these areas to allow the channel to move toward geomorphic equilibrium. There are a few areas along

the reach where buffers could be widened to improve wildlife habitat and increase resistance to erosion. As with all of the studied reaches, future human encroachments within the river corridor should be avoided to prevent potential flooding and erosion hazards.



Figure 1: M01 Cross Section.

4.2.2 Reach M02

Reach M02 is located on the Trout River mainstem from the confluence with Alder Brook to the confluence with Black Falls Brook. Similar to Reach M01, this reach is dominated by agricultural land with buffers ranging from 5 to 100 feet. The reach was found to be in regime with its reference stream type of C-gravel riffle-pool. The dominant adjustment factors were historic degradation and active widening, aggradation, and planform adjustments. The reach was found to be in evolution stage III with habitat and geomorphic scores of 0.66 and 0.59 respectively and a sensitivity rating of very high. The incision ratio of 1.4 suggests that the reach has degraded but still has access to some of its floodplain during flow events slightly greater than bankfull. Historic dredging was noted during the Phase 1 SGA, and likely was responsible for

the degradation observed. No active dredging was observed throughout the reach. Multiple large point bars and steep riffles were observed as evidence of the widening and aggradation currently ongoing in the reach. Two major problem areas were observed in M02, both being large areas of bank erosion near Longley Bridge Road (Figures 2-4).




Figure 2: M02 Areas of Extensive Bank of Erosion



Figure 3: Bank Failure near Longley Bridge Road



Figure 4: Failed Rip Rap just Downstream of Longley Bridge.

The major restoration projects within M02 are centered on these areas of erosion shown in Figures 2 and 3 above. Both are relatively close to roads and will have to be stabilized sometime soon to protect the infrastructure. Given the widening, aggradation and planform adjustment processes currently ongoing within the reach, and the very high sensitivity to future adjustments, it would be important to incorporate some corridor protection in conjunction with the bank stabilization project to allow for areas where these anticipated adjustments could proceed without conflicting with human interests.

4.2.3 Reach M03




Figure 5: M03B and C

Reach M03 extends from the confluence with Black Falls Brook upstream to just north of Montgomery Center. The reach was segmented into three parts, M03A, M03B, and M03C. M03A and C were very similar and found to be in regime with their reference Phase 1 stream type of C-gravel, riffle-pool. Segment B is located in the southern portion of the reach and was found to be a braided D-type channel. The segment was characterized as an alluvial fan where the valley widens, and the river slows down as it comes out of the steeper valley above and drops out a great deal of sediment. This area is inherently unstable with an extreme sensitivity value, and saw a great deal of adjustments during the 1997 flood event. The Trout River Restoration Project was completed here by VT ANR in 2000, to restore some of the damage done during 1997. The work of the restoration project succeeded in moving this unstable section of stream away from the road and other vulnerable infrastructure to an area where it could naturally move around without causing further structural damage. All three segments were found to be in evolution stage III, with aggradation and widening to be the dominant adjustment processes. All three segments were found to be slightly incised, though they still have some access to their floodplain during high flow events. A few minor areas of erosion were noted throughout the reach, though most of the eroding banks have been rip-rapped. The riparian corridor was dominated by agricultural lands with sparse residential properties scattered along Route 118, which runs along the northern and eastern portions of the river corridor.



Figure 6: Alluvial Fan portion of Reach M03

The main restoration/conservation project associated with M03 is protection of the river corridor surrounding Segment B. This alluvial fan portion of the reach is inherently unstable and is an area where sediment deposits and channel migration are common during flood events so it is important to keep the river corridor free of potential human conflicts to allow for these expected adjustments to occur. Protecting this corridor may also prevent other conflicts further upstream and downstream by providing a release valve for adjustments to occur in Segment B which may prevent them from happening elsewhere.

4.2.4 Reach M04

Reach M04 extends from the upstream end of M03 to the confluence with Hannah Clark Brook. A majority of the reach runs through the village of Montgomery Center. The upstream end of the reach is dominated by a large bedrock gorge located at the confluence with Hannah Clark Brook. M04 was found to be an F-cobble stream which is a stream type departure from its reference B-type. The stream type departure is mainly caused by extensive channelization and degradation throughout Montgomery Center, which has caused the stream to lose access to its

floodplain. A majority of both banks of the reach are covered in rip-rap or gabion baskets to provide bank stability. The stream was found to be in evolution stage II, due to the historic degradation. The habitat and geomorphic assessment scores were 0.58 and 0.61 respectively, both in the “fair” category and the reach had a sensitivity rating of very high. The riparian corridor was dominated by residential property on both banks with forest and hay fields being the sub-dominant land use. Two flood chutes were noted on the right bank just downstream of the village where the rip-rap ends, which is expected as this is the first place in the reach where high flows can leave the channel.



Figure 7: Reach M04 in the village of Montgomery Center

Due to the extensive channel management and residential encroachment in this reach no restoration projects have been identified. In order to protect the human infrastructure here, the reach will have to continue to be managed in its current state. If possible, efforts should be made to limit further development within the river corridor to prevent damage when the next large scale flood event occurs. Implementing the corridor protection in M03B discussed above is also important to this reach as any encroachments or attempts to limit channel management downstream may instigate channel adjustments upstream in M04.

4.2.5 Reach M05

M05 extends from the bedrock grade control located near the confluence with Hannah Clark Brook to the confluence of Wade Brook and Jay Brook approximately 1 mile upstream. The reach was found to be in regime with its reference Phase 1 stream type (Cb-cobble) with a slope of 2.7%. The major adjustment processes were historic degradation and minor widening. Dredging was documented throughout the reach after the 1997 flood in the Phase 1 Assessment, however, no active dredging was observed during the Phase 2 Assessment. It is likely that this historic dredging initiated the degradation which accounted for the incision ratio of 1.4. Though moderately incised, the reach still has some access to its historic floodplain during high flow events. Several bedrock grade controls were noted throughout the reach, and were important in preventing upstream migration of any headcuts initiated during the historic dredging. The measured channel width of 60 feet was slightly wider than the reference width of 49 feet indicating that the channel is widening in response to the partial loss of floodplain connection. Despite the widening channel only minor areas of erosion were noted. The habitat and geomorphic assessment scores were 0.81 and 0.84, in the “good” range and close to reference conditions. The sensitivity rating for M05 was moderate, meaning that it is less likely to undergo further adjustments than the other mainstem reaches. The riparian corridor was dominated by forest land with virtually no human encroachments observed. No restoration projects were identified in this reach as no major problem areas were noted. The reach appears to be relatively stable and there are no human encroachments which threaten its ability to adjust to future changes.

4.2.6 Reach T1-01

Reach T1-01 is the downstream end of Alder Brook, the first major tributary of the Trout River. This reach extends from the confluence with the Trout just upstream of Hopkins Bridge Road to approximately 1 mile upstream where the valley narrows and the stream channel steepens. The reach was found to be in regime with its Phase 1 reference type (C-gravel, riffle pool) and the dominant adjustment processes were minor aggradation and widening, placing the stream in evolution stage III with a high sensitivity rating. The habitat and geomorphic scores

were 0.7 and 0.72 respectively, both in the “good” range. With an incision ratio of 1.2, the stream still has access to most of its historic floodplain. Some minor planform adjustments in the form of enlarged bars and a future potential neck cut-off were observed at the downstream end of the reach near the confluence with the Trout River. The riparian corridor was dominated by hay and pasture on the right and forest on the left. Buffer widths ranged from 5 feet to >100 feet. Overall the reach appeared relatively stable with no major problem areas noted. No large scale restoration and/or conservation projects were identified for this reach.



Figure 8: Cross Section location T1-01

4.2.7 Reach T1-02

Reach T1-02 is located from the end of T1-01 to just north of the culvert located on Wightman Hill Road, approximately 1.5 miles upstream. The reach was found to be in regime with its Phase 1 reference stream type (B-cobble). The habitat and geomorphic scores were 0.85 and 0.90 respectively, both in the “reference” range and the reach was found to be in evolution stage I with a low sensitivity rating. No major adjustment processes were noted and the reach appeared to be relatively stable. Several bedrock grade controls and waterfalls were located

throughout the reach. The riparian corridor was almost completely forested with the exception of immediately adjacent to the culvert along Wightman Hill Road. No restoration or conservation projects have been identified in this reach.

4.2.8 Reach T2-01

Reach T2-01 (West Hill Brook) extends from its confluence with the Trout to the large bedrock gorge located approximately ½ mile upstream. The reach was segmented in T2-01A and T2-01B. T2-01A is the lower ½ of the reach downstream of the Route 118 bridge and is located on an alluvial fan. The segment was found to be in regime with its Phase 1 reference stream type (C-gravel). The habitat and geomorphic scores were 0.54 (fair) and 0.73 (good) respectively. As expected with an alluvial fan, the dominant adjustment processes were aggradation and widening with lots of large gravel bars observed and the reach was found to be in evolution stage III. The reach had a very high sensitivity rating, meaning that it will likely continue to undergo further aggradation and widening in the future. Historic dredging was noted during the Phase 1 Assessment, though no active dredging was observed. The incision ratio of 1.3 suggests that historic degradation had occurred, though the channel is actively aggrading and does have access to most of its historic floodplain. No major areas of erosion were noted. The riparian corridor was dominated by corn and hay fields intermixed with small patches of forest with buffer widths averaging 5 to 50 feet. The bridge which separates the two segments was heavily clogged with gravel. See Section 4.3 for recommendations.

T2-01B is the upper ½ of the reach and was found to be a B-gravel stream due to its steeper slope and narrower valley. The upper 300 feet of the segment was dominated by a large bedrock gorge which was excluded from the assessment. The habitat and geomorphic scores were 0.77 and 0.79, both in the “good” range. Historic degradation was found to be the dominant adjustment process, and with an incision ratio of 1.9. The reach has lost access to most of its historic floodplain and is in evolution stage II. A large portion of both banks was stabilized with rip-rap and gabion baskets, and the riparian corridor was dominated by residential development. Given the large amount of development, no restoration and/or conservation

projects were identified for this reach. Segment A is an alluvial fan, which is inherently unstable, so efforts should be made to prevent any future development on this portion of the reach.



Figure 9: large gravel bar in T2-01A

4.2.9 Reach T3-01

Reach T3-01 is the most downstream reach of Black Falls Brook and extends from its confluence with the Trout River upstream to the bridge on Black Falls Road. The reach was segmented into T3-01A and T3-01B due to differences in channel dimensions and reference stream types. T3-01A is the downstream end of the reach and was found to be an alluvial fan. The segment was in regime with its Phase 1 reference stream type (C-gravel) and in evolution stage III. Dominant adjustment processes were active aggradation, widening and planform adjustments and historic degradation. The habitat and geomorphic scores were 0.64 and 0.61, both fair conditions. Being an alluvial fan, the reach had a very high sensitivity rating. The incision ratio of 1.5 suggests that the stream still has some access to its historic floodplain during high flow events. Historic dredging was noted during the Phase 1 Assessment, though no active dredging was observed during the Phase 2 Assessment. The riparian corridor was dominated by corn and hay fields with some residential development on the left bank. Multiple floodchutes

and a channel avulsion were present showing the amount of historic adjustment the segment has undergone. The main problem area associated with this segment is the mobile home located within the floodplain in the lower part of the segment. The home was heavily damaged during the 1997 flood, and a newer structure was put in the same spot after the flood. Given the inherent instability of this segment, and the location of the current mobile home, it is likely that the structure will be further damaged during the next flood event if no action is taken. The most appropriate action for this area would be to move the mobile home out of the floodplain. Dredging or berming the stream would not be valid techniques here as they would simply transmit the instability of the area to upstream or downstream portions of the river.




Figure 10: T3-01A and B



Figure 11: Mobile Home in Floodplain T3-01A

T3-01B extends from a few hundred feet below Fuller Bridge upstream to Black Falls Road bridge and runs through Montgomery Village. The segment was found to be in regime with its reference stream type (B-cobble) and in evolution stage II with a moderate sensitivity rating. The dominant adjustment process was historic degradation. The habitat and geomorphic scores were 0.73 and 0.80 respectively, both in the good range. A majority of both banks were covered with rip-rap or other revetments. The riparian corridor was dominated by residential development with hay fields along the left bank near the upstream end of the segment. Given the extensive channelization and residential encroachment, no restoration projects were identified in this segment. One area of failed rip-rap and bank erosion was noted mid-segment which may soon threaten the mobile home located near it. In order to prevent structural damage, the streambank will have to be stabilized, or the structure will have to be moved.



Figure 12: Failed Rip-Rap along T3-01B

4.2.10 Reach T3-02

Reach T3-02 extends from the Black Falls Road bridge at the end of T3-01 upstream approximately 1 mile to a large bedrock waterfall. The reach was found to be in regime with its Phase 1 reference stream type (B-cobble). The stream was determined to be in reference condition with habitat and geomorphic scores of 0.86 and a moderate sensitivity rating. No major adjustment processes were noted. One large mass failure was noted in the lower portion of the segment where the stream has bumped against the valley wall. The riparian corridor was dominated by forest and several bedrock waterfalls and grade controls were observed. Overall the reach appeared relatively stable, and no restoration and/or conservation projects were identified.

4.2.11 Reach T4-01

Reach T4-01 is the most downstream reach of the South Branch tributary. It extends from its confluence with the Trout River in Montgomery Center upstream to Hutchins Bridge Road. The upper portion of the reach was not included in the assessment as it was dominated by a large bedrock gorge. The reach was in regime with its Phase 1 reference stream type (C-gravel) though historic degradation has placed the stream in evolution stage II with a high

sensitivity rating. Historic dredging and possible straightening were noted during the Phase 1 Assessment which likely is responsible for the relatively high incision ratio of 1.8 measured during the Phase 2 Assessment. No active dredging or channelization was observed during the Phase 2 Assessment. The dominant adjustment process was the historic degradation, with minor active widening. The riparian corridor was dominated by agricultural activities, namely hay fields and pasture with relatively narrow buffers between 5 and 25 feet. A significant amount of rip-rap was present on both banks, and consequently relatively minor amounts of bank erosion were observed.

The major restoration opportunity associated with this reach is protection of the river corridor and establishment of adequate buffers. Given the historic stressors and current evolution stage it is likely that the reach will undergo significant adjustment processes to re-establish floodplain connection and a more natural meander pattern. Protecting the river corridor will allow for these adjustment processes to take place without human related conflicts and allow the stream to move toward geomorphic equilibrium. Alternatively, a more active floodplain restoration effort could be used to re-establish floodplain connection by lowering the adjacent streambanks with heavy equipment. Enhancing the current woody buffer would improve wildlife habitat and help prevent excess erosion.



Figure 13: Cross Section T4-01 Showing High Incision

4.2.12 Reach T4-02

Reach T4-02 extends from Hutchins Road bridge upstream for approximately 1 mile to where the valley widens. The reach was in regime with its Phase 1 reference stream type (B-cobble) and found to be in reference condition or evolution stage I. The habitat and geomorphic scores were 0.89 and 0.86 respectively. No major adjustment processes were observed and overall the reach appeared to be stable giving it a moderate sensitivity rating. Historic dredging was noted in the Phase 1 Assessment but no active dredging was observed. The riparian corridor was dominated by forest with a few small hay fields mixed in. Overall, relatively wide riparian buffers were present averaging 50 to 100 feet. Five separate bedrock grade controls and/or waterfalls were noted throughout the reach. No restoration/conservation projects were identified within the reach.

4.2.13 Reach T4-03

Reach T4-03 extends from the end of T4-02 upstream for approximately $\frac{3}{4}$ mile to the Sundell Road Bridge. The reach was in regime with its Phase 1 reference stream type (C-gravel riffle pool) though major aggradation, widening, and planform adjustments were observed. The

habitat and geomorphic scores were 0.58 and 0.64, both in the “fair” range, and the reach was found to be in evolution stage III. Historic degradation has increased the incision ratio to 1.3, though the channel still has access to most of its historic floodplain during high flow events. Significant planform adjustments were observed between the Phase 1 river center line and the current meander centerline. Bar scalping was observed on a few of the large point bars in the middle of the reach. The riparian corridor was dominated by hay and corn fields with relatively narrow buffers ranging from 0 to 25 feet.




Figure 14: T4-03

Given the current adjustment processes observed, and the very high sensitivity rating, the most appropriate restoration/conservation projects for this reach are corridor protection and buffer enhancement. These techniques would allow the expected channel adjustments to occur

and the channel to reach geomorphic equilibrium while increasing the sediment and nutrient retention potential and improving wildlife habitat.



Figure 15: Bank failure and debris along T4-03

4.2.14 Reach T4-04

Reach T4-04 is located from just downstream of Sundell Road upstream for approximately 1 mile to the confluence with Pacific Brook. The stream type was found to be C-gravel riffle pool, which is consistent with the Phase 1 reference type. The habitat and geomorphic scores were 0.66 and 0.78, both in the “good” category, and the reach was found to be in evolution stage II. The dominant adjustment processes were minor historic degradation, and minor active aggradation. The incision ratio of 1.2 suggests that the stream has degraded, but still has some level of floodplain access. The riparian corridor was dominated by hay and corn fields on the right and forest on the left with buffers ranging from 5 to 100 feet. Based on visual observations it appears that the channel may have been straightened in the past, and bar scalping was observed near the bridge located on South Branch Road.

The main restoration project associated with this reach involves re-establishment of adequate buffers between the hay and corn fields along the right bank and the stream channel and protection of the river corridor to allow for the expected channel adjustments to occur.

4.2.15 Reach T5-01

Reach T5-01 (Hannah Clark Brook) extends from its confluence with the Trout just upstream of Montgomery Center to the first major tributary located near the Route 242 crossing. The habitat and geomorphic scores were 0.87 and 0.85 respectively. The stream was found to be in reference condition, with no major adjustment processes occurring and had a low sensitivity rating. The A cobble step pool stream type was consistent with the Phase 1 reference stream type. The riparian corridor was dominated by forest land with a few hay fields mixed in and buffers ranging from 50 to 100 feet. No major areas of erosion were noted. Remnants of a concrete dam were observed in the middle of the reach. The dam is no longer in place, but portions of the left abutment built into the existing bedrock were still visible. The dam no longer holds back any water and the channel width in this location is not significantly wider than it would be without the abutment. Several large bedrock grade controls and waterfalls were noted throughout the reach. No restoration and/or conservation projects were identified here.

4.2.16 Reach T6-01

Reach T6-01 (Jay Brook) extends from its confluence with Wade Brook in Montgomery upstream for approximately ½ mile to the first major tributary confluence. The B-cobble step pool stream type was consistent with its Phase 1 reference type. The stream was found to be in evolution stage III with historic degradation and minor active widening to be the dominant adjustment processes. Despite these adjustment processes the stream had a moderate sensitivity rating as B-cobble streams are more resistant to change than other stream types. Historic dredging was noted during the Phase 1 Assessment, though no active dredging was observed during the Phase 2 Assessment. The habitat and geomorphic scores were 0.83 and 0.79, both in the “good” range. The riparian corridor was dominated by forest with no observed human related encroachments. No major areas of bank erosion were noted with the exception of a few small bank failures in the lower portion of the reach. Overall, the reach appeared stable and no restoration/conservation projects were identified.

4.2.17 Reach T7-01

Reach T7-01 (Wade Brook) extends from the confluence with Jay Brook upstream for approximately 2 miles to the Amadon Road Bridge. The stream was found to be in reference condition with no major adjustment processes observed. The B-cobble step pool stream type was consistent with the Phase 1 reference type. The riparian corridor was dominated by forests on both sides with no human related encroachments observed. Multiple bedrock grade controls were noted throughout the reach. No major areas of erosion were noted with the exception of four mass failures located where the channel has bumped against the valley wall. Overall, the reach appeared relatively stable and no restoration/conservation projects were identified.



Figure 16: Cross Section Location Reach T7-01

4.2.18 Reach M1S1.01

Reach M1S1.01 is the first small unnamed tributary of the Trout located approximately 1 mile upstream of its confluence with the Missisquoi River. The reach extends from its confluence with the Trout upstream to where the valley narrows approximately $\frac{3}{4}$ mile upstream. The B-cobble step pool stream type was consistent with the Phase 1 reference stream type. The major adjustment factor was found to be historic degradation which has increased the incision ratio to 2.0. The habitat and geomorphic scores were 0.52 and 0.59 both in the “fair” range and the reach had a very high sensitivity rating. Active widening was observed in the downstream

end of the reach below the culvert crossing Route 118. The riparian corridor was dominated by pasture and hay fields and the middle of the reach runs through a barn yard where cows have access to the stream channel. Narrow buffers of 0 to 25 feet were observed throughout, except downstream of the Route 118 culvert where willow trees have been planted by Missisquoi River Basin Association providing adequate buffer space. The major restoration/conservation project associated with this reach is to exclude the cattle from the stream channel within the barnyard and increase the buffer widths throughout the reach.




Figure 17: M1S1.01



Figure 18: Barnyard located in M1S1.01

4.2.19 Reach M2S3.01

Reach M2S3.01 extends from its confluence with the Trout upstream for approximately ¼ mile to just beyond the arch crossing on Longley Bridge Road. The stream was found to be in regime with its Phase 1 reference stream type (B-cobble) and in evolution stage II. The habitat and geomorphic scores were 0.65 and 0.79 in the “good” range. The dominant adjustment process was historic degradation which has raised the incision ratio to 1.6. The stream has lost access to some of its historic floodplain except during high flow events larger than bankfull. The riparian corridor was dominated by pasture and hay fields with woody buffers averaging approximately 25 feet. No major areas of erosion were noted within the reach. Overall the reach appeared relatively stable, despite the historic degradation. No restoration/conservation projects were identified in this reach.

4.2.20 Reach M2S3.02

Reach M2S3.02 extends from just above the arch on Longley Bridge Road upstream for approximately 1.5 miles to the headwaters of the stream. The stream was found to be in regime with its Phase 1 reference stream type (B-cobble) and in evolution stage III. The habitat and geomorphic scores were 0.80, “good”. The dominant adjustment processes were found to be historic degradation and minor active widening and planform adjustments. Several mass failures

were noted where the stream has bumped against the relatively narrow valley walls. Several large debris jams were also noted near these locations and are contributing to the channel planform adjustments. Several large bedrock grade controls and waterfalls were observed throughout the reach. The riparian corridor was dominated by forest land with virtually no human related encroachments observed. No restoration/conservation projects were identified within the reach.

4.3 BRIDGE AND CULVERT ASSESSMENTS

A total of 23 Bridge and Culvert Assessments were completed within the study area. Summary reports from the VT ANR DMS are included in Appendix A. Of the 23 assessed structures, three were identified as being undersized and/or at risk of damage during future flood events. The three structures were located in reaches T1-01, T2-01, and T4-04. The structure in T1-01 is located on Route 118 just south of Hutchins Bridge Road. The structure is undersized and was found to be partially clogged with sediment. Similar problems were noted with the Route 118 Bridge located in T2-01 between West Hill and Hill West Roads. Both of these structures could be damaged during future flood events as the excess gravel may cause erosion around and/or under the abutments. The third structure located in T4-04 on South Branch Road was found to be slightly undersized and it appeared that the right abutment had been recently repaired. This is a private structure and significant manipulation of nearby gravel bars was observed upstream and downstream of the structure. Gravel was used to berm along the stream channel above and below the structure to prevent flooding and damage to the abutments. Pictures of the three bridges are shown below.



Figure 19: T1-01 Bridge



Figure 20: T2-01 Bridge Clogged with Sediment



Figure 21: T4-04 Bridge – South Branch Road

4.4 POTENTIAL PROJECT AREAS

Based on the results of the Phase 2 Assessments and visual observations, potential restoration/conservation projects identified within the watershed are described below. Each of the project areas is also discussed in the individual reach narratives in Section 4.2 along with photos and location maps. The projects identified are intended to reduce sediment and nutrient inputs into the watershed while allowing the stream to move toward geomorphic equilibrium conditions and reduce conflicts between neighboring landowners and the stream. It is important to note that many of these strategies are not short term fixes but long term solutions whose benefit may not be seen for some time. Historic techniques such as bank armoring, dredging and channelization may seem effective in the short term, but almost always fail during future flood events, and usually transmit channel instability upstream and downstream to other areas of the watershed. While these techniques may be required to protect infrastructure, it is important to also focus on larger scale restoration/conservation sites that will be beneficial to the watershed as a whole and reduce the future need for channel management activities.

- **Reach M02** – Priorities for this reach include addressing the major erosion occurring just downstream of Longley Bridge. Given the proximity of Route 118 and Longley Bridge Road some form of bank stabilization will be needed to protect these assets. In addition to the stabilization measures, buffer enhancement and some form of corridor protection and/or floodplain restoration should also be implemented at this site to increase the sediment and nutrient retention potential of the reach and prevent future landowner conflicts.
- **Reach M03** – The restoration/conservation technique for this reach involves protection of the river corridor in Segment B, which is the alluvial fan portion of the reach. This area is inherently unstable and will likely undergo significant planform adjustments during future flood events. Protecting the corridor from development will allow this segment to continue to function as a sediment and nutrient storage area and prevent future conflicts both within the reach and in upstream and downstream reaches.
- **Reach T3-01** – Two major problems were identified in T3-01. One is an eroding bank and failed rip-rap in the middle of the reach which is threatening a nearby mobile home. Given the current level of residential development in this area the only valid restoration technique appears to be re-stabilization of the eroding bank to prevent future structural damage. The other area of concern in T3-01 is the downstream end of the reach which is on an alluvial fan. Currently a mobile home is located in the floodplain and may be damaged during future flood events. In order to retain this important sediment and nutrient storage asset, the ideal project would involve moving the mobile home to restore the area to its natural depositional role. If this cannot be accomplished, then more traditional flood prevention measures may be required.
- **Reach T4-01** – Reach T4-01 is an incised reach which runs through agricultural land and suffers from a lack of floodplain access and adequate riparian buffers. The preferred restoration/conservation strategy for this reach is to protect the river corridor to allow the expected widening and aggradational processes to proceed as the channel re-establishes floodplain connection. It is expected that, over time, if the channel is allowed to evolve, floodplain connection and a more natural meander pattern will be established which will enhance the sediment and nutrient retention potential of the reach and reduce excess erosion both in this reach and in upstream and downstream reaches. A key part of any corridor protection plan should include re-establishment of adequate woody buffers to filter out excess nutrients, stabilize streambanks, and improve wildlife habitat.
- **Reach T4-03** – Given the observed planform adjustments which have been documented in T4-03, and the expected future adjustments, a corridor protection plan should be established for reach T4-03. The plan would limit channel management and encroachments to allow for the expected widening, aggradation, and planform adjustments to occur as the channel evolves toward geomorphic equilibrium. A key part of any corridor protection plan should include re-establishment of adequate woody buffers to filter out excess nutrients, stabilize streambanks, and improve wildlife habitat.
- **Reach T4-04** – As with T4-01 and T4-03, the main restoration/conservation strategy for T4-04 involves re-establishment of adequate woody buffers and protection of the river corridor to allow the expected adjustments to occur which, over time, will bring the

channel back toward equilibrium and enhance the nutrient and sediment storage capacity and reduce excess erosion.

- **Reach M1S1-01** – The main problem associated with this reach is the lack of riparian buffer and cattle access to the stream channel in the middle of the reach. The restoration strategy for M1S1-01 would involve fencing schemes to limit the cows' access to the stream channel and planting riparian buffers to prevent excess sediment and nutrients from entering the stream channel.

5.0 REFERENCES

Doll, Charles, Centennial Geologic Map of Vermont, State of Vermont Geologists Office, 1961.

http://www.anr.state.vt.us/dec/waterq/rivers/htm/rv_geoassess.htm

Northwest Regional Planning Commission, Phase 1 Geomorphic Assessment of the Trout River Watershed, 2004.

Stewart, D.P. and MacClintock, P., Surficial Geologic Map of Vermont; State of Vermont, 1970.

United States Department of Agriculture Soil Conservation Service, Soil Survey of Franklin County, Vermont, 1979.

Vermont Agency of Natural Resources, Department of Environmental Conservation, Trout River Project, A Natural Channel Restoration Project of the Vermont DEC River Management Program, January 5, 2001.

Vermont Agency of Natural Resources, Vermont Stream Geomorphic Assessment Phase 2 Handbook and Appendices, 2006.

APPENDIX A

PHASE 2 DATA MANAGEMENT SYSTEM REPORTS

Project: **Trout River Mouth**
Stream: **Trout River**
Organization: **Johnson Company**
Segment Length (ft): **13,591**

Phase 2 Segment Summary page 1 of 2
Reach # **M01**
Observers: **Adam Robtoy, Noelia**
Segment Location: **from confluence with Missisquoi to confluence with Alder Brook**

March 20, 2007
Completion Date: **July 6, 2006**
FIT: **Yes**
Rain: **Yes**

Step 1. Valley and Floodplain

1.1 Segmentation	None		
1.2 Alluvial Fan	No		
1.3 Corridor Encroachments			
Length (ft)	One	Both	
Berm	0	0	
Roads	209	0	
Railroads	0	0	
Improved Paths	0	0	
Development	93	0	
1.4 Adjacent Side	Left	Right	
Hillside Slope	Steep	Steep	
Continuous w/ Sometimes	Never		
W/in 1 Bankfill Sometimes	Never		
Texture	Bedrock	Not Evalua	
1.5 Valley Features			
Valley Width (ft)	1,470		
Width Determination	Estimated		
Confinement Type	Very Broad		
Rock Gorge?	No		
Human-caused changed valley width?	No		

Notes:

historic straightening, minor bar scalping on bar mid-reach, lower 1/4 of reach below new bridge on 118 slightly wider bankful width than upper portion of reach, lots of large point bars, extensive channel work (rip rap, tree planting, planform changes) for several hundred feet upstream of new bridge on Rt. 118, historic dredging noted on phase 1, no active dredging observed except for bar scalping noted above

Step 2. Stream Channel	112
2.1 Bankfull Width	6.00
2.2 Max Depth (ft)	4.90
2.3 Mean Depth (ft)	7.50
2.4 Floodprone Width (ft)	22.86
2.5 Aband. Floodpln	6.70
2.6 Width/Depth Ratio	1.25
2.7 Entrenchment Ratio	Moderate
2.8 Incision Ratio	Sedimented
2.9 Sinuosity	600
2.10 Riffles Type	
2.11 Riffle/Step Spacing (ft)	
2.12 Substrate Composition	
Bedrock	1 %
Boulder	0 %
Cobble	1 %
Coarse Gravel	40 %
Fine Gravel	26 %
Sand	32 %

Silt/Clay Present?	Yes
Detritus	20 %
# Large Woody	42
2.13 Average Largest Particle on	
Bed	163.0 mm
Bar	72.0 mm

2.14 Stream Type

Stream Type: **C**
Bed Material: **Gravel**
Subclass Slope: **None**

Bed Form: **Riffle-Pool**
2.15 Reference Stream Type
(if different from Phase 1)

Step 3. Riparian Features

3.1 Stream Banks	
Typical Bank Slope	Steep
Bank Texture	Left Right
Upper	
Material Type	Gravel
Consistency	Non-cohesive
Lower	
Material Type	Gravel
Consistency	Non-cohesive
Bank Erosion	Non-cohesive
Erosion Length (ft)	341
Erosion Height (ft)	7.00
Revetmt. Type	Rip-Rap
Revetmt. Length (ft)	1,634
Near Bank Veg. Type	Left Right
Dominant	Shrubs/Saplin Shrubs/Saplin
Sub-dominant	Deciduous
Bank Canopy	Left Right
Canopy %	26-50 26-50
Mid-Channel Canopy	Open

3.2 Riparian Buffer	
Buffer Width	Left Right
Dominant	26-50 26-50
Sub-dominant	5-25 5-25
Buffer Veg. Type	Left Right
Dominant	Shrubs/Saplin Shrubs/Saplin
Sub-dominant	Mixed Trees
3.3 Riparian Corridor	
Corridor Land	Left Right
Dominant	Hay Crop
Sub-dominant	Forest Hay
Mass Failures	Amount Mean Height
Gullies	None 0.00
	None 0.00

Step 4. Flow & Flow Modifiers

4.1 Springs / Seeps	Some
4.2 Adjacent Wetlands	Some
4.3 Flow Status	Moderate
4.4 # of Debris Jams	1
4.5 Impoundments	None
Impoundmt. Location	
4.6 # of Stormwater Inputs	0
4.7 Upstream Flow	None
4.9 # of Beaver Dams	0
Affected Length (ft)	0

Step 5. Channel Bed and Planform Changes

<u>5.1 Bar Types</u>		
<u>Mid</u>	<u>Point</u>	<u>Side</u>
2	11	6
<u>Diagonal</u>	<u>Delta</u>	<u>Island</u>
2	1	1

5.2 Other Features

Flood	Neck Cutoff	Avulsion	Braiding
2	0	0	1

5.3 Steep Riffles and Head Cuts

Steep Riffles	Head Cuts	Trib Rejuv.
1	0	No

5.4 Stream Ford or Animal

5.4 Stream Ford or Animal	Yes
---------------------------	-----

5.5 Straightening

5.5 Straightening	Yes
-------------------	-----

Straightening Length:

Straightening Length:	1,080
-----------------------	-------

5.5 Dredging

5.5 Dredging	Dredging
--------------	----------

Note:

Step 1.6 - Grade Controls and
Step 4.8 - Channel Constrictions
are on The second page of this
report - Steps 6 through 7.

1.6 Grade Controls None				
Type	Location	Total	Total Height Above Water	Photo Taken GPSTaken

Step 7. Rapid Geomorphic Assessment Data				
Confinement Type	Unconfined	Score	STD	Historic
7.1 Channel Degradation		14	None	Yes
7.2 Channel Aggradation		15	None	No
7.3 Widening Channel		12		No
7.4 Change in Planform		15		No
Total Score		56		
Geomorphic Rating		0.7		
Channel Evolution Model		F		
Channel Evolution Stage		III		
Geomorphic Condition		Good		
Stream Sensitivity		High		

Step 6. Rapid Habitat Assessment Data				
Stream Gradient Type	High	Score		
6.1 Epifaunal Substrate - Available Cover		14		
6.2 Embeddedness		9		
6.3 Velocity/Depth Patterns		18		
6.4 Sediment Deposition		11		
6.5 Channel Flow Status		14		
6.6 Channel Alteration		14		
6.7 Frequency of Riffles/Steps		16		
6.8 Bank Stability		Left: 8 Right: 8		
6.9 Bank Vegetation Protection		Left: 7 Right: 7		
6.10 Riparian Vegetation Zone Width		Left: 5 Right: 5		
Total Score		136		
Habitat Rating		0.68		
Habitat Stream Condition		Good		

Narrative:
historic minor degradation, active minor aggradation and widening

Project: **Trout River Mouth**
Stream: **Trout River**
Organization: **Johnson Company**
Segment Length (ft): **15,792**

Phase 2 Segment Summary page 1 of 2
Reach # **M02**
Observers: **Adam Robtoy, E. Crandell**
Segment Location: **from Alder Brook confluence to Black Falls Brook**

March 20, 2007 **FIT: Yes**
Completion Date: **August 18, 2006**
Rain: **No**

Step 1. Valley and Floodplain				Step 2. Stream Channel				Step 3. Riparian Features				Step 4. Flow & Flow Modifiers			
1.1 Segmentation None				2.1 Bankfull Width 102				3.1 Stream Banks				4.1 Springs / Seeps Some			
1.2 Alluvial Fan No				2.2 Max Depth (ft) 4.20				Typical Bank Slope Steep				4.2 Adjacent Wetlands Some			
1.3 Corridor Encroachments				2.3 Mean Depth (ft) 2.80				Bank Texture				4.3 Flow Status Moderate			
Length (ft) One Both				2.4 Floodprone Width (ft) 900				Upper				4.4 # of Debris Jams 0			
Berm 0				2.5 Aband. Floodpln 5.90				Material Type Gravel				4.5 Impoundments None			
Roads 783				2.6 Width/Depth Ratio 36.43				Consistency Non-cohesive				Impoundmt. Location			
Railroads 0				2.7 Entrenchment Ratio 8.82				Lower				4.6 # of Stormwater Inputs 0			
Improved Paths 0				2.8 Incision Ratio 1.40				Material Type Bedrock				4.7 Upstream Flow None			
Development 0				2.9 Sinuosity Moderate				Consistency Cohesive				4.9 # of Beaver Dams 0			
1.4 Adjacent Side				2.10 Riffles Type Sedimented				Bank Erosion Left				Affected Length (ft) 0			
Hillside Slope Steep				2.11 Riffle/Step Spacing (ft) 600				Erosion Length (ft) 2,806				Step 5. Channel Bed and Planform Changes			
Continuous w/Sometimes				2.12 Substrate Composition				Erosion Height (ft) 6.57				5.1 Bar Types			
W/in 1 Bankfill Sometimes				Bedrock 0 %				Revetmt. Type Rip-Rap				Mid			
Texture Bedrock				Boulder 0 %				Revetmt. Length (ft) 154				Point			
1.5 Valley Features				Cobble 30 %				Near Bank Veg. Type Left				Side			
Valley Width (ft) 1,214				Coarse Gravel 56 %				Dominant Herbaceous				Delta			
Width Determination Estimated				Fine Gravel 8 %				Sub-dominant Shrubs/Saplin Shrubs/Saplin				Island			
Confinement Type Very Broad				Sand 5 %				Bank Canopy Left				1			
Rock Gorge? No				Silt/Clay Present? No				Canopy % 26-50				Flood			
Human-caused changed valley width? no				Detritus 5 %				Mid-Channel Canopy Open				Neck Cutoff			
Notes:				# Large Woody 39				3.2 Riparian Buffer				Avulsion			
Lots of large point bars - aggradation and planform adjustments, portion of reach downstream of longley bridge slightly more incised (1.7) than remainder of reach. historic dredging noted in phase 1 assessment, no active dredging observed				2.13 Average Largest Particle on				Buffer Width Left				Braiding			
				Bed 140.0 mm				Dominant Mixed Trees				5.3 Steep Riffles and Head Cuts			
				Bar 100.0 mm				Sub-dominant Herbaceous				Steep Riffles			
				2.14 Stream Type				3.3 Riparian Corridor				Head Cuts			
				Stream Type: C				Corridor Land Left				Trib Rejuv.			
				Bed Material: Gravel				Dominant Forest				4			
				Subclass Slope: None				Sub-dominant Crop				5.4 Stream Ford or Animal No			
				Bed Form: Riffle-Pool				Amount Mean Height				5.5 Straightening Yes			
				2.15 Reference Stream Type				Mass Failures None				Straightening Length: 1,372			
				(if different from Phase 1)				Gullies None				5.5 Dredging None			
												Note:			
												Step 1.6 - Grade Controls and			
												Step 4.8 - Channel Constrictions			
												are on The second page of this			
												report - Steps 6 through 7.			

1.6 Grade Controls None				
Type	Location	Total	Total Height Above Water	Photo Taken GPSTaken
4.8 Channel Constrictions				
Type	Width	Photo Taken?	GPS Taken?	Channel Constriction?
Bridge	90.0	Yes	Yes	No
	Problem None			Yes
Bridge	160.	Yes	Yes	No
	Problem None			Yes
Step 6. Rapid Habitat Assessment Data				
Stream Gradient Type	High	Score		
6.1 Epifaunal Substrate - Available Cover		14		
6.2 Embeddedness		11		
6.3 Velocity/Depth Patterns		18		
6.4 Sediment Deposition		6		
6.5 Channel Flow Status		10		
6.6 Channel Alteration		15		
6.7 Frequency of Riffles/Steps		16		
6.8 Bank Stability		Left: 6 Right: 7		
6.9 Bank Vegetation Protection		Left: 9 Right: 6		
6.10 Riparian Vegetation Zone Width		Left: 8 Right: 6		
Total Score		132		
Habitat Rating		0.66		
Habitat Stream Condition		Good		
Step 7. Rapid Geomorphic Assessment Data				
Confinement Type	Unconfined	Score	STD	Historic
7.1 Channel Degradation		13	None	Yes
7.2 Channel Aggradation		12	None	No
7.3 Widening Channel		10		No
7.4 Change in Planform		12		No
Total Score		47		
Geomorphic Rating		0.5875		
Channel Evolution Model		F		
Channel Evolution Stage		III		
Geomorphic Condition		Fair		
Stream Sensitivity		Very High		
Step 6. Rapid Habitat Assessment Data				
Stream Gradient Type	High	Score		
6.1 Epifaunal Substrate - Available Cover		14		
6.2 Embeddedness		11		
6.3 Velocity/Depth Patterns		18		
6.4 Sediment Deposition		6		
6.5 Channel Flow Status		10		
6.6 Channel Alteration		15		
6.7 Frequency of Riffles/Steps		16		
6.8 Bank Stability		Left: 6 Right: 7		
6.9 Bank Vegetation Protection		Left: 9 Right: 6		
6.10 Riparian Vegetation Zone Width		Left: 8 Right: 6		
Total Score		132		
Habitat Rating		0.66		
Habitat Stream Condition		Good		
Narrative:				
historic degradation, active aggradation, widening and planform adjustments				

March 20, 2007 **FIT: Yes**
Completion Date: September 20, 2006
Rain: Yes

Phase 2 Segment Summary page 1 of 2
 Reach # M1S1.01 Segment: 0
 Observers: Adam Robtoy, P.Stanley Why Not assessed:
 Segment Location: From confluence with Trout to ~3/4 mi upstream

Step 1. Valley and Floodplain			Step 2. Stream Channel			Step 3. Riparian Features			Step 4. Flow & Flow Modifiers		
1.1 Segmentation None			2.1 Bankfull Width 20			3.1 Stream Banks			4.1 Springs / Seeps		
1.2 Alluvial Fan None			2.2 Max Depth (ft) 2.00			Typical Bank Slope Steep			4.2 Adjacent Wetlands None		
1.3 Corridor Encroachments			2.3 Mean Depth (ft) 1.20			Bank Texture Left			4.3 Flow Status Moderate		
Length (ft) One Both			2.4 Floodprone Width (ft) 28			Upper			4.4 # of Debris Jams 1		
Berns 0			2.5 Aband. Floodpln 4.00			Material Type Gravel			4.5 Impoundments None		
Roads 768			2.6 Width/Depth Ratio 16.67			Consistency Non-cohesive			Impoundmt. Location		
Railroads 0			2.7 Entrenchment Ratio 1.40			Lower			4.6 # of Stormwater Inputs 1		
Improved Paths 0			2.8 Incision Ratio 2.00			Material Type Silt/Clay			4.7 Upstream Flow None		
Development 0			2.9 Sinuosity Low			Consistency Cohesive			4.9 # of Beaver Dams 0		
1.4 Adjacent Side Left Right			2.10 Riffles Type Complete			Bank Erosion Left			Affected Length (ft) 0		
Hillside Slope Very Steep Very Steep			2.11 Riffle/Step Spacing (ft) 100			Erosion Length (ft) 258			Step 5. Channel Bed and Planform Changes		
Continuous w/ Sometimes Sometimes			2.12 Substrate Composition			Erosion Height (ft) 4.67			5.1 Bar Types		
W/in 1 Bankfill Sometimes Sometimes			Bedrock 2 %			Revetmt. Type Rip-Rap			Mid Point Side		
Texture Other Other			Boulder 5 %			Revetmt. Length (ft) 132			1 10 5		
1.5 Valley Features			Cobble 31 %			Near Bank Veg. Type Left			Diagonal Delta Island		
Valley Width (ft) 180			Coarse Gravel 43 %			Dominant Pasture			0 1 0		
Width Determination Estimated			Fine Gravel 15 %			Sub-dominant Herbaceous			5.2 Other Features		
Confinement Type Very Broad			Sand 4 %			Bank Canopy Left			Flood Neck Cutoff Avulsion Braiding		
Rock Gorge? No						Canopy % 1-25			0 0 0 0		
Human-caused changed valley width? no						Mid-Channel Canopy Open			5.3 Steep Riffles and Head Cuts		
Notes:			Silt/Clay Present? Yes			3.2 Riparian Buffer			Steep Riffles Head Cuts Trib Rejuv.		
Stream runs through barnyard.			Detritus 20 %			Buffer Width Left			2 0 No		
Cows in stream, upstream of culvert slightly less incised (1.8)			# Large Woody 5			Dominant <5			5.4 Stream Ford or Animal Yes		
			2.13 Average Largest Particle on			Sub-dominant 5-25			5.5 Straightening No		
			Bed 80.0 mm			Buffer Veg. Type Left			Straightening Length: 0		
			Bar 75.0 mm			Dominant Herbaceous			5.5 Dredging None		
			2.14 Stream Type			Sub-dominant Shrubs/Saplin Shrubs/Saplin					
			Stream Type: B			3.3 Riparian Corridor					
			Bed Material: Gravel			Corridor Land Left					
			Subclass Slope: None			Dominant Pasture					
			Bed Form: Step-Pool			Sub-dominant Hay					
			2.15 Reference Stream Type			Mass Failures Amount Mean Height					
			(if different from Phase 1)			One 12.00					
						None 0.00					
									Note:		
									Step 1.6 - Grade Controls and		
									Step 4.8 - Channel Constrictions		
									are on The second page of this		
									report - Steps 6 through 7.		

Project: Trout River Mouth
Stream: Unnamed 1 to M1
Organization: Johnson Company
Segment Length (ft): 3,516

1.6 Grade Controls None

Type	Location	Total	Total Height Above Water	Photo Taken	GPSTaken
------	----------	-------	--------------------------	-------------	----------

Step 7. Rapid Geomorphic Assessment Data

Confinement Type	Unconfined	Score	STD	Historic
7.1 Channel Degradation	5	Yes		
7.2 Channel Aggradation	16	None		
7.3 Widening Channel	12	No		
7.4 Change in Planform	14	No		
Total Score		47		
Geomorphic Rating		0.5875		
Channel Evolution Model		F		
Channel Evolution Stage		III		
Geomorphic Condition		Fair		
Stream Sensitivity		Very High		

Step 6. Rapid Habitat Assessment Data

Stream Gradient Type	High	Score
6.1 Epifaunal Substrate - Available Cover		8
6.2 Embeddedness		8
6.3 Velocity/Depth Patterns		11
6.4 Sediment Deposition		15
6.5 Channel Flow Status		12
6.6 Channel Alteration		11
6.7 Frequency of Rifles/Steps		16
6.8 Bank Stability	Left: 7 Right: 6	
6.9 Bank Vegetation Protection	Left: 3 Right: 3	
6.10 Riparian Vegetation Zone Width	Left: 2 Right: 2	
Total Score		104
Habitat Rating		0.52

Narrative:

Major historic degradation, active widening particularly downstream of RT. 118 culvert and upstream of Woodward Neighborhood road culvert

[illegible]

1.6 Grade Controls None			
Type	Location	Total	Total Height Above Water
			Photo Taken GPSTaken
Step 7. Rapid Geomorphic Assessment Data			
Confinement Type		Unconfined	
		Score	STD Historic
7.1 Channel Degradation		12	None Yes
7.2 Channel Aggradation		16	None No
7.3 Widening Channel		17	No No
7.4 Change in Planform		18	No No
Total Score		63	
Geomorphic Rating		0.7875	
Channel Evolution Model		F	
Channel Evolution Stage		II	
Geomorphic Condition		Good	
Stream Sensitivity		Moderate	
Step 6. Rapid Habitat Assessment Data			
Stream Gradient Type		High	
		Score	
6.1 Epifaunal Substrate - Available Cover		10	
6.2 Embeddedness		14	
6.3 Velocity/Depth Patterns		11	
6.4 Sediment Deposition		15	
6.5 Channel Flow Status		13	
6.6 Channel Alteration		16	
6.7 Frequency of Riffles/Steps		16	
6.8 Bank Stability		Left: 9 Right: 9	
6.9 Bank Vegetation Protection		Left: 7 Right: 5	
6.10 Riparian Vegetation Zone Width		Left: 3 Right: 2	
Total Score		130	
Habitat Rating		0.65	
Habitat Stream Condition		Good	
Narrative:			
Minor degradation, no other adjustments observed			

Project: Trout River Mouth
Stream: Unnamed 3 to M2
Organization: Johnson Company
Segment Length (ft): 7,331

Reach #	Phase 2 Segment Summary	page 1 of 2
M2S3.02	Observers: Adam Robtoy, Paul Stanley	Segment: 0
	nt Location: from M2S3.02 to Head Quarters	Why Not assessed:

March 20, 2007 **FIT: Yes**
Completion Date: September 21, 2006
Rain: Yes

Step 1. Valley and Floodplain				Step 2. Stream Channel				Step 3. Riparian Features				Step 4. Flow & Flow Modifiers			
1.1 Segmentation None				2.1 Bankfull Width 17				3.1 Stream Banks				4.1 Springs / Seeps Some			
1.2 Alluvial Fan No				2.2 Max Depth (ft) 1.90				Typical Bank Slope Step				4.2 Adjacent Wetlands None			
1.3 Corridor Encroachments				2.3 Mean Depth (ft) 1.20				Bank Texture				4.3 Flow Status Moderate			
Length (ft)				2.4 Floodprone Width (ft) 27				Upper				4.4 # of Debris Jams 5			
Berns 0				2.5 Aband. Floodpln 3.70				Material Type Gravel				4.5 Impoundments None			
Roads 0				2.6 Width/Depth Ratio 14.17				Consistency Non-cohesive				Impoundmt. Location			
Railroads 0				2.7 Entrenchment Ratio 1.59				Lower				4.6 # of Stormwater Inputs 0			
Improved Paths 0				2.8 Incision Ratio 1.95				Material Type Bedrock				4.7 Upstream Flow None			
Development 0				2.9 Sinuosity Low				Consistency Cohesive				4.9 # of Beaver Dams 0			
1.4 Adjacent Side				2.10 Riffles Type Complete				Bank Erosion				Affected Length (ft) 0			
Left				2.11 Riffle/Step Spacing (ft) 75				Erosion Length (ft) 297				Step 5. Channel Bed and Planform Changes			
Right				2.12 Substrate Composition				Erosion Height (ft) 5.40				5.1 Bar Types			
Hillside Slope Very Steep				Bedrock 2 %				Revetmt. Type None				Mid			
Continuous w/ Sometimes				Boulder 6 %				Revetmt. Length (ft) 0				Point			
W/in 1 Bankfill Sometimes				Cobble 50 %				Near Bank Veg. Type Left				Side			
Sometimes				Coarse Gravel 31 %				Dominant Shrubs/Saplin				Delta			
Bedrock				Fine Gravel 9 %				Sub-dominant Coniferous				Island			
Bedrock				Sand 2 %				Bank Canopy				0			
50								Canopy % 76-100				5.2 Other Features			
Measured								Mid-Channel Canopy Closed				Flood			
Semi-confined								3.2 Riparian Buffer				Neck Cutoff			
No								Buffer Width				Avulsion			
No								Dominant				Braiding			
No								Sub-dominant				0			
No								Dominant				0			
No								Sub-dominant				0			
No								Dominant				0			
No								Sub-dominant				0			
No								Dominant				0			
No								Sub-dominant				0			
No								Dominant				0			
No								Sub-dominant				0			
No								Dominant				0			
No								Sub-dominant				0			
No								Dominant				0			
No								Sub-dominant				0			
No								Dominant				0			
No								Sub-dominant				0			
No								Dominant				0			
No								Sub-dominant				0			
No								Dominant				0			
No								Sub-dominant				0			
No								Dominant				0			
No								Sub-dominant				0			
No								Dominant				0			
No								Sub-dominant				0			
No								Dominant				0			
No								Sub-dominant				0			
No								Dominant				0			
No								Sub-dominant				0			
No								Dominant				0			
No								Sub-dominant				0			
No								Dominant				0			
No								Sub-dominant				0			
No								Dominant				0			
No								Sub-dominant				0			
No								Dominant				0			
No								Sub-dominant				0			
No								Dominant				0			
No								Sub-dominant				0			
No								Dominant				0			
No								Sub-dominant				0			
No								Dominant				0			
No								Sub-dominant				0			
No								Dominant				0			
No								Sub-dominant				0			
No								Dominant				0			
No								Sub-dominant				0			
No								Dominant				0			
No								Sub-dominant				0			
No								Dominant				0			
No								Sub-dominant				0			
No								Dominant				0			
No								Sub-dominant				0			
No								Dominant				0			
No								Sub-dominant				0			
No								Dominant				0			
No								Sub-dominant				0			
No								Dominant				0			
No								Sub-dominant				0			
No								Dominant				0			
No								Sub-dominant				0			
No								Dominant				0			
No								Sub-dominant				0			
No								Dominant				0			
No								Sub-dominant				0			
No								Dominant				0			
No								Sub-dominant				0			
No								Dominant				0			
No								Sub-dominant				0			
No								Dominant				0			
No								Sub-dominant				0			
No								Dominant				0			
No								Sub-dominant				0			
No								Dominant				0			
No								Sub-dominant				0			
No								Dominant				0			
No								Sub-dominant				0			
No								Dominant				0			
No								Sub-dominant				0			
No								Dominant				0			
No								Sub-dominant				0			
No								Dominant				0			
No															

Project: **Trout River Mouth** Phase 2 Reach Summary page 2 of 2 March 20, 2007
 Stream: **Unnamed 3 to M2** Reach # **M2S3.02** Segment: **6** Completion Date: **September 21,**
 Organization: **Johnson Company** Observers: **Adam Robtoy, Paul Stanley** Rain: **Yes**
 Segment Length (ft): **7,331** Segment Location: **from M2S3.02 to Head Quarters**

1.6 Grade Controls					Step 7. Rapid Geomorphic Assessment Data			
Type	Location	Total	Total Height Above Water	Photo Taken	GPSTaken	Confinement Type	Confined	Historic
Waterfall	Mid-Segment	20.00	15.00					
Waterfall	Upstream	8.00	5.00					
Waterfall	Upstream	30.00	20.00					
Waterfall	Mid-Segment	6.00	4.00					
					Total Score	64		
					Geomorphic Rating	0.8		
					Channel Evolution Model	F		
					Channel Evolution Stage	III		
					Geomorphic Condition	Good		
					Stream Sensitivity	Moderate		

Step 6. Rapid Habitat Assessment Data		
Stream Gradient Type	High	Score
6.1 Epifaunal Substrate - Available Cover		18
6.2 Embeddedness		15
6.3 Velocity/Depth Patterns		17
6.4 Sediment Deposition		14
6.5 Channel Flow Status		15
6.6 Channel Alteration		19
6.7 Frequency of Riffles/Steps		17
6.8 Bank Stability		Left: 8 Right: 8
6.9 Bank Vegetation Protection		Left: 9 Right: 9
6.10 Riparian Vegetation Zone Width		Left: 9 Right: 9
Total Score		167
Habitat Rating		0.835

Habitat Stream Condition **Good**

Narrative:
 Minor Planform

Project: Trout River Mouth
Stream: Unnamed Tributary 1
Organization: Johnson Company
Segment Length (ft): 5,090

Phase 2 Segment Summary page 1 of 2
Reach # T1.01
Observers: AWR, NBR
Segment Location: 1/4 mile south intersection of route 118 and Hopkins Bridge Road

March 20, 2007
Completion Date: July 26, 2006
FIT: Yes
Rain: Yes

Why Not assessed:

Step 1. Valley and Floodplain

1.1 Segmentation	None	
1.2 Alluvial Fan	No	
1.3 Corridor Encroachments		Both
Length (ft)	One	
Berm	0	0
Roads	0	52
Railroads	0	0
Improved Paths	0	0
Development	0	0
1.4 Adjacent Side	Left	Right
Hillside Slope	Very Steep	Steep
Continuous w/ Sometimes		Never
W/in 1 Bankfill Sometimes		Never
Texture	Bedrock	Not Evaluated
1.5 Valley Features		
Valley Width (ft)	627	
Width Determination	Estimated	
Confinement Type	Very Broad	
Rock Gorge?	No	
Human-caused changed valley width?	no	

Notes:

lots of enlarged bars and steep riffles in lower portion of reach below road, upper ~500 feet slightly steeper with larger substrates. Neck cut-off/future avulsion at meander near confluence with Trout

Step 2. Stream Channel	37
2.1 Bankfull Width	
2.2 Max Depth (ft)	3.10
2.3 Mean Depth (ft)	2.60
2.4 Floodprone Width (ft)	190
2.5 Aband. Floodpin	3.60
2.6 Width/Depth Ratio	14.23
2.7 Entrenchment Ratio	5.14
2.8 Incision Ratio	1.16
2.9 Sinuosity	Moderate
2.10 Riffles Type	Sedimented
2.11 Riffle/Step Spacing (ft)	150
2.12 Substrate Composition	
Bedrock	0 %
Boulder	1 %
Cobble	26 %
Coarse Gravel	48 %
Fine Gravel	16 %
Sand	9 %
Silt/Clay Present?	Yes
Detritus	2 %
# Large Woody	27
2.13 Average Largest Particle on	
Bed	120.0 mm
Bar	100.0 mm
2.14 Stream Type	
Stream Type:	C
Bed Material:	Gravel
Subclass Slope:	None
Bed Form:	Riffle-Pool
2.15 Reference Stream Type	
(if different from Phase 1)	

Step 3. Riparian Features	
3.1 Stream Banks	
Typical Bank Slope	Steep
Bank Texture	Left
Upper	Right
Material Type	Sand
Consistency	Non-cohesive
Lower	Sand
Material Type	Gravel
Consistency	Non-cohesive
Bank Erosion	Non-cohesive
Erosion Length (ft)	185
Erosion Height (ft)	4.00
Revetmt. Type	Rip-Rap
Revetmt. Length (ft)	251
Near Bank Veg. Type	Left
Dominant	Shrubs/Saplin
Sub-dominant	Deciduous
Bank Canopy	Left
Canopy %	51-75
Mid-Channel Canopy	Open
3.2 Riparian Buffer	
Buffer Width	Left
Dominant	>100
Sub-dominant	5-25
Buffer Veg. Type	Left
Dominant	Mixed Trees
Sub-dominant	Herbaceous
3.3 Riparian Corridor	
Corridor Land	Left
Dominant	Forest
Sub-dominant	Hay
Mass Failures	Amount
Gullies	None
Mean Height	0.00
Mean Height	0.00

Step 4. Flow & Flow Modifiers		
4.1 Springs / Seeps	Some	
4.2 Adjacent Wetlands	Some	
4.3 Flow Status	High	
4.4 # of Debris Jams	2	
4.5 Impoundments	None	
Impoundmt. Location		
4.6 # of Stormwater Inputs	0	
4.7 Upstream Flow	None	
4.9 # of Beaver Dams	0	
Affected Length (ft)	0	
Step 5. Channel Bed and Planform Changes		
5.1 Bar Types		
Mid	Point	Side
0	24	2
Diagonal	Delta	Island
4	1	0
5.2 Other Features		
Flood	Neck Cutoff	Avulsion
2	1	0
5.3 Steep Riffles and Head Cuts		
Steep Riffles	Head Cuts	Trib Rejuv.
5	0	No
5.4 Stream Ford or Animal	No	
5.5 Straightening	Yes	
Straightening Length:		95
5.5 Dredging	None	

Note:

Step 1.6 - Grade Controls and

Step 4.8 - Channel Constrictions

are on The second page of this

Note:

Step 1.6 - Grade Controls and
Step 4.8 - Channel Constrictions
are on The second page of this
report - Steps 6 through 7.

1.6 Grade Controls None				
Type	Location	Total	Total Height Above Water	Photo Taken GPSTaken
Step 7. Rapid Geomorphic Assessment Data				
Confinement Type	Unconfined		Score	STD
7.1 Channel Degradation			16	None
7.2 Channel Aggradation			12	None
7.3 Widening Channel			13	No
7.4 Change in Planform			15	No
Total Score 56				
Geomorphic Rating 0.7				
Channel Evolution Model F				
Channel Evolution Stage III				
Geomorphic Condition Good				
Stream Sensitivity High				
Step 6. Rapid Habitat Assessment Data				
Stream Gradient Type	High		Score	
6.1 Epifaunal Substrate - Available Cover				15
6.2 Embeddedness				14
6.3 Velocity/Depth Patterns				17
6.4 Sediment Deposition				10
6.5 Channel Flow Status				12
6.6 Channel Alteration				15
6.7 Frequency of Riffles/Steps				18
6.8 Bank Stability				Left: 8 Right: 8
6.9 Bank Vegetation Protection				Left: 8 Right: 5
6.10 Riparian Vegetation Zone Width				Left: 9 Right: 5
Total Score				144
Habitat Rating				0.72
Habitat Stream Condition				Good

Narrative:

minor aggradation and widening

Project: Trout River Mouth
Stream: Unnamed Tributary 1
Organization: Johnson Company
Segment Length (ft): 7,219

Phase 2 Segment Summary page 1 of 2
Reach # T1.02 Segment: 0
Observers: Adam Robtoy, Brian Lerich Why Not assessed:
Segment Location: from T1-01 to just north of Wightman Hill Road

March 20, 2007
Completion Date: July 27, 2006
FIT: Yes
Rain: Yes

Step 1. Valley and Floodplain		Step 2. Stream Channel		Step 3. Riparian Features		Step 4. Flow & Flow Modifiers	
1.1 Segmentation	None	2.1 Bankfull Width	30	3.1 Stream Banks		4.1 Springs / Seeps	Some
1.2 Alluvial Fan	None	2.2 Max Depth (ft)	2.70	Typical Bank Slope	Steep	4.2 Adjacent Wetlands	None
1.3 Corridor Encroachments		2.3 Mean Depth (ft)	1.90	Bank Texture	Left	4.3 Flow Status	Moderate
Length (ft)	One	2.4 Floodprone Width (ft)	60	Upper		4.4 # of Debris Jams	0
Berm	Both	2.5 Aband. Floodpin	3.50	Material Type	Gravel	4.5 Impoundments	None
Roads	0	2.6 Width/Depth Ratio	15.79	Consistency	Non-cohesive	Impoundmt. Location	
Railroads	0	2.7 Entrenchment Ratio	2.00	Lower		4.6 # of Stormwater Inputs	0
Improved Paths	0	2.8 Incision Ratio	1.30	Material Type	Bedrock	4.7 Upstream Flow	None
Development	0	2.9 Sinuosity	Low	Consistency	Cohesive	4.9 # of Beaver Dams	0
1.4 Adjacent Side	Left	2.10 Riffles Type	Complete	Bank Erosion	Left	Affected Length (ft)	0
Hillside Slope	Very Steep	2.11 Riffle/Step Spacing (ft)	75	Erosion Length (ft)	118	Step 5. Channel Bed and Planform Changes	
Continuous w/ Sometimes	Sometimes			Erosion Height (ft)	9.00	5.1 Bar Types	
W/in 1 Bankfill Sometimes	Sometimes	2.12 Substrate Composition		Revetmt. Type	None	Mid	Point
Texture	Bedrock	Bedrock	6 %	Revetmt. Length (ft)	0	6	Side
1.5 Valley Features		Boulder	14 %	Near Bank Veg. Type	Left	Diagonal	Delta
Valley Width (ft)	110	Cobble	52 %	Dominant	Coniferous	0	1
Width Determination	Measured	Coarse Gravel	20 %	Sub-dominant	Deciduous	5.2 Other Features	
Confinement Type	Narrow	Fine Gravel	6 %	Bank Canopy	Left	Flood	Neck Cutoff
Rock Gorge?	No	Sand	2 %	Canopy %	76-100	0	0
Human-caused changed valley width?	no			Mid-Channel Canopy	Closed	0	0
Notes:				3.2 Riparian Buffer		Steep Riffles	Head Cuts
reach found to be in reference condition (B3a stream type), several bedrock grade controls throughout, wide woody buffers, not encroachments except for culvert along road		Silt/Clay Present?	No	Buffer Width	Left	0	0
		Detritus	0 %	Dominant	>100	Trib Rejuv.	
		# Large Woody	11	Sub-dominant	51-100	5.4 Stream Ford or Animal	No
		2.13 Average Largest Particle on		Buffer Veg. Type	Left	5.5 Straightening	No
		Bed	250.0 mm	Dominant	Mixed Trees	Straightening Length:	0
		Bar	180.0 mm	Sub-dominant	Shrubs/Saplin Shrubs/Saplin	5.5 Dredging	None
		2.14 Stream Type		3.3 Riparian Corridor			
		Stream Type: B		Corridor Land	Left		
		Bed Material: Cobble		Dominant	Forest		
		Subclass Slope: a		Sub-dominant	None		
		Bed Form: Step-Pool		Amount	Mean Height		
		2.15 Reference Stream Type		Mass Failures	Multiple		
		(if different from Phase 1)		Gullies	None		

Note:
Step 1.6 - Grade Controls and
Step 4.8 - Channel Constrictions
are on The second page of this
report - Steps 6 through 7.

Project: **Trout River Mouth** Phase 2 Reach Summary page 2 of 2 March 20, 2007
 Stream: **Unnamed Tributary 1** Reach: # **T1.02** Segment: **0** Completion Date: **July 27, 2006**
 Organization: **Johnson Company** Observers: **Adam Robtoy, Brian Lerich** Rain: **Yes**
 Segment Length (ft): **7,219** Segment Location: **from T1-01 to just north of Wightman Hill Road**

Step 7. Rapid Geomorphic Assessment Data				
Type	Location	Total	Confinement Type	Score
Waterfall	Upstream	30.00	Confined	18
Ledge	Upstream	4.00		16
Ledge	Upstream	4.00		14
Ledge	Upstream	4.00		20
Ledge	Upstream	4.00		68
Ledge	Upstream	4.00		0.85
Ledge	Upstream	4.00		F
Ledge	Mid-Segment	4.00		I
Ledge	Mid-Segment	10.00		Referenc
Stream Sensitivity				Low

Step 6. Rapid Habitat Assessment Data		
Stream Gradient Type	High	Score
6.1 Epifaunal Substrate - Available Cover		18
6.2 Embeddedness		15
6.3 Velocity/Depth Patterns		20
6.4 Sediment Deposition		15
6.5 Channel Flow Status		15
6.6 Channel Alteration		20
6.7 Frequency of Riffles/Steps		19
6.8 Bank Stability		Left: 9 Right: 10
6.9 Bank Vegetation Protection		Left: 9 Right: 9
6.10 Riparian Vegetation Zone Width		Left: 10 Right: 10
Total Score		179
Habitat Rating		0.895

Habitat Stream Condition **Referen**

Narrative:
 Minor widening though reach still found to be in reference condition, no major erosion noted

[illegible]

Project:	Trout River Mouth	Phase 2 Reach Summary	page 2 of 2	March 20, 2007
Stream:	Unnamed Tributary 2	Reach # T2.01	Segment: A	Completion Date: September 14,
Organization:	Johnson Company	Observers:	Adam Robtoy, DB	Rain: Yes
Segment Length (ft):	90C	Segment Location:	From confluence with Trout to Route 118 Bridge.	

1.6 Grade Controls None

Type	Location	Total	Total Height Above Water	Photo Taken	GPSTaken

Step 7. Rapid Geomorphic Assessment Data

Confinement Type	Unconfined	Score	STD	Historic
7.1 Channel Degradation		14	None	Yes
7.2 Channel Aggradation		13	None	No
7.3 Widening Channel		14		No
7.4 Change in Planform		17		No
Total Score		58		
Geomorphic Rating		0.725		
Channel Evolution Model		F		
Channel Evolution Stage		III		
Geomorphic Condition		Good		
Stream Sensitivity		Very High		

Step 6. Rapid Habitat Assessment Data

Stream Gradient Type	High	Score
6.1 Epifaunal Substrate - Available Cover		8
6.2 Embeddedness		10
6.3 Velocity/Depth Patterns		12
6.4 Sediment Deposition		6
6.5 Channel Flow Status		7
6.6 Channel Alteration		16
6.7 Frequency of Riffles/Steps		16
6.8 Bank Stability	Left: 8 Right: 8	
6.9 Bank Vegetation Protection	Left: 5 Right: 5	
6.10 Riparian Vegetation Zone Width	Left: 4 Right: 2	
Total Score		107
Habitat Rating		0.535
Habitat Stream Condition		Fair

Narrative:
Aggradation/ Widening, alluvial fan portion of reach

Project: **Trout River Mouth**
Stream: **Unnamed Tributary 2**
Organization: **Johnson Company**
Segment Length (ft): **1,301**

Reach # **72.01**
Observers: **Adam Robtoy, DB**
Segment Location: **From Route 118 Bridge to Bedrock Gorge located ~1/4 mile upstream**

March 20, 2007
Completion Date: **September 14, 2006**
Rain: **Yes**

Step 1. Valley and Floodplain				Step 2. Stream Channel				Step 3. Riparian Features				Step 4. Flow & Flow Modifiers			
1.1 Segmentation	Planform	and Scope		2.1 Bankfull Width	43			3.1 Stream Banks				4.1 Springs / Seeps	None		
1.2 Alluvial Fan	No			2.2 Max Depth (ft)	2.70			Typical Bank Slope	Steep			4.2 Adjacent Wetlands	None		
1.3 Corridor Encroachments				2.3 Mean Depth (ft)	2.20			Bank Texture	Left			4.3 Flow Status	Moderate		
	Length (ft)	One	Both	2.4 Floodprone Width (ft)	68			Upper				4.4 # of Debris Jams	0		
	Berm	0	0	2.5 Aband. Floodpln	5.10			Material Type	Gravel			4.5 Impoundments	None		
	Roads	501	325	2.6 Width/Depth Ratio	19.55			Consistency	Non-cohesive			Impoundmt. Location			
	Railroads	0	0	2.7 Entrenchment Ratio	1.58			Lower				4.6 # of Stormwater Inputs	1		
	Improved Paths	0	0	2.8 Incision Ratio	1.89			Material Type	Gravel			4.7 Upstream Flow	None		
	Development	0	236	2.9 Sinuosity	Low			Consistency	Non-cohesive			4.9 # of Beaver Dams	0		
1.4 Adjacent Side	Left		Right	2.10 Riffles Type	Complete			Bank Erosion	Left			Affected Length (ft)	0		
Hillside Slope	Extremely		Extremely	2.11 Riffle/Step Spacing (ft)	150			Erosion Length (ft)	0			Step 5. Channel Bed and Planform Changes			
Continuous w/	Sometimes		Sometimes	2.12 Substrate Composition				Erosion Height (ft)	0.00			5.1 Bar Types			
W/in 1 Bankfill	Sometimes		Sometimes	Bedrock	0 %			Revetmt. Type	Rip-Rap			Mid		Point	Side
Texture	Bedrock		Bedrock	Boulder	4 %			Revetmt. Length (ft)	442			Diagonal	0	Delta	Island
Valley Width (ft)	200			Cobble	38 %			Dominant	Invasives				0	0	0
Width Determination	Measured			Coarse Gravel	40 %			Sub-dominant	Herbaceous			5.2 Other Features			
Confinement Type	Narrow			Fine Gravel	12 %			Bank Canopy	Left			Flood	0	Neck Cutoff	Avulsion
Rock Gorge?	Yes			Sand	6 %			Canopy %	26-50				0	0	0
Human-caused changed valley width?	no							Mid-Channel Canopy	Open			5.3 Steep Riffles and Head Cuts			
Notes:				Silt/Clay Present?	No			3.2 Riparian Buffer				Steep Riffles	Head Cuts		Trib Rejuv.
Bedrock Gorge located on upper 300 feet of reach, dominated by residential development on lower 1/2 of sub-reach, riprap dominates banks on both sides, historic dredging noted in phase 1, no active dredging observed				Detritus	5 %			Buffer Width	Left			0	0		No
				# Large Woody	2			Dominant	5-25			5.4 Stream Ford or Animal			No
				2.13 Average Largest Particle on				Sub-dominant	<5			5.5 Straightening			Yes
				Bed	200.0	mm		Buffer Veg. Type	Left			Straightening Length:			212
				Bar	170.0	mm		Dominant	Mixed Trees			5.5 Dredging			None
								Sub-dominant	Invasives						
				2.14 Stream Type				3.3 Riparian Corridor							
				Stream Type:	B			Corridor Land	Left						
				Bed Material:	Gravel			Dominant	Residential						
				Subclass Slope:	None			Sub-dominant	Forest						
				Bed Form:	Step-Pool			Amount	Mean Height						
				2.15 Reference Stream Type				Mass Failures	None						
				(if different from Phase 1)				Gullies	None						

Note:
Step 1.6 - Grade Controls and
Step 4.8 - Channel Constrictions
are on The second page of this
report - Steps 6 through 7.

Project: **Trout River Mouth** **Phase 2 Reach Summary** page 2 of 2 March 20, 2007
 Subunit: **Unnamed Tributary 2** Reach # **T2.01**
 Organization: **Johnson Company** Observers: **Adam Robtoy, DB**
 Segment Length (ft): **1,301** Segment Location: **From Route 118 Bridge to Badrock Gorge located ~1/4 mile upstream** Completion Date: **September 14,** Rain: **Yes**

Step 7. Rapid Geomorphic Assessment Data				
Confinement Type	Unconfined	Score	STD	Historic
7.1 Channel Degradation		13	None	Yes
7.2 Channel Aggradation		18	None	No
7.3 Widening Channel		16		No
7.4 Change in Planform		16		No
Total Score		63		
Geomorphic Rating		0.7875		
Channel Evolution Model		F		
Channel Evolution Stage		II		
Geomorphic Condition		Good		
Stream Sensitivity		Moderate		

Step 6. Rapid Habitat Assessment Data		
Stream Gradient Type	High	Score
6.1 Epifaunal Substrate - Available Cover		12
6.2 Embeddedness		14
6.3 Velocity/Depth Patterns		14
6.4 Sediment Deposition		19
6.5 Channel Flow Status		18
6.6 Channel Alteration		18
6.7 Frequency of Riffles/Steps		15
6.8 Bank Stability	Left: 10 Right: 10	
6.9 Bank Vegetation Protection	Left: 8 Right: 8	
6.10 Riparian Vegetation Zone Width	Left: 4 Right: 4	
Total Score		154
Habitat Rating		0.77
Habitat Stream Condition		Good

4.8 Channel Constrictions			
Type	Width	Photo Taken?	GPS Taken?
Bedrock	20.0	Yes	Yes
Problem	None		

1.6 Grade Controls			
Type	Location	Total	Total Height Above Water
Waterfall	Upstream	30.00	25.00

Narrative:
 Historic Incision, highly encroached by development and rip-rap,

Project: **Trout River Head**
Stream: **Trout River**
Organization: **Johnson Company**
Segment Length (ft): **13,386**

Reach # **M03**
Observers: **Adam Robtoy, E. Crandell**
Segment Location: **from M02 to braided segment 2200' downstream of end of M03**

March 20, 2007
Completion Date: **August 24, 2006**
Rain: **Yes**

Phase 2 Segment Summary page 1 of 2
Segment: **A**

Step 1. Valley and Floodplain

1.1 Segmentation Channel Dimensions

1.2 Alluvial Fan **No**

1.3 Corridor Encroachments

Length (ft) One Both

Bermes **0** **0**

Roads **0** **0**

Railroads **0** **0**

Improved Paths **0** **0**

Development **1,641** **0**

1.4 Adjacent Side Left Right

Hillside Slope **Very Steep** **Steep**

Continuous w/ **Sometimes** **Never**

W/in 1 Bankfill **Sometimes** **Never**

Texture **Bedrock** **Not Evalua**

1.5 Valley Features

Valley Width (ft) **1,991**

Width Determination **Estimated**

Confinement Type **Very Broad**

Rock Gorge? **No**

Human-caused changed valley width? **no**

Notes:

historic gravel mining, extensive bar scalping just downstream of Vincents Bridge Road Bridge, bedrock gorge located just upstream of Cornstock bridge

Step 2. Stream Channel

2.1 Bankfull Width **74**

2.2 Max Depth (ft) **3.50**

2.3 Mean Depth (ft) **2.80**

2.4 Floodprone Width (ft) **500**

2.5 Aband. Floodpln **4.90**

2.6 Width/Depth Ratio **26.43**

2.7 Entrenchment Ratio **6.76**

2.8 Incision Ratio **1.40**

2.9 Sinuosity **Moderate**

2.10 Riffles Type **Sedimented**

2.11 Riffle/Step Spacing (ft) **400**

2.12 Substrate Composition

Bedrock **0 %**

Boulder **0 %**

Cobble **14 %**

Coarse Gravel **63 %**

Fine Gravel **15 %**

Sand **8 %**

Silt/Clay Present? **No**

Detritus **0 %**

Large Woody **28**

2.13 Average Largest Particle on

Bed **100.0 mm**

Bar **75.0 mm**

2.14 Stream Type

Stream Type: **C**

Bed Material: **Gravel**

Subclass Slope: **None**

Bed Form: **Riffle-Pool**

2.15 Reference Stream Type

(if different from Phase 1)

Step 3. Riparian Features

3.1 Stream Banks

Typical Bank Slope **Steep**

Bank Texture Left Right

Upper Sand Sand

Material Type **Non-cohesive** **Non-cohesive**

Consistency **Non-cohesive** **Non-cohesive**

Lower **Gravel** **Gravel**

Material Type **Non-cohesive** **Non-cohesive**

Consistency **Non-cohesive** **Non-cohesive**

Bank Erosion Left Right

Erosion Length (ft) **628** **909**

Erosion Height (ft) **5.20** **5.50**

Revetmt. Type **Rip-Rap** **Rip-Rap**

Revetmt. Length (ft) **195** **1,649**

Near Bank Veg. Type Left Right

Dominant **Shrubs/Saplin Shrubs/Saplin**

Sub-dominant **Deciduous** **Deciduous**

Bank Canopy Left Right

Canopy % **26-50** **26-50**

Mid-Channel Canopy **Open**

3.2 Riparian Buffer

Buffer Width Left Right

Dominant **51-100** **26-50**

Sub-dominant **>100** **51-100**

Buffer Veg. Type Left Right

Dominant **Mixed Trees** **Mixed Trees**

Sub-dominant **Shrubs/Saplin Shrubs/Saplin**

3.3 Riparian Corridor

Corridor Land Left Right

Dominant **Hay** **Crop**

Sub-dominant **Forest** **Forest**

Amount Mean Height

Mass Failures **None** **0.00**

Gullies **None** **0.00**

Step 4. Flow & Flow Modifiers

4.1 Springs / Seeps **Some**

4.2 Adjacent Wetlands **Some**

4.3 Flow Status **Moderate**

4.4 # of Debris Jams **0**

4.5 Impoundments **None**

Impoundmt. Location

4.6 # of Stormwater Inputs **1**

4.7 Upstream Flow **None**

4.9 # of Beaver Dams **0**

Affected Length (ft) **0**

Step 5. Channel Bed and Planform Changes

5.1 Bar Types

Mid Point Side

0 **19** **4**

Diagonal Delta Island

1 **1** **0**

5.2 Other Features

Flood Neck Cutoff Avulsion Braiding

0 **0** **0** **0**

5.3 Steep Riffles and Head Cuts

Steep Riffles Head Cuts Trib Rejuv.

1 **0** **No**

5.4 Stream Ford or Animal **Yes**

5.5 Straightening **No**

Straightening Length: **0**

5.5 Dredging **Dredging**

Note:

Step 1.6 - Grade Controls and
Step 4.8 - Channel Constrictions
are on The second page of this
report - Steps 6 through 7.

Project: **Trout River Head** **Phase 2 Reach Summary** page 2 of 2 March 20, 2007
Stream: **Trout River** Reach # **M03** Segment: **A** Completion Date: **August 24, 2006**
Organization: **Johnson Company** Observers: **Adam Robtoy, E. Crandell** Rain: **Yes**
Segment Length (ft): **13,386** Segment Location: **from M02 to braided segment 2200' downstream of end of M03**

Step 7. Rapid Geomorphic Assessment Data				
Confinement Type	Unconfined	Score	STD	Historic
7.1 Channel Degradation	11	None	Yes	
7.2 Channel Aggradation	13	None	No	
7.3 Widening Channel	12		No	
7.4 Change in Planform	14		No	
Total Score 50				
Geomorphic Rating 0.625				
Channel Evolution Model F				
Channel Evolution Stage III				
Geomorphic Condition Fair				
Stream Sensitivity Very High				

Step 6. Rapid Habitat Assessment Data		
Stream Gradient Type	High	Score
6.1 Epifaunal Substrate - Available Cover		15
6.2 Embeddedness		13
6.3 Velocity/Depth Patterns		16
6.4 Sediment Deposition		10
6.5 Channel Flow Status		10
6.6 Channel Alteration		13
6.7 Frequency of Riffles/Steps		16
6.8 Bank Stability		Left: 8 Right: 8
6.9 Bank Vegetation Protection		Left: 9 Right: 9
6.10 Riparian Vegetation Zone Width		Left: 8 Right: 7
Total Score		142
Habitat Rating		0.71
Habitat Stream Condition		Good

1.6 Grade Controls None			
Type	Location	Total	Total Height Above Water Photo Take GPSTaken

4.8 Channel Constrictions				
Type	Width	Photo Taken?	GPS Taken?	Floodprone Constriction?
Bedrock	45.0	No	No	Yes
Problem	Deposition Above			
Bridge	38.0	Yes	Yes	Yes
Problem	Deposition Below, Scour Below			
Bridge	125.	Yes	Yes	Yes
Problem	Deposition Above			
Bridge	82.0	Yes	Yes	Yes
Problem	Scour Below			

Narrative:
historic degradation, active minor widening and aggradation

Project: **Trout River Head**
Stream: **Trout River**
Organization: **Johnson Company**
Segment Length (ft): **1,400**

Reach # **M03**
Observers: **Adam Robtoy, E. Crandell**
Segment Location: **Braided section of M03, from 3200' downstream of end of M03 to 1200' downstream of end**

March 20, 2007
Completion Date: **August 24, 2006**

FIT: **Yes**
Rain: **Yes**

Phase 2 Segment Summary page 1 of 2
Segment: **B**
Why Not assessed:

Step 1. Valley and Floodplain Segmentation Channel Dimensions				Step 2. Stream Channel		Step 3. Riparian Features				Step 4. Flow & Flow Modifiers											
1.1 Segmentation		Channel Dimensions		1.2 Alluvial Fan		Yes		1.3 Corridor Encroachments		Length (ft)		One		Both		4.1 Springs / Seeps		None			
1.2 Alluvial Fan		Yes		1.3 Corridor Encroachments		Length (ft)		One		Both		Berm		0		0		4.2 Adjacent Wetlands		Some	
1.3 Corridor Encroachments		Length (ft)		One		Both		Berm		0		Roads		0		0		4.3 Flow Status		Moderate	
Roads		0		0		0		Railroads		0		Improved Paths		0		0		4.4 # of Debris Jams		1	
Development		0		0		0		1.4 Adjacent Side		Left		Hillside Slope		Steep		Steep		4.5 Impoundments		None	
Continuous w/		W/in 1 Bankfill		Never		Never		Texture		Not Evalua		Not Evalua		Not Evalua		Not Evalua		Impoundmt. Location			
Valley Features		Valley Width (ft)		1,991		Width Determination		Estimated		Confinement Type		Very Broad		Rock Gorge?		No		4.6 # of Stormwater Inputs		0	
Human-caused changed valley width?		no		Notes:		braided section which includes trout river restoration area,												4.7 Upstream Flow		None	
																		4.9 # of Beaver Dams		0	
																		Affected Length (ft)		0	

Project: **Trout River Head** **Phase 2 Reach Summary** page 2 of 2 March 20, 2007
 Stream: **Trout River** Reach # **M03** Segment: **B** Completion Date: **August 24, 2006**
 Organization: **Johnson Company** Observers: **Adam Robtoy, E. Crandell**
 Segment Length (ft): **1,400** Segment Location: **Braided section of M03, from 3200' downstream of end of M03 to 1200' downstream of**
 Rain: **Yes**

Step 7. Rapid Geomorphic Assessment Data				
Confinement Type	Unconfined	Score	STD	Historic
7.1 Channel Degradation	13	None		Yes
7.2 Channel Aggradation	8	C to D		No
7.3 Widening Channel	6			No
7.4 Change in Planform	12			No
Total Score 39				
Geomorphic Rating 0.4875				
Channel Evolution Model F				
Channel Evolution Stage III				
Geomorphic Condition Fair				
Stream Sensitivity Extreme				

Step 6. Rapid Habitat Assessment Data		
Stream Gradient Type	High	Score
6.1 Epifaunal Substrate - Available Cover		5
6.2 Embeddedness		7
6.3 Velocity/Depth Patterns		8
6.4 Sediment Deposition		3
6.5 Channel Flow Status		10
6.6 Channel Alteration		15
6.7 Frequency of Riffles/Steps		9
6.8 Bank Stability		Left: 8 Right: 10
6.9 Bank Vegetation Protection		Left: 9 Right: 9
6.10 Riparian Vegetation Zone Width		Left: 8 Right: 8
Total Score		109
Habitat Rating		0.545

Habitat Stream Condition Fair

1.6 Grade Controls None			
Type	Location	Total	Total Height Above Water
			GPSTaken

4.8 Channel Constrictions None			
Type	Width	Photo Taken?	GPS Taken?

Channel Constriction? Floodprone Constriction?			

Narrative:
 major aggradation and widening, braided D type channel

Project: **Trout River Head**
Stream: **Trout River**
Organization: **Johnson Company**
Segment Length (ft): **2,000**

Phase 2 Segment Summary page 1 of 2
Reach # **M03** Segment: **C**
Observers: **Adam Robtoy, E. Crandell** Why Not assessed:
Segment Location: **Upstream end of M03 (2,000' long)**

March 20, 2007 **FIT: Yes**
Completion Date: **August 24, 2006**
Rain: **Yes**

Step 1. Valley and Floodplain		Step 2. Stream Channel		Step 3. Riparian Features		Step 4. Flow & Flow Modifiers	
1.1 Segmentation Channel Dimensions		74		3.1 Stream Banks		4.1 Springs / Seeps	
1.2 Alluvial Fan		3.50		Typical Bank Slope		4.2 Adjacent Wetlands	
1.3 Corridor Encroachments		2.80		Bank Texture		4.3 Flow Status	
Length (ft)		500		Upper		4.4 # of Debris Jams	
One		4.90		Material Type		4.5 Impoundments	
Both		26.43		Consistency		Impoundmt. Location	
Berm		6.76		Non-cohesive		4.6 # of Stormwater Inputs	
Roads		1.40		Gravel		4.7 Upstream Flow	
Railroads		Moderate		Non-cohesive		4.9 # of Beaver Dams	
Improved Paths		Sedimented		Non-cohesive		Affected Length (ft)	
Development		400		Gravel			
1.4 Adjacent Side		2.10 Riffles Type		Bank Erosion			
Left		2.11 Riffle/Step Spacing (ft)		Erosion Length (ft)			
Right		400		0			
Hillside Slope		2.12 Substrate Composition		Revetmt. Type			
Very Steep		Bedrock		None			
Steep		0 %		Rip-Rap			
Never		Boulder		0			
Never		Cobble		Shrubs/Saplin			
Never		Coarse Gravel		Herbaceous			
Never		Fine Gravel		Sub-dominant			
Not Evalua		Sand		Bank Canopy			
Not Evalua		8 %		Canopy %			
Not Evalua		Silt/Clay Present?		Mid-Channel Canopy			
Not Evalua		No		Open			
Not Evalua		Detritus		3.2 Riparian Buffer			
Not Evalua		0 %		Buffer Width			
Not Evalua		# Large Woody		Dominant			
Not Evalua		0		Sub-dominant			
Not Evalua		2.13 Average Largest Particle on		Buffer Veg. Type			
Not Evalua		Bed		Shrubs/Saplin			
Not Evalua		100.0		Mixed Trees			
Not Evalua		Bar		Herbaceous			
Not Evalua		75.0		3.3 Riparian Corridor			
Not Evalua		mm		Corridor Land			
Not Evalua		mm		Dominant			
Not Evalua		2.14 Stream Type		Crop Shrubs/Saplin			
Not Evalua		Stream Type: C		Forest			
Not Evalua		Bed Material: Gravel		Residential			
Not Evalua		Subclass Slope: None		Amount			
Not Evalua		Bed Form: Riffle-Pool		Mean Height			
Not Evalua		2.15 Reference Stream Type		None			
Not Evalua		(if different from Phase 1)		None			
Notes:		historic straightening, segment just upstream of braided segment B		Straightening Length:		397	
				5.5 Dredging		None	
				5.3 Steep Riffles and Head Cuts		5.2 Other Features	
				Steep Riffles		Flood Neck Cutoff	
				Head Cuts		Avulsion	
				Trib Rejuv.		Braiding	
				1		0	
				5.4 Stream Ford or Animal		Island	
				5.5 Straightening		0	
				Straightening Length:		397	
				5.5 Dredging		None	
				5.3 Steep Riffles and Head Cuts		5.2 Other Features	
				Steep Riffles		Flood Neck Cutoff	
				Head Cuts		Avulsion	
				Trib Rejuv.		Braiding	
				1		0	
				5.4 Stream Ford or Animal		Island	
				5.5 Straightening		0	
				Straightening Length:		397	
				5.5 Dredging		None	
				5.3 Steep Riffles and Head Cuts		5.2 Other Features	
				Steep Riffles		Flood Neck Cutoff	
				Head Cuts		Avulsion	
				Trib Rejuv.		Braiding	
				1		0	
				5.4 Stream Ford or Animal		Island	
				5.5 Straightening		0	
				Straightening Length:		397	
				5.5 Dredging		None	

Note:
Step 1.6 - Grade Controls and
Step 4.8 - Channel Constrictions
are on The second page of this
report - Steps 6 through 7.

Project: **Trout River Head** **Phase 2 Reach Summary** page 2 of 2 March 20, 2007
 Stream: **Trout River** Reach # **M03** Segment: **C** Completion Date: **August 24, 2006**
 Organization: **Johnson Company** Observers: **Adam Robtoy, E. Crandell** Rain: **Yes**
 Segment Length (ft): **2,000** Segment Location: **Upstream end of M03 (2,000' long)**

Step 7. Rapid Geomorphic Assessment Data				
Confinement Type	Unconfined	Score	STD	Historic
7.1 Channel Degradation	11	None	Yes	Yes
7.2 Channel Aggradation	13	None	No	No
7.3 Widening Channel	12		No	No
7.4 Change in Planform	14		No	No
Total Score 50				
Geomorphic Rating 0.625				
Channel Evolution Model F				
Channel Evolution Stage III				
Geomorphic Condition Fair				
Stream Sensitivity Very High				

Step 6. Rapid Habitat Assessment Data		
Stream Gradient Type	High	Score
6.1 Epifaunal Substrate - Available Cover		15
6.2 Embeddedness		13
6.3 Velocity/Depth Patterns		16
6.4 Sediment Deposition		10
6.5 Channel Flow Status		10
6.6 Channel Alteration		13
6.7 Frequency of Riffles/Steps		16
6.8 Bank Stability		Left: 8 Right: 8
6.9 Bank Vegetation Protection		Left: 9 Right: 9
6.10 Riparian Vegetation Zone Width		Left: 8 Right: 7
Total Score		142
Habitat Rating		0.71

Habitat Stream Condition

Good

Narrative:
 historic degradation, active minor aggradation, widening, and planform adjustments

March 20, 2007 **FIT: Yes**
Completion Date: August 16, 2006
Rain: No

Step 7. Rapid Geomorphic Assessment Data				
Confinement Type	Unconfined	Score	STD	Historic
7.1 Channel Degradation		5	B to F	Yes
7.2 Channel Aggradation		15	None	No
7.3 Widening Channel		14		No
7.4 Change in Planform		15		No
Total Score 49				
Geomorphic Rating 0.6125				
Channel Evolution Model F				
Channel Evolution Stage II				
Geomorphic Condition Fair				
Stream Sensitivity Very High				
Step 6. Rapid Habitat Assessment Data				
Stream Gradient Type	High	Score		
6.1 Epifaunal Substrate - Available Cover		12		
6.2 Embeddedness		12		
6.3 Velocity/Depth Patterns		10		
6.4 Sediment Deposition		12		
6.5 Channel Flow Status		14		
6.6 Channel Alteration		6		
6.7 Frequency of Riffles/Steps		10		
6.8 Bank Stability		Left: 9 Right: 9		
6.9 Bank Vegetation Protection		Left: 8 Right: 3		
6.10 Riparian Vegetation Zone Width		Left: 8 Right: 2		
Total Score		115		
Habitat Rating		0.575		
Habitat Stream Condition		Fair		

Narrative:
Historic degradation, B to F,

Project: **Trout River Head**
Stream: **Trout River**
Organization: **Johnson Company**
Segment Length (ft): **6,340**

Phase 2 Segment Summary page 1 of 2
Reach # **M05** Segment: **0**
Observers: **Adam Robtoy, E. Crandell** Why Not assessed:
Segment Location: **from M04 to confluence of Wade Brook and Jay Brook**

March 20, 2007 **FIT: Yes**
Completion Date: **August 25, 2006**
Rain: **Yes**

Step 1. Valley and Floodplain		Step 2. Stream Channel		Step 3. Riparian Features		Step 4. Flow & Flow Modifiers	
1.1 Segmentation None		2.1 Bankfull Width 60		3.1 Stream Banks		4.1 Springs / Seeps Some	
1.2 Alluvial Fan No		2.2 Max Depth (ft) 3.20		Typical Bank Slope Steep		4.2 Adjacent Wetlands None	
1.3 Corridor Encroachments		2.3 Mean Depth (ft) 2.40		Bank Texture Left		4.3 Flow Status Moderate	
Length (ft) One Both		2.4 Floodprone Width (ft) 120		Upper		4.4 # of Debris Jams 0	
Berm 0		2.5 Aband. Floodpln 4.60		Material Type Gravel		4.5 Impoundments None	
Roads 0		2.6 Width/Depth Ratio 25.00		Consistency Non-cohesive		Impoundmt. Location	
Railroads 0		2.7 Entrenchment Ratio 2.00		Lower		4.6 # of Stormwater Inputs 0	
Improved Paths 0		2.8 Incision Ratio 1.44		Material Type Bedrock		4.7 Upstream Flow None	
Development 0		2.9 Sinuosity Low		Consistency Cohesive		4.9 # of Beaver Dams 0	
1.4 Adjacent Side Left Right		2.10 Riffles Type Complete		Bank Erosion Left		Affected Length (ft) 0	
Hillside Slope Very Steep Very Steep		2.11 Riffle/Step Spacing (ft) 150		Erosion Length (ft) 86		Step 5. Channel Bed and Planform Changes	
Continuous w/Sometimes Sometimes		2.12 Substrate Composition		Erosion Height (ft) 8.00		5.1 Bar Types	
W/in 1 Bankfill Sometimes Sometimes		Bedrock 2 %		Revetmt. Type None		Mid 1	
Texture Bedrock Bedrock		Boulder 9 %		Near Bank Veg. Type Left		Point 5	
1.5 Valley Features		Cobble 48 %		Dominant Coniferous		Diagonal Delta	
Valley Width (ft) 426		Coarse Gravel 26 %		Sub-dominant Deciduous		Island 2	
Width Determination Estimated		Fine Gravel 11 %		Bank Canopy Left		5.2 Other Features	
Confinement Type Broad		Sand 4 %		Canopy % 51-75		Flood Neck Cutoff 0	
Rock Gorge? No				Mid-Channel Canopy Open		Avulsion 0	
Human-caused changed valley width? no				3.2 Riparian Buffer		Braiding 0	
Notes:		Silt/Clay Present? No		Buffer Width Left		5.3 Steep Riffles and Head Cuts	
Based on VT DEC info. historic dredging occurred in reach after 1997 flood. No evidence of this was observed during the Phase 2. lots of side bars noted, minor degradation, several bedrock grade controls located throughout,		Detritus 0 %		Dominant >100		Steep Riffles 0	
		# Large Woody 26		Sub-dominant None		Head Cuts 0	
		2.13 Average Largest Particle on		Buffer Veg. Type Left		5.4 Stream Ford or Animal No	
		Bed 250.0 mm		Dominant Mixed Trees		5.5 Straightening No	
		Bar 200.0 mm		Sub-dominant Shrubs/Saplin		Straightening Length: 0	
		2.14 Stream Type		3.3 Riparian Corridor		5.5 Dredging None	
		Stream Type: C		Corridor Land Left			
		Bed Material: Cobble		Dominant Forest			
		Subclass Slope: b		Sub-dominant None			
		Bed Form: Step-Pool		Amount Mean Height			
		2.15 Reference Stream Type		Mass Failures None			
		(if different from Phase 1)		Gullies None			
				Mean Height 0.00			
				None 0.00			
				Note:			
				Step 1.6 - Grade Controls and			
				Step 4.8 - Channel Constrictions			
				are on The second page of this			
				report - Steps 6 through 7.			

Project: **Trout River Head** **Phase 2 Reach Summary** page 2 of 2 March 20, 2007
 Stream: **Trout River** **Reach # M05** Segment: **0** Completion Date: **August 25, 2006**
 Organization: **Johnson Company** Observers: **Adam Robtoy, E. Crandell**
 Segment Length (ft): **5,340** Segment Location: **from M04 to confluence of Wade Brook and Jay Brook** Rain: **Yes**

1.6 Grade Controls					Step 7. Rapid Geomorphic Assessment Data			
Type	Location	Total	Total Height Above Water	Photo Taken	Confinement Type	Unconfined Score	STD	Historic
Waterfall	Downstream	40.00	40.00	GPSTaken		14	None	Yes
Waterfall	Mid-Segment	6.00	6.00			17	None	No
Waterfall	Downstream	6.00	6.00			14		No
						20		No
Total Score						65		
Geomorphic Rating						0.8125		
Channel Evolution Model						F		
Channel Evolution Stage						III		
Geomorphic Condition						Good		
Stream Sensitivity						Moderate		

Step 6. Rapid Habitat Assessment Data		
Stream Gradient Type	High	Score
6.1 Epifaunal Substrate - Available Cover		17
6.2 Embeddedness		15
6.3 Velocity/Depth Patterns		20
6.4 Sediment Deposition		15
6.5 Channel Flow Status		10
6.6 Channel Alteration		20
6.7 Frequency of Riffles/Steps		16
6.8 Bank Stability		Left: 10 Right: 10
6.9 Bank Vegetation Protection		Left: 9 Right: 9
6.10 Riparian Vegetation Zone Width		Left: 9 Right: 9
Total Score		169
Habitat Rating		0.845

Narrative: historic minor degradation, active minor widening, possible historic dredging after 1997 flood, but several grade controls located throughout prevented major impacts from dredging

Habitat Stream Condition **Referen**

Project: **Trout River Head** **Phase 2 Segment Summary** page 1 of 2 March 20, 2007 FIT: Yes

Stream: **Unnamed Tributary 3 to Trout** Reach # **T3.01** Segment: **A** Completion Date: **August 1, 2006**

Organization: **Johnson Company** Observers: **Adam Robtoy, JPR** Why Not assessed: Rain: Yes

Segment Length (ft): **2,000** Segment Location: **From confluence with Trout River to just downstream of Fuller Bridge.**

Step 1. Valley and Floodplain				Step 2. Stream Channel				Step 3. Riparian Features				Step 4. Flow & Flow Modifiers			
1.1 Segmentation Channel Dimensions				2.1 Bankfull Width				3.1 Stream Banks				4.1 Springs / Seeps			
1.2 Alluvial Fan Yes				2.2 Max Depth (ft)				Typical Bank Slope Steep				4.2 Adjacent Wetlands			
1.3 Corridor Encroachments				2.3 Mean Depth (ft)				Bank Texture				4.3 Flow Status			
Length (ft) One Both				2.4 Floodprone Width (ft)				Upper				4.4 # of Debris Jams			
Berm				2.5 Aband. Floodpin				Material Type				4.5 Impoundments			
Roads				2.6 Width/Depth Ratio				Consistency				Impoundmt. Location			
Railroads				2.7 Entrenchment Ratio				Lower				4.6 # of Stormwater Inputs			
Improved Paths				2.8 Incision Ratio				Material Type				4.7 Upstream Flow			
Development				2.9 Sinuosity				Consistency				4.9 # of Beaver Dams			
311				Moderate				Non-cohesive				0			
1.4 Adjacent Side				2.10 Riffles Type				Bank Erosion				Affected Length (ft)			
Left Right				Sedimented				Left				0			
Hillside Slope				2.11 Riffle/Step Spacing (ft)				Erosion Length (ft)				Step 5. Channel Bed and Planform Changes			
Steep				120				54				5.1 Bar Types			
Continuous w/								Erosion Height (ft)							
Never								6.00							
W/in 1 Bankfill								Revetmt. Type							
Never								Rip-Rap							
Texture								Revetmt. Length (ft)							
Not Evalua								327							
Not Evalua								Near Bank Veg. Type							
Not Evalua								Left							
1.5 Valley Features								Dominant							
Valley Width (ft)								Herbaceous							
715								Lawn Shrubs/Saplin							
Width Determination								Sub-dominant							
Estimated								Bank Canopy							
Confinement Type								Left							
Very Broad								Right							
Rock Gorge?								Canopy %							
No								1-25							
Human-caused changed valley width?								Mid-Channel Canopy							
no								Open							
Notes:								3.2 Riparian Buffer							
Lower end of reach on alluvial fan, trailer								Buffer Width							
located in flood plain near lower end of								Left							
segment. historic dredging within reach								Dominant							
based on data from VT DEC, though no								5-25							
active dredging observed.								Sub-dominant							
								26-50							
								Buffer Veg. Type							
								Left							
								Right							
								Dominant							
								Herbaceous Shrubs/Saplin							
								Sub-dominant							
								Shrubs/Saplin							
								Herbaceous							
								3.3 Riparian Corridor							
								Corridor Land							
								Left							
								Dominant							
								Forest							
								Sub-dominant							
								Residential							
								Amount							
								Mean Height							
								None							
								0.00							
								0.00							
								Mass Failures							
								Gullies							
								Note:							
								Step 1.6 - Grade Controls and							
								Step 4.8 - Channel Constrictions							
								are on The second page of this							
								report - Steps 6 through 7.							

Note:
 Step 1.6 - Grade Controls and
 Step 4.8 - Channel Constrictions
 are on The second page of this
 report - Steps 6 through 7.

1.6 Grade Controls

Type	Location	Total	Total Height Above Water	Photo Taken	GPS Taken
Ledge	Mid-Segment	3.00	1.00		

4.8 Channel Constrictions

Type	Width	None		Channel Constriction?	Floodprone Constriction?
		Photo Taken?	GPS Taken?		

Narrative:

Historic degradation, active aggradation, widening and plaform. Historic dredging based on info. from VT DEC. No active dredging observed. alluvial fan portion of reach, mobile home located in floodplain

Step 7. Rapid Geomorphic Assessment Data

Confinement Type	Unconfined	Score	STD	Historic
7.1 Channel Degradation		13	None	Yes
7.2 Channel Aggradation		12	None	No
7.3 Widening Channel		12		No
7.4 Change in Planform		12		No
Total Score		49		
Geomorphic Rating		0.6125		
Channel Evolution Model		F		
Channel Evolution Stage		III		
Geomorphic Condition		Fair		
Stream Sensitivity		Very High		

Step 6. Rapid Habitat Assessment Data

Stream Gradient Type	High	Score
6.1 Epifaunal Substrate - Available Cover		13
6.2 Embeddedness		11
6.3 Velocity/Depth Patterns		13
6.4 Sediment Deposition		13
6.5 Channel Flow Status		9
6.6 Channel Alteration		9
6.7 Frequency of Riffles/Steps		15
6.8 Bank Stability		Left: 9 Right: 9
6.9 Bank Vegetation Protection		Left: 8 Right: 8
6.10 Riparian Vegetation Zone Width		Left: 5 Right: 5
Total Score		127
Habitat Rating		0.635
Habitat Stream Condition		Good

Project: **Trout River Head** Phase 2 Reach Summary page 2 of 2 March 20, 2007
Stream: **Unnamed Tributary 3 to Trout** Reach # **T3.01** Completion Date: **August 1, 2006**
Organization: **Johnson Company** Observers: **Adam Robtoy, JPR** Segment: **B** Rain: **Yes**
Segment Length (ft): **2,345** Segment Location: **From just downstream of Fuller Bridge to Black Falls road bridge.**

1.6 Grade Controls None

Type	Location	Total	Total Height Above Water	Photo Taken	GPSTaken
------	----------	-------	--------------------------	-------------	----------

Step 7. Rapid Geomorphic Assessment Data

Confinement Type	Unconfined	Score	STD	Historic
7.1 Channel Degradation		14	None	Yes
7.2 Channel Aggradation		18	None	No
7.3 Widening Channel		15		
7.4 Change in Planform		17		
Total Score 64				
Geomorphic Rating 0.8				
Channel Evolution Model F				
Channel Evolution Stage II				
Geomorphic Condition Good				
Stream Sensitivity Moderate				

Step 6. Rapid Habitat Assessment Data

Stream Gradient Type	High	Score
6.1 Epifaunal Substrate - Available Cover		13
6.2 Embeddedness		16
6.3 Velocity/Depth Patterns		16
6.4 Sediment Deposition		20
6.5 Channel Flow Status		19
6.6 Channel Alteration		7
6.7 Frequency of Riffles/Steps		16
6.8 Bank Stability		Left: 9 Right: 9
6.9 Bank Vegetation Protection		Left: 5 Right: 5
6.10 Riparian Vegetation Zone Width		Left: 5 Right: 5
Total Score		145
Habitat Rating		0.725
Habitat Stream Condition		Good

Narrative:

Historic degradation, reach dominated by rip-rap, residential encroachment along portions of both banks

Project:	Trout River Head		Phase 2 Reach Summary		page 2 of 2	March 20, 2007
Stream:	Unnamed Tributary 3 to Trout		Reach #	T3.02	Segment: 3	Completion Date: August 4, 2006
Organization:	Johnson Company		Observers:	Adam Robtoy, Evan Crandell		Rain: Yes
Segment Length (ft):	6,971		Segment Location:	from Black Falls Road Bridge to Bedrock Falls ~1 mile upstream		

Phase 2 Reach Summary

Segment: 0 Completion Date: August 4, 2006
Rain: Yes

Bedrock Falls ~1 mile upstream

1.6 Grade Controls

Type	Location	Total	Total Height Above Water	Photo Take ~ GPSTaken
Waterfall	Upstream	40.00	35.00	
Ledge	Mid-Segment	6.00	2.00	
Ledge	Downstream	5.00	2.00	
Ledge	Downstream	0.00	0.00	
Ledge	Downstream	0.00	0.00	
Ledge	Upstream	0.00	0.00	

4.8 Channel Constrictions

Type	Width	Photo Taken?	GPS Taken?	Channel Constriction?	Floodprone Constriction?
Bedrock	20.0	Yes	No	Yes	Yes
Problem Deposition Above					

Narrative:
measured channel width slightly wider than reference width

Step 7. Rapid Geomorphic Assessment Data

Confinement Type	Confined	Score	STD	Historic
7.1 Channel Degradation		16	None	No
7.2 Channel Aggradation		19	None	No
7.3 Widening Channel		15		No
7.4 Change in Planform		19		No
Total Score				
Geomorphic Rating		69		
		0.8625		
Channel Evolution Model		F		
Channel Evolution Stage		I		
Geomorphic Condition		Referenc		
Stream Sensitivity		Moderate		

Step 6. Rapid Habitat Assessment Data

Stream Gradient Type	High	Score
6.1 Epifaunal Substrate - Available Cover		17
6.2 Embeddedness		15
6.3 Velocity/Depth Patterns		19
6.4 Sediment Deposition		15
6.5 Channel Flow Status		14
6.6 Channel Alteration		19
6.7 Frequency of Riffles/Steps		18
6.8 Bank Stability	Left: 9 Right: 9	
6.9 Bank Vegetation Protection	Left: 9 Right: 9	
6.10 Riparian Vegetation Zone Width	Left: 9 Right: 9	
Total Score		171
Habitat Rating		0.855

Habitat Stream Condition

Step 1. Valley and Floodplain			Step 2. Stream Channel		Step 3. Riparian Features		Step 4. Flow & Flow Modifiers	
1.1 Segmentation	None		2.1 Bankfull Width	40	3.1 Stream Banks		4.1 Springs / Seeps	Some
1.2 Alluvial Fan	No		2.2 Max Depth (ft)	2.80	Typical Bank Slope	Steep	4.2 Adjacent Wetlands	None
1.3 Corridor Encroachments			2.3 Mean Depth (ft)	2.30	Bank Texture	Left	4.3 Flow Status	Moderate
Length (ft)	One	Both	2.4 Floodprone Width (ft)	125	Upper		4.4 # of Debris Jams	0
Berns	0	0	2.5 Aband. Floodpln	5.10	Material Type	Sand	4.5 Impoundments	None
Roads	0	0	2.6 Width/Depth Ratio	17.39	Consistency	Non-cohesive	Impoundmt. Location	
Railroads	0	0	2.7 Entrenchment Ratio	3.13	Lower		4.6 # of Stormwater Inputs	0
Improved Paths	0	0	2.8 Incision Ratio	1.82	Material Type	Gravel	4.7 Upstream Flow	None
Development	0	0	2.9 Sinuosity	Moderate	Consistency	Non-cohesive	4.9 # of Beaver Dams	1
1.4 Adjacent Side	Left	Right	2.10 Riffles Type	Sedimented	Bank Erosion	Left	Affected Length (ft)	0
Hillside Slope	Steep	Very Steep	2.11 Riffle/Step Spacing (ft)	250	Erosion Length (ft)	143	Step 5. Channel Bed and Planform Changes	
Continuous w/ Sometimes	Sometimes	Sometimes			Erosion Height (ft)	5.00	5.1 Bar Types	
W/in 1 Bankfill Sometimes	Sometimes	Sometimes	2.12 Substrate Composition		Revetmt. Type	Rip-Rap	Mid	Point
Texture	Bedrock	Bedrock	Bedrock	0 %	Revetmt. Length (ft)	1,080	3	18
Valley Width (ft)	674		Boulder	0 %	Near Bank Veg. Type	Left	Diagonal	Delta
Width Determination	Estimated		Cobble	8 %	Dominant	Herbaceous	3	1
Confinement Type	Very Broad		Coarse Gravel	57 %	Sub-dominant	Shrubs/Saplin Shrubs/Saplin	5.2 Other Features	
Rock Gorge?	No		Fine Gravel	27 %	Bank Canopy	Right	Flood Neck Cutoff	Avulsion
Human-caused changed valley width?	no		Sand	8 %	Canopy %	1-25	0	0
					Mid-Channel Canopy	Open	5.3 Steep Riffles and Head Cuts	
Notes:			Silt/Clay Present?	No	3.2 Riparian Buffer		Steep Riffles	Head Cuts
Upper portion of the Reach (800') dominated by bedrock gorge, and old dam mill (no longer there).			Detritus	5 %	Buffer Width	Left	0	0
Lower 1/2 of reach slightly more incised (~1.8) than upper portion (~1.5).			# Large Woody	36	Dominant	5-25	5.4 Stream Ford or Animal	Yes
Beaver dam being built in middle of reach just downstream of the two small tributaries which feed into reach. Dam not yet complete and not holding back any water at the time of the assessment			2.13 Average Largest Particle on		Sub-dominant	26-50	5.5 Straightening	Yes
historic dredging noted in phase 1, no active dredging observed			Bed	50.0 mm	Buffer Veg. Type	Left	Straightening Length:	1,432
			Bar	40.0 mm	Dominant	Shrubs/Saplin Shrubs/Saplin	5.5 Dredging	None
			2.14 Stream Type		Sub-dominant	Herbaceous		
			Stream Type:	C	3.3 Riparian Corridor			
			Bed Material:	Gravel	Corridor Land	Left		
			Subclass Slope:	None	Dominant	Hay		
			Bed Form:	Riffle-Pool	Sub-dominant	Pasture		
			2.15 Reference Stream Type		Mass Failures	None		
			(if different from Phase 1)		Gullies	None		
					Mean Height	0.00		
						0.00		

Note:
Step 1.6 - Grade Controls and
Step 4.8 - Channel Constrictions
are on The second page of this
report - Steps 6 through 7.

Project: **Trout River Head**
Stream: **Unnamed Tributary 4 to Trout**
Organization: **Johnson Company**
Segment Length (ft): **8,561**

Phase 2 Reach Summary
Reach # **T4.01**
Observers: **Adam Robtoy, Paul Stanley**
Segment Location: **from confluence with Trout to Hutchins Bridge Road.**

page 2 of 2
Segment: **C**
Completion Date: **August 30, 2006**
Rain: **Yes**

March 20, 2007

1.6 Grade Controls				
Type	Location	Total	Total Height Above Water	Photo Taken GPSTaken
Waterfall	Upstream	10.00	10.00	

Step 7. Rapid Geomorphic Assessment Data				
Confinement Type	Unconfined	Score	STD	Historic
7.1 Channel Degradation		8	None	Yes
7.2 Channel Aggradation		14	None	No
7.3 Widening Channel		12		No
7.4 Change in Planform		13		No
Total Score		47		
Geomorphic Rating		0.5875		
Channel Evolution Model		F		
Channel Evolution Stage		II		
Geomorphic Condition		Fair		
Stream Sensitivity		High		

Step 6. Rapid Habitat Assessment Data				
Stream Gradient Type	High	Score		
6.1 Epifaunal Substrate - Available Cover		10		
6.2 Embeddedness		10		
6.3 Velocity/Depth Patterns		14		
6.4 Sediment Deposition		10		
6.5 Channel Flow Status		11		
6.6 Channel Alteration		9		
6.7 Frequency of Riffles/Steps		13		
6.8 Bank Stability		Left: 9 Right: 7		
6.9 Bank Vegetation Protection		Left: 7 Right: 7		
6.10 Riparian Vegetation Zone Width		Left: 5 Right: 5		
Total Score		117		
Habitat Rating		0.585		
Habitat Stream Condition		Fair		

4.8 Channel Constrictions					
Type	Width	Photo Taken?	GPS Taken?	Channel Constriction?	Floodprone Constriction?
Bedrock	20.0	No	No	Yes	Yes
Problem	None				

Narrative:

Historic degradation, historic straightening, lots of rip-rap,

FIT: Yes
August 31, 2006
Rain: Yes
cream.

Weight	0.00	0.00
--------	------	------

Step 1.6 - Grade Controls and
Step 4.8 - Channel Constrictions
are on The second page of this
report - Steps 6 through 7.

Project: **Trout River Head** **Phase 2 Reach Summary** page 2 of 2 March 20, 2007
 Stream: **Unnamed Tributary 4 to Trout** Reach # **T4.02** Segment: **C** Completion Date: **August 31, 2006**
 Organization: **Johnson Company** Observers: **Adam Robtoy, Sue Brassett**
 Segment Length (ft): **4,835** Segment Location: **From Hutchins Bridge to where valley widens approximately 1 mile upstream.** Rain: **Yes**

Step 7. Rapid Geomorphic Assessment Data				
Confinement Type	Unconfined	Score	STD	Historic
7.1 Channel Degradation		16	None	Yes
7.2 Channel Aggradation		18	None	No
7.3 Widening Channel		16		No
7.4 Change in Planform		19		No
Total Score		69		
Geomorphic Rating		0.8625		
Channel Evolution Model		F		
Channel Evolution Stage		I		
Geomorphic Condition		Referenc		
Stream Sensitivity		Moderate		

Step 6. Rapid Habitat Assessment Data		
Stream Gradient Type	High	Score
6.1 Epifaunal Substrate - Available Cover		15
6.2 Embeddedness		15
6.3 Velocity/Depth Patterns		19
6.4 Sediment Deposition		15
6.5 Channel Flow Status		15
6.6 Channel Alteration		20
6.7 Frequency of Riffles/Steps		18
6.8 Bank Stability		Left: 10 Right: 10
6.9 Bank Vegetation Protection		Left: 10 Right: 10
6.10 Riparian Vegetation Zone Width		Left: 10 Right: 10
Total Score		177
Habitat Rating		0.885

Habitat Stream Condition Referen

Narrative:

reach found to be in reference condition, historic dredging noted by VT DEC, though no evidence observed during Phase 2.

1.6 Grade Controls

None

Type

Location

Total

Total Height Above Water

Photo Taken

GPSTaken

4.8 Channel Constrictions

None

Type

Width

Photo Taken?

GPS Taken?

Channel Constriction?

Floodprone Constriction?

Narrative:

widening and planform adjustments, meander pattern opposite of Phase I meander centerline pattern

Step 7. Rapid Geomorphic Assessment Data

Confinement Type

Unconfined

Score

STD

Historic

7.1 Channel Degradation

14

None

Yes

7.2 Channel Aggradation

12

None

No

7.3 Widening Channel

12

No

7.4 Change in Planform

13

No

Total Score

51

Geomorphic Rating

0.6375

Channel Evolution Model

F

Channel Evolution Stage

III

Geomorphic Condition

Fair

Stream Sensitivity

Very High

Step 6. Rapid Habitat Assessment Data

Stream Gradient Type

High

Score

6.1 Epifaunal Substrate - Available Cover

8

6.2 Embeddedness

10

6.3 Velocity/Depth Patterns

14

6.4 Sediment Deposition

12

6.5 Channel Flow Status

10

6.6 Channel Alteration

10

6.7 Frequency of Riffles/Steps

16

6.8 Bank Stability

Left: 7 Right: 7

6.9 Bank Vegetation Protection

Left: 8 Right: 5

6.10 Riparian Vegetation Zone Width

Left: 5 Right: 3

Total Score

115

Habitat Rating

0.575

Habitat Stream Condition

Fair

Project: **Trout River Head** March 20, 2007 **FIT: Yes**
Stream: **Unnamed Tributary 4 to Trout** Reach # **T4.04** page 1 of 2 **Phase 2 Segment Summary** Completion Date: **September 13, 2006**
Organization: **Johnson Company** Observers: **Adam Robtoy, Paul Stanley** Segment: **0** Why Not assessed: **Rain: Yes**
Segment Length (ft): **4,895** Segment Location: **from Sundell Road to confluences with Pacific Brook**

Step 1. Valley and Floodplain			Step 2. Stream Channel			Step 3. Riparian Features			Step 4. Flow & Flow Modifiers		
1.1 Segmentation None			2.1 Bankfull Width 36			3.1 Stream Banks			4.1 Springs / Seeps Some		
1.2 Alluvial Fan No			2.2 Max Depth (ft) 3.00			Typical Bank Slope Steep			4.2 Adjacent Wetlands Some		
1.3 Corridor Encroachments			2.3 Mean Depth (ft) 2.40			Bank Texture			4.3 Flow Status Moderate		
Length (ft)			2.4 Floodprone Width (ft) 310			Upper			4.4 # of Debris Jams 1		
Berm			2.5 Aband. Floodpln 3.60			Material Type			4.5 Impoundments None		
Roads			2.6 Width/Depth Ratio 15.00			Consistency			Impoundmt. Location		
Railroads			2.7 Entrenchment Ratio 8.61			Lower			4.6 # of Stormwater Inputs 0		
Improved Paths			2.8 Incision Ratio 1.20			Material Type			4.7 Upstream Flow None		
Development			2.9 Sinuosity Moderate			Consistency			4.9 # of Beaver Dams 0		
0			2.10 Riffles Type Sedimented			Bank Erosion			Affected Length (ft) 0		
1.4 Adjacent Side			2.11 Riffle/Step Spacing (ft) 400			Erosion Length (ft)			Step 5. Channel Bed and Planform Changes		
Left			2.12 Substrate Composition			Erosion Height (ft)			5.1 Bar Types		
Steep			Bedrock			Revetmt. Type			Mid		
Never			Boulder			Revetmt. Length (ft)			Point		
Never			Cobble			Near Bank Veg. Type			Delta		
Never			Coarse Gravel			Dominant			Island		
Never			Fine Gravel			Sub-dominant			0		
Never			Sand			Bank Canopy			0		
No			Silt/Clay Present? No			Canopy %			5.2 Other Features		
no			Detritus 10 %			Mid-Channel Canopy			Flood		
			# Large Woody 8			Open			Neck Cutoff		
			2.13 Average Largest Particle on			3.2 Riparian Buffer			Avulsion		
			Bed 125.0 mm			Buffer Width			Head Cuts		
			Bar 120.0 mm			Dominant			Trib Rejuv.		
			2.14 Stream Type			Sub-dominant			5.3 Steep Riffles and Head Cuts		
			Stream Type: C			Dominant			Steep Riffles		
			Bed Material: Gravel			Sub-dominant			0		
			Subclass Slope: None			Buffer Veg. Type			0		
			Bed Form: Riffle-Pool			Dominant			5.4 Stream Ford or Animal		
			2.15 Reference Stream Type			Sub-dominant			5.5 Straightening		
			(if different from Phase 1)			3.3 Riparian Corridor			Straightening Length: 669		
						Corridor Land			5.5 Dredging		
						Dominant			Commercial Mining		
						Sub-dominant					
						Mass Failures			Note:		
						Gullies			Step 1.6 - Grade Controls and		
									Step 4.8 - Channel Constrictions		
									are on The second page of this		
									report - Steps 6 through 7.		

Project: **Trout River Head** **Phase 2 Reach Summary** page 2 of 2 March 20, 2007
 Stream: **Unnamed Tributary 4 to Trout** Reach # **T4.04** Segment: **C** Completion Date: **September 13,**
 Organization: **Johnson Company** Observers: **Adam Robtoy, Paul Stanley** Rain: **Yes**
 Segment Length (ft): **4,395** Segment Location: **from Sundell Road to confluences with Pacific Brook**

Step 7. Rapid Geomorphic Assessment Data				
Confinement Type	Unconfined	Score	STD	Historic
7.1 Channel Degradation		16	None	Yes
7.2 Channel Aggradation		16	None	No
7.3 Widening Channel		15		No
7.4 Change in Planform		15		No
Total Score		62		
Geomorphic Rating		0.775		
Channel Evolution Model		F		
Channel Evolution Stage		II		
Geomorphic Condition		Good		
Stream Sensitivity		High		

Step 6. Rapid Habitat Assessment Data

Stream Gradient Type	High	Score
6.1 Epifaunal Substrate - Available Cover		12
6.2 Embeddedness		10
6.3 Velocity/Depth Patterns		12
6.4 Sediment Deposition		10
6.5 Channel Flow Status		13
6.6 Channel Alteration		14
6.7 Frequency of Riffles/Steps		13
6.8 Bank Stability		Left: 10 Right: 7
6.9 Bank Vegetation Protection		Left: 10 Right: 6
6.10 Riparian Vegetation Zone Width		Left: 10 Right: 5
Total Score		132
Habitat Rating		0.66

Habitat Stream Condition **Good**

1.6 Grade Controls			
Type	Location	Total	Total Height Above Water GPSTaken
Waterfall	Downstream	6.00	4.00

4.8 Channel Constrictions

Type	Width	Photo Taken?	GPS Taken?	Channel Constriction?	Floodprone Constriction?
Bedrock	25.0	Yes	Yes	Yes	Yes
Problem	Deposition Above,	Deposition Below			
Bridge	44.0	Yes	Yes	No	Yes
Problem	Deposition Above,	Deposition Below			
Bridge	30.0	Yes	Yes	Yes	Yes
Problem	Deposition Above				

Narrative:
 Minor historic degradation, widening and planform

Project: **Trout River Head** **Phase 2 Reach Summary** page 2 of 2 March 20, 2007
 Stream: **Unnamed Tributary 5 to Trout** Reach # **T5.01** Segment: **0** Completion Date: **August 23, 2006**
 Organization: **Johnson Company** Observers: **Adam Robtoy, J.P.R.** Rain: **Yes**
 Segment Length (ft): **2,419** Segment Location: **From confluence with Trout River to confluence with 1st major tributary.**

1.6 Grade Controls					Step 7. Rapid Geomorphic Assessment Data			
Type	Location	Total	Total Height Above Water	Photo Taken	Confinement Type	Score	STD	Historic
Ledge	Downstream	5.00	3.00	GPSTaken	Confined	17	None	No
Ledge	Downstream	5.00	3.00			17	None	No
Waterfall	Downstream	8.00	7.00			15		No
Waterfall	Mid-Segment	8.00	7.00			19		No
					Total Score	68		
					Geomorphic Rating	0.85		
					Channel Evolution Model	F		
					Channel Evolution Stage	I		
					Geomorphic Condition	Referenc		
					Stream Sensitivity	Low		

Step 6. Rapid Habitat Assessment Data		
Stream Gradient Type	High	Score
6.1 Epifaunal Substrate - Available Cover		18
6.2 Embeddedness		16
6.3 Velocity/Depth Patterns		17
6.4 Sediment Deposition		16
6.5 Channel Flow Status		15
6.6 Channel Alteration		19
6.7 Frequency of Riffles/Steps		18
6.8 Bank Stability		Left: 8 Right: 10
6.9 Bank Vegetation Protection		Left: 9 Right: 9
6.10 Riparian Vegetation Zone Width		Left: 9 Right: 9
Total Score		173
Habitat Rating		0.865

Narrative: **Minor Widening**
 Habitat Stream Condition **Referen**

Step 1. Valley and Floodplain				Step 2. Stream Channel				Step 3. Riparian Features				Step 4. Flow & Flow Modifiers			
1.1 Segmentation		None		2.1 Bankfull Width		43		3.1 Stream Banks				4.1 Springs / Seeps		Some	
1.2 Alluvial Fan		No		2.2 Max Depth (ft)		3.20		Typical Bank Slope		Steep		4.2 Adjacent Wetlands		None	
1.3 Corridor Encroachments				2.3 Mean Depth (ft)		2.30		Bank Texture		Left		4.3 Flow Status		Moderate	
		Length (ft)		One		Both		Upper				4.4 # of Debris Jams		0	
		Berms		0		0		Material Type		Gravel		4.5 Impoundments		None	
		Roads		0		0		Consistency		Non-cohesive		Impoundmt. Location		0	
		Railroads		0		0		Lower				4.6 # of Stormwater Inputs		None	
		Improved Paths		0		0		Material Type		Bedrock		4.7 Upstream Flow		0	
		Development		0		Low		Consistency		Cohesive		4.9 # of Beaver Dams		0	
1.4 Adjacent Side		Left		Right				Bank Erosion		Left		Affected Length (ft)		0	
Hillside Slope		Very Steep		Very Steep		200		Erosion Length (ft)		234		34			
Continuous w/Sometimes		Sometimes		Sometimes				Erosion Height (ft)		6.50		7.00			
W/in 1 Bankfill		Sometimes		Sometimes				Revetmt. Type		None		None			
		Texture		Bedrock		Other		Reveitmt. Length (ft)		0		0			
1.5 Valley Features								Near Bank Veg. Type		Left		Right			
Valley Width (ft)		200						Dominant		Deciduous		Deciduous			
Width Determination		Measured						Sub-dominant		Shrubs/Saplin Shrubs/Saplin		Right			
Confinement Type		Narrow						Bank Canopy		Left		Right			
Rock Gorge?		No						Canopy %		51-75		51-75			
Human-caused changed valley width?		No						Mid-Channel Canopy		Open					
								3.2 Riparian Buffer							
Notes:								Buffer Width		Left		Right			
historic dredging noted in phase 1, no active dredging observed, no major adjustments observed except for minor historic degradation and two islands with split flows on either side, no encroachments								Dominant		>100		>100			
								Sub-dominant		None		26-50			
								Buffer Veg. Type		Left		Right			
								Dominant		Mixed Trees		Mixed Trees			
								Sub-dominant		Shrubs/Saplin Shrubs/Saplin		Shrubs/Saplin			
								3.3 Riparian Corridor							
								Corridor Land		Left		Right			
								Dominant		Forest		Forest			
								Sub-dominant		None		None			
								Amount		Mean Height					
								Mass Failures		None		0.00			
								Gullies		None		0.00			

Project: **Trout River Head** **Phase 2 Reach Summary** page 2 of 2 March 20, 2007
 Stream: **Unnamed Tributary 5 to Trout** Reach # **T6.01** Segment: **C** Completion Date: **August 29, 2006**
 Organization: **Johnson Company** Observers: **Adam Robtoy, D.B.** Rain: **Yes**
 Segment Length (ft): **2,701** Segment Location: **From confluence with Wade Brook to 1st major tributary ~ 1/2 mile upstream.**

1.6 Grade Controls				
Type	Location	Total	Total Height Above Water	Photo Taken
Waterfall	Mid-Segment	5.00	2.00	GPSTaken

Step 7. Rapid Geomorphic Assessment Data				
Confinement Type	Unconfined			
	Score	STD	Historic	
7.1 Channel Degradation	15	None	Yes	
7.2 Channel Aggradation	16	None	No	
7.3 Widening Channel	15		No	
7.4 Change in Planform	17		No	
Total Score		63		
Geomorphic Rating		0.7875		
Channel Evolution Model		F		
Channel Evolution Stage		III		
Geomorphic Condition		Good		
Stream Sensitivity		Moderate		

Step 6. Rapid Habitat Assessment Data				
Stream Gradient Type	High			
	Score			
6.1 Epifaunal Substrate - Available Cover	16			
6.2 Embeddedness	16			
6.3 Velocity/Depth Patterns	16			
6.4 Sediment Deposition	14			
6.5 Channel Flow Status	11			
6.6 Channel Alteration	19			
6.7 Frequency of Riffles/Steps	16			
6.8 Bank Stability	Left: 8 Right: 9			
6.9 Bank Vegetation Protection	Left: 10 Right: 10			
6.10 Riparian Vegetation Zone Width	Left: 10 Right: 10			
Total Score		165		
Habitat Rating		0.825		
Habitat Stream Condition		Good		

Narrative:
 Minor widening and historic degradation. historic dredging from phase 1, no active dredging observed, minor bank erosion at a few spots, but no major problem areas noted

Project: Trout River Head

Stream: Unnamed Tributary 7 to Trout

Phase 2 Segment Summary

page 1 of 2

March 20, 2007

FIT: Yes

Segment Length (ft): 10,973

Reach # T7.01

Segment: 0

Completion Date: September 14, 2006

Organization: Johnson Company

Observers: Adam Robtoy, Brian Lerich

Why Not assessed:

Rain: Yes

Segment Location: from confluence with Jay Brook to just upstream of Amadon Road Bridge

Step 1. Valley and Floodplain1.1 Segmentation **None**1.2 Alluvial Fan **No**

1.3 Corridor Encroachments

Length (ft) One Both

Bermes 0 0

Roads 0 0

Railroads 0 0

Improved Paths 0 0

Development 0 0

1.4 Adjacent Side

Left Right

Hillslope Slope **Very Steep** **Very Steep**Continuous w/ **Sometimes** **Sometimes**W/in 1 Bankfill **Sometimes** **Sometimes**Texture **Bedrock** **Bedrock**

1.5 Valley Features

Valley Width (ft) **150**Width Determination **Measured**Confinement Type **Semi-confined**Rock Gorge? **No**Human-caused changed valley width? **No****Notes:**

reach appears to be reference B-type stream, no encroachments or major conflict areas noted,

Step 2. Stream Channel2.1 Bankfull Width **39**2.2 Max Depth (ft) **3.10**2.3 Mean Depth (ft) **2.50**2.4 Floodprone Width (ft) **66**2.5 Aband. Floodpln **3.10**2.6 Width/Depth Ratio **15.60**2.7 Entrenchment Ratio **1.69**2.8 Incision Ratio **1.00**2.9 Sinuosity **Moderate**2.10 Riffles Type **Complete**2.11 Riffle/Step Spacing (ft) **150**

2.12 Substrate Composition

Bedrock **0 %**Boulder **7 %**Cobble **51 %**Coarse Gravel **30 %**Fine Gravel **7 %**Sand **5 %**Silt/Clay Present? **No**Detritus **10 %**# Large Woody **57**

2.13 Average Largest Particle on

Bed **230.0 mm**Bar **175.0 mm****2.14 Stream Type**Stream Type: **B**Bed Material: **Cobble**Subclass Slope: **None**Bed Form: **Step-Pool**

2.15 Reference Stream Type

(if different from Phase 1)

Step 3. Riparian Features

3.1 Stream Banks

Typical Bank Slope **Steep**Bank Texture **Left Right**Upper **Gravel**Material Type **Gravel**Consistency **Non-cohesive**Lower **Non-cohesive**Material Type **Bedrock**Consistency **Cohesive**Bank Erosion **Left Right**Erosion Length (ft) **40 0**Erosion Height (ft) **6.00 0.00**Revetmt. Type **None**Revetmt. Length (ft) **0 0**Near Bank Veg. Type **Left Right**Dominant **Coniferous**Sub-dominant **Coniferous**Bank Canopy **Shrubs/Saplin Shrubs/Saplin**Canopy % **Left Right**Mid-Channel Canopy **51-75 51-75**

3.2 Riparian Buffer

Buffer Width **Open**Dominant **Left Right**Sub-dominant **>100 >100**Buffer Veg. Type **None**Dominant **Left Right**Sub-dominant **Mixed Trees**

3.3 Riparian Corridor

Corridor Land **Left Right**Dominant **Forest**Sub-dominant **Forest**Mass Failures **None**Gullies **Multiple**Mean Height **28.50**Amount **0.00****Step 4. Flow & Flow Modifiers**4.1 Springs / Seeps **Some**4.2 Adjacent Wetlands **None**4.3 Flow Status **Moderate**4.4 # of Debris Jams **0**4.5 Impoundments **None**

Impoundmt. Location

4.6 # of Stormwater Inputs **0**4.7 Upstream Flow **None**4.9 # of Beaver Dams **0**Affected Length (ft) **0****Step 5. Channel Bed and Planform Changes**

5.1 Bar Types

Mid **Point Side**Diagonal **11 5**Island **2 0**

5.2 Other Features

Flood Neck Cutoff **Avulsion Braiding**Steep Riffles **Head Cuts Trib Rejuv.**

5.3 Steep Riffles and Head Cuts

Stream Riffles **Head Cuts Trib Rejuv.**5.4 Stream Ford or Animal **No**5.5 Straightening **No**Straightening Length: **0**5.5 Dredging **None**

Note:

Step 1.6 - Grade Controls and
Step 4.8 - Channel Constrictions
are on The second page of this
report - Steps 6 through 7.

Project: **Trout River Head**
Stream: **Unnamed Tributary 7 to Trout**
Organization: **Johnson Company**
Segment Length (ft): **10,073**

Phase 2 Reach Summary
Reach # **T7.01**
Observers: **Adam Robtoy, Brian Lerich**
Segment Location: **from confluence with Jay Brook to just upstream of Amadon Road Bridge**

page 2 of 2
Segment: **C**
Completion Date: **September 14,**
Rain: **Yes**

March 20, 2007

1.6 Grade Controls				
Type	Location	Total	Total Height Above Water	Photo Taken
Waterfall	Downstream	8.00	5.00	GPSTaken
Step 7. Rapid Geomorphic Assessment Data				
Confinement Type	Confined	Score	STD	Historic
7.1 Channel Degradation		17	None	No
7.2 Channel Aggradation		19	None	No
7.3 Widening Channel		16		No
7.4 Change in Planform		20		No
Total Score		72		
Geomorphic Rating		0.9		
Channel Evolution Model		F		
Channel Evolution Stage		I		
Geomorphic Condition		Referenc		
Stream Sensitivity		Moderate		

Step 6. Rapid Habitat Assessment Data		
Stream Gradient Type	High	Score
6.1 Epifaunal Substrate - Available Cover		17
6.2 Embeddedness		15
6.3 Velocity/Depth Patterns		17
6.4 Sediment Deposition		18
6.5 Channel Flow Status		15
6.6 Channel Alteration		20
6.7 Frequency of Riffles/Steps		19
6.8 Bank Stability	Left: 9 Right: 9	
6.9 Bank Vegetation Protection	Left: 10 Right: 10	
6.10 Riparian Vegetation Zone Width	Left: 10 Right: 10	
Total Score		179
Habitat Rating		0.895
Habitat Stream Condition		Referen

Narrative:
no major adjustments noted, reach found to be in reference condition

Stream Geomorphic Assessment

VT DEC

Culvert Summary Report

General Information			
VTrans Structure ID	vtrans-700011022506033	Local Structure ID	---
Assessment Date	09/20/2006	Observers	Adam Robtoy, Staci Po
Town	Berkshire		
Location	---		
Latitude	44.93	Longitude	-72.70
Road Name	WOODWARD NEIGHBORHOOD RD	Road Type	Gravel
Stream Name	Unnamed Tributary	High flow stage	No
Culvert Information			
Material	Steel Corrugated	Number of culverts	1
Culvert Length	45 ft.	Skewed to roadway?	No
Culvert Height	72 inches (6.0 ft.)	Culvert Overflow Pipe	No
Culvert Width	108 inches (9.0 ft.)		
Geomorphic Information			
Floodplain filled by roadway approaches	Entirely		
Structure is located at significant break in valley slope	No		
Obstructions at the opening of the structure	---		
Culvert slope as compared with channel slope is significantly	Same		
Steep riffle present immediately upstream of structure	Yes		
If channel avulses, stream will	Cross Road		
Estimated distance avulsion would follow road	--- ft.		
Angle of stream flow approaching structure	Sharp Bend		
Culvert outlet invert	Cascade		
Outlet drop (invert to water surface)	0.7 ft.		
Water depth in culvert (at outlet)	0.1 ft.		
Pool present immediately downstream of structure	Yes		
Downstream bank heights are substantially higher than upstream bank heights	Yes		
More Geomorphic Information			
Dominant Bed Material	Gravel		
Bedrock Present	No		
Material Present throughout	No		
Type of Sediment Deposits	---		
Elevation of sediment deposits greater than 1/2 bankfull	Yes		
Bank Erosion	None		
Hard Bank Armoring	Intact		
Stream bed scour causing undermining around or under structure	---		
Beaver Dam near Structure	No		
Beaver Dam distance (ft.)	---		
Vegetation			
Upstream	Downstream	In Structure	
Dominant Vegetation Type - Left	Herbaceous/Grass	Herbaceous/Grass	
Dominant Vegetation Type - Right	Herbaceous/Grass	Herbaceous/Grass	
Does a band of shrub/forest vegetation 50 ft. wide start within 25 ft. of the structure and extend at least 500 ft. up/downstream?	No	No	
Vegetation Band - Left	No		
Vegetation Band - Right	No		

Wildlife			
Species			
Other Information			
Spatial location data collected with GPS?			
Comments			

VT DEC • 103 South Main Street • Waterbury, VT 05671

Vermont Department of Environmental Conservation

A Vermont Government Website Copyright © 2004-2006 State of Vermont - All rights reserved



Stream Geomorphic Assessment



Bridge Summary Report

General Information			
Vtrans Structure ID	vtrans-700011022206033	Local Structure ID	---
Assessment Date	07/06/2006	Observers	Adam Robtoy, Staci Po
Town	Berkshire		
Location	---		
Latitude	44.93	Longitude	-72.69
Road Name	Route 118	Road Type	Paved
Stream Name	Trout River		
Channel width	117 ft. (Measured)	High flow stage	No
Bridge/Arch Information			
Material	Steel	Number of bridge piers/arches	0
Bridge Width	33 ft.	Skewed to roadway?	No
Bridge Clearance	16 ft.		
Bridge/Arch Span	144 ft.		
Geomorphic Information			
Floodplain filled by roadway approaches			
Structure is located at significant break in valley slope			
Obstructions at the opening of the structure			
Steep riffle present immediately upstream of structure			
If channel avulses, stream will			
Estimated distance avulsion would follow road			
Angle of stream flow approaching structure			
Pool present immediately downstream of structure			
Downstream bank heights are substantially higher than upstream bank heights			
Stepped footers			
More Geomorphic Information			
Dorninant Bed Material			
Gravel			
Bedrock Present			
Type of Sediment Deposits			

Elevation of sediment deposits greater than 1/2 bankfull			
No			
Bank Erosion			
None			
Hard Bank Armoring			
Intact			
Stream bed scour causing undermining around or under structure			

Beaver Dam near Structure			
No			
Beaver Dam distance (ft.)			


Vegetation			
Upstream			
Downstream			
In Structure			
Dominant Vegetation Type - Left			
Herbaceous/Grass			
Dominant Vegetation Type - Right			
Herbaceous/Grass			
Does a band of shrub/forest vegetation 50 ft. wide start within 25 ft. of the structure and extend at least 500 ft. up/downstream?			
No			
Vegetation Band - Left			
No			
Vegetation Band - Right			
No			
Wildlife			
Roadkill			
Outside Structure			
Inside Structure			
Species			

Other Information			
Spatial location data collected with GPS?		Comments	
Spatial location data collected with GPS?	Yes	Photos taken?	Pilon showing on upper stream right side.

VT DEC • 103 South Main Street • Waterbury, VT 05671

Vermont Department of Environmental Conservation

A Vermont Government Website Copyright © 2004-2006 State of Vermont - All rights reserved



Stream Geomorphic Assessment

VT DEC

Arch Summary Report

General Information			
VTrans Structure ID	vtrans-700011022606033	Local Structure ID	---
Assessment Date	09/20/2006	Observers	Adam Robtoy, Staci Po
Town	Berkshire		
Location	---		
Latitude	44.93	Longitude	-72.70
Road Name	Route 118	Road Type	Paved
Stream Name	M1S1.01		
Channel width	11 ft. (Measured)	High flow stage	No
Bridge/Arch Information			
Material	Concrete	Number of bridge piers/arches	0
Bridge Width	50 ft.	Skewed to roadway?	No
Bridge Clearance	5 ft.		
Bridge/Arch Span	11 ft.		
Geomorphic Information			
Floodplain filled by roadway approaches		Partially	
Structure is located at significant break in valley slope		No	
Obstructions at the opening of the structure		---	
Steep riffle present immediately upstream of structure		Yes	
If channel avulses, stream will		Cross Road	
Estimated distance avulsion would follow road		--- ft.	
Angle of stream flow approaching structure		Mild Bend	
Pool present immediately downstream of structure		No	
Downstream bank heights are substantially higher than upstream bank heights		No	
Stepped footers		No	
More Geomorphic Information			
	Upstream	Downstream	In Structure
Dominant Bed Material	Gravel	Gravel	Gravel
Bedrock Present	No	No	No
Type of Sediment Deposits	---	---	---
Elevation of sediment deposits greater than 1/2 bankfull	No	No	No
Bank Erosion	None	None	
Hard Bank Armoring	Intact	Intact	
Stream bed scour causing undermining around or under structure	---	---	
Beaver Dam near Structure	No	No	
Beaver Dam distance (ft.)	---	---	
Vegetation			
	Upstream	Downstream	In Structure
Dominant Vegetation Type - Left	Road Embankment	Bare	
Dominant Vegetation Type - Right	Road Embankment	Bare	
Does a band of shrub/forest vegetation 50 ft. wide start within 25 ft. of the structure and extend at least 500 ft. up/downstream?			
Vegetation Band - Left	No	No	
Vegetation Band - Right	No	No	
Wildlife			
	Roadkill	Outside Structure	Inside Structure
Species	---	---	---

Other Information			
Spatial location data collected with GPS?	Yes	Photos taken?	Yes
Comments	---		

VT DEC • 103 South Main Street • Waterbury, VT 05671

Vermont Department of Environmental Conservation

A Vermont Government Website Copyright © 2004-2006 State of Vermont - All rights reserved



Stream Geomorphic Assessment

VT DEC

Bridge Summary Report

General Information			
VTrans Structure ID	vtrans-700002003206103	Local Structure ID	---
Assessment Date	08/30/2006	Observers	Adam Robtoy, Staci Po
Town	Montgomery		
Location	Farm Bridge T4-01		
Latitude	44.88	Longitude	-72.61
Road Name	---	Road Type	Gravel
Stream Name	South Branch		
Channel width	40 ft. (Measured)	High flow stage	No
Bridge/Arch Information			
Material	Steel	Number of bridge piers/arches	0
Bridge Width	16 ft.	Skewed to roadway?	No
Bridge Clearance	10 ft.		
Bridge/Arch Span	40 ft.		
Geomorphic Information			
Floodplain filled by roadway approaches		Entirely	
Structure is located at significant break in valley slope		No	
Obstructions at the opening of the structure		---	
Steep riffle present immediately upstream of structure		No	
If channel avulses, stream will		Cross Road	
Estimated distance avulsion would follow road		--- ft.	
Angle of stream flow approaching structure		Mild Bend	
Pool present immediately downstream of structure		Yes	
Downstream bank heights are substantially higher than upstream bank heights		No	
Stepped footers		No	
More Geomorphic Information			
	Upstream	Downstream	In Structure
Dominant Bed Material	Gravel	Gravel	Gravel
Bedrock Present	No	Yes	No
Type of Sediment Deposits	---	---	---
Elevation of sediment deposits greater than 1/2 bankfull	No	No	No
Bank Erosion	None	None	
Hard Bank Armoring	Intact	Intact	
Stream bed scour causing undermining around or under structure	---	---	
Beaver Dam near Structure	No	No	
Beaver Dam distance (ft.)	---	---	
Vegetation			
	Upstream	Downstream	In Structure
Dominant Vegetation Type - Left	Herbaceous/Grass	Bare	
Dominant Vegetation Type - Right	Herbaceous/Grass	Bare	
Does a band of shrub/forest vegetation 50 ft. wide start within 25 ft. of the structure and extend at least 500 ft. up/downstream?			
Vegetation Band - Left	No	No	
Vegetation Band - Right	No	No	
Wildlife			
	Roadkill	Outside Structure	Inside Structure
Species	---	---	---

Other Information			
Spatial location data collected with GPS?	Yes	Photos taken?	Yes
Comments	---		

VT DEC • 103 South Main Street • Waterbury, VT 05671

Vermont Department of Environmental Conservation

A Vermont Government Website Copyright © 2004-2006 State of Vermont - All rights reserved



Stream Geomorphic Assessment

VT DEC

Arch Summary Report

General Information			
VTrans Structure ID	vtrans-700019027206103	Local Structure ID	---
Assessment Date	09/14/2006	Observers	Adam Robtoy, B. Lerich
Town	Montgomery		
Location	upstream end of T7-01		
Latitude	44.87	Longitude	-72.55
Road Name	AMIDON RD	Road Type	Gravel
Stream Name	Wade Brook		
Channel width	20 ft. (Measured)	High flow stage	No

Bridge/Arch Information			
Material	Steel	Number of bridge piers/arches	0
Bridge Width	100 ft.	Skewed to roadway?	Yes
Bridge Clearance	17 ft.		
Bridge/Arch Span	24 ft.		

Geomorphic Information	
Floodplain filled by roadway approaches	Entirely
Structure is located at significant break in valley slope	No
Obstructions at the opening of the structure	---
Steep riffle present immediately upstream of structure	Yes
If channel avulses, stream will	Cross Road
Estimated distance avulsion would follow road	--- ft.
Angle of stream flow approaching structure	Mild Bend
Pool present immediately downstream of structure	Yes
Downstream bank heights are substantially higher than upstream bank heights	No
Stepped footers	Yes

More Geomorphic Information			
	Upstream	Downstream	In Structure
Dominant Bed Material	Cobble	Cobble	Cobble
Bedrock Present	No	No	No
Type of Sediment Deposits	---	---	---
Elevation of sediment deposits greater than 1/2 bankfull	Yes	No	No
Bank Erosion	None	None	
Hard Bank Armoring	Intact	Intact	
Stream bed scour causing undermining around or under structure	---	---	
Beaver Dam near Structure	No	No	
Beaver Dam distance (ft.)	---	---	

Vegetation			
	Upstream	Downstream	In Structure
Dominant Vegetation Type - Left	Coniferous Forest	Coniferous Forest	
Dominant Vegetation Type - Right	Coniferous Forest	Herbaceous/Grass	
Does a band of shrub/forest vegetation 50 ft. wide start within 25 ft. of the structure and extend at least 500 ft. up/downstream?			
Vegetation Band - Left	Yes	Yes	
Vegetation Band - Right	Yes	Yes	

Wildlife			
	Roadkill	Outside Structure	Inside Structure
Species	---	---	---

Other Information			
Spatial location data collected with GPS?	Yes	Photos taken?	Yes
Comments	1989 construction date		

VT DEC • 103 South Main Street • Waterbury, VT 05671

Vermont Department of Environmental Conservation

A Vermont Government Website Copyright © 2004-2006 State of Vermont - All rights reserved



Stream Geomorphic Assessment

VT DEC

Bridge Summary Report

General Information			
VTrans Structure ID	vtrans-700001001706103	Local Structure ID	—
Assessment Date	08/01/2006	Observers	Adam Robtoy, JPR
Town	Montgomery		
Location	Black Falls Road- T3-01 - T3-02		
Latitude	44.91	Longitude	-72.63
Road Name	BLACK FALLS RD	Road Type	Gravel
Stream Name	Black Falls Brook		
Channel width	32 ft. (Measured)	High flow stage	Yes

Bridge/Arch Information			
Material	Concrete	Number of bridge piers/arches	0
Bridge Width	38 ft.	Skewed to roadway?	Yes
Bridge Clearance	9 ft.		
Bridge/Arch Span	51 ft.		

Geomorphic Information	
Floodplain filled by roadway approaches	Partially
Structure is located at significant break in valley slope	No
Obstructions at the opening of the structure	---
Steep riffle present immediately upstream of structure	No
If channel avulses, stream will	Cross Road
Estimated distance avulsion would follow road	--- ft.
Angle of stream flow approaching structure	Mild Bend
Pool present immediately downstream of structure	Yes
Downstream bank heights are substantially higher than upstream bank heights	No
Stepped footers	No

More Geomorphic Information			
	Upstream	Downstream	In Structure
Dominant Bed Material	Cobble	Cobble	Cobble
Bedrock Present	Yes	Yes	Yes
Type of Sediment Deposits	---	---	---
Elevation of sediment deposits greater than 1/2 bankfull	No	No	Yes
Bank Erosion	None	None	
Hard Bank Armoring	Intact	Intact	
Stream bed scour causing undermining around or under structure	---	---	
Beaver Dam near Structure	No	No	
Beaver Dam distance (ft.)	---	---	

Vegetation			
	Upstream	Downstream	In Structure
Dominant Vegetation Type - Left	Herbaceous/Grass	Herbaceous/Grass	
Dominant Vegetation Type - Right	Herbaceous/Grass	Shrub/Sapling	
Does a band of shrub/forest vegetation 50 ft. wide start within 25 ft. of the structure and extend at least 500 ft. up/downstream?			
Vegetation Band - Left	Yes	No	
Vegetation Band - Right	Yes	No	

Wildlife			
	Roadkill	Outside Structure	Inside Structure
Species	---	---	---

Other Information			
Spatial location data collected with GPS?	Yes	Photos taken?	Yes
Comments	Newer Bridge- Old rock abutment still in place upstream.		

VT DEC • 103 South Main Street • Waterbury, VT 05671

Vermont Department of Environmental Conservation

A Vermont Government Website Copyright © 2004-2006 State of Vermont - All rights reserved



Stream Geomorphic Assessment

VT DEC

Bridge Summary Report

General Information			
VTrans Structure ID	vtrans-700001001606103	Local Structure ID	---
Assessment Date	08/24/2006	Observers	Adam Robtoy, E. Crand
Town	Montgomery		
Location	---		
Latitude	44.90	Longitude	-72.64
Road Name	COMSTOCK BRIDGE RD	Road Type	Paved
Stream Name	Trout River		
Channel width	38 ft. (Measured)	High flow stage	No
Bridge/Arch Information			
Material	Timber	Number of bridge piers/arches	0
Bridge Width	20 ft.	Skewed to roadway?	Yes
Bridge Clearance	18 ft.		
Bridge/Arch Span	38 ft.		
Geomorphic Information			
Floodplain filled by roadway approaches		Entirely	
Structure is located at significant break in valley slope		No	
Obstructions at the opening of the structure		---	
Steep riffle present immediately upstream of structure		No	
If channel avulses, stream will		Cross Road	
Estimated distance avulsion would follow road		--- ft.	
Angle of stream flow approaching structure		Sharp Bend	
Pool present immediately downstream of structure		Yes	
Downstream bank heights are substantially higher than upstream bank heights		No	
Stepped footers		Yes	
More Geomorphic Information			
	Upstream	Downstream	In Structure
Dominant Bed Material	Sand	Sand	Sand
Bedrock Present	Yes	No	Yes
Type of Sediment Deposits	---	---	---
Elevation of sediment deposits greater than 1/2 bankfull	No	No	No
Bank Erosion	None	None	
Hard Bank Armoring	Intact	Intact	
Stream bed scour causing undermining around or under structure	---	---	
Beaver Dam near Structure	No	No	
Beaver Dam distance (ft.)	---	---	
Vegetation			
	Upstream	Downstream	In Structure
Dominant Vegetation Type - Left	Shrub/Sapling	Herbaceous/Grass	
Dominant Vegetation Type - Right	Shrub/Sapling	Herbaceous/Grass	
Does a band of shrub/forest vegetation 50 ft. wide start within 25 ft. of the structure and extend at least 500 ft. up/downstream?			
Vegetation Band - Left	Yes	No	
Vegetation Band - Right	No	No	
Wildlife			
	Roadkill	Outside Structure	Inside Structure
Species	---	---	---

Other Information			
Spatial location data collected with GPS?	Yes	Photos taken?	Yes
Comments	---		

VT DEC • 103 South Main Street • Waterbury, VT 05671

Vermont Department of Environmental Conservation

A Vermont Government Website Copyright © 2004-2006 State of Vermont - All rights reserved



Stream Geomorphic Assessment

VT DEC

Bridge Summary Report

General Information			
VTrans Structure ID	vtrans-990001001506103	Local Structure ID	—
Assessment Date	08/01/2006	Observers	Adam Robtoy
Town	Montgomery		
Location	Covered Bridge- Fuller Bridge/Brook Road		
Latitude	44.90	Longitude	-72.64
Road Name	FULLER BRIDGE RD	Road Type	Paved
Stream Name	Black Falls Brook		
Channel width	36 ft. (Measured)	High flow stage	Yes
Bridge/Arch Information			
Material	Timber	Number of bridge piers/arches	0
Bridge Width	20 ft.	Skewed to roadway?	No
Bridge Clearance	8 ft.		
Bridge/Arch Span	36 ft.		
Geomorphic Information			
Floodplain filled by roadway approaches		Entirely	
Structure is located at significant break in valley slope		No	
Obstructions at the opening of the structure		---	
Steep riffle present immediately upstream of structure		No	
If channel avulses, stream will		Cross Road	
Estimated distance avulsion would follow road		--- ft.	
Angle of stream flow approaching structure		Channelized Straight	
Pool present immediately downstream of structure		No	
Downstream bank heights are substantially higher than upstream bank heights		No	
Stepped footers		No	
More Geomorphic Information			
	Upstream	Downstream	In Structure
Dominant Bed Material	Cobble	Cobble	Cobble
Bedrock Present	No	No	No
Type of Sediment Deposits	---	---	---
Elevation of sediment deposits greater than 1/2 bankfull	No	No	No
Bank Erosion	None	None	
Hard Bank Armoring	Intact	Intact	
Stream bed scour causing undermining around or under structure	---	---	
Beaver Dam near Structure	No	No	
Beaver Dam distance (ft.)	---	---	
Vegetation			
	Upstream	Downstream	In Structure
Dominant Vegetation Type - Left	Road Embankment	Road Embankment	
Dominant Vegetation Type - Right	Herbaceous/Grass	Road Embankment	
Does a band of shrub/forest vegetation 50 ft. wide start within 25 ft. of the structure and extend at least 500 ft. up/downstream?			
Vegetation Band - Left	No	No	
Vegetation Band - Right	No	No	
Wildlife			
	Roadkill	Outside Structure	Inside Structure
Species	---	---	---

Other Information			
Spatial location data collected with GPS?	Yes	Photos taken?	Yes
Comments	---		

VT DEC • 103 South Main Street • Waterbury, VT 05671

Vermont Department of Environmental Conservation

A Vermont Government Website Copyright © 2004-2006 State of Vermont - All rights reserved



Stream Geomorphic Assessment

VT DEC

Bridge Summary Report

General Information			
VTrans Structure ID	vtrans-700043029406103	Local Structure ID	---
Assessment Date	08/31/2006	Observers	Adam Robtoy, Sue Bros
Town	Montgomery		
Location	Gibou Road		
Latitude	44.85	Longitude	-72.61
Road Name	GIBOU RD	Road Type	Gravel
Stream Name	South Branch/Trout River		
Channel width	40 ft. (Measured)	High flow stage	No

Bridge/Arch Information			
Material	Concrete	Number of bridge piers/arches	0
Bridge Width	30 ft.	Skewed to roadway?	No
Bridge Clearance	50 ft.		
Bridge/Arch Span	70 ft.		

Geomorphic Information	
Floodplain filled by roadway approaches	Entirely
Structure is located at significant break in valley slope	No
Obstructions at the opening of the structure	---
Steep riffle present immediately upstream of structure	Yes
If channel avulses, stream will	Cross Road
Estimated distance avulsion would follow road	--- ft.
Angle of stream flow approaching structure	Mild Bend
Pool present immediately downstream of structure	Yes
Downstream bank heights are substantially higher than upstream bank heights	No
Stepped footers	No

More Geomorphic Information			
	Upstream	Downstream	In Structure
Dominant Bed Material	Bedrock	Bedrock	Bedrock
Bedrock Present	Yes	Yes	Yes
Type of Sediment Deposits	---	---	---
Elevation of sediment deposits greater than 1/2 bankfull	No	No	No
Bank Erosion	None	None	
Hard Bank Armoring	Intact	Intact	
Stream bed scour causing undermining around or under structure	---	---	
Beaver Dam near Structure	No	No	
Beaver Dam distance (ft.)	---	---	

Vegetation			
	Upstream	Downstream	In Structure
Dominant Vegetation Type - Left	Road Embankment	Shrub/Sapling	
Dominant Vegetation Type - Right	Shrub/Sapling	Shrub/Sapling	
Does a band of shrub/forest vegetation 50 ft. wide start within 25 ft. of the structure and extend at least 500 ft. up/downstream?			
Vegetation Band - Left	Yes	Yes	
Vegetation Band - Right	Yes	Yes	

Wildlife			
	Roadkill	Outside Structure	Inside Structure
Species	---	---	---

Other Information

Spatial location data collected with GPS?

Yes

Photos taken?

Yes

Comments

Newer Bridge-old abutment from previous covered bridge still in place just upstream.

VT DEC • 103 South Main Street • Waterbury, VT 05671

Vermont Department of Environmental Conservation

A Vermont Government Website Copyright © 2004-2006 State of Vermont - All rights reserved



Stream Geomorphic Assessment

VT DEC

Bridge Summary Report

General Information			
VTrans Structure ID	vtrans-700043039806103	Local Structure ID	---
Assessment Date	08/31/2006	Observers	Adam Robtoy, Sue Brox
Town	Montgomery		
Location	Hutchins Bridge		
Latitude	44.86	Longitude	-72.61
Road Name	HUTCHINS BRIDGE RD	Road Type	Paved
Stream Name	South Branch/Trout River		
Channel width	40 ft. (Measured)	High flow stage	No

Bridge/Arch Information			
Material	Timber	Number of bridge piers/arches	0
Bridge Width	20 ft.	Skewed to roadway?	No
Bridge Clearance	21 ft.		
Bridge/Arch Span	60 ft.		

Geomorphic Information	
Floodplain filled by roadway approaches	Entirely
Structure is located at significant break in valley slope	No
Obstructions at the opening of the structure	---
Steep riffle present immediately upstream of structure	No
If channel avulses, stream will	Cross Road
Estimated distance avulsion would follow road	--- ft.
Angle of stream flow approaching structure	Sharp Bend
Pool present immediately downstream of structure	No
Downstream bank heights are substantially higher than upstream bank heights	No
Stepped footers	No

More Geomorphic Information			
	Upstream	Downstream	In Structure
Dominant Bed Material	Bedrock	Bedrock	Bedrock
Bedrock Present	Yes	Yes	Yes
Type of Sediment Deposits	---	---	---
Elevation of sediment deposits greater than 1/2 bankfull	No	No	No
Bank Erosion	None	None	
Hard Bank Armoring	Intact	Intact	
Stream bed scour causing undermining around or under structure	---	---	
Beaver Dam near Structure	No	No	
Beaver Dam distance (ft.)	---	---	

Vegetation			
	Upstream	Downstream	In Structure
Dominant Vegetation Type - Left	Mixed Forest	Mixed Forest	
Dominant Vegetation Type - Right	Mixed Forest	Mixed Forest	
Does a band of shrub/forest vegetation 50 ft. wide start within 25 ft. of the structure and extend at least 500 ft. up/downstream?			
Vegetation Band - Left	Yes	Yes	
Vegetation Band - Right	Yes	Yes	

Wildlife			
	Roadkill	Outside Structure	Inside Structure
Species	---	---	---

Other Information

Spatial location data collected with
GPS?

Yes

Photos taken?

Yes

Comments

VT DEC • 103 South Main Street • Waterbury, VT 05671

Vermont Department of Environmental Conservation

A Vermont Government Website Copyright © 2004-2006 State of Vermont - All rights reserved



Stream Geomorphic Assessment

VT DEC

Culvert Summary Report

General Information			
VTrans Structure ID	vtrans-700004009006103	Local Structure ID	---
Assessment Date	09/20/2006	Observers	Adam Robtoy, Paul Sta
Town	Montgomery		
Location	---		
Latitude	44.91	Longitude	-72.67
Road Name	LONGLEY BRIDGE RD	Road Type	Gravel
Stream Name	Unnamed Tributary		
Channel width	15 ft. (Measured)	High flow stage	No
Culvert Information			
Material	Concrete	Number of culverts	0
Culvert Length	42 ft.	Skewed to roadway?	No
Culvert Height	84 inches (7.0 ft.)	Culvert Overflow Pipe	No
Culvert Width	84 inches (7.0 ft.)		
Geomorphic Information			
Floodplain filled by roadway approaches		Entirely	
Structure is located at significant break in valley slope		No	
Obstructions at the opening of the structure		---	
Culvert slope as compared with channel slope is significantly		Lower	
Steep riffle present immediately upstream of structure		Yes	
If channel avulses, stream will		Cross Road	
Estimated distance avulsion would follow road		--- ft.	
Angle of stream flow approaching structure		Mild Bend	
Culvert outlet invert		Free Fall	
Outlet drop (invert to water surface)		1.2 ft.	
Water depth in culvert (at outlet)		0.1 ft.	
Pool present immediately downstream of structure		Yes	
Downstream bank heights are substantially higher than upstream bank heights		No	
More Geomorphic Information			
	Upstream	Downstream	In Structure
Dominant Bed Material	Cobble	Cobble	None
Bedrock Present	No	No	
Material Present throughout			No
Type of Sediment Deposits	---	---	---
Elevation of sediment deposits greater than 1/2 bankfull	No	No	No
Bank Erosion	None	None	
Hard Bank Armoring	Intact	Intact	
Stream bed scour causing undermining around or under structure	---	---	
Beaver Dam near Structure	No	No	
Beaver Dam distance (ft.)	---	---	
Vegetation			
	Upstream	Downstream	In Structure
Dominant Vegetation Type - Left	Road Embankment	Road Embankment	
Dominant Vegetation Type - Right	Road Embankment	Road Embankment	
Does a band of shrub/forest vegetation 50 ft. wide start within 25 ft. of the structure and extend at least 500 ft. up/downstream?			
Vegetation Band - Left	Yes	No	
Vegetation Band - Right	Yes	No	

Wildlife			
	Roadkill	Outside Structure	Inside Structure
Species	---	---	---
Other Information			
Spatial location data collected with GPS?	Yes	Photos taken?	Yes
Comments	New in 1998		

VT DEC • 103 South Main Street • Waterbury, VT 05671

Vermont Department of Environmental Conservation

A Vermont Government Website Copyright © 2004-2006 State of Vermont - All rights reserved



Stream Geomorphic Assessment

VT DEC

Bridge Summary Report

General Information			
VTrans Structure ID	vtrans-990001000510101	Local Structure ID	---
Assessment Date	08/18/2006	Observers	Adam Robtoy, E. Crand
Town	Montgomery		
Location	Longley Bridge Road		
Latitude	44.91	Longitude	-72.02
Road Name	LONGLEY BRIDGE RD	Road Type	Gravel
Stream Name	Trout River		
Channel width	90 ft. (Measured)	High flow stage	No

Bridge/Arch Information			
Material	Timber	Number of bridge piers/arches	0
Bridge Width	20 ft.	Skewed to roadway?	No
Bridge Clearance	24 ft.		
Bridge/Arch Span	90 ft.		

Geomorphic Information	
Floodplain filled by roadway approaches	Entirely
Structure is located at significant break in valley slope	No
Obstructions at the opening of the structure	---
Steep riffle present immediately upstream of structure	No
If channel avulses, stream will	Cross Road
Estimated distance avulsion would follow road	--- ft.
Angle of stream flow approaching structure	Mild Bend
Pool present immediately downstream of structure	Yes
Downstream bank heights are substantially higher than upstream bank heights	No
Stepped footers	No

More Geomorphic Information			
	Upstream	Downstream	In Structure
Dominant Bed Material	Gravel	Gravel	Gravel
Bedrock Present	Yes	No	No
Type of Sediment Deposits	---	---	---
Elevation of sediment deposits greater than 1/2 bankfull	No	No	No
Bank Erosion	None	None	
Hard Bank Armoring	Intact	Intact	
Stream bed scour causing undermining around or under structure	---	---	
Beaver Dam near Structure	No	No	
Beaver Dam distance (ft.)	---	---	

Vegetation			
	Upstream	Downstream	In Structure
Dominant Vegetation Type - Left	Herbaceous/Grass	Shrub/Sapling	
Dominant Vegetation Type - Right	Herbaceous/Grass	Shrub/Sapling	
Does a band of shrub/forest vegetation 50 ft. wide start within 25 ft. of the structure and extend at least 500 ft. up/downstream?			
Vegetation Band - Left	No	No	
Vegetation Band - Right	Yes	No	

Wildlife			
	Roadkill	Outside Structure	Inside Structure
Species	---	---	---

Other Information

Spatial location data collected with GPS?	Yes	Photos taken?	Yes
Comments	---		

VT DEC • 103 South Main Street • Waterbury, VT 05671

Vermont Department of Environmental Conservation

A Vermont Government Website Copyright © 2004-2006 State of Vermont - All rights reserved



Stream Geomorphic Assessment

VT DEC

Bridge Summary Report

General Information			
VTrans Structure ID	vtrans-700008016406103	Local Structure ID	---
Assessment Date	09/13/2006	Observers	Adam Robtoy, Staci Po
Town	Montgomery		
Location	South Branch Road T4-04		
Latitude	44.84	Longitude	-72.61
Road Name	S BRANCH RD	Road Type	Gravel
Stream Name	South Branch/Trout River		
Channel width	38 ft. (Measured)	High flow stage	No
Bridge/Arch Information			
Material	Steel	Number of bridge piers/arches	0
Bridge Width	10 ft.	Skewed to roadway?	No
Bridge Clearance	7 ft.		
Bridge/Arch Span	44 ft.		
Geomorphic Information			
Floodplain filled by roadway approaches		Not Significant	
Structure is located at significant break in valley slope		No	
Obstructions at the opening of the structure		---	
Steep riffle present immediately upstream of structure		Yes	
If channel avulses, stream will		Cross Road	
Estimated distance avulsion would follow road		--- ft.	
Angle of stream flow approaching structure		Sharp Bend	
Pool present immediately downstream of structure		No	
Downstream bank heights are substantially higher than upstream bank heights		No	
Stepped footers		No	
More Geomorphic Information			
	Upstream	Downstream	In Structure
Dominant Bed Material	Gravel	Gravel	Gravel
Bedrock Present	No	No	No
Type of Sediment Deposits	---	---	---
Elevation of sediment deposits greater than 1/2 bankfull	No	No	No
Bank Erosion	None	None	
Hard Bank Armoring	None	None	
Stream bed scour causing undermining around or under structure	---	---	
Beaver Dam near Structure	No	No	
Beaver Dam distance (ft.)	---	---	
Vegetation			
	Upstream	Downstream	In Structure
Dominant Vegetation Type - Left	Shrub/Sapling	Bare	
Dominant Vegetation Type - Right	Shrub/Sapling	Mixed Forest	
Does a band of shrub/forest vegetation 50 ft. wide start within 25 ft. of the structure and extend at least 500 ft. up/downstream?			
Vegetation Band - Left	Yes	No	
Vegetation Band - Right	No	No	
Wildlife			
	Roadkill	Outside Structure	Inside Structure
Species	---	---	---

Other Information

Spatial location data collected with GPS?

Yes

Photos taken?

Yes

Comments

Bridge abutment on right recently repaired. Lots of gravel manipulation upstream, downstream and in-

VT DEC • 103 South Main Street • Waterbury, VT 05671

Vermont Department of Environmental Conservation

A Vermont Government Website Copyright © 2004-2006 State of Vermont - All rights reserved



Stream Geomorphic Assessment

VT DEC

Bridge Summary Report

General Information			
VTrans Structure ID	vtrans-700006009906103	Local Structure ID	---
Assessment Date	08/24/2006	Observers	Adam Robtoy, E. Crand
Town	Montgomery		
Location	---		
Latitude	44.90	Longitude	-72.63
Road Name	VINCENTS BRIDGE RD	Road Type	Gravel
Stream Name	Trout River		
Channel width	74 ft. (Measured)	High flow stage	No
Bridge/Arch Information			
Material	Steel	Number of bridge piers/arches	0
Bridge Width	15 ft.	Skewed to roadway?	Yes
Bridge Clearance	22 ft.		
Bridge/Arch Span	82 ft.		
Geomorphic Information			
Floodplain filled by roadway approaches		Entirely	
Structure is located at significant break in valley slope		No	
Obstructions at the opening of the structure		---	
Steep riffle present immediately upstream of structure		No	
If channel avulses, stream will		Cross Road	
Estimated distance avulsion would follow road		--- ft.	
Angle of stream flow approaching structure		Mild Bend	
Pool present immediately downstream of structure		Yes	
Downstream bank heights are substantially higher than upstream bank heights		No	
Stepped footers		No	
More Geomorphic Information			
	Upstream	Downstream	In Structure
Dominant Bed Material	Gravel	Gravel	Gravel
Bedrock Present	No	No	No
Type of Sediment Deposits	---	---	---
Elevation of sediment deposits greater than 1/2 bankfull	No	No	No
Bank Erosion	Low	None	
Hard Bank Armoring	Intact	Intact	
Stream bed scour causing undermining around or under structure	---	---	
Beaver Dam near Structure	No	No	
Beaver Dam distance (ft.)	---	---	
Vegetation			
	Upstream	Downstream	In Structure
Dominant Vegetation Type - Left	Shrub/Sapling	Shrub/Sapling	
Dominant Vegetation Type - Right	Shrub/Sapling	Shrub/Sapling	
Does a band of shrub/forest vegetation 50 ft. wide start within 25 ft. of the structure and extend at least 500 ft. up/downstream?			
Vegetation Band - Left	Yes	Yes	
Vegetation Band - Right	No	Yes	
Wildlife			
	Roadkill	Outside Structure	Inside Structure
Species	---	---	---

Other Information

Spatial location data collected with GPS?

Yes

Photos taken?

Yes

Comments

Barscalping on mid-channel bar downstream of bridge.

VT DEC • 103 South Main Street • Waterbury, VT 05671

Vermont Department of Environmental Conservation

A Vermont Government Website Copyright © 2004-2006 State of Vermont - All rights reserved



Stream Geomorphic Assessment

VT DEC

Culvert Summary Report

General Information			
VTrans Structure ID	vtrans-700028033106033	Local Structure ID	---
Assessment Date	09/21/2006	Observers	Adam Robtoy, Paul Sta
Town	Montgomery		
Location	Demming Road		
Latitude	44.90	Longitude	-72.68
Road Name	Demming Road	Road Type	Gravel
Stream Name	Unnamed Tributary		
Channel width	17 ft. (Measured)	High flow stage	No
Culvert Information			
Material	Steel Corrugated	Number of culverts	1
Culvert Length	40 ft.	Skewed to roadway?	No
Culvert Height	60 inches (5.0 ft.)	Culvert Overflow Pipe	No
Culvert Width	60 inches (5.0 ft.)		
Geomorphic Information			
Floodplain filled by roadway approaches	Entirely		
Structure is located at significant break in valley slope	No		
Obstructions at the opening of the structure	---		
Culvert slope as compared with channel slope is significantly	Same		
Steep riffle present immediately upstream of structure	Yes		
If channel avulses, stream will	Cross Road		
Estimated distance avulsion would follow road	--- ft.		
Angle of stream flow approaching structure	Naturally Straight		
Culvert outlet invert	Free Fall		
Outlet drop (invert to water surface)	7.0 ft.		
Water depth in culvert (at outlet)	0.2 ft.		
Pool present immediately downstream of structure	Yes		
Downstream bank heights are substantially higher than upstream bank heights	Yes		
More Geomorphic Information			
	Upstream	Downstream	In Structure
Dominant Bed Material	Cobble	Gravel	None
Bedrock Present	No	No	
Material Present throughout			No
Type of Sediment Deposits	---	---	---
Elevation of sediment deposits greater than 1/2 bankfull	No	No	No
Bank Erosion	None	High	
Hard Bank Armoring	Intact	Intact	
Stream bed scour causing undermining around or under structure	---	---	
Beaver Dam near Structure	No	No	
Beaver Dam distance (ft.)	---	---	
Vegetation			
	Upstream	Downstream	In Structure
Dominant Vegetation Type - Left	Shrub/Sapling	Shrub/Sapling	
Dominant Vegetation Type - Right	Shrub/Sapling	Shrub/Sapling	
Does a band of shrub/forest vegetation 50 ft. wide start within 25 ft. of the structure and extend at least 500 ft. up/downstream?			
Vegetation Band - Left	Yes	Yes	
Vegetation Band - Right	Yes	Yes	

Wildlife

	Roadkill	Outside Structure	Inside Structure
Species	---	---	---

Other Information

Spatial location data collected with GPS?	Yes	Photos taken?	Yes
Comments	---		

VT DEC • 103 South Main Street • Waterbury, VT 05671

Vermont Department of Environmental Conservation

A Vermont Government Website Copyright © 2004-2006 State of Vermont - All rights reserved



Stream Geomorphic Assessment

VT DEC

Bridge Summary Report

General Information			
VTrans Structure ID	vtrans-100603005206031	Local Structure ID	---
Assessment Date	07/06/2006	Observers	Adam Robtoy, Noelia B
Town	Montgomery		
Location	Hopkins Bridge Road		
Latitude	44.92	Longitude	-72.67
Road Name	Hopkins Bridge Road	Road Type	Gravel
Stream Name	Trout River		
Channel width	73 ft. (Measured)	High flow stage	No

Bridge/Arch Information			
Material	Timber	Number of bridge piers/arches	0
Bridge Width	23 ft.	Skewed to roadway?	No
Bridge Clearance	13 ft.		
Bridge/Arch Span	73 ft.		

Geomorphic Information	
Floodplain filled by roadway approaches	Partially
Structure is located at significant break in valley slope	No
Obstructions at the opening of the structure	---
Steep riffle present immediately upstream of structure	No
If channel avulses, stream will	Cross Road
Estimated distance avulsion would follow road	--- ft.
Angle of stream flow approaching structure	Channelized Straight
Pool present immediately downstream of structure	Yes
Downstream bank heights are substantially higher than upstream bank heights	No
Stepped footers	No

More Geomorphic Information			
	Upstream	Downstream	In Structure
Dominant Bed Material	Gravel	Gravel	Gravel
Bedrock Present	No	No	No
Type of Sediment Deposits	---	---	---
Elevation of sediment deposits greater than 1/2 bankfull	No	No	No
Bank Erosion	None	None	
Hard Bank Armoring	Intact	Intact	
Stream bed scour causing undermining around or under structure	---	---	
Beaver Dam near Structure	No	No	
Beaver Dam distance (ft.)	---	---	

Vegetation			
	Upstream	Downstream	In Structure
Dominant Vegetation Type - Left	Shrub/Sapling	Shrub/Sapling	
Dominant Vegetation Type - Right	Shrub/Sapling	Shrub/Sapling	
Does a band of shrub/forest vegetation 50 ft. wide start within 25 ft. of the structure and extend at least 500 ft. up/downstream?			
Vegetation Band - Left	No	No	
Vegetation Band - Right	No	No	

Wildlife			
	Roadkill	Outside Structure	Inside Structure
Species	---	---	---

Other Information

Spatial location data collected with
GPS?

Yes

Photos taken?

Yes

Comments

VT DEC • 103 South Main Street • Waterbury, VT 05671

Vermont Department of Environmental Conservation

A Vermont Government Website Copyright © 2004-2006 State of Vermont - All rights reserved



Stream Geomorphic Assessment

VT DEC

Bridge Summary Report

General Information			
VTrans Structure ID	vtrans-700001002406103	Local Structure ID	---
Assessment Date	08/18/2006	Observers	Adam Robtoy
Town	Montgomery		
Location	Rt. 118 Just west of Hill West Rd.		
Latitude	44.90	Longitude	-72.65
Road Name	Route 118	Road Type	Paved
Stream Name	Trout River		
Channel width	110 ft. (Measured)	High flow stage	No
Bridge/Arch Information			
Material	Steel	Number of bridge piers/arches	2
Bridge Width	30 ft.	Skewed to roadway?	No
Bridge Clearance	20 ft.		
Bridge/Arch Span	160 ft.		
Geomorphic Information			
Floodplain filled by roadway approaches		Entirely	
Structure is located at significant break in valley slope		No	
Obstructions at the opening of the structure		---	
Steep riffle present immediately upstream of structure		No	
If channel avulses, stream will		Cross Road	
Estimated distance avulsion would follow road		--- ft.	
Angle of stream flow approaching structure		Channelized Straight	
Pool present immediately downstream of structure		Yes	
Downstream bank heights are substantially higher than upstream bank heights		Yes	
Stepped footers		No	
More Geomorphic Information			
	Upstream	Downstream	In Structure
Dominant Bed Material	Gravel	Gravel	Gravel
Bedrock Present	Yes	No	No
Type of Sediment Deposits	---	---	---
Elevation of sediment deposits greater than 1/2 bankfull	No	No	No
Bank Erosion	None	None	
Hard Bank Armoring	Intact	Intact	
Stream bed scour causing undermining around or under structure	---	---	
Beaver Dam near Structure	No	No	
Beaver Dam distance (ft.)	---	---	
Vegetation			
	Upstream	Downstream	In Structure
Dominant Vegetation Type - Left	Herbaceous/Grass	Herbaceous/Grass	
Dominant Vegetation Type - Right	Herbaceous/Grass	Herbaceous/Grass	
Does a band of shrub/forest vegetation 50 ft. wide start within 25 ft. of the structure and extend at least 500 ft. up/downstream?			
Vegetation Band - Left	Yes	No	
Vegetation Band - Right	Yes	No	
Wildlife			
	Roadkill	Outside Structure	Inside Structure
Species	---	---	---

Other Information

Spatial location data collected with GPS?

Yes

Photos taken?

Yes

Comments

Bridge under construction.

VT DEC • 103 South Main Street • Waterbury, VT 05671

Vermont Department of Environmental Conservation

A Vermont Government Website Copyright © 2004-2006 State of Vermont - All rights reserved



Stream Geomorphic Assessment

VT DEC

Bridge Summary Report

General Information			
VTrans Structure ID	vtrans-700002003506103	Local Structure ID	---
Assessment Date	08/16/2006	Observers	Adam Robtoy, Evan Cr
Town	Montgomery		
Location	Route 118		
Latitude	44.88	Longitude	-72.61
Road Name	Route 118	Road Type	Paved
Stream Name	Trout River		
Channel width	50 ft. (Measured)	High flow stage	No
Bridge/Arch Information			
Material	Concrete	Number of bridge piers/arches	0
Bridge Width	30 ft.	Skewed to roadway?	No
Bridge Clearance	14 ft.		
Bridge/Arch Span	52 ft.		
Geomorphic Information			
Floodplain filled by roadway approaches		Entirely	
Structure is located at significant break in valley slope		No	
Obstructions at the opening of the structure		---	
Steep riffle present immediately upstream of structure		No	
If channel avulses, stream will		Cross Road	
Estimated distance avulsion would follow road		--- ft.	
Angle of stream flow approaching structure		Mild Bend	
Pool present immediately downstream of structure		No	
Downstream bank heights are substantially higher than upstream bank heights		No	
Stepped footers		No	
More Geomorphic Information			
	Upstream	Downstream	In Structure
Dominant Bed Material	Cobble	Cobble	Gravel
Bedrock Present	No	No	No
Type of Sediment Deposits	---	---	---
Elevation of sediment deposits greater than 1/2 bankfull	No	No	No
Bank Erosion	None	None	
Hard Bank Armoring	Intact	Intact	
Stream bed scour causing undermining around or under structure	---	---	
Beaver Dam near Structure	No	No	
Beaver Dam distance (ft.)	---	---	
Vegetation			
	Upstream	Downstream	In Structure
Dominant Vegetation Type - Left	Road Embankment	Road Embankment	
Dominant Vegetation Type - Right	Road Embankment	Road Embankment	
Does a band of shrub/forest vegetation 50 ft. wide start within 25 ft. of the structure and extend at least 500 ft. up/downstream?			
Vegetation Band - Left	No	No	
Vegetation Band - Right	No	No	
Wildlife			
	Roadkill	Outside Structure	Inside Structure
Species	---	---	---

Other Information

Spatial location data collected with GPS?

Yes

Photos taken?

Yes

Comments

VT DEC • 103 South Main Street • Waterbury, VT 05671

Vermont Department of Environmental Conservation

A Vermont Government Website Copyright © 2004-2006 State of Vermont - All rights reserved



Stream Geomorphic Assessment

VT DEC

Bridge Summary Report

General Information			
VTrans Structure ID	vtrans-700012020606103	Local Structure ID	---
Assessment Date	09/14/2006	Observers	Adam Robtoy
Town	Montgomery		
Location	Route 118 Near West Hill Road		
Latitude	44.90	Longitude	-72.65
Road Name	Route 118	Road Type	Paved
Stream Name	Trout River- West Hill Brook		
Channel width	40 ft. (Measured)	High flow stage	No
Bridge/Arch Information			
Material	Concrete	Number of bridge piers/arches	2
Bridge Width	42 ft.	Skewed to roadway?	No
Bridge Clearance	5 ft.		
Bridge/Arch Span	130 ft.		
Geomorphic Information			
Floodplain filled by roadway approaches		Partially	
Structure is located at significant break in valley slope		No	
Obstructions at the opening of the structure		---	
Steep riffle present immediately upstream of structure		Yes	
If channel avulses, stream will		Cross Road	
Estimated distance avulsion would follow road		--- ft.	
Angle of stream flow approaching structure		Mild Bend	
Pool present immediately downstream of structure		No	
Downstream bank heights are substantially higher than upstream bank heights		No	
Stepped footers		No	
More Geomorphic Information			
	Upstream	Downstream	In Structure
Dominant Bed Material	Gravel	Gravel	Gravel
Bedrock Present	No	No	No
Type of Sediment Deposits	---	---	---
Elevation of sediment deposits greater than 1/2 bankfull	No	Yes	Yes
Bank Erosion	None	Low	
Hard Bank Armoring	Intact	None	
Stream bed scour causing undermining around or under structure	---	---	
Beaver Dam near Structure	No	No	
Beaver Dam distance (ft.)	---	---	
Vegetation			
	Upstream	Downstream	In Structure
Dominant Vegetation Type - Left	Shrub/Sapling	Shrub/Sapling	
Dominant Vegetation Type - Right	Shrub/Sapling	Shrub/Sapling	
Does a band of shrub/forest vegetation 50 ft. wide start within 25 ft. of the structure and extend at least 500 ft. up/downstream?			
Vegetation Band - Left	No	No	
Vegetation Band - Right	No	No	
Wildlife			
	Roadkill	Outside Structure	Inside Structure
Species	---	---	---

Other Information

Spatial location data collected with
GPS?

Yes

Photos taken?

Yes

Comments

Bridge clogged with sediment.

VT DEC • 103 South Main Street • Waterbury, VT 05671

Vermont Department of Environmental Conservation

A Vermont Government Website Copyright © 2004-2006 State of Vermont - All rights reserved



Stream Geomorphic Assessment

VT DEC

Bridge Summary Report

General Information			
VTrans Structure ID	vtrans-990042039606103	Local Structure ID	---
Assessment Date	08/24/2006	Observers	Adam Robtoy, E. Crand
Town	Montgomery		
Location	Route 118 Start of Reach M03		
Latitude	44.90	Longitude	-72.65
Road Name	Route 118	Road Type	Paved
Stream Name	Trout River		
Channel width	115 ft. (Measured)	High flow stage	No

Bridge/Arch Information			
Material	Steel	Number of bridge piers/arches	2
Bridge Width	30 ft.	Skewed to roadway?	No
Bridge Clearance	9 ft.		
Bridge/Arch Span	125 ft.		

Geomorphic Information	
Floodplain filled by roadway approaches	Partially
Structure is located at significant break in valley slope	No
Obstructions at the opening of the structure	---
Steep riffle present immediately upstream of structure	Yes
If channel avulses, stream will	Cross Road
Estimated distance avulsion would follow road	--- ft.
Angle of stream flow approaching structure	Channelized Straight
Pool present immediately downstream of structure	Yes
Downstream bank heights are substantially higher than upstream bank heights	No
Stepped footers	No

More Geomorphic Information			
	Upstream	Downstream	In Structure
Dominant Bed Material	Gravel	Gravel	Gravel
Bedrock Present	No	No	No
Type of Sediment Deposits	---	---	---
Elevation of sediment deposits greater than 1/2 bankfull	No	No	No
Bank Erosion	None	None	
Hard Bank Armoring	Intact	Intact	
Stream bed scour causing undermining around or under structure	---	---	
Beaver Dam near Structure	No	No	
Beaver Dam distance (ft.)	---	---	

Vegetation			
	Upstream	Downstream	In Structure
Dominant Vegetation Type - Left	Herbaceous/Grass	Herbaceous/Grass	
Dominant Vegetation Type - Right	Herbaceous/Grass	Shrub/Sapling	
Does a band of shrub/forest vegetation 50 ft. wide start within 25 ft. of the structure and extend at least 500 ft. up/downstream?			
Vegetation Band - Left	No	No	
Vegetation Band - Right	No	No	

Wildlife			
	Roadkill	Outside Structure	Inside Structure
Species	---	---	---

Other Information

Spatial location data collected with
GPS?

Yes

Photos taken?

Yes

Comments

VT DEC • 103 South Main Street • Waterbury, VT 05671

Vermont Department of Environmental Conservation

A Vermont Government Website Copyright © 2004-2006 State of Vermont - All rights reserved



APPENDIX B

DATA QUALITY ASSURANCE SUMMARY REPORT

March 21, 2007

QA Notes For: **Trout River Mouth and Head**
Data checked by Jared Carrano

The review of the Trout River data was done by Jared Carrano and reviewed by Staci Pomeroy. Data from both Phase 1 and Phase 2 was reviewed. The DMS and ArcView projects were also used to help support review of data. Information from both phases was used to help look at what may be occurring on the reach/segment as noted in the Phase 2 information. Overall the Trout River Phase 2 data seemed well done.

Listed below are comments and the general types of errors/questions for particular steps and then those specific to a reach. These comments and questions are intended to: help insure that the data is as accurate as possible, allow for further explanation by the consultant who collected the data, point out areas where there may be issues that need to be addressed and/or recognized in using the data, and help document things that came up as data was reviewed. After review of the information noted, the consultant should update the document with what steps, if any, were taken to address the comments/questions. The consultant comments/updates were done by Adam Robtoy of The Johnson Company between 2-23-07 and 2-28-07.

General:

1) Part of a phase2 evaluation is to verify or update phase1 information. It is very important that you take the phase1 report with you into the field and check if its data is accurate. Some phase1 fields will get updated automatically, but others need to be edited manually. These include **phase1 steps 2.10 (confinement type), 4.3 (riparian buffer), and 6.3 (channel bars)**. It is also important to update those fields that, for one reason or another, weren't ever completed in phase1. After phase2 is completed, you should be able to update certain phase1 fields that are either blank or were entered as "No Data". Phase1 steps common to this project are **2.12 (bedform), 5.1 (flow regulations), and 7.1 (sub-class slope)**. All reaches have at least some data that can be updated. Please go through this project and make any relevant updates. Relevant portions of the Phase 1 have been updated.

2) There is currently a bug in the FIT upload that does not allow for the automatic update of phase1 5.5 (dredging history) with the data indexed with FIT. In this case the bug was actually helpful in finding a significant oversight in your data. The dredging parameter is not only meant to capture current dredging, but also any historic activity. This might come from local knowledge or contact with River Management personnel. In this project, phase1 shows that there was indeed historic dredging on multiple reaches. Your phase2 data does not account for this. Had this bug not been present, all phase1 dredging data would have been lost when you uploaded FIT. This is why it is crucial that you carefully field check phase1 data in the field.

Trout Mouth - see Reaches: **M01, M02, M1S1.01, and T2.01.**

Trout Head – see Reaches: **M04, M05, T3.01, T4.01, T4.02 and T6.01**

This information of historic dredging data will potentially affect some of the RGA scores. Please review the RGA data after reviewing the reach information to confirm that the RGA reflects the impact correctly. The RGAs and reach comments have been adjusted to reflect these changes.

3) It is important to provide detailed comments for each reach. A narrative that both supports the data and describes those things that the data does not capture is helpful for others trying to picture conditions on the reach. It is also important to describe the bankfull indicators used to establish bankfull. Similarly, the Narrative section of the RGA is meant as a way to support in words the RGA scores given for a reach. The comments you do provide are helpful, however, some are altogether missing. This portion of the evaluation is best to fill out soon after walking the reach, so that it is fresh in your mind.

Trout Mouth - See reaches: **M2S3.01 and T1.02.**

Trout Head – See reaches: **M05, T3.02, T4.02, T6.01 and T7.01**

Comments have been added for these reaches.

4) Phase1 Steps 6.5 and 6.6: These steps should be entered as “not applicable” for A and B stream types. While these are typically captured during Phase 1, they were missed on some reaches. If the stream is an E or C, you do not have to calculate these, but you should note in your report that this info is missing and needs to be updated in the future.

Trout Mouth – See reaches: **M1S1.01, M2S3.01, M2S3.02 and T1.02**

Trout Head – see reaches: **T3.01, T3.02, T5.01, T6.01 and T7.01**

The Phase 1 data has been updated for these reaches.

5) Bridge and Culvert data is updated with FIT in phase1 – step 5.2, but must be manually entered in phase2 – step 4.8. Some reaches have conflicting data.

Trout Mouth – See reaches: **M01, M02 and T2.01 - (P1 = 2, P2 =1)**

Trout Head – See reaches: **M03 (P1 = 3, P2 =1), M04 (P1 =2, P2 = 1), T4.02 (P1 = 2, P2 =0) and T4.04 (P1 = 2, P2 =1)**

The DMS has been updated for these reaches. The phase 2 data for T2.01 is correct, the reach only has 1 bridge/culvert but the Phase 1 still says 2 even after uploading the FIT. Thank you for this note, it will help with data review; I will look at the FIT files and let the IT know that there may be a bug in the upload.

Trout Mouth Reaches:

M01 You note in your comments that there is “minor bar scalping” yet you have not indexed this with FIT. Please update the FIT file and DMS with this information. FIT and DMS updated on 2-23-07.

M1S1.01

- The confinement types between the phases does not match; Phase 1 = narrow, Phase 2 = broad. When a channel has significantly over-widened, you are supposed to calculate the confinement ratio using the phase1, or “reference” channel width (see protocols). Since phase1 is using 13’ and phase2 is using 20’ you are getting different confinement values. If 20’ is the “reference” width (ie. no widening has occurred yet) then you must update both the phase1 channel width and the phase1 confinement type. If 20’ is the over-widened width, you should use the phase1 width to determine confinement.

The Phase 1 and 2 confinement was updated on 2-23-07 using the Phase 1 channel width of 13’. Both valley widths have been changed to very broad (valley = 180’, channel = 13’).

- Phase1 step 6.4: Meander migration says “Avulsion” but there are no avulsions noted in phase2. Please confirm that there is no avulsion and update phase1 to appropriate migration pattern.

No avulsions were noted during the Phase 2 assessment so the phase 1 has been updated to none.

- The channel evolution stage is noted as 2 – with some of the widening that is noted, do you think this may have or is moving into stage 3? I agree, the evolution stage was updated to III on 2-23-07.

M2S3.01 - The incision ratio, 1.65, seems high for a reach in “good” condition. This is a “Ba” stream, and “recently abandon floodplains” may be difficult to determine in the field. The cross-section sheet downloaded from the DMS, does not have a “bench” feature at the “abandoned floodplain” elevation, simply a point. This reach also has a “very broad” valley with a >4% slope. In looking at the topo and reach breaks it appears that there is a steeper portion of the reach that was lumped in with an area that comes into the broader valley. Should this reach have been segmented? Are the slope and valley type appropriate for the entire reach? Does the incision ratio represent the lower portion of the reach or the upper? After reviewing this reach, the stream type has been updated to B3 with no subclass slope. Step 7.1 has been updated to reflect the incision (score changed from 16 to 12). After looking at the cross section data and photos, I think the incision ratio is correct and the reach has undergone some historic degradation. The cross section was taken about halfway between the culvert located in the upper portion of the reach and the downstream end of the reach and is representative of this portion. The upper ~300’ above the culvert is steeper and similar to M2S3.02 and should probably be included with this reach. No segmentation was done because this upstream portion was so short. I have added a comment in the DMS to reflect this. Good documentation.

M2S3.02

- In this case, you correctly calculate the confinement type in phase2. However, the point of the QC Check is to point out that you need to update phase1 when the Phase 2 data is more accurate. Phase 1 valley width updated on 2-23-07 to SC.
- Phase1 Step 4.4: Ground water inputs in phase1 are “abundant” while phase2 says that there are “some” springs and seeps, and no wetlands. Does this make sense? Or should phase1 be updated to “some”? The phase 1 has been left as abundant as the choices are either abundant, minimal or none. I think abundant is more appropriate in this case than minimal. Okay
- You have noted a dam in phase2 under grade controls, however, you did not mention this as an impoundment in step 4.5. If there is a dam this would also need to be updated in Phase 1 step 5.1. There is no dam within the reach, the FIT/DMS was updated on 2-23-07.

T1.02

- Reconcile phase1 and phase2 buffer data. The right bank is significantly different between phases. DMS updated on 2-26-07.
- You have the same value for road encroachment length between one and both sides. This looks like it may be a data entry error. FIT/DMS revised to include road encroachments on both banks only. Okay
- You have left Step 7 “stream type departure” and “historic data blank”. Choose “none” and “no” rather than leave them blank. DMS updated on 2-23-07.

T2.01A – In step 2.14, the “subclass slope” is “none”, the Phase 1 slope is > 2%, this suggests a “b”. 2.14 was updated to “b” on 2-23-07.

Trout Head Reaches:

M03 B & C -Why is the presence of an alluvial fan “unknown”? If you didn’t see one, it should be “no”. If there is a reason for choosing unknown, you should comment on this in the notes. DMS was updated on 2-23-07 to indicate no alluvial fans for segment C, and alluvial fan in Segment B was added to the FIT. Good documentation.

M03B

- The bankfull width of this segment is 140% larger than the expected phase1 width (Phase 2 = 190 ft; Phase 1 = 77.6). It seems that you’ve given this segment too high a score for channel widening (score = 10). In looking at the DMS, for widening: row 4 would be perhaps better as “poor” instead of fair, as there is multiple braiding, bars, and islands; row 5 would be, at a minimum, in “good” as there has been channel alterations in the restoration and there are flood related sediments working through the reach. Please review and determine if the score originally given is still appropriate. Agreed. The scores have been updated (2-23-07) to reflect these changes.

M03 A & C

- In both segments your notes say that there has been straightening, however, neither reach indicates a length of reach straightened in step 5.5. Confirm that there is straightening and update the FIT and DMS as needed. The DMS/FIT have been updated to indicate the straightening in Segment C.
- It looks like you’ve used the same x-section data for both these segments. If a reach is segmented, each segment needs at least one (but preferably two) x-sections taken. If you only took one x-section between the two segments, make it clear which segment it was actually taken in, and provide a comment explaining why another was not taken. If more were taken, but the one chosen seemed to best represent your observations, than you must explain this clearly in your comments and report. The same cross section was used for both segments as they were very similar and would not have been segmented if not for the alluvial fan segment B located between them. The cross section was taken in Segment A. Good documentation
- The same is true for your pebble count data and average largest particle data. See the comment above. Segments A and C were segmented only because of the alluvial fan segment B which was located between them.

M04

- There is 500 ft of bedrock gorge noted in the upper portion of the reach. It is suggested in the future that this is broken out as its own segment/sub-reach. Agreed. In the future large gorges will be broken out into separate segments.
- In step 2.14 the subclass slope is listed as “none”; the Phase 1 slope is > 2%, suggesting a “b”. The DMS was updated on 2-26-07 to indicate the subclass slope of b.

M05

- With an incision ratio of 1.4, a RGA condition of “reference” in stage “I” seems inconsistent. The Phase 1 data suggested that there had been dredging in the reach. Review the RGA and consider the information of dredging in the reach and how this will affect this score and stage of channel evolution. Evolution stage changed to III as the cross section data was ~20% wider than the Phase I cross section. Condition changed to “good” based on the historic dredging.
- Phase 1 noted that there was bifurcation, there were no indications in the Phase 2 data that there had been changes in the channel (such as flood chutes, neck cuts, avulsions). Does the bifurcation still seem appropriate in Phase 1. There were 2 islands noted during the Phase 2, but no avulsions or cutoffs so the bifurcation in Phase 1 was changed on 2-26-07.
- The cross-section data (entrenchment 2, width/depth 25) is on the cusp of a C / B. With a +/- of 0.2 allowed for entrenchment the reach could be considered a C. Do you feel confident with a “B” in a broad valley? Are there other cross-sections to support the “B” versus a “Cb”? After reviewing the cross section data and photos it seems reasonable to change the stream type to a Cb. The DMS was updated on 2-26-07. Good documentation.

T3.01-

- In phase1, drinking water was identified as a type of flow regulation. In phase2 there were no impoundments for either segment. If you can confirm the drinking water withdrawal, please provide a comment about this in the relevant reach. If there was not a withdrawal, please update phase1 to “none”. No drinking water withdrawals were noted during the phase 2, so the phase 1 has been updated to none.
- The valley type is listed as “very broad”, with a slope of > 3% slope. In looking at the topo it appears that there was a section of steeper stream narrower stream lumped with a wider section. Do both segments have the same valley type and slope? It is difficult to tell from the topo, but Segment B would seem to be different in valley type, do your field observations give better evidence as to valley type? Segment B does have a narrower valley and steeper slope. The phase 1 and 2 data has been updated to narrow valley for this segment.

T3.01 A This segment’s stream type does not match the phase1 stream type (Phase 1 = B, Phase 2 = B). It must either be a stream type departure in step 7 OR a sub-reach in step 2.15. The segment has been designated as a sub-reach.

T3.01 B

- Your comments in the Notes section are important and should be included in your report. Agreed.
- In your narrative you note historic dredging but it is not included in step 5.5. Please confirm and update the FIT and DMS. The DMS has been updated with comments in section . The location of the dredging is unknown so dredging was not indicated with the FIT. Okay.

T3.02

- In step 1.3, the distance for roads is the same for one side/ both sides – 99 ft. Is this correct? No, the FIT was updated on 2-26-07 to indicate roads on one side only.
- The incision ratio, 1.83, seems high for a reach in “reference” condition and stage I of channel evolution. This is a “B” stream, and “recently abandon floodplains” may be difficult to determine in the field. The cross-section sheet downloaded from the DMS, does not have a “bench” feature

at the “abandoned floodplain” elevation, simply a point. There does not seem to be evidence that there was recent incision in looking at what was checked under degradation on the DMS. Do you feel this was an abandoned floodplain that was seen along the entire reach, or a geologic feature? Probably more of a geologic feature than a RAF. Based on the other data and visual observations it does not appear that significant degradation has occurred in this reach so the incision ratio has been updated to reflect this. Good documentation

T4.01

- In the notes there is 800 ft of bedrock gorge noted. In the future it is recommended that this be broken out as its own segment/sub-reach. Agreed.
- There is a note in the QA comments on the beaver dam and length affected, or in this case not affected; please add the comment about beaver dam not yet causing impoundment to the “notes” to help with data evaluation and use. Completed 2-26-07.
- This reach has a very high incision ratio, 1.82, has had some straightening, has sedimented riffles, has been significantly rip-rapped. These seem to suggest that a score of “Good” is too high. Re-evaluate the score and either add comments that support it or adjust it to reflect the data. Data updated to reflect stressors, reach score is now “fair”.

T4.02 – The incision ratio, 1.76, seems high for a reach in “good” condition. This is a “B” stream, and “recently abandon floodplains” may be difficult to determine in the field. The cross-section sheet downloaded from the DMS, does not have a “bench” feature at the “abandoned floodplain” elevation, simply a point. There does not seem to be evidence that there was recent incision in looking at what was checked under degradation on the DMS. Though in Phase 1 there is gravel mining noted, so this may have caused historic degradation. Do you feel this was an abandoned floodplain that was seen along the entire reach, or a geologic feature? After reviewing the data and photos, the incision of 1.8 does not seem accurate and the RAF indicated on the cross section was probably more of a feature and not an abandoned floodplain. No evidence of dredging was noted during the phase 2. The incision ratio has been updated and the evolution stage and condition changed to “reference” and stage I. Good documentation

T4.04 – The buffer widths between Phase 1 and Phase 2 are significantly different, Phase 1 = 0-25 both sides; Phase 2, left >100 and right =26-50. Update Phase 1 if possible. Updated 2-26-07. Thank you.

T4.03

- Under step 7.1 – degradation the “historic” is noted as “no”; is there still degradation happening or likely to happen? Should have been historic, DMS updated 2-26-07.
- Your note of change in planform is good, please be sure to include it in your report discussion. Were you able to make a shapefile of where the new stream line should be? There are not many clues (such as flood chutes, avulsions; low bank erosion amounts) that there was such a dramatic change. There are several point bars and a couple diagonal bars. Did this appear to be flood related or what other features were left on the landscape from the old channel? There wasn’t much on the ground evidence of the planform changes other than the diagonal bars and recent point bars, though they are evident when comparing the phase 1 stream line to the 2003 aerial

photo. We have created a shapefile which shows the current stream line. Thank you. It is interesting along the Trout to see how dramatically it can change planform.

T5.01 –

- An “A” stream type is listed in step 2.14; cross-section measurements (entrenchment 1.43, width/depth 14) suggested a “B” stream type. There is the ability to use a +/- 2 factor for width/depth and this could then support the “A” stream type given. Are there additional cross-sections that support an “A” versus a “B” and/or explain why the +/- 2 factor was used to support an “A” stream type. The Phase 1 slope, 4.22 % is on the cusp of a B and A, as is the confinement type; so additional information to support the “A” stream type will be helpful. The data is right on the edge of being an A or B, A was chosen based mainly on field observations (steeper steps/pools) which suggested A was more appropriate. Also the Phase 1 reference type was A. Good documentation.
- Is the old concrete dam noted in the “notes” across the channel or just along the sides? Would it act as a grade control? The dam was built mostly on bedrock but was no longer spanning the channel so it would not be a grade control. The dam remnants were only along the left bank.
- The incision ratio, 2.2, seems high for a reach in “reference” condition and stage “I”. This is a “A / B” stream, and “recently abandon floodplains” may be difficult to determine in the field. The cross-section sheet downloaded from the DMS, does not have a “bench” feature at the “abandoned floodplain” elevation, simply a point. There does not seem to be evidence that there was recent incision in looking at what was checked under degradation on the DMS. Also, if the incision really is 2.2; that would automatically put the score for step 7.1 –degradation in “poor”. Do you feel this was an abandoned floodplain that was seen along the entire reach, or a geologic feature? As with the other cross sections for the A and B stream types the RAF was probably not correctly defined and the feature captured was just a geologic feature. The DMS has been updated to account for this error. Good documentation.

T6.01 - There are multiple types of bars listed in Phase 2, and only “point” listed in Phase 1, please update Phase 1. Done 2-27-07.

T7.01 – The incision ratio, 1.56, seems high for a reach in “reference” condition and stage of channel evolution of “I”. This is a “B” stream in a semi-confined valley, and “recently abandon floodplains” may be difficult to determine in the field. The cross-section sheet downloaded from the DMS, does not have a “bench” feature at the “abandoned floodplain” elevation, simply a point. There does not seem to be evidence that there was recent incision in looking at what was checked under degradation on the DMS. Do you feel this was an abandoned floodplain that was seen along the entire reach, or a geologic feature? See similar comments above. The RAF and incision have been updated. Okay.

Trout River Report Review

Staci Pomeroy reviewed the report in April 2007. A digital copy was not available so a list of things to be corrected is noted here. The overall format and information is fine, helpful thoughts on what types of potential projects a reach may have was also good. There were just some minor corrections. Please respond to the corrections noted to help track the changes made. *Adam Robtoy addressed the comments on 4-27-07. My responses are in Italics.*

- 1) Please go back into the Phase 1 database and update the tributary names for those tribs that are actually named. I didn't catch this on the first QA review, but as was reading the report and going back to look at data realized that you had a name (ie: West Hill Brook, but the top of the data sheet was "un-named trib to M..."). You do not need to reprint the data sheets, but it would be good for future efforts when the data sheets are re-printed to actually see the name of the brooks that have names. *The Phase I database was updated on 4/27/07 to include the tributary names.*
- 2) page 2 – Geographic Setting
 - First sentence – "The Tyler Branch....." This is the "Trout River" *The report was updated on 4/27/07.*
- 3) Page 4 – Ecological Setting
 - Do you have a reference for the statement " the Trout River was known for its fishing opportunities though in recent years the quality of the fishery has diminished". Is this a known fact, where it has been documented that the fisheries had diminished or is it a perception? If you are not able to find a reference, please restate the sentence to allow for more data to be researched to back up that statement. *The report was updated on 4/27/07. The reference for this statement was added (VT DEC Trout River Restoration Report from 2001).*
- 3) page 16 - Reach M05 -
 - third sentence; update the stream type noted for "reference Phase 1 to (Cb-cobble). You have noted that it is a 2.7% slope, so the sub-script for slope should be added. *The report was updated on 4/27/07.*
 - fourth sentence from bottom - The sensitivity rating for M05further adjustments that change "that" to "than" *The report was updated on 4/27/07.*
- 4) page 18- Reach T2-01
 - T2-01A; the habitat geomorphic scores - 0.54 is "fair" you have it listed as "good" *The report was updated on 4/27/07.*
 - T2.01B - I missed this in the first QA, but reading it made me want to confirm with you the incision ratio for this reach; similar to some of the other B streams where you'd had a high incision ratio; I had asked if you felt this was truly a historic flood plain or was it a geologic feature. The incision ratio is 1.9, and the reach was given a "good" for geomorphic condition. Much of the reach has been rip-rapped too, which may be keeping it from adjusting. The adjustment is noted as historic, and may have been triggered from the gravel mining that happens at the bridge. Please confirm that the feature noted as "abandoned floodplain" is an abandoned floodplain and not a geologic feature, and do you feel a "good" rating (moderate adjustment) is still an accurate depiction of this reach. *After reviewing the cross section data the incision of 1.9 was deemed to be accurate. The overall geomorphic rating of "good" was retained due to the lack of aggradation, planform, and widening adjustment processes observed. The degradation score was in the low "fair" category, but when added with the "good" scores for aggradation, planform, and widening the overall geomorphic score was "good".*
- 5) page 21 – Reach T3.01B
 - fifth sentence; "scores were 0.73 and 0.80..... ; please add "respectively" or some other way of knowing which score goes with habitat and geomorphic *The report was updated on 4/27/07.*
- 6) Page 31 – Bridge and Culvert Assessment
 - Do you know the landowner on Reach T4-04, South Branch Rd., it is noted that there has been manipulation of the gravel bars upstream and downstream of the private structure, and berming. I have contacted Chris Brunelle to see if there was a permit given for this activity; there was not. We would like

to determine who the landowner is, and work with them to get a permit and/or find alternatives to this practice. *I am not sure who the current landowner is, MRBA conducted the landowner outreach for the Trout so they may have this information.*

APPENDIX C

REACH BREAK LOCATION MAPS




Plate 1 Locations of Reaches M01, M02, T1-01, T1-02, T2-01, M1S1.01, M2S3.01 and M2S3.02 along the Trout River watershed.




Plate 2 Locations of Reaches M03, M04, T3-01, T3-02 and T5-01 along the Trout River watershed.




Plate 3 Locations of Reaches M05, T4-01, T4-02, T4-03, T4-04, T6-01, and T7-01 along the Trout River watershed.

