



FIT Affected Segments Report

Hungerford Brook

Reach - Segment	Affected by FIT (Feature Indexing Tool)
M3T1.03 - 0	Yes
M3T1.04 - A	No
M3T1.04 - B	No
M4T2.01 - 0	Yes
M4T2.02 - 0	Yes
M4T2.03 - 0	Yes
M4T2.04 - A	Yes
M4T2.04 - B	Yes
M4T2.04 - C	Yes
M4T2.04 - D	Yes
M4T2.05 - 0	No
M04 - 0	Yes
M4S1.01 - A	No
M4S1.01 - B	No
M05 - 0	Yes
M06 - 0	Yes
M07 - A	Yes
M07 - B	Yes
M08 - A	Yes
M08 - B	Yes
M09 - A	No
M09 - B	No
M3T1.01 - A	Yes
M3T1.01 - B	Yes
M3T1.01 - C	Yes
M3T1.02 - 0	Yes