



Phase 2 - FIT - Legacy Data Report

Allen Brook

SGAT Version: 3

Reach: **M03 -B**

| <u>Step</u> | <u>Description</u> | <u>Value</u> | |
|-------------|--------------------------------|----------------|----------------|
| 1.2 | Alluvial Fan: | None | |
| 1.3 | <u>Encroachments - Side</u> | <u>One</u> | <u>Both</u> |
| | Berm Length (ft.): | | |
| | Path Length (ft.): | | |
| | Road Length (ft.): | | |
| | Railroad Lenth (ft.): | | |
| | Development Length: | | |
| 3.1 | <u>Erosion - Bank</u> | <u>Left</u> | <u>Right</u> |
| | Erosion Length (ft.): | 2,112.0 | 2,112.0 |
| | Erosion Height (ft.): | 2.0 | 2.0 |
| | Revetment Type: | Rip-Rap | Rip-Rap |
| | Revetment length: | 70.0 | 70.0 |
| 3.2 | <u>Buffer Less Than 25 ft.</u> | | |
| 3.3 | <u>Riparian Corridor</u> | | |
| | Mass Failures: | None | |
| | Average Height (ft.): | | |
| | Gullies: | | |
| | Average Height (ft.): | | |

| <u>Step</u> | <u>Description</u> | <u>Value</u> |
|-------------|-----------------------------|--------------|
| 4.4 | Number of Debris Jams: | 2 |
| 4.7 | Stormwater Inputs | 7 |
| 4.9 | Beaver Dams: | 0 |
| | Affected length: | 0 |
| 5.2 | Migration Features | |
| | Flood Chutes: | 2 |
| | Neck Cutoffs: | 1 |
| | Channel Avulsions: | 0 |
| | Braiding: | 0 |
| 5.3 | Steep Riffles and Head Cuts | |
| | Steep Riffles: | 0 |
| | Head Cuts: | 0 |
| 5.4 | Animal Crossings: | No |
| 5.5 | Channel Alterations | |
| | Straightening: | None |
| | Dredging: | None |



Phase 2 - FIT - Legacy Data Report

Allen Brook

SGAT Version: 3

Reach: **M03 -D**

| <u>Step</u> | <u>Description</u> | <u>Value</u> | |
|-------------|--------------------------------|-----------------|----------------|
| 1.2 | Alluvial Fan: | None | |
| 1.3 | <u>Encroachments - Side</u> | <u>One</u> | <u>Both</u> |
| | Berm Length (ft.): | | |
| | Path Length (ft.): | | |
| | Road Length (ft.): | | |
| | Railroad Lenth (ft.): | | |
| | Development Length: | | |
| 3.1 | <u>Erosion - Bank</u> | <u>Left</u> | <u>Right</u> |
| | Erosion Length (ft.): | 1,762.0 | 1,762.0 |
| | Erosion Height (ft.): | 2.0 | 2.0 |
| | Revetment Type: | None | None |
| | Revetment length: | | |
| 3.2 | <u>Buffer Less Than 25 ft.</u> | | |
| 3.3 | <u>Riparian Corridor</u> | | |
| | Mass Failures: | Multiple | |
| | Average Height (ft.): | 15.0 | |
| | Gullies: | | |
| | Average Height (ft.): | | |

| <u>Step</u> | <u>Description</u> | <u>Value</u> |
|-------------|-----------------------------|--------------|
| 4.4 | Number of Debris Jams: | 1 |
| 4.7 | Stormwater Inputs | 2 |
| 4.9 | Beaver Dams: | 0 |
| | Affected length: | 0 |
| 5.2 | Migration Features | |
| | Flood Chutes: | 2 |
| | Neck Cutoffs: | 1 |
| | Channel Avulsions: | 0 |
| | Braiding: | 1 |
| 5.3 | Steep Riffles and Head Cuts | |
| | Steep Riffles: | 2 |
| | Head Cuts: | 0 |
| 5.4 | Animal Crossings: | No |
| 5.5 | Channel Alterations | |
| | Straightening: | None |
| | Dredging: | None |



Phase 2 - FIT - Legacy Data Report

Allen Brook

SGAT Version: 3

Reach: **M04 -B**

| <u>Step</u> | <u>Description</u> | <u>Value</u> | |
|-------------|--------------------------------|----------------|----------------|
| 1.2 | Alluvial Fan: | None | |
| 1.3 | <u>Encroachments - Side</u> | <u>One</u> | <u>Both</u> |
| | Berm Length (ft.): | | |
| | Path Length (ft.): | | |
| | Road Length (ft.): | | |
| | Railroad Lenth (ft.): | | |
| | Development Length: | | |
| 3.1 | <u>Erosion - Bank</u> | <u>Left</u> | <u>Right</u> |
| | Erosion Length (ft.): | 1,103.0 | 1,103.0 |
| | Erosion Height (ft.): | 2.2 | 2.2 |
| | Revetment Type: | None | None |
| | Revetment length: | 0.0 | 0.0 |
| 3.2 | <u>Buffer Less Than 25 ft.</u> | | |
| 3.3 | <u>Riparian Corridor</u> | | |
| | Mass Failures: | None | |
| | Average Height (ft.): | | |
| | Gullies: | | |
| | Average Height (ft.): | | |

| <u>Step</u> | <u>Description</u> | <u>Value</u> |
|-------------|-----------------------------|----------------------|
| 4.4 | Number of Debris Jams: | 1 |
| 4.7 | Stormwater Inputs | 0 |
| 4.9 | Beaver Dams: | 0 |
| | Affected length: | 0 |
| 5.2 | Migration Features | |
| | Flood Chutes: | 2 |
| | Neck Cutoffs: | 0 |
| | Channel Avulsions: | 0 |
| | Braiding: | 0 |
| 5.3 | Steep Riffles and Head Cuts | |
| | Steep Riffles: | 0 |
| | Head Cuts: | 0 |
| 5.4 | Animal Crossings: | No |
| 5.5 | Channel Alterations | |
| | Straightening: | Straightening |
| | Dredging: | None |



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
June, 17 2026

Phase 2 - FIT - Legacy Data Report

Allen Brook

SGAT Version: 3

Reach: **M08 -0**

| <u>Step</u> | <u>Description</u> | <u>Value</u> | |
|-------------|--------------------------------|--------------|--------------|
| 1.2 | Alluvial Fan: | None | |
| 1.3 | <u>Encroachments - Side</u> | <u>One</u> | <u>Both</u> |
| | Berm Length (ft.): | | |
| | Path Length (ft.): | | |
| | Road Length (ft.): | | |
| | Railroad Lenth (ft.): | | |
| | Development Length: | | |
| 3.1 | <u>Erosion - Bank</u> | <u>Left</u> | <u>Right</u> |
| | Erosion Length (ft.): | 200.0 | 200.0 |
| | Erosion Height (ft.): | 1.0 | 1.0 |
| | Revetment Type: | None | None |
| | Revetment length: | 0.0 | 0.0 |
| 3.2 | <u>Buffer Less Than 25 ft.</u> | | |
| 3.3 | <u>Riparian Corridor</u> | | |
| | Mass Failures: | None | |
| | Average Height (ft.): | | |
| | Gullies: | | |
| | Average Height (ft.): | | |

| <u>Step</u> | <u>Description</u> | <u>Value</u> |
|-------------|-----------------------------|--------------|
| 4.4 | Number of Debris Jams: | 10 |
| 4.7 | Stormwater Inputs | 0 |
| 4.9 | Beaver Dams: | 2 |
| | Affected length: | 300 |
| 5.2 | Migration Features | |
| | Flood Chutes: | 2 |
| | Neck Cutoffs: | 0 |
| | Channel Avulsions: | 0 |
| | Braiding: | 1 |
| 5.3 | Steep Riffles and Head Cuts | |
| | Steep Riffles: | 0 |
| | Head Cuts: | 0 |
| 5.4 | Animal Crossings: | No |
| 5.5 | Channel Alterations | |
| | Straightening: | None |
| | Dredging: | None |



Phase 2 - FIT - Legacy Data Report

Allen Brook

SGAT Version: 3

Reach: **M12 -0**

| <u>Step</u> | <u>Description</u> | <u>Value</u> | |
|-------------|--------------------------------|--------------|--------------|
| 1.2 | Alluvial Fan: | None | |
| 1.3 | <u>Encroachments - Side</u> | <u>One</u> | <u>Both</u> |
| | Berm Length (ft.): | | |
| | Path Length (ft.): | | |
| | Road Length (ft.): | | |
| | Railroad Lenth (ft.): | | |
| | Development Length: | | |
| 3.1 | <u>Erosion - Bank</u> | <u>Left</u> | <u>Right</u> |
| | Erosion Length (ft.): | 0.0 | 0.0 |
| | Erosion Height (ft.): | 0.0 | 0.0 |
| | Revetment Type: | None | None |
| | Revetment length: | 0.0 | 0.0 |
| 3.2 | <u>Buffer Less Than 25 ft.</u> | | |
| 3.3 | <u>Riparian Corridor</u> | | |
| | Mass Failures: | None | |
| | Average Height (ft.): | | |
| | Gullies: | | |
| | Average Height (ft.): | | |

| <u>Step</u> | <u>Description</u> | <u>Value</u> |
|-------------|-----------------------------|--------------|
| 4.4 | Number of Debris Jams: | |
| 4.7 | Stormwater Inputs | |
| 4.9 | Beaver Dams: | |
| | Affected length: | |
| 5.2 | Migration Features | |
| | Flood Chutes: | |
| | Neck Cutoffs: | |
| | Channel Avulsions: | |
| | Braiding: | |
| 5.3 | Steep Riffles and Head Cuts | |
| | Steep Riffles: | |
| | Head Cuts: | |
| 5.4 | Animal Crossings: | |
| 5.5 | Channel Alterations | |
| | Straightening: | None |
| | Dredging: | None |



Phase 2 - FIT - Legacy Data Report

Allen Brook

SGAT Version: 3

Reach: **M04 -A**

| <u>Step</u> | <u>Description</u> | <u>Value</u> | |
|-------------|--------------------------------|-----------------|----------------|
| 1.2 | Alluvial Fan: | None | |
| 1.3 | <u>Encroachments - Side</u> | <u>One</u> | <u>Both</u> |
| | Berm Length (ft.): | | |
| | Path Length (ft.): | | |
| | Road Length (ft.): | | |
| | Railroad Lenth (ft.): | | |
| | Development Length: | | |
| 3.1 | <u>Erosion - Bank</u> | <u>Left</u> | <u>Right</u> |
| | Erosion Length (ft.): | 440.0 | 220.0 |
| | Erosion Height (ft.): | 2.0 | 2.0 |
| | Revetment Type: | Rip-Rap | Rip-Rap |
| | Revetment length: | 200.0 | 500.0 |
| 3.2 | <u>Buffer Less Than 25 ft.</u> | | |
| 3.3 | <u>Riparian Corridor</u> | | |
| | Mass Failures: | Multiple | |
| | Average Height (ft.): | 10.0 | |
| | Gullies: | | |
| | Average Height (ft.): | | |

| <u>Step</u> | <u>Description</u> | <u>Value</u> |
|-------------|-----------------------------|----------------------|
| 4.4 | Number of Debris Jams: | 0 |
| 4.7 | Stormwater Inputs | 1 |
| 4.9 | Beaver Dams: | 0 |
| | Affected length: | 0 |
| 5.2 | Migration Features | |
| | Flood Chutes: | 0 |
| | Neck Cutoffs: | 0 |
| | Channel Avulsions: | 0 |
| | Braiding: | 0 |
| 5.3 | Steep Riffles and Head Cuts | |
| | Steep Riffles: | 0 |
| | Head Cuts: | 0 |
| 5.4 | Animal Crossings: | No |
| 5.5 | Channel Alterations | |
| | Straightening: | Straightening |
| | Dredging: | None |



Phase 2 - FIT - Legacy Data Report

Allen Brook

SGAT Version: 3

Reach: **M10 -A**

| <u>Step</u> | <u>Description</u> | <u>Value</u> | |
|-------------|--------------------------------|----------------|----------------|
| 1.2 | Alluvial Fan: | None | |
| 1.3 | <u>Encroachments - Side</u> | <u>One</u> | <u>Both</u> |
| | Berm Length (ft.): | 0.0 | 0.0 |
| | Path Length (ft.): | 0.0 | 0.0 |
| | Road Length (ft.): | 0.0 | 0.0 |
| | Railroad Lenth (ft.): | 0.0 | 0.0 |
| | Development Length: | 0.0 | 0.0 |
| 3.1 | <u>Erosion - Bank</u> | <u>Left</u> | <u>Right</u> |
| | Erosion Length (ft.): | 1,000.0 | 1,000.0 |
| | Erosion Height (ft.): | 1.5 | 1.5 |
| | Revetment Type: | None | None |
| | Revetment length: | 0.0 | 0.0 |
| 3.2 | <u>Buffer Less Than 25 ft.</u> | | |
| 3.3 | <u>Riparian Corridor</u> | | |
| | Mass Failures: | None | |
| | Average Height (ft.): | | |
| | Gullies: | | |
| | Average Height (ft.): | | |

| <u>Step</u> | <u>Description</u> | <u>Value</u> |
|-------------|-----------------------------|--------------|
| 4.4 | Number of Debris Jams: | 8 |
| 4.7 | Stormwater Inputs | 0 |
| 4.9 | Beaver Dams: | 0 |
| | Affected length: | |
| 5.2 | Migration Features | |
| | Flood Chutes: | 2 |
| | Neck Cutoffs: | 0 |
| | Channel Avulsions: | 2 |
| | Braiding: | 0 |
| 5.3 | Steep Riffles and Head Cuts | |
| | Steep Riffles: | 2 |
| | Head Cuts: | 0 |
| 5.4 | Animal Crossings: | No |
| 5.5 | Channel Alterations | |
| | Straightening: | None |
| | Dredging: | None |



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
June, 17 2026

Phase 2 - FIT - Legacy Data Report

Allen Brook

SGAT Version: **3**

Reach: **M03 -C**

| <u>Step</u> | <u>Description</u> | <u>Value</u> | |
|-------------|--------------------------------|----------------|----------------|
| 1.2 | Alluvial Fan: | None | |
| 1.3 | <u>Encroachments - Side</u> | <u>One</u> | <u>Both</u> |
| | Berm Length (ft.): | | |
| | Path Length (ft.): | | |
| | Road Length (ft.): | | |
| | Railroad Lenth (ft.): | | |
| | Development Length: | | |
| 3.1 | <u>Erosion - Bank</u> | <u>Left</u> | <u>Right</u> |
| | Erosion Length (ft.): | 5,000.0 | 5,000.0 |
| | Erosion Height (ft.): | 2.5 | 2.5 |
| | Revetment Type: | Rip-Rap | Rip-Rap |
| | Revetment length: | 30.0 | 30.0 |
| 3.2 | <u>Buffer Less Than 25 ft.</u> | | |
| 3.3 | <u>Riparian Corridor</u> | | |
| | Mass Failures: | None | |
| | Average Height (ft.): | | |
| | Gullies: | | |
| | Average Height (ft.): | | |

| <u>Step</u> | <u>Description</u> | <u>Value</u> |
|-------------|-----------------------------|--------------|
| 4.4 | Number of Debris Jams: | 7 |
| 4.7 | Stormwater Inputs | 3 |
| 4.9 | Beaver Dams: | 0 |
| | Affected length: | |
| 5.2 | Migration Features | |
| | Flood Chutes: | 2 |
| | Neck Cutoffs: | 2 |
| | Channel Avulsions: | 0 |
| | Braiding: | 0 |
| 5.3 | Steep Riffles and Head Cuts | |
| | Steep Riffles: | 0 |
| | Head Cuts: | 1 |
| 5.4 | Animal Crossings: | No |
| 5.5 | Channel Alterations | |
| | Straightening: | None |
| | Dredging: | None |



Phase 2 - FIT - Legacy Data Report

Allen Brook

SGAT Version: 3

Reach: **M11 -0**

| <u>Step</u> | <u>Description</u> | <u>Value</u> | |
|-------------|--------------------------------|--------------|--------------|
| 1.2 | Alluvial Fan: | None | |
| 1.3 | <u>Encroachments - Side</u> | <u>One</u> | <u>Both</u> |
| | Berm Length (ft.): | | |
| | Path Length (ft.): | | |
| | Road Length (ft.): | | |
| | Railroad Lenth (ft.): | | |
| | Development Length: | | |
| 3.1 | <u>Erosion - Bank</u> | <u>Left</u> | <u>Right</u> |
| | Erosion Length (ft.): | 0.0 | 0.0 |
| | Erosion Height (ft.): | 0.0 | 0.0 |
| | Revetment Type: | None | None |
| | Revetment length: | 0.0 | 0.0 |
| 3.2 | <u>Buffer Less Than 25 ft.</u> | | |
| 3.3 | <u>Riparian Corridor</u> | | |
| | Mass Failures: | None | |
| | Average Height (ft.): | | |
| | Gullies: | | |
| | Average Height (ft.): | | |

| <u>Step</u> | <u>Description</u> | <u>Value</u> |
|-------------|-----------------------------|----------------------|
| 4.4 | Number of Debris Jams: | 0 |
| 4.7 | Stormwater Inputs | 0 |
| 4.9 | Beaver Dams: | 0 |
| | Affected length: | |
| 5.2 | Migration Features | |
| | Flood Chutes: | 0 |
| | Neck Cutoffs: | 0 |
| | Channel Avulsions: | 0 |
| | Braiding: | 0 |
| 5.3 | Steep Riffles and Head Cuts | |
| | Steep Riffles: | 0 |
| | Head Cuts: | 0 |
| 5.4 | Animal Crossings: | Yes |
| 5.5 | Channel Alterations | |
| | Straightening: | Straightening |
| | Dredging: | Dredging |



Phase 2 - FIT - Legacy Data Report

Allen Brook

SGAT Version: 3

Reach: **M01 -0**

| <u>Step</u> | <u>Description</u> | <u>Value</u> | |
|-------------|--------------------------------|----------------|----------------|
| 1.2 | Alluvial Fan: | None | |
| 1.3 | <u>Encroachments - Side</u> | <u>One</u> | <u>Both</u> |
| | Berm Length (ft.): | | |
| | Path Length (ft.): | | |
| | Road Length (ft.): | | |
| | Railroad Lenth (ft.): | | |
| | Development Length: | | |
| 3.1 | <u>Erosion - Bank</u> | <u>Left</u> | <u>Right</u> |
| | Erosion Length (ft.): | 5,093.0 | 4,775.0 |
| | Erosion Height (ft.): | 3.5 | 3.5 |
| | Revetment Type: | Rip-Rap | Rip-Rap |
| | Revetment length: | 445.0 | 125.0 |
| 3.2 | <u>Buffer Less Than 25 ft.</u> | | |
| 3.3 | <u>Riparian Corridor</u> | | |
| | Mass Failures: | One | |
| | Average Height (ft.): | 10.0 | |
| | Gullies: | | |
| | Average Height (ft.): | | |

| <u>Step</u> | <u>Description</u> | <u>Value</u> |
|-------------|-----------------------------|----------------------|
| 4.4 | Number of Debris Jams: | 2 |
| 4.7 | Stormwater Inputs | 1 |
| 4.9 | Beaver Dams: | 0 |
| | Affected length: | |
| 5.2 | Migration Features | |
| | Flood Chutes: | 0 |
| | Neck Cutoffs: | 0 |
| | Channel Avulsions: | 0 |
| | Braiding: | 0 |
| 5.3 | Steep Riffles and Head Cuts | |
| | Steep Riffles: | 2 |
| | Head Cuts: | 0 |
| 5.4 | Animal Crossings: | Yes |
| 5.5 | Channel Alterations | |
| | Straightening: | Straightening |
| | Dredging: | None |



Phase 2 - FIT - Legacy Data Report

Allen Brook

SGAT Version: 3

Reach: **M03 -A**

| <u>Step</u> | <u>Description</u> | <u>Value</u> | |
|-------------|--------------------------------|-----------------|----------------|
| 1.2 | Alluvial Fan: | None | |
| 1.3 | <u>Encroachments - Side</u> | <u>One</u> | <u>Both</u> |
| | Berm Length (ft.): | | |
| | Path Length (ft.): | | |
| | Road Length (ft.): | | |
| | Railroad Lenth (ft.): | | |
| | Development Length: | | |
| 3.1 | <u>Erosion - Bank</u> | <u>Left</u> | <u>Right</u> |
| | Erosion Length (ft.): | 2,750.0 | 2,750.0 |
| | Erosion Height (ft.): | 1.9 | 1.9 |
| | Revetment Type: | Rip-Rap | Rip-Rap |
| | Revetment length: | 100.0 | 150.0 |
| 3.2 | <u>Buffer Less Than 25 ft.</u> | | |
| 3.3 | <u>Riparian Corridor</u> | | |
| | Mass Failures: | Multiple | |
| | Average Height (ft.): | 10.0 | |
| | Gullies: | | |
| | Average Height (ft.): | | |

| <u>Step</u> | <u>Description</u> | <u>Value</u> |
|-------------|-----------------------------|--------------|
| 4.4 | Number of Debris Jams: | 3 |
| 4.7 | Stormwater Inputs | 4 |
| 4.9 | Beaver Dams: | 0 |
| | Affected length: | 0 |
| 5.2 | Migration Features | |
| | Flood Chutes: | 2 |
| | Neck Cutoffs: | 0 |
| | Channel Avulsions: | 0 |
| | Braiding: | 0 |
| 5.3 | Steep Riffles and Head Cuts | |
| | Steep Riffles: | 0 |
| | Head Cuts: | 0 |
| 5.4 | Animal Crossings: | No |
| 5.5 | Channel Alterations | |
| | Straightening: | None |
| | Dredging: | None |



Phase 2 - FIT - Legacy Data Report

Allen Brook

SGAT Version: 3

Reach: **M04 -C**

| <u>Step</u> | <u>Description</u> | <u>Value</u> | |
|-------------|--------------------------------|--------------|--------------|
| 1.2 | Alluvial Fan: | None | |
| 1.3 | <u>Encroachments - Side</u> | <u>One</u> | <u>Both</u> |
| | Berm Length (ft.): | | |
| | Path Length (ft.): | | |
| | Road Length (ft.): | | |
| | Railroad Lenth (ft.): | | |
| | Development Length: | | |
| 3.1 | <u>Erosion - Bank</u> | <u>Left</u> | <u>Right</u> |
| | Erosion Length (ft.): | 280.0 | 145.0 |
| | Erosion Height (ft.): | 3.0 | 3.0 |
| | Revetment Type: | None | None |
| | Revetment length: | | |
| 3.2 | <u>Buffer Less Than 25 ft.</u> | | |
| 3.3 | <u>Riparian Corridor</u> | | |
| | Mass Failures: | None | |
| | Average Height (ft.): | | |
| | Gullies: | None | |
| | Average Height (ft.): | | |

| <u>Step</u> | <u>Description</u> | <u>Value</u> |
|-------------|-----------------------------|----------------------|
| 4.4 | Number of Debris Jams: | 0 |
| 4.7 | Stormwater Inputs | |
| 4.9 | Beaver Dams: | 2 |
| | Affected length: | 800 |
| 5.2 | Migration Features | |
| | Flood Chutes: | 0 |
| | Neck Cutoffs: | 0 |
| | Channel Avulsions: | 0 |
| | Braiding: | 0 |
| 5.3 | Steep Riffles and Head Cuts | |
| | Steep Riffles: | 0 |
| | Head Cuts: | 0 |
| 5.4 | Animal Crossings: | Yes |
| 5.5 | Channel Alterations | |
| | Straightening: | Straightening |
| | Dredging: | None |



Phase 2 - FIT - Legacy Data Report

Allen Brook

SGAT Version: 3

Reach: **M02 -0**

| <u>Step</u> | <u>Description</u> | <u>Value</u> | |
|-------------|--------------------------------|-----------------|----------------|
| 1.2 | Alluvial Fan: | None | |
| 1.3 | <u>Encroachments - Side</u> | <u>One</u> | <u>Both</u> |
| | Berm Length (ft.): | | |
| | Path Length (ft.): | | |
| | Road Length (ft.): | | |
| | Railroad Lenth (ft.): | | |
| | Development Length: | | |
| 3.1 | <u>Erosion - Bank</u> | <u>Left</u> | <u>Right</u> |
| | Erosion Length (ft.): | 5,600.0 | 5,600.0 |
| | Erosion Height (ft.): | 3.0 | 3.0 |
| | Revetment Type: | Rip-Rap | Rip-Rap |
| | Revetment length: | 200.0 | 200.0 |
| 3.2 | <u>Buffer Less Than 25 ft.</u> | | |
| 3.3 | <u>Riparian Corridor</u> | | |
| | Mass Failures: | Multiple | |
| | Average Height (ft.): | 15.0 | |
| | Gullies: | | |
| | Average Height (ft.): | | |

| <u>Step</u> | <u>Description</u> | <u>Value</u> |
|-------------|-----------------------------|--------------|
| 4.4 | Number of Debris Jams: | 7 |
| 4.7 | Stormwater Inputs | 7 |
| 4.9 | Beaver Dams: | 0 |
| | Affected length: | 0 |
| 5.2 | Migration Features | |
| | Flood Chutes: | 2 |
| | Neck Cutoffs: | 1 |
| | Channel Avulsions: | 0 |
| | Braiding: | 0 |
| 5.3 | Steep Riffles and Head Cuts | |
| | Steep Riffles: | 0 |
| | Head Cuts: | 0 |
| 5.4 | Animal Crossings: | No |
| 5.5 | Channel Alterations | |
| | Straightening: | None |
| | Dredging: | None |



Phase 2 - FIT - Legacy Data Report

Allen Brook

SGAT Version: 3

Reach: **M10 -B**

| <u>Step</u> | <u>Description</u> | <u>Value</u> | |
|-------------|--------------------------------|--------------|--------------|
| 1.2 | Alluvial Fan: | | |
| 1.3 | <u>Encroachments - Side</u> | <u>One</u> | <u>Both</u> |
| | Berm Length (ft.): | | |
| | Path Length (ft.): | | |
| | Road Length (ft.): | | |
| | Railroad Lenth (ft.): | | |
| | Development Length: | | |
| 3.1 | <u>Erosion - Bank</u> | <u>Left</u> | <u>Right</u> |
| | Erosion Length (ft.): | | |
| | Erosion Height (ft.): | | |
| | Revetment Type: | | |
| | Revetment length: | | |
| 3.2 | <u>Buffer Less Than 25 ft.</u> | | |
| 3.3 | <u>Riparian Corridor</u> | | |
| | Mass Failures: | | |
| | Average Height (ft.): | | |
| | Gullies: | | |
| | Average Height (ft.): | | |

| <u>Step</u> | <u>Description</u> | <u>Value</u> |
|-------------|-----------------------------|--------------|
| 4.4 | Number of Debris Jams: | |
| 4.7 | Stormwater Inputs | |
| 4.9 | Beaver Dams: | |
| | Affected length: | |
| 5.2 | Migration Features | |
| | Flood Chutes: | |
| | Neck Cutoffs: | |
| | Channel Avulsions: | |
| | Braiding: | |
| 5.3 | Steep Riffles and Head Cuts | |
| | Steep Riffles: | |
| | Head Cuts: | |
| 5.4 | Animal Crossings: | |
| 5.5 | Channel Alterations | |
| | Straightening: | |
| | Dredging: | |



Phase 2 - FIT - Legacy Data Report

Allen Brook

SGAT Version: 3

Reach: **M04 -D**

| <u>Step</u> | <u>Description</u> | <u>Value</u> | |
|-------------|--------------------------------|--------------|--------------|
| 1.2 | Alluvial Fan: | None | |
| 1.3 | <u>Encroachments - Side</u> | <u>One</u> | <u>Both</u> |
| | Berm Length (ft.): | | |
| | Path Length (ft.): | | |
| | Road Length (ft.): | | |
| | Railroad Lenth (ft.): | | |
| | Development Length: | | |
| 3.1 | <u>Erosion - Bank</u> | <u>Left</u> | <u>Right</u> |
| | Erosion Length (ft.): | 90.0 | 60.0 |
| | Erosion Height (ft.): | 1.5 | 1.5 |
| | Revetment Type: | None | None |
| | Revetment length: | | |
| 3.2 | <u>Buffer Less Than 25 ft.</u> | | |
| 3.3 | <u>Riparian Corridor</u> | | |
| | Mass Failures: | None | |
| | Average Height (ft.): | | |
| | Gullies: | None | |
| | Average Height (ft.): | | |

| <u>Step</u> | <u>Description</u> | <u>Value</u> |
|-------------|-----------------------------|----------------------|
| 4.4 | Number of Debris Jams: | 0 |
| 4.7 | Stormwater Inputs | |
| 4.9 | Beaver Dams: | 0 |
| | Affected length: | 0 |
| 5.2 | Migration Features | |
| | Flood Chutes: | 3 |
| | Neck Cutoffs: | 1 |
| | Channel Avulsions: | 0 |
| | Braiding: | 0 |
| 5.3 | Steep Riffles and Head Cuts | |
| | Steep Riffles: | 0 |
| | Head Cuts: | 0 |
| 5.4 | Animal Crossings: | Yes |
| 5.5 | Channel Alterations | |
| | Straightening: | Straightening |
| | Dredging: | None |



Phase 2 - FIT - Legacy Data Report

Allen Brook

SGAT Version: 3

Reach: **M05 -B**

| <u>Step</u> | <u>Description</u> | <u>Value</u> | |
|-------------|--------------------------------|----------------|----------------|
| 1.2 | Alluvial Fan: | None | |
| 1.3 | <u>Encroachments - Side</u> | <u>One</u> | <u>Both</u> |
| | Berm Length (ft.): | | |
| | Path Length (ft.): | | |
| | Road Length (ft.): | | |
| | Railroad Lenth (ft.): | | |
| | Development Length: | | |
| 3.1 | <u>Erosion - Bank</u> | <u>Left</u> | <u>Right</u> |
| | Erosion Length (ft.): | 2,114.0 | 2,114.0 |
| | Erosion Height (ft.): | 1.5 | 1.5 |
| | Revetment Type: | None | None |
| | Revetment length: | 0.0 | 0.0 |
| 3.2 | <u>Buffer Less Than 25 ft.</u> | | |
| 3.3 | <u>Riparian Corridor</u> | | |
| | Mass Failures: | None | |
| | Average Height (ft.): | | |
| | Gullies: | | |
| | Average Height (ft.): | | |

| <u>Step</u> | <u>Description</u> | <u>Value</u> |
|-------------|-----------------------------|----------------------|
| 4.4 | Number of Debris Jams: | 4 |
| 4.7 | Stormwater Inputs | 0 |
| 4.9 | Beaver Dams: | 0 |
| | Affected length: | 0 |
| 5.2 | Migration Features | |
| | Flood Chutes: | 2 |
| | Neck Cutoffs: | 1 |
| | Channel Avulsions: | 1 |
| | Braiding: | 0 |
| 5.3 | Steep Riffles and Head Cuts | |
| | Steep Riffles: | 0 |
| | Head Cuts: | 0 |
| 5.4 | Animal Crossings: | No |
| 5.5 | Channel Alterations | |
| | Straightening: | Straightening |
| | Dredging: | None |



Phase 2 - FIT - Legacy Data Report

Allen Brook

SGAT Version: 3

Reach: **M06 -0**

| <u>Step</u> | <u>Description</u> | <u>Value</u> | |
|-------------|--------------------------------|--------------|--------------|
| 1.2 | Alluvial Fan: | None | |
| 1.3 | <u>Encroachments - Side</u> | <u>One</u> | <u>Both</u> |
| | Berm Length (ft.): | | |
| | Path Length (ft.): | | |
| | Road Length (ft.): | | |
| | Railroad Lenth (ft.): | | |
| | Development Length: | | |
| 3.1 | <u>Erosion - Bank</u> | <u>Left</u> | <u>Right</u> |
| | Erosion Length (ft.): | 632.0 | 632.0 |
| | Erosion Height (ft.): | 1.0 | 1.0 |
| | Revetment Type: | None | None |
| | Revetment length: | 0.0 | 0.0 |
| 3.2 | <u>Buffer Less Than 25 ft.</u> | | |
| 3.3 | <u>Riparian Corridor</u> | | |
| | Mass Failures: | One | |
| | Average Height (ft.): | 15.0 | |
| | Gullies: | | |
| | Average Height (ft.): | | |

| <u>Step</u> | <u>Description</u> | <u>Value</u> |
|-------------|-----------------------------|--------------|
| 4.4 | Number of Debris Jams: | 3 |
| 4.7 | Stormwater Inputs | 4 |
| 4.9 | Beaver Dams: | 0 |
| | Affected length: | |
| 5.2 | Migration Features | |
| | Flood Chutes: | 0 |
| | Neck Cutoffs: | 1 |
| | Channel Avulsions: | 0 |
| | Braiding: | 0 |
| 5.3 | Steep Riffles and Head Cuts | |
| | Steep Riffles: | 0 |
| | Head Cuts: | 0 |
| 5.4 | Animal Crossings: | Yes |
| 5.5 | Channel Alterations | |
| | Straightening: | None |
| | Dredging: | None |



Phase 2 - FIT - Legacy Data Report

Allen Brook

SGAT Version: 3

Reach: **M05 -A**

| <u>Step</u> | <u>Description</u> | <u>Value</u> | |
|-------------|--------------------------------|----------------|----------------|
| 1.2 | Alluvial Fan: | None | |
| 1.3 | <u>Encroachments - Side</u> | <u>One</u> | <u>Both</u> |
| | Berm Length (ft.): | | |
| | Path Length (ft.): | | |
| | Road Length (ft.): | | |
| | Railroad Lenth (ft.): | | |
| | Development Length: | | |
| 3.1 | <u>Erosion - Bank</u> | <u>Left</u> | <u>Right</u> |
| | Erosion Length (ft.): | 800.0 | 800.0 |
| | Erosion Height (ft.): | 2.0 | 2.0 |
| | Revetment Type: | Rip-Rap | Rip-Rap |
| | Revetment length: | 8.0 | 8.0 |
| 3.2 | <u>Buffer Less Than 25 ft.</u> | | |
| 3.3 | <u>Riparian Corridor</u> | | |
| | Mass Failures: | None | |
| | Average Height (ft.): | | |
| | Gullies: | | |
| | Average Height (ft.): | | |

| <u>Step</u> | <u>Description</u> | <u>Value</u> |
|-------------|-----------------------------|--------------|
| 4.4 | Number of Debris Jams: | 0 |
| 4.7 | Stormwater Inputs | 0 |
| 4.9 | Beaver Dams: | 1 |
| | Affected length: | 2000 |
| 5.2 | Migration Features | |
| | Flood Chutes: | 0 |
| | Neck Cutoffs: | 0 |
| | Channel Avulsions: | 0 |
| | Braiding: | 0 |
| 5.3 | Steep Riffles and Head Cuts | |
| | Steep Riffles: | 0 |
| | Head Cuts: | 0 |
| 5.4 | Animal Crossings: | No |
| 5.5 | Channel Alterations | |
| | Straightening: | None |
| | Dredging: | None |



Phase 2 - FIT - Legacy Data Report

Allen Brook

SGAT Version: 3

Reach: **M07 -0**

| <u>Step</u> | <u>Description</u> | <u>Value</u> | |
|-------------|--------------------------------|--------------|--------------|
| 1.2 | Alluvial Fan: | None | |
| 1.3 | <u>Encroachments - Side</u> | <u>One</u> | <u>Both</u> |
| | Berm Length (ft.): | | |
| | Path Length (ft.): | | |
| | Road Length (ft.): | | |
| | Railroad Lenth (ft.): | | |
| | Development Length: | | |
| 3.1 | <u>Erosion - Bank</u> | <u>Left</u> | <u>Right</u> |
| | Erosion Length (ft.): | 100.0 | 100.0 |
| | Erosion Height (ft.): | 1.5 | 1.5 |
| | Revetment Type: | None | None |
| | Revetment length: | 0.0 | 0.0 |
| 3.2 | <u>Buffer Less Than 25 ft.</u> | | |
| 3.3 | <u>Riparian Corridor</u> | | |
| | Mass Failures: | None | |
| | Average Height (ft.): | | |
| | Gullies: | | |
| | Average Height (ft.): | | |

| <u>Step</u> | <u>Description</u> | <u>Value</u> |
|-------------|-----------------------------|----------------------|
| 4.4 | Number of Debris Jams: | 3 |
| 4.7 | Stormwater Inputs | 0 |
| 4.9 | Beaver Dams: | 0 |
| | Affected length: | |
| 5.2 | Migration Features | |
| | Flood Chutes: | 2 |
| | Neck Cutoffs: | 0 |
| | Channel Avulsions: | 0 |
| | Braiding: | 0 |
| 5.3 | Steep Riffles and Head Cuts | |
| | Steep Riffles: | 0 |
| | Head Cuts: | 0 |
| 5.4 | Animal Crossings: | Yes |
| 5.5 | Channel Alterations | |
| | Straightening: | Straightening |
| | Dredging: | Dredging |