



Phase 2 - FIT - Legacy Data Report

Indian Brook

SGAT Version: 3

Reach: **M02 -0**

| <u>Step</u> | <u>Description</u> | <u>Value</u> | |
|-------------|--------------------------------|----------------|----------------|
| 1.2 | Alluvial Fan: | None | |
| 1.3 | <u>Encroachments - Side</u> | <u>One</u> | <u>Both</u> |
| | Berm Length (ft.): | | |
| | Path Length (ft.): | | |
| | Road Length (ft.): | | |
| | Railroad Lenth (ft.): | | |
| | Development Length: | | |
| 3.1 | <u>Erosion - Bank</u> | <u>Left</u> | <u>Right</u> |
| | Erosion Length (ft.): | 2,400.0 | 2,400.0 |
| | Erosion Height (ft.): | 2.0 | 2.0 |
| | Revetment Type: | None | None |
| | Revetment length: | 0.0 | 0.0 |
| 3.2 | <u>Buffer Less Than 25 ft.</u> | | |
| 3.3 | <u>Riparian Corridor</u> | | |
| | Mass Failures: | One | |
| | Average Height (ft.): | 7.0 | |
| | Gullies: | | |
| | Average Height (ft.): | | |

| <u>Step</u> | <u>Description</u> | <u>Value</u> |
|-------------|-----------------------------|----------------------|
| 4.4 | Number of Debris Jams: | 6 |
| 4.7 | Stormwater Inputs | 1 |
| 4.9 | Beaver Dams: | 2 |
| | Affected length: | 1300 |
| 5.2 | Migration Features | |
| | Flood Chutes: | 1 |
| | Neck Cutoffs: | 0 |
| | Channel Avulsions: | 0 |
| | Braiding: | 0 |
| 5.3 | Steep Riffles and Head Cuts | |
| | Steep Riffles: | 0 |
| | Head Cuts: | 0 |
| 5.4 | Animal Crossings: | No |
| 5.5 | Channel Alterations | |
| | Straightening: | Straightening |
| | Dredging: | None |



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
July, 17 2024

Phase 2 - FIT - Legacy Data Report

Indian Brook

SGAT Version: **3**

Reach: **M09 -A**

| <u>Step</u> | <u>Description</u> | <u>Value</u> | |
|-------------|--------------------------------|--------------|----------------|
| 1.2 | Alluvial Fan: | None | |
| 1.3 | <u>Encroachments - Side</u> | <u>One</u> | <u>Both</u> |
| | Berm Length (ft.): | | |
| | Path Length (ft.): | | |
| | Road Length (ft.): | | |
| | Railroad Lenth (ft.): | | |
| | Development Length: | | |
| 3.1 | <u>Erosion - Bank</u> | <u>Left</u> | <u>Right</u> |
| | Erosion Length (ft.): | 30.0 | 10.0 |
| | Erosion Height (ft.): | 2.0 | 2.0 |
| | Revetment Type: | None | Rip-Rap |
| | Revetment length: | 0.0 | 10.0 |
| 3.2 | <u>Buffer Less Than 25 ft.</u> | | |
| 3.3 | <u>Riparian Corridor</u> | | |
| | Mass Failures: | None | |
| | Average Height (ft.): | | |
| | Gullies: | | |
| | Average Height (ft.): | | |

| <u>Step</u> | <u>Description</u> | <u>Value</u> |
|-------------|-----------------------------|--------------|
| 4.4 | Number of Debris Jams: | 2 |
| 4.7 | Stormwater Inputs | 1 |
| 4.9 | Beaver Dams: | 5 |
| | Affected length: | 1500 |
| 5.2 | Migration Features | |
| | Flood Chutes: | 2 |
| | Neck Cutoffs: | 0 |
| | Channel Avulsions: | 0 |
| | Braiding: | 0 |
| 5.3 | Steep Riffles and Head Cuts | |
| | Steep Riffles: | 1 |
| | Head Cuts: | 1 |
| 5.4 | Animal Crossings: | No |
| 5.5 | Channel Alterations | |
| | Straightening: | None |
| | Dredging: | None |



Phase 2 - FIT - Legacy Data Report

Indian Brook

SGAT Version: 3

Reach: **M12 -0**

| <u>Step</u> | <u>Description</u> | <u>Value</u> | |
|-------------|--------------------------------|--------------|--------------|
| 1.2 | Alluvial Fan: | None | |
| 1.3 | <u>Encroachments - Side</u> | <u>One</u> | <u>Both</u> |
| | Berm Length (ft.): | | |
| | Path Length (ft.): | | |
| | Road Length (ft.): | | |
| | Railroad Lenth (ft.): | | |
| | Development Length: | | |
| 3.1 | <u>Erosion - Bank</u> | <u>Left</u> | <u>Right</u> |
| | Erosion Length (ft.): | 120.0 | 0.0 |
| | Erosion Height (ft.): | 2.0 | 0.0 |
| | Revetment Type: | None | None |
| | Revetment length: | 0.0 | 0.0 |
| 3.2 | <u>Buffer Less Than 25 ft.</u> | | |
| 3.3 | <u>Riparian Corridor</u> | | |
| | Mass Failures: | One | |
| | Average Height (ft.): | 7.0 | |
| | Gullies: | | |
| | Average Height (ft.): | | |

| <u>Step</u> | <u>Description</u> | <u>Value</u> |
|-------------|-----------------------------|----------------------|
| 4.4 | Number of Debris Jams: | 10 |
| 4.7 | Stormwater Inputs | 1 |
| 4.9 | Beaver Dams: | |
| | Affected length: | |
| 5.2 | Migration Features | |
| | Flood Chutes: | 2 |
| | Neck Cutoffs: | 0 |
| | Channel Avulsions: | 0 |
| | Braiding: | 0 |
| 5.3 | Steep Riffles and Head Cuts | |
| | Steep Riffles: | 0 |
| | Head Cuts: | 0 |
| 5.4 | Animal Crossings: | No |
| 5.5 | Channel Alterations | |
| | Straightening: | Straightening |
| | Dredging: | None |



Phase 2 - FIT - Legacy Data Report

Indian Brook

SGAT Version: 3

Reach: **M07 -0**

| <u>Step</u> | <u>Description</u> | <u>Value</u> | |
|-------------|--------------------------------|--------------|--------------|
| 1.2 | Alluvial Fan: | None | |
| 1.3 | <u>Encroachments - Side</u> | <u>One</u> | <u>Both</u> |
| | Berm Length (ft.): | | |
| | Path Length (ft.): | | |
| | Road Length (ft.): | | |
| | Railroad Lenth (ft.): | | |
| | Development Length: | | |
| 3.1 | <u>Erosion - Bank</u> | <u>Left</u> | <u>Right</u> |
| | Erosion Length (ft.): | 250.0 | 250.0 |
| | Erosion Height (ft.): | 1.5 | 1.5 |
| | Revetment Type: | None | None |
| | Revetment length: | 0.0 | 0.0 |
| 3.2 | <u>Buffer Less Than 25 ft.</u> | | |
| 3.3 | <u>Riparian Corridor</u> | | |
| | Mass Failures: | None | |
| | Average Height (ft.): | | |
| | Gullies: | | |
| | Average Height (ft.): | | |

| <u>Step</u> | <u>Description</u> | <u>Value</u> |
|-------------|-----------------------------|--------------|
| 4.4 | Number of Debris Jams: | 2 |
| 4.7 | Stormwater Inputs | 0 |
| 4.9 | Beaver Dams: | 1 |
| | Affected length: | 1524 |
| 5.2 | Migration Features | |
| | Flood Chutes: | 0 |
| | Neck Cutoffs: | 0 |
| | Channel Avulsions: | 0 |
| | Braiding: | 0 |
| 5.3 | Steep Riffles and Head Cuts | |
| | Steep Riffles: | 0 |
| | Head Cuts: | 0 |
| 5.4 | Animal Crossings: | No |
| 5.5 | Channel Alterations | |
| | Straightening: | None |
| | Dredging: | None |



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
July, 17 2024

Phase 2 - FIT - Legacy Data Report

Indian Brook

SGAT Version: 3

Reach: **M08 -0**

| <u>Step</u> | <u>Description</u> | <u>Value</u> | |
|-------------|--------------------------------|--------------|--------------|
| 1.2 | Alluvial Fan: | None | |
| 1.3 | <u>Encroachments - Side</u> | <u>One</u> | <u>Both</u> |
| | Berm Length (ft.): | | |
| | Path Length (ft.): | | |
| | Road Length (ft.): | | |
| | Railroad Lenth (ft.): | | |
| | Development Length: | | |
| 3.1 | <u>Erosion - Bank</u> | <u>Left</u> | <u>Right</u> |
| | Erosion Length (ft.): | 433.0 | 433.0 |
| | Erosion Height (ft.): | 1.5 | 1.5 |
| | Revetment Type: | None | None |
| | Revetment length: | 0.0 | 0.0 |
| 3.2 | <u>Buffer Less Than 25 ft.</u> | | |
| 3.3 | <u>Riparian Corridor</u> | | |
| | Mass Failures: | None | |
| | Average Height (ft.): | | |
| | Gullies: | | |
| | Average Height (ft.): | | |

| <u>Step</u> | <u>Description</u> | <u>Value</u> |
|-------------|-----------------------------|--------------|
| 4.4 | Number of Debris Jams: | 2 |
| 4.7 | Stormwater Inputs | 0 |
| 4.9 | Beaver Dams: | 1 |
| | Affected length: | 550 |
| 5.2 | Migration Features | |
| | Flood Chutes: | 2 |
| | Neck Cutoffs: | 1 |
| | Channel Avulsions: | 0 |
| | Braiding: | 0 |
| 5.3 | Steep Riffles and Head Cuts | |
| | Steep Riffles: | 0 |
| | Head Cuts: | 0 |
| 5.4 | Animal Crossings: | No |
| 5.5 | Channel Alterations | |
| | Straightening: | None |
| | Dredging: | None |



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
July, 17 2024

Phase 2 - FIT - Legacy Data Report

Indian Brook

SGAT Version: 3

Reach: **M13 -B**

| <u>Step</u> | <u>Description</u> | <u>Value</u> | |
|-------------|--------------------------------|--------------|--------------|
| 1.2 | Alluvial Fan: | None | |
| 1.3 | <u>Encroachments - Side</u> | <u>One</u> | <u>Both</u> |
| | Berm Length (ft.): | | |
| | Path Length (ft.): | | |
| | Road Length (ft.): | | |
| | Railroad Lenth (ft.): | | |
| | Development Length: | | |
| 3.1 | <u>Erosion - Bank</u> | <u>Left</u> | <u>Right</u> |
| | Erosion Length (ft.): | 0.0 | 10.0 |
| | Erosion Height (ft.): | 0.0 | 4.0 |
| | Revetment Type: | None | None |
| | Revetment length: | 0.0 | 0.0 |
| 3.2 | <u>Buffer Less Than 25 ft.</u> | | |
| 3.3 | <u>Riparian Corridor</u> | | |
| | Mass Failures: | None | |
| | Average Height (ft.): | | |
| | Gullies: | | |
| | Average Height (ft.): | | |

| <u>Step</u> | <u>Description</u> | <u>Value</u> |
|-------------|-----------------------------|--------------|
| 4.4 | Number of Debris Jams: | 0 |
| 4.7 | Stormwater Inputs | 0 |
| 4.9 | Beaver Dams: | 0 |
| | Affected length: | 0 |
| 5.2 | Migration Features | |
| | Flood Chutes: | 2 |
| | Neck Cutoffs: | 2 |
| | Channel Avulsions: | 0 |
| | Braiding: | 0 |
| 5.3 | Steep Riffles and Head Cuts | |
| | Steep Riffles: | 0 |
| | Head Cuts: | 0 |
| 5.4 | Animal Crossings: | No |
| 5.5 | Channel Alterations | |
| | Straightening: | None |
| | Dredging: | None |



Phase 2 - FIT - Legacy Data Report

Indian Brook

SGAT Version: 3

Reach: **M01 -0**

| <u>Step</u> | <u>Description</u> | <u>Value</u> | |
|-------------|--------------------------------|--------------|--------------|
| 1.2 | Alluvial Fan: | None | |
| 1.3 | <u>Encroachments - Side</u> | <u>One</u> | <u>Both</u> |
| | Berm Length (ft.): | | |
| | Path Length (ft.): | | |
| | Road Length (ft.): | | |
| | Railroad Lenth (ft.): | | |
| | Development Length: | | |
| 3.1 | <u>Erosion - Bank</u> | <u>Left</u> | <u>Right</u> |
| | Erosion Length (ft.): | 586.0 | 586.0 |
| | Erosion Height (ft.): | 2.9 | 2.9 |
| | Revetment Type: | None | None |
| | Revetment length: | 0.0 | 0.0 |
| 3.2 | <u>Buffer Less Than 25 ft.</u> | | |
| 3.3 | <u>Riparian Corridor</u> | | |
| | Mass Failures: | None | |
| | Average Height (ft.): | | |
| | Gullies: | | |
| | Average Height (ft.): | | |

| <u>Step</u> | <u>Description</u> | <u>Value</u> |
|-------------|-----------------------------|----------------------|
| 4.4 | Number of Debris Jams: | 6 |
| 4.7 | Stormwater Inputs | 0 |
| 4.9 | Beaver Dams: | 3 |
| | Affected length: | 500 |
| 5.2 | Migration Features | |
| | Flood Chutes: | 0 |
| | Neck Cutoffs: | 0 |
| | Channel Avulsions: | 0 |
| | Braiding: | 0 |
| 5.3 | Steep Riffles and Head Cuts | |
| | Steep Riffles: | 0 |
| | Head Cuts: | 0 |
| 5.4 | Animal Crossings: | No |
| 5.5 | Channel Alterations | |
| | Straightening: | Straightening |
| | Dredging: | None |



Phase 2 - FIT - Legacy Data Report

Indian Brook

SGAT Version: 3

Reach: **M03 -0**

| <u>Step</u> | <u>Description</u> | <u>Value</u> | |
|-------------|--------------------------------|-----------------|----------------|
| 1.2 | Alluvial Fan: | None | |
| 1.3 | <u>Encroachments - Side</u> | <u>One</u> | <u>Both</u> |
| | Berm Length (ft.): | | |
| | Path Length (ft.): | | |
| | Road Length (ft.): | | |
| | Railroad Lenth (ft.): | | |
| | Development Length: | | |
| 3.1 | <u>Erosion - Bank</u> | <u>Left</u> | <u>Right</u> |
| | Erosion Length (ft.): | 200.0 | 500.0 |
| | Erosion Height (ft.): | 3.0 | 5.0 |
| | Revetment Type: | Rip-Rap | Rip-Rap |
| | Revetment length: | 180.0 | 330.0 |
| 3.2 | <u>Buffer Less Than 25 ft.</u> | | |
| 3.3 | <u>Riparian Corridor</u> | | |
| | Mass Failures: | Multiple | |
| | Average Height (ft.): | 8.0 | |
| | Gullies: | | |
| | Average Height (ft.): | | |

| <u>Step</u> | <u>Description</u> | <u>Value</u> |
|-------------|-----------------------------|--------------|
| 4.4 | Number of Debris Jams: | 13 |
| 4.7 | Stormwater Inputs | 3 |
| 4.9 | Beaver Dams: | 0 |
| | Affected length: | 0 |
| 5.2 | Migration Features | |
| | Flood Chutes: | 2 |
| | Neck Cutoffs: | 2 |
| | Channel Avulsions: | 2 |
| | Braiding: | 0 |
| 5.3 | Steep Riffles and Head Cuts | |
| | Steep Riffles: | 2 |
| | Head Cuts: | 0 |
| 5.4 | Animal Crossings: | No |
| 5.5 | Channel Alterations | |
| | Straightening: | None |
| | Dredging: | None |



Phase 2 - FIT - Legacy Data Report

Indian Brook

SGAT Version: 3

Reach: **M09 -B**

| <u>Step</u> | <u>Description</u> | <u>Value</u> | |
|-------------|--------------------------------|----------------|----------------|
| 1.2 | Alluvial Fan: | None | |
| 1.3 | <u>Encroachments - Side</u> | <u>One</u> | <u>Both</u> |
| | Berm Length (ft.): | | |
| | Path Length (ft.): | | |
| | Road Length (ft.): | | |
| | Railroad Lenth (ft.): | | |
| | Development Length: | | |
| 3.1 | <u>Erosion - Bank</u> | <u>Left</u> | <u>Right</u> |
| | Erosion Length (ft.): | 120.0 | 120.0 |
| | Erosion Height (ft.): | 4.0 | 2.0 |
| | Revetment Type: | Rip-Rap | Rip-Rap |
| | Revetment length: | 100.0 | 100.0 |
| 3.2 | <u>Buffer Less Than 25 ft.</u> | | |
| 3.3 | <u>Riparian Corridor</u> | | |
| | Mass Failures: | None | |
| | Average Height (ft.): | | |
| | Gullies: | | |
| | Average Height (ft.): | | |

| <u>Step</u> | <u>Description</u> | <u>Value</u> |
|-------------|-----------------------------|--------------|
| 4.4 | Number of Debris Jams: | 0 |
| 4.7 | Stormwater Inputs | 1 |
| 4.9 | Beaver Dams: | |
| | Affected length: | |
| 5.2 | Migration Features | |
| | Flood Chutes: | 1 |
| | Neck Cutoffs: | 0 |
| | Channel Avulsions: | 1 |
| | Braiding: | 0 |
| 5.3 | Steep Riffles and Head Cuts | |
| | Steep Riffles: | 0 |
| | Head Cuts: | 0 |
| 5.4 | Animal Crossings: | No |
| 5.5 | Channel Alterations | |
| | Straightening: | None |
| | Dredging: | None |



Phase 2 - FIT - Legacy Data Report

Indian Brook

SGAT Version: 3

Reach: **M10 -B**

| <u>Step</u> | <u>Description</u> | <u>Value</u> | |
|-------------|--------------------------------|--------------|--------------|
| 1.2 | Alluvial Fan: | None | |
| 1.3 | <u>Encroachments - Side</u> | <u>One</u> | <u>Both</u> |
| | Berm Length (ft.): | | |
| | Path Length (ft.): | | |
| | Road Length (ft.): | | |
| | Railroad Lenth (ft.): | | |
| | Development Length: | | |
| 3.1 | <u>Erosion - Bank</u> | <u>Left</u> | <u>Right</u> |
| | Erosion Length (ft.): | 700.0 | 700.0 |
| | Erosion Height (ft.): | 1.5 | 1.5 |
| | Revetment Type: | None | None |
| | Revetment length: | 0.0 | 0.0 |
| 3.2 | <u>Buffer Less Than 25 ft.</u> | | |
| 3.3 | <u>Riparian Corridor</u> | | |
| | Mass Failures: | None | |
| | Average Height (ft.): | | |
| | Gullies: | | |
| | Average Height (ft.): | | |

| <u>Step</u> | <u>Description</u> | <u>Value</u> |
|-------------|-----------------------------|--------------|
| 4.4 | Number of Debris Jams: | 1 |
| 4.7 | Stormwater Inputs | 9 |
| 4.9 | Beaver Dams: | 1 |
| | Affected length: | 2500 |
| 5.2 | Migration Features | |
| | Flood Chutes: | 1 |
| | Neck Cutoffs: | 1 |
| | Channel Avulsions: | 0 |
| | Braiding: | 0 |
| 5.3 | Steep Riffles and Head Cuts | |
| | Steep Riffles: | 0 |
| | Head Cuts: | 0 |
| 5.4 | Animal Crossings: | No |
| 5.5 | Channel Alterations | |
| | Straightening: | None |
| | Dredging: | None |



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
July, 17 2024

Phase 2 - FIT - Legacy Data Report

Indian Brook

SGAT Version: **3**

Reach: **M04 -0**

| <u>Step</u> | <u>Description</u> | <u>Value</u> | |
|-------------|--------------------------------|-----------------|----------------|
| 1.2 | Alluvial Fan: | None | |
| 1.3 | <u>Encroachments - Side</u> | <u>One</u> | <u>Both</u> |
| | Berm Length (ft.): | | |
| | Path Length (ft.): | | |
| | Road Length (ft.): | | |
| | Railroad Lenth (ft.): | | |
| | Development Length: | | |
| 3.1 | <u>Erosion - Bank</u> | <u>Left</u> | <u>Right</u> |
| | Erosion Length (ft.): | 2,800.0 | 2,800.0 |
| | Erosion Height (ft.): | 1.5 | 1.5 |
| | Revetment Type: | Rip-Rap | Rip-Rap |
| | Revetment length: | 40.0 | 40.0 |
| 3.2 | <u>Buffer Less Than 25 ft.</u> | | |
| 3.3 | <u>Riparian Corridor</u> | | |
| | Mass Failures: | Multiple | |
| | Average Height (ft.): | 40.0 | |
| | Gullies: | | |
| | Average Height (ft.): | | |

| <u>Step</u> | <u>Description</u> | <u>Value</u> |
|-------------|-----------------------------|--------------|
| 4.4 | Number of Debris Jams: | 7 |
| 4.7 | Stormwater Inputs | 2 |
| 4.9 | Beaver Dams: | 2 |
| | Affected length: | 1200 |
| 5.2 | Migration Features | |
| | Flood Chutes: | 1 |
| | Neck Cutoffs: | 0 |
| | Channel Avulsions: | 1 |
| | Braiding: | 0 |
| 5.3 | Steep Riffles and Head Cuts | |
| | Steep Riffles: | 0 |
| | Head Cuts: | 0 |
| 5.4 | Animal Crossings: | No |
| 5.5 | Channel Alterations | |
| | Straightening: | None |
| | Dredging: | None |



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
July, 17 2024

Phase 2 - FIT - Legacy Data Report

Indian Brook

SGAT Version: **3**

Reach: **M10 -A**

| <u>Step</u> | <u>Description</u> | <u>Value</u> | |
|-------------|--------------------------------|----------------|----------------|
| 1.2 | Alluvial Fan: | None | |
| 1.3 | <u>Encroachments - Side</u> | <u>One</u> | <u>Both</u> |
| | Berm Length (ft.): | | |
| | Path Length (ft.): | | |
| | Road Length (ft.): | | |
| | Railroad Lenth (ft.): | | |
| | Development Length: | | |
| 3.1 | <u>Erosion - Bank</u> | <u>Left</u> | <u>Right</u> |
| | Erosion Length (ft.): | 1,937.0 | 1,937.0 |
| | Erosion Height (ft.): | 1.5 | 1.5 |
| | Revetment Type: | Rip-Rap | None |
| | Revetment length: | 40.0 | 0.0 |
| 3.2 | <u>Buffer Less Than 25 ft.</u> | | |
| 3.3 | <u>Riparian Corridor</u> | | |
| | Mass Failures: | None | |
| | Average Height (ft.): | | |
| | Gullies: | | |
| | Average Height (ft.): | | |

| <u>Step</u> | <u>Description</u> | <u>Value</u> |
|-------------|-----------------------------|----------------------|
| 4.4 | Number of Debris Jams: | 5 |
| 4.7 | Stormwater Inputs | 3 |
| 4.9 | Beaver Dams: | 2 |
| | Affected length: | 1500 |
| 5.2 | Migration Features | |
| | Flood Chutes: | 2 |
| | Neck Cutoffs: | 0 |
| | Channel Avulsions: | 0 |
| | Braiding: | 0 |
| 5.3 | Steep Riffles and Head Cuts | |
| | Steep Riffles: | 0 |
| | Head Cuts: | 0 |
| 5.4 | Animal Crossings: | No |
| 5.5 | Channel Alterations | |
| | Straightening: | Straightening |
| | Dredging: | None |



Phase 2 - FIT - Legacy Data Report

Indian Brook

SGAT Version: 3

Reach: **M11 -B**

| <u>Step</u> | <u>Description</u> | <u>Value</u> | |
|-------------|--------------------------------|----------------|----------------|
| 1.2 | Alluvial Fan: | None | |
| 1.3 | <u>Encroachments - Side</u> | <u>One</u> | <u>Both</u> |
| | Berm Length (ft.): | | |
| | Path Length (ft.): | | |
| | Road Length (ft.): | | |
| | Railroad Lenth (ft.): | | |
| | Development Length: | | |
| 3.1 | <u>Erosion - Bank</u> | <u>Left</u> | <u>Right</u> |
| | Erosion Length (ft.): | 2,225.0 | 2,225.0 |
| | Erosion Height (ft.): | 1.5 | 1.5 |
| | Revetment Type: | Rip-Rap | Rip-Rap |
| | Revetment length: | 130.0 | 130.0 |
| 3.2 | <u>Buffer Less Than 25 ft.</u> | | |
| 3.3 | <u>Riparian Corridor</u> | | |
| | Mass Failures: | None | |
| | Average Height (ft.): | | |
| | Gullies: | | |
| | Average Height (ft.): | | |

| <u>Step</u> | <u>Description</u> | <u>Value</u> |
|-------------|-----------------------------|----------------------|
| 4.4 | Number of Debris Jams: | 3 |
| 4.7 | Stormwater Inputs | 19 |
| 4.9 | Beaver Dams: | 0 |
| | Affected length: | |
| 5.2 | Migration Features | |
| | Flood Chutes: | 1 |
| | Neck Cutoffs: | 0 |
| | Channel Avulsions: | 0 |
| | Braiding: | 0 |
| 5.3 | Steep Riffles and Head Cuts | |
| | Steep Riffles: | 0 |
| | Head Cuts: | 1 |
| 5.4 | Animal Crossings: | No |
| 5.5 | Channel Alterations | |
| | Straightening: | Straightening |
| | Dredging: | None |



Phase 2 - FIT - Legacy Data Report

Indian Brook

SGAT Version: 3

Reach: **M14 -0**

| <u>Step</u> | <u>Description</u> | <u>Value</u> | |
|-------------|--------------------------------|--------------|--------------|
| 1.2 | Alluvial Fan: | | |
| 1.3 | <u>Encroachments - Side</u> | <u>One</u> | <u>Both</u> |
| | Berm Length (ft.): | | |
| | Path Length (ft.): | | |
| | Road Length (ft.): | | |
| | Railroad Lenth (ft.): | | |
| | Development Length: | | |
| 3.1 | <u>Erosion - Bank</u> | <u>Left</u> | <u>Right</u> |
| | Erosion Length (ft.): | | |
| | Erosion Height (ft.): | | |
| | Revetment Type: | | |
| | Revetment length: | | |
| 3.2 | <u>Buffer Less Than 25 ft.</u> | | |
| 3.3 | <u>Riparian Corridor</u> | | |
| | Mass Failures: | | |
| | Average Height (ft.): | | |
| | Gullies: | | |
| | Average Height (ft.): | | |

| <u>Step</u> | <u>Description</u> | <u>Value</u> |
|-------------|-----------------------------|--------------|
| 4.4 | Number of Debris Jams: | |
| 4.7 | Stormwater Inputs | |
| 4.9 | Beaver Dams: | |
| | Affected length: | |
| 5.2 | Migration Features | |
| | Flood Chutes: | |
| | Neck Cutoffs: | |
| | Channel Avulsions: | |
| | Braiding: | |
| 5.3 | Steep Riffles and Head Cuts | |
| | Steep Riffles: | |
| | Head Cuts: | |
| 5.4 | Animal Crossings: | |
| 5.5 | Channel Alterations | |
| | Straightening: | |
| | Dredging: | |



Phase 2 - FIT - Legacy Data Report

Indian Brook

SGAT Version: 3

Reach: **M11 -A**

| <u>Step</u> | <u>Description</u> | <u>Value</u> | |
|-------------|--------------------------------|----------------|----------------|
| 1.2 | Alluvial Fan: | None | |
| 1.3 | <u>Encroachments - Side</u> | <u>One</u> | <u>Both</u> |
| | Berm Length (ft.): | | |
| | Path Length (ft.): | | |
| | Road Length (ft.): | | |
| | Railroad Lenth (ft.): | | |
| | Development Length: | | |
| 3.1 | <u>Erosion - Bank</u> | <u>Left</u> | <u>Right</u> |
| | Erosion Length (ft.): | 1,950.0 | 1,950.0 |
| | Erosion Height (ft.): | 1.5 | 1.5 |
| | Revetment Type: | None | None |
| | Revetment length: | 0.0 | 0.0 |
| 3.2 | <u>Buffer Less Than 25 ft.</u> | | |
| 3.3 | <u>Riparian Corridor</u> | | |
| | Mass Failures: | None | |
| | Average Height (ft.): | | |
| | Gullies: | | |
| | Average Height (ft.): | | |

| <u>Step</u> | <u>Description</u> | <u>Value</u> |
|-------------|-----------------------------|----------------------|
| 4.4 | Number of Debris Jams: | 5 |
| 4.7 | Stormwater Inputs | 9 |
| 4.9 | Beaver Dams: | 0 |
| | Affected length: | |
| 5.2 | Migration Features | |
| | Flood Chutes: | 1 |
| | Neck Cutoffs: | 0 |
| | Channel Avulsions: | 0 |
| | Braiding: | 0 |
| 5.3 | Steep Riffles and Head Cuts | |
| | Steep Riffles: | 1 |
| | Head Cuts: | 0 |
| 5.4 | Animal Crossings: | Yes |
| 5.5 | Channel Alterations | |
| | Straightening: | Straightening |
| | Dredging: | None |



Phase 2 - FIT - Legacy Data Report

Indian Brook

SGAT Version: 3

Reach: **M16 -A**

| <u>Step</u> | <u>Description</u> | <u>Value</u> | |
|-------------|--------------------------------|--------------|--------------|
| 1.2 | Alluvial Fan: | None | |
| 1.3 | <u>Encroachments - Side</u> | <u>One</u> | <u>Both</u> |
| | Berm Length (ft.): | | |
| | Path Length (ft.): | | |
| | Road Length (ft.): | | |
| | Railroad Lenth (ft.): | | |
| | Development Length: | | |
| 3.1 | <u>Erosion - Bank</u> | <u>Left</u> | <u>Right</u> |
| | Erosion Length (ft.): | 907.0 | 907.0 |
| | Erosion Height (ft.): | 2.0 | 2.0 |
| | Revetment Type: | None | None |
| | Revetment length: | 0.0 | 0.0 |
| 3.2 | <u>Buffer Less Than 25 ft.</u> | | |
| 3.3 | <u>Riparian Corridor</u> | | |
| | Mass Failures: | None | |
| | Average Height (ft.): | | |
| | Gullies: | | |
| | Average Height (ft.): | | |

| <u>Step</u> | <u>Description</u> | <u>Value</u> |
|-------------|-----------------------------|--------------|
| 4.4 | Number of Debris Jams: | 11 |
| 4.7 | Stormwater Inputs | 0 |
| 4.9 | Beaver Dams: | 0 |
| | Affected length: | |
| 5.2 | Migration Features | |
| | Flood Chutes: | 2 |
| | Neck Cutoffs: | 0 |
| | Channel Avulsions: | 0 |
| | Braiding: | 0 |
| 5.3 | Steep Riffles and Head Cuts | |
| | Steep Riffles: | 0 |
| | Head Cuts: | 0 |
| 5.4 | Animal Crossings: | No |
| 5.5 | Channel Alterations | |
| | Straightening: | None |
| | Dredging: | None |



Phase 2 - FIT - Legacy Data Report

Indian Brook

SGAT Version: 3

Reach: **M18 -0**

| <u>Step</u> | <u>Description</u> | <u>Value</u> | |
|-------------|--------------------------------|--------------|--------------|
| 1.2 | Alluvial Fan: | None | |
| 1.3 | <u>Encroachments - Side</u> | <u>One</u> | <u>Both</u> |
| | Berm Length (ft.): | | |
| | Path Length (ft.): | | |
| | Road Length (ft.): | | |
| | Railroad Lenth (ft.): | | |
| | Development Length: | | |
| 3.1 | <u>Erosion - Bank</u> | <u>Left</u> | <u>Right</u> |
| | Erosion Length (ft.): | 100.0 | 20.0 |
| | Erosion Height (ft.): | 2.0 | 2.0 |
| | Revetment Type: | None | None |
| | Revetment length: | | |
| 3.2 | <u>Buffer Less Than 25 ft.</u> | | |
| 3.3 | <u>Riparian Corridor</u> | | |
| | Mass Failures: | None | |
| | Average Height (ft.): | | |
| | Gullies: | | |
| | Average Height (ft.): | | |

| <u>Step</u> | <u>Description</u> | <u>Value</u> |
|-------------|-----------------------------|----------------------|
| 4.4 | Number of Debris Jams: | 25 |
| 4.7 | Stormwater Inputs | 0 |
| 4.9 | Beaver Dams: | 0 |
| | Affected length: | |
| 5.2 | Migration Features | |
| | Flood Chutes: | 2 |
| | Neck Cutoffs: | 0 |
| | Channel Avulsions: | 0 |
| | Braiding: | 0 |
| 5.3 | Steep Riffles and Head Cuts | |
| | Steep Riffles: | 0 |
| | Head Cuts: | 0 |
| 5.4 | Animal Crossings: | Yes |
| 5.5 | Channel Alterations | |
| | Straightening: | Straightening |
| | Dredging: | None |



Phase 2 - FIT - Legacy Data Report

Indian Brook

SGAT Version: 3

Reach: **M11 -C**

| <u>Step</u> | <u>Description</u> | <u>Value</u> | |
|-------------|--------------------------------|--------------|--------------|
| 1.2 | Alluvial Fan: | None | |
| 1.3 | <u>Encroachments - Side</u> | <u>One</u> | <u>Both</u> |
| | Berm Length (ft.): | | |
| | Path Length (ft.): | | |
| | Road Length (ft.): | | |
| | Railroad Lenth (ft.): | | |
| | Development Length: | | |
| 3.1 | <u>Erosion - Bank</u> | <u>Left</u> | <u>Right</u> |
| | Erosion Length (ft.): | 750.0 | 750.0 |
| | Erosion Height (ft.): | 1.0 | 1.0 |
| | Revetment Type: | None | None |
| | Revetment length: | | |
| 3.2 | <u>Buffer Less Than 25 ft.</u> | | |
| 3.3 | <u>Riparian Corridor</u> | | |
| | Mass Failures: | None | |
| | Average Height (ft.): | | |
| | Gullies: | | |
| | Average Height (ft.): | | |

| <u>Step</u> | <u>Description</u> | <u>Value</u> |
|-------------|-----------------------------|--------------|
| 4.4 | Number of Debris Jams: | 1 |
| 4.7 | Stormwater Inputs | 4 |
| 4.9 | Beaver Dams: | 0 |
| | Affected length: | |
| 5.2 | Migration Features | |
| | Flood Chutes: | 1 |
| | Neck Cutoffs: | 0 |
| | Channel Avulsions: | 0 |
| | Braiding: | 0 |
| 5.3 | Steep Riffles and Head Cuts | |
| | Steep Riffles: | 0 |
| | Head Cuts: | 0 |
| 5.4 | Animal Crossings: | No |
| 5.5 | Channel Alterations | |
| | Straightening: | None |
| | Dredging: | None |



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
July, 17 2024

Phase 2 - FIT - Legacy Data Report

Indian Brook

SGAT Version: **3**

Reach: **M13 -A**

| <u>Step</u> | <u>Description</u> | <u>Value</u> | |
|-------------|--------------------------------|----------------|----------------|
| 1.2 | Alluvial Fan: | None | |
| 1.3 | <u>Encroachments - Side</u> | <u>One</u> | <u>Both</u> |
| | Berm Length (ft.): | | |
| | Path Length (ft.): | | |
| | Road Length (ft.): | | |
| | Railroad Lenth (ft.): | | |
| | Development Length: | | |
| 3.1 | <u>Erosion - Bank</u> | <u>Left</u> | <u>Right</u> |
| | Erosion Length (ft.): | 50.0 | 50.0 |
| | Erosion Height (ft.): | 2.0 | 2.0 |
| | Revetment Type: | Rip-Rap | Rip-Rap |
| | Revetment length: | 15.0 | 15.0 |
| 3.2 | <u>Buffer Less Than 25 ft.</u> | | |
| 3.3 | <u>Riparian Corridor</u> | | |
| | Mass Failures: | None | |
| | Average Height (ft.): | | |
| | Gullies: | | |
| | Average Height (ft.): | | |

| <u>Step</u> | <u>Description</u> | <u>Value</u> |
|-------------|-----------------------------|----------------------|
| 4.4 | Number of Debris Jams: | 1 |
| 4.7 | Stormwater Inputs | 0 |
| 4.9 | Beaver Dams: | 0 |
| | Affected length: | |
| 5.2 | Migration Features | |
| | Flood Chutes: | 1 |
| | Neck Cutoffs: | 0 |
| | Channel Avulsions: | 0 |
| | Braiding: | 0 |
| 5.3 | Steep Riffles and Head Cuts | |
| | Steep Riffles: | 0 |
| | Head Cuts: | 0 |
| 5.4 | Animal Crossings: | No |
| 5.5 | Channel Alterations | |
| | Straightening: | Straightening |
| | Dredging: | None |



Phase 2 - FIT - Legacy Data Report

Indian Brook

SGAT Version: 3

Reach: **M15 -0**

| <u>Step</u> | <u>Description</u> | <u>Value</u> | |
|-------------|--------------------------------|----------------|----------------|
| 1.2 | Alluvial Fan: | None | |
| 1.3 | <u>Encroachments - Side</u> | <u>One</u> | <u>Both</u> |
| | Berm Length (ft.): | | |
| | Path Length (ft.): | | |
| | Road Length (ft.): | | |
| | Railroad Lenth (ft.): | | |
| | Development Length: | | |
| 3.1 | <u>Erosion - Bank</u> | <u>Left</u> | <u>Right</u> |
| | Erosion Length (ft.): | 200.0 | 200.0 |
| | Erosion Height (ft.): | 1.3 | 1.3 |
| | Revetment Type: | Rip-Rap | Rip-Rap |
| | Revetment length: | 60.0 | 60.0 |
| 3.2 | <u>Buffer Less Than 25 ft.</u> | | |
| 3.3 | <u>Riparian Corridor</u> | | |
| | Mass Failures: | None | |
| | Average Height (ft.): | | |
| | Gullies: | | |
| | Average Height (ft.): | | |

| <u>Step</u> | <u>Description</u> | <u>Value</u> |
|-------------|-----------------------------|----------------------|
| 4.4 | Number of Debris Jams: | 4 |
| 4.7 | Stormwater Inputs | 1 |
| 4.9 | Beaver Dams: | 3 |
| | Affected length: | 475 |
| 5.2 | Migration Features | |
| | Flood Chutes: | 2 |
| | Neck Cutoffs: | 0 |
| | Channel Avulsions: | 0 |
| | Braiding: | 0 |
| 5.3 | Steep Riffles and Head Cuts | |
| | Steep Riffles: | 0 |
| | Head Cuts: | 0 |
| 5.4 | Animal Crossings: | No |
| 5.5 | Channel Alterations | |
| | Straightening: | Straightening |
| | Dredging: | None |



Phase 2 - FIT - Legacy Data Report

Indian Brook

SGAT Version: 3

Reach: **M16 -B**

| <u>Step</u> | <u>Description</u> | <u>Value</u> | |
|-------------|--------------------------------|--------------|--------------|
| 1.2 | Alluvial Fan: | None | |
| 1.3 | <u>Encroachments - Side</u> | <u>One</u> | <u>Both</u> |
| | Berm Length (ft.): | | |
| | Path Length (ft.): | | |
| | Road Length (ft.): | | |
| | Railroad Lenth (ft.): | | |
| | Development Length: | | |
| 3.1 | <u>Erosion - Bank</u> | <u>Left</u> | <u>Right</u> |
| | Erosion Length (ft.): | 106.0 | 106.0 |
| | Erosion Height (ft.): | 2.0 | 2.0 |
| | Revetment Type: | | |
| | Revetment length: | | |
| 3.2 | <u>Buffer Less Than 25 ft.</u> | | |
| 3.3 | <u>Riparian Corridor</u> | | |
| | Mass Failures: | None | |
| | Average Height (ft.): | | |
| | Gullies: | | |
| | Average Height (ft.): | | |

| <u>Step</u> | <u>Description</u> | <u>Value</u> |
|-------------|-----------------------------|--------------|
| 4.4 | Number of Debris Jams: | 4 |
| 4.7 | Stormwater Inputs | 0 |
| 4.9 | Beaver Dams: | 1 |
| | Affected length: | 600 |
| 5.2 | Migration Features | |
| | Flood Chutes: | 2 |
| | Neck Cutoffs: | 0 |
| | Channel Avulsions: | 0 |
| | Braiding: | 0 |
| 5.3 | Steep Riffles and Head Cuts | |
| | Steep Riffles: | 0 |
| | Head Cuts: | 0 |
| 5.4 | Animal Crossings: | No |
| 5.5 | Channel Alterations | |
| | Straightening: | None |
| | Dredging: | None |



Phase 2 - FIT - Legacy Data Report

Indian Brook

SGAT Version: 3

Reach: **M05 -0**

| <u>Step</u> | <u>Description</u> | <u>Value</u> | |
|-------------|--------------------------------|--------------|--------------|
| 1.2 | Alluvial Fan: | None | |
| 1.3 | <u>Encroachments - Side</u> | <u>One</u> | <u>Both</u> |
| | Berm Length (ft.): | | |
| | Path Length (ft.): | | |
| | Road Length (ft.): | | |
| | Railroad Lenth (ft.): | | |
| | Development Length: | | |
| 3.1 | <u>Erosion - Bank</u> | <u>Left</u> | <u>Right</u> |
| | Erosion Length (ft.): | 400.0 | 400.0 |
| | Erosion Height (ft.): | 1.0 | 1.0 |
| | Revetment Type: | None | None |
| | Revetment length: | 0.0 | 0.0 |
| 3.2 | <u>Buffer Less Than 25 ft.</u> | | |
| 3.3 | <u>Riparian Corridor</u> | | |
| | Mass Failures: | None | |
| | Average Height (ft.): | | |
| | Gullies: | | |
| | Average Height (ft.): | | |

| <u>Step</u> | <u>Description</u> | <u>Value</u> |
|-------------|-----------------------------|--------------|
| 4.4 | Number of Debris Jams: | 1 |
| 4.7 | Stormwater Inputs | 2 |
| 4.9 | Beaver Dams: | 0 |
| | Affected length: | 0 |
| 5.2 | Migration Features | |
| | Flood Chutes: | 0 |
| | Neck Cutoffs: | 0 |
| | Channel Avulsions: | 0 |
| | Braiding: | 0 |
| 5.3 | Steep Riffles and Head Cuts | |
| | Steep Riffles: | 0 |
| | Head Cuts: | 0 |
| 5.4 | Animal Crossings: | No |
| 5.5 | Channel Alterations | |
| | Straightening: | None |
| | Dredging: | None |



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
July, 17 2024

Phase 2 - FIT - Legacy Data Report

Indian Brook

SGAT Version: **3**

Reach: **M06 -0**

| <u>Step</u> | <u>Description</u> | <u>Value</u> | |
|-------------|--------------------------------|--------------|--------------|
| 1.2 | Alluvial Fan: | None | |
| 1.3 | <u>Encroachments - Side</u> | <u>One</u> | <u>Both</u> |
| | Berm Length (ft.): | | |
| | Path Length (ft.): | | |
| | Road Length (ft.): | | |
| | Railroad Lenth (ft.): | | |
| | Development Length: | | |
| 3.1 | <u>Erosion - Bank</u> | <u>Left</u> | <u>Right</u> |
| | Erosion Length (ft.): | 25.0 | 25.0 |
| | Erosion Height (ft.): | 1.5 | 1.5 |
| | Revetment Type: | None | None |
| | Revetment length: | | |
| 3.2 | <u>Buffer Less Than 25 ft.</u> | | |
| 3.3 | <u>Riparian Corridor</u> | | |
| | Mass Failures: | None | |
| | Average Height (ft.): | | |
| | Gullies: | | |
| | Average Height (ft.): | | |

| <u>Step</u> | <u>Description</u> | <u>Value</u> |
|-------------|-----------------------------|--------------|
| 4.4 | Number of Debris Jams: | 6 |
| 4.7 | Stormwater Inputs | 1 |
| 4.9 | Beaver Dams: | 2 |
| | Affected length: | 4500 |
| 5.2 | Migration Features | |
| | Flood Chutes: | 0 |
| | Neck Cutoffs: | 0 |
| | Channel Avulsions: | 0 |
| | Braiding: | 0 |
| 5.3 | Steep Riffles and Head Cuts | |
| | Steep Riffles: | 0 |
| | Head Cuts: | 0 |
| 5.4 | Animal Crossings: | No |
| 5.5 | Channel Alterations | |
| | Straightening: | None |
| | Dredging: | None |



Phase 2 - FIT - Legacy Data Report

Indian Brook

SGAT Version: 3

Reach: **M13 -C**

| <u>Step</u> | <u>Description</u> | <u>Value</u> | |
|-------------|--------------------------------|--------------|--------------|
| 1.2 | Alluvial Fan: | None | |
| 1.3 | <u>Encroachments - Side</u> | <u>One</u> | <u>Both</u> |
| | Berm Length (ft.): | | |
| | Path Length (ft.): | | |
| | Road Length (ft.): | | |
| | Railroad Lenth (ft.): | | |
| | Development Length: | | |
| 3.1 | <u>Erosion - Bank</u> | <u>Left</u> | <u>Right</u> |
| | Erosion Length (ft.): | 0.0 | 0.0 |
| | Erosion Height (ft.): | 0.0 | 0.0 |
| | Revetment Type: | None | None |
| | Revetment length: | 0.0 | 0.0 |
| 3.2 | <u>Buffer Less Than 25 ft.</u> | | |
| 3.3 | <u>Riparian Corridor</u> | | |
| | Mass Failures: | None | |
| | Average Height (ft.): | | |
| | Gullies: | | |
| | Average Height (ft.): | | |

| <u>Step</u> | <u>Description</u> | <u>Value</u> |
|-------------|-----------------------------|--------------|
| 4.4 | Number of Debris Jams: | 0 |
| 4.7 | Stormwater Inputs | 0 |
| 4.9 | Beaver Dams: | 2 |
| | Affected length: | 1200 |
| 5.2 | Migration Features | |
| | Flood Chutes: | |
| | Neck Cutoffs: | |
| | Channel Avulsions: | |
| | Braiding: | |
| 5.3 | Steep Riffles and Head Cuts | |
| | Steep Riffles: | |
| | Head Cuts: | |
| 5.4 | Animal Crossings: | |
| 5.5 | Channel Alterations | |
| | Straightening: | |
| | Dredging: | |



Phase 2 - FIT - Legacy Data Report

Indian Brook

SGAT Version: 3

Reach: **M13 -D**

| <u>Step</u> | <u>Description</u> | <u>Value</u> | |
|-------------|--------------------------------|--------------|--------------|
| 1.2 | Alluvial Fan: | None | |
| 1.3 | <u>Encroachments - Side</u> | <u>One</u> | <u>Both</u> |
| | Berm Length (ft.): | | |
| | Path Length (ft.): | | |
| | Road Length (ft.): | | |
| | Railroad Lenth (ft.): | | |
| | Development Length: | | |
| 3.1 | <u>Erosion - Bank</u> | <u>Left</u> | <u>Right</u> |
| | Erosion Length (ft.): | 350.0 | 350.0 |
| | Erosion Height (ft.): | 0.5 | 0.5 |
| | Revetment Type: | | |
| | Revetment length: | | |
| 3.2 | <u>Buffer Less Than 25 ft.</u> | | |
| 3.3 | <u>Riparian Corridor</u> | | |
| | Mass Failures: | One | |
| | Average Height (ft.): | 5.0 | |
| | Gullies: | | |
| | Average Height (ft.): | | |

| <u>Step</u> | <u>Description</u> | <u>Value</u> |
|-------------|-----------------------------|----------------------|
| 4.4 | Number of Debris Jams: | 3 |
| 4.7 | Stormwater Inputs | 1 |
| 4.9 | Beaver Dams: | 0 |
| | Affected length: | |
| 5.2 | Migration Features | |
| | Flood Chutes: | 0 |
| | Neck Cutoffs: | 0 |
| | Channel Avulsions: | 0 |
| | Braiding: | 0 |
| 5.3 | Steep Riffles and Head Cuts | |
| | Steep Riffles: | 0 |
| | Head Cuts: | 0 |
| 5.4 | Animal Crossings: | No |
| 5.5 | Channel Alterations | |
| | Straightening: | Straightening |
| | Dredging: | None |