



FIT Affected Segments Report

Deerfield - North Branch

Reach - Segment	Affected by FIT (Feature Indexing Tool)
T2.01 - 0	No
T2.02 - 0	No
T2.03 - A	No
T2.03 - B	No
T2.04 - A	No
T2.04 - B	No
T2.05 - 0	No
T2.06 - 0	No
T2.07 - 0	No
T2.08 - A	No
T2.08 - B	No
T2.09 - 0	No
T2.10 - 0	No
T2.11 - A	No
T2.11 - B	No
T2.13 - A	No
T2.13 - B	No
T2.13 - C	No
T2.14 - A	No
T2.14 - B	No
T2.14 - C	No
T2.14 - D	No