

M E M O R A N D U M

TO: Larabee's File #411  
THRU: Chuck Schwert, <sup>S</sup>PLUST Coordinator  
FROM: Bob Haslam, Environmental Technician <sup>BH</sup>  
DATE: January 23, 1990  
SUBJECT: Trip Report

On December 5, 1989 I went to West Danville to check to Larabee's Lumber site. I took HNu readings in the basement. They were ND. They had sealed the cracks in the basement where we previously detected vapors. They had installed the p-trap we recommended and replaced and sealed the floor drain.

I returned to the site on January 8, 1990. Basement PID readings were again ND. I took water samples from their spring, through the bathroom tap. The results were ND. I checked the monitoring well with a bailer. There was no free product, no sheens, and some odor.

It appears <sup>that</sup> ~~as~~ the p-trap has effectively blocked vapors from entering the basement. The site is currently listed as high. I feel we could drop this priority to medium as the vapor problem seems to be solved.

BH/awl282