



State of Vermont

Department of Fish and Wildlife
Department of Forests, Parks and Recreation
Department of Environmental Conservation
State Geologist
Natural Resources Conservation Council

AGENCY OF NATURAL RESOURCES
Department of Environmental Conservation

Hazardous Materials Management Division
103 South Main Street / West Building
Waterbury, VT 05671-0404
802-244-8702

August 7, 1992

Michael Morissette
Vermont Agency of Transportation
133 State Street
Montpelier, VT 05633

RE: Lyndon Maintenance Garage (Site #91-1087)

Dear Mr. Morissette:

Enclosed are the results of the monitoring well samples from the Lyndon Maintenance Garage. The samples were obtained by the Technical Services Section (TSS) on June 4, 1992.

Samples were analyzed according to EPA Methods 8240 and 418.1. No contamination was detected in any of the samples.

Samples were obtained from the three onsite monitoring wells. No sample could be obtained from the culvert well, in the former tank area, because of a heavy sewer grate on that well.

Although the results of the monitoring well samples were non-detect, the SMS does not feel that enough information has been presented in order to make a decision as to the future plans for the site. In order to make this decision, the SMS has determined that a sample should be obtained from the culvert well. We will schedule this with TSS, and will appreciate AOT's assistance with removing the cover on the day of sampling. Also, we would like to have the onsite supply well sampled at that time.

Please feel free to call with any questions.

Sincerely,

Cindy Woods, Environmental Engineer
Sites Management Section

CW/longterm/Lyndon.let