



# State of Vermont

Department of Fish and Wildlife  
Department of Forests, Parks and Recreation  
Department of Environmental Conservation  
State Geologist

RELAY SERVICE FOR THE HEARING IMPAIRED  
1-800-253-0191 TDD>Voice  
1-800-253-0195 Voice>TDD

AGENCY OF NATURAL RESOURCES  
Department of Environmental Conservation

Hazardous Materials Management Division  
103 South Main Street/West Bldg.  
Waterbury, VT 05671-0404  
(802)241-3888  
FAX (802)241-3296

October 16, 1995

Mr. David Dill  
Town of Lyndon  
Office of Municipal Assistant  
P.O. Box 167  
20 Park Ave.  
Lyndonville, VT 05851

RE: Lyndon Town Garage (Site #91-1178)

Dear Mr. Dill:

The Sites Management Section (SMS) has received the August 23, 1995 letter from Griffin International, Inc. regarding spreading of the stockpiled soil at the above referenced site. Based on the information in the letter, the SMS has determined that the Town of Lyndon has met the requirements outlined in the initial January 3, 1992 letter. These requirements included that an investigation be performed to determine the degree and extent of contamination present at the site resulting from the former underground storage tank (UST).

This determination was made based on the following information:

1. The likely source of contamination was the former underground storage tank system which was removed from the ground on December 20, 1991.
2. Groundwater no longer contains petroleum contaminants in excess of Vermont Groundwater Enforcement Standards, as indicated by analytical results of the onsite monitoring wells.
3. The approximately 175 cubic yards of stockpiled soil contained non-detect levels of volatile organic compounds when screened with a field instrument. Therefore, the soil has been spread onsite.
4. Little to no risk is posed to sensitive receptors, such as the Passumpsic River, from any residual contamination which may remain in the subsurface.

Based on the results of the investigation, the site has been assigned a Site Management Activity Completed (SMAC) designation. Sites which the Hazardous Materials Management Division have determined require no further management are given a SMAC designation. The designation does not release the Town of Lyndon from any past or future liability which may arise from the petroleum contamination which originated from the former UST at the Lyndon Town Garage. The SMAC designation does mean that the SMS isn't requiring any additional work be performed at this site in response to the initial contamination.

Please feel free to contact either me or Richard Spiese with any further questions or comments you may have.

Sincerely,



Chuck Schwer, Acting Chief  
Sites Management Section

c: Erik Sandblom, Griffin International, Inc.  
DEC Regional Office

lp/smac9111