



State of Vermont

Department of Fish and Wildlife
Department of Forests, Parks and Recreation
Department of Environmental Conservation
State Geologist
Natural Resources Conservation Council

AGENCY OF NATURAL RESOURCES
Department of Environmental Conservation

Hazardous Materials Management Division
103 South Main Street / West Building
Waterbury, VT 05671-0404
(802) 244-8702

December 28, 1992

Michael Morissette
VT Agency of Transportation
133 State Street
Montpelier, VT 05633

RE: Petroleum contamination at the Bennington Monument (Site #92-1211)

Dear Mr. Morissette:

The Sites Management Section (SMS) has received the letters dated December 11 and 17, 1992, regarding the above referenced site. We have noted the observations of the past three site visitations, and are pleased to see the soils measure non detect as of the last monitoring. We concur with your recommendation to retest the soil in April. If the soils again are non detect, you may spread the soil at the present location of the Airport landfarm site. Please inform us when the soils have been spread so that we may begin the site closure process.

We appreciate your cooperation at this site, and feel free to contact us with any questions.

Sincerely,

Charles B. Schwer, Supervisor
Sites Management Section

cc: John Olstrom, Buildings Division

mg/1211