

77-0008:

Tansitor Electronics:

The site is a capacitor manufacturing facility. Waste solvents (primarily 1,1,1-TCA) were disposed of on site in a waste disposal area and by a methanol burning area probably from the 1950's through the early 1970s. Groundwater in the unconsolidated aquifer at the site is contaminated with 1,1,1-TCA. There is likely DNAPL in the upper portion of the subsurface. No contamination is migrating off site.

The site was a Superfund site and was investigated under Superfund Authority. The Site received a Technical Impracticability Waiver of MCLs because it is virtually impossible to actively remediate groundwater in the tills that are present on site. The site remedy is long term monitoring with contingencies to renew investigations and possibly install remedial systems in case it appears that contamination is migrating off site. This is unlikely. The Site was de-listed from the NPL and monitoring is being conducted under State oversight.