



State of Vermont

Department of Fish and Wildlife
Department of Forests, Parks and Recreation
Department of Environmental Conservation
State Geologist
Natural Resources Conservation Council

AGENCY OF NATURAL RESOURCES
Department of Environmental Conservation
Hazardous Materials Management Division
103 South Main Street / West Building
Waterbury, VT 05671-0404
802-244-8702

May 8, 1992

Michael B. Morrisette
State of Vermont / Agency of Transportation
133 State Street, Administration Building
Montpelier, Vermont 05633

RE: Petroleum Contamination at WYSB, Site #91-1176

Dear Mr. Morrisette:

The Sites Management Section (SMS) has completed its review of the WYSB site. Due to the low risk posed by this release and the apparent limited extent of contamination at the site, the SMS will not require that any further subsurface investigation be performed.

During the tank removal, 8-12 cubic yards of petroleum contaminated soil was excavated and stockpiled on the site. This soil should be either be treated on site or disposed of at an approved facility (see enclosed "Interim Soil Guideline Levels and Treatment Options" for additional information on treatment and disposal options).

Once the excavated soil has been dealt with in a satisfactory manner, the site will be eligible for closure. If you have any questions, please call.

Sincerely,

Charles B. Schwer, Supervisor
Sites Management Section

CBS:BW/.../sites/WYSB.let