



## State of Vermont

---

AGENCY OF NATURAL RESOURCES  
Department of Environmental Conservation  
Waste Management Division  
103 South Main Street / West Building  
Waterbury, Vermont 05671-0404  
(802) 241-3888  
FAX (802) 241-3296

Department of Fish and Wildlife  
Department of Forests, Parks and Recreation  
Department of Environmental Conservation  
State Geologist  
RELAY SERVICE FOR THE HEARING IMPAIRED  
1-800-253-0191   TDD>Voice  
1-800-253-0195   Voice>TDD

August 31, 2000

Brenda Wright  
Wright's Construction  
RR#1, Box 780  
Franklin, VT 05457

Re: Site Management Activity Completed (SMAC), Wright's Construction, Franklin, VT (Site #92-1199)

Dear Brenda Wright:

The Sites Management Section (SMS) has reviewed the August 2, 1996 letter from Inchcape Testing Services referencing a report for soil screening for petroleum contamination in the vicinity of the removed UST's at Wright's Construction property. The SMS has also reviewed information contained in the site file.

With this information, the SMS can now make the following conclusions:


- On February 19, 1992 one 1,000 gallon diesel fuel underground storage tank (UST) was removed from the Wright's Construction property in Franklin, VT.
- Twelve cubic yards of petroleum contaminated soils were removed from the ground and stockpiled onsite. Additional subsurface work was performed around the perimeter of the pulled UST on May 27, 1993. Low levels of petroleum contamination were measured during this work but at concentrations below the SMS soil guideline levels. Groundwater was found at approximately four feet below ground surface. No petroleum sheens were observed and therefore no groundwater samples were collected for laboratory analysis.
- The contaminated soils were tested after being stockpiled for eight months - all test results were below the SMS soil guideline requirements. The soils were excavated back into the site at Wright's Constructions, Franklin, VT as outlined in the June 9, 1993 report.
- No unacceptable risk to human health and the environment is present due to any residual contamination remaining in the ground from the former UST at your property.

Page 2  
August 31, 2000

Based on the above, the SMS is assigning this site a Site Management Activity Completed (SMAC) designation. This SMAC designation does not release you of any past or future liability associated with the petroleum contamination onsite. It does, however, mean that the SMS is not requesting any additional work in response to the UST removal in 1992.

Please feel free to call with any questions.

Sincerely,



George Desch, Chief, P.E.  
Sites Management Section

cc: Franklin Selectboard  
Franklin Health Officer  
DEC Regional Office

Wrightconstr1199smac.wpd