



FIT Affected Segments Report

Mill River

Reach - Segment	Affected by FIT (Feature Indexing Tool)
M03 - 0	Yes
M04 - A	Yes
M04 - B	Yes
M05 - 0	Yes
M07 - A	Yes
M07 - B	Yes
M08 - 0	Yes
M7S2.01 - A	Yes
M7S2.01 - B	Yes
M2T2.02 - A	Yes
M2T2.02 - B	Yes
M2T2.03 - A	Yes
M2T2.03 - B	Yes
M2T2.05 - 0	No
M2T2.06 - A	Yes
M2T2.06 - B	Yes
M2T2.06 - C	Yes
M2T2.06 - D	Yes
M2T2.2S2.01 - A	Yes
M2T2.2S2.01 - B	Yes
M2T2.2S1.03 - A	Yes
M2T2.2S1.03 - B	Yes
M2T2.2S1.04 - 0	Yes
M2T2.2S1.3S3.01 - A	Yes
M2T2.2S1.3S3.01 - B	Yes
M01 - A	No
M01 - B	Yes
M01 - C	Yes
M01 - D	Yes
M01 - E	Yes
M2T2.2S1.2S2.01 - A	Yes
M2T2.2S1.2S2.01 - B	Yes



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov

November, 22 2024

M02 - A	Yes
M02 - B	Yes
M2T2.01 - 0	Yes
M2T2.1S1.1S1.01 - A	Yes
M2T2.1S1.1S1.01 - B	Yes
M2T2.04 - A	No
M2T2.04 - B	Yes
M2T2.04 - C	No
M2T2.2S1.2S2.02 - A	Yes
M2T2.2S1.2S2.02 - B	Yes
M06 - A	Yes
M06 - B	Yes
M7S1.01 - A	No
M7S1.01 - B	No