



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
July, 17 2024

Phase 1 - FIT - Legacy Data Report

Neshobe

SGAT Version: **4.56**

Reach: **M01**

<u>Step</u>	<u>Description</u>	<u>Value</u>		<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None		5.5	Dredging History:	None	
3.2	Grade Control:	Ledge		6.1	Berms & Roads Data:		
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>			<u>One Side</u>	<u>Both Sides</u>
		0	0		Berms & Roads:	581.8400	0.0000
5.1	Flow Regulation - Type:	Small Withdrawal			Berm:	0.0000	0.0000
	Use:	Other			Path:	581.840	0.000
5.2	# of Bridges or Culverts:	0			Road:	0.0000	0.00000
	Total Length:	0.000			Railroad:	0.0000	0.00
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	6.2	Corridor Development Data:		
		15.4300	0.00000		Length:	1845.7800	0.0000
	Data Armoring:	0		6.4	Miander Migration:	Multiple	
5.4	Straightening Length:	2410.93018		7.2	Bank Erosion:	<u>Old</u>	<u>New</u>
	Straightening Data:				Bank Height:	None	1590.150024
						4	4.457



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
July, 17 2024

Reach: **M02**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	Multiple	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		989	859
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	4	
	Total Length:	1281.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		1943.94	1986.16
		995	003
	Data Armoring:		
5.4	Straightening Length:	2450.88013	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	3302.8398	1095.3400
	Berm:	312.5700	0.0000
	Path:	0.000	0.000
	Road:	2990.2700	1095.33997
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	3259.9302	639.3000
6.4	Miander Migration:	Migration	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	2236.620117
			2
	Bank Height:	N.D.	5.642

Reach: **M03**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		408	0
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	1	
	Total Length:	412.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		178.649	199.429
		99	99
	Data Armoring:		
5.4	Straightening Length:	3369.62012	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	2146.9299	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	2146.9299	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	1283.5200	0.0000
6.4	Miander Migration:	Multiple	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	1376.609985
			4
	Bank Height:	N.D.	3.937



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
July, 17 2024

Reach: **M04**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	Ledge	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		2323	389
5.1	Flow Regulation - Type:	Small Withdrawal	
	Use:	Other	
5.2	# of Bridges or Culverts:	4	
	Total Length:	571.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		1829.64	0.00000
		001	
	Data Armoring:		
5.4	Straightening Length:	2911.41016	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	2673.2600	142.4900
	Berm:	0.0000	0.0000
	Path:	1699.210	0.000
	Road:	974.0500	142.49001
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	0.0000
6.4	Miander Migration:	Migration	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	587.6900024
	Bank Height:	N.D.	4.649

Reach: **M05**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	Ledge	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		2360	2032
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	1	
	Total Length:	540.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		122.320	677.950
		00	01
	Data Armoring:		
5.4	Straightening Length:	526.53003	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	687.9600	0.0000
6.4	Miander Migration:	Multiple	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	935.6199951
	Bank Height:	N.D.	3.986



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
July, 17 2024

Reach: **M06**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		1582	262
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	1	
	Total Length:	277.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		705.479	152.660
		98	00
	Data Armoring:		
5.4	Straightening Length:	2705.68994	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	3184.2600	0.0000
	Berm:	2388.1101	0.0000
	Path:	0.000	0.000
	Road:	796.1500	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	1570.8700	858.4600
6.4	Miander Migration:	Flood Chute	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	349.1600037
	Bank Height:	N.D.	5.001

Reach: **M07**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	Ledge	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		0	0
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	0	
	Total Length:	0.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	1757.87000	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	782.3300	0.0000
	Berm:	782.3300	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	0.0000
6.4	Miander Migration:	Flood Chute	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	1420.030029
	Bank Height:	N.D.	4.133



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
July, 17 2024

Reach: **M08**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	Multiple	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		720	610
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	0	
	Total Length:	0.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	234.42999
	Data Armoring:		
5.4	Straightening Length:	1936.69995	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	483.8900	0.0000
	Berm:	307.7100	0.0000
	Path:	0.000	0.000
	Road:	176.1800	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	0.0000
6.4	Miander Migration:	Flood Chute	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	324.7300110
	Bank Height:	N.D.	2.175

Reach: **M09**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	Ledge	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		0	0
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	1	
	Total Length:	302.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		66.67000	222.42999
	Data Armoring:	0	99
5.4	Straightening Length:	2834.71997	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	2289.1001	0.0000
	Berm:	281.3400	0.0000
	Path:	0.000	0.000
	Road:	2007.7600	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	0.0000
6.4	Miander Migration:	Flood Chute	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	345.7500000
	Bank Height:	N.D.	7.684



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
July, 17 2024

Reach: **M11**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	Ledge	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		0	219
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	4	
	Total Length:	390.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	680.79004
	Data Armoring:		
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	5683.1602	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	5683.1602	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	0.0000
6.4	Miander Migration:	Flood Chute	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	396.0800171
	Bank Height:	N.D.	5.516

Reach: **M12**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	Dam	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		0	0
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	0	
	Total Length:	0.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	No Data	
6.1	Berms & Roads Data:	Not Evaluated	
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:	Not Evaluated	
	Length:	0.0000	0.0000
6.4	Miander Migration:		
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
July, 17 2024

Reach: **M13**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		0	282
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	2	
	Total Length:	90.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		20.7800	174.4900
		0	01
	Data Armoring:		
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	226.4000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	226.4000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	391.0100	0.0000
6.4	Miander Migration:	Flood Chute	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	363.0700073
	Bank Height:	N.D.	5.185

Reach: **M14**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		306	355
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	5	
	Total Length:	380.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		220.7100	324.2399
		01	99
	Data Armoring:		
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	901.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	901.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	276.4500	147.1700
6.4	Miander Migration:	Flood Chute	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	445.4700012
	Bank Height:	N.D.	2.605



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
July, 17 2024

Reach: **M15**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	Multiple	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		103	98
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	2	
	Total Length:	120.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	636.3500	0.0000
	Berm:	0.0000	0.0000
	Path:	636.350	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	0.0000
6.4	Miander Migration:	Flood Chute	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	129.1600037
	Bank Height:	N.D.	3.787

Reach: **T1.01**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	0	
	Total Length:	0.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	376.9600	0.0000
	Berm:		
	Path:		
	Road:	376.9600	
	Railroad:		
6.2	Corridor Development Data:		
	Length:	106.8000	0.0000
6.4	Miander Migration:	None	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
July, 17 2024

Reach: **T1.02**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	0	
	Total Length:	0.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	1263.8301	204.5300
	Berm:		
	Path:		
	Road:	1263.8301	204.53000
	Railroad:		
6.2	Corridor Development Data:		
	Length:	405.6800	0.0000
6.4	Miander Migration:	None	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000

Reach: **T1.03**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	1	
	Total Length:	150.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	127.9800	1005.1900
	Berm:		
	Path:		
	Road:	127.9800	1005.19000
	Railroad:		
6.2	Corridor Development Data:		
	Length:	0.0000	257.6800
6.4	Miander Migration:	None	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
July, 17 2024

Reach: **T1.S1.01**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		135	
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	1	
	Total Length:	120.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	Dredging	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	1694.3900	0.0000
	Berm:		
	Path:		
	Road:	1694.3900	
	Railroad:		
6.2	Corridor Development Data:		
	Length:	373.6400	0.0000
6.4	Miander Migration:	None	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000

Reach: **T1.S1.02**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		85	89
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	1	
	Total Length:	200.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	549.6400	0.0000
	Berm:		
	Path:		
	Road:	549.6400	
	Railroad:		
6.2	Corridor Development Data:		
	Length:	0.0000	0.0000
6.4	Miander Migration:	None	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
July, 17 2024

Reach: **T1.04**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		94	
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	1	
	Total Length:	200.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	Dredging	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	4494.9199	0.0000
	Berm:		
	Path:		
	Road:	4494.9199	
	Railroad:		
6.2	Corridor Development Data:		
	Length:	581.7100	0.0000
6.4	Miander Migration:	None	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000

Reach: **T1.05**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	0	
	Total Length:	0.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:		
	Path:		
	Road:		
	Railroad:		
6.2	Corridor Development Data:		
	Length:	181.8000	0.0000
6.4	Miander Migration:	None	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
July, 17 2024

Reach: **T1.06**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	2	
	Total Length:	70.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	86.7100
	Berm:		
	Path:		
	Road:		86.71000
	Railroad:		
6.2	Corridor Development Data:		
	Length:	0.0000	0.0000
6.4	Miander Migration:	None	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000

Reach: **T1.07**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:		
3.2	Grade Control:		
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
5.1	Flow Regulation - Type:		
	Use:		
5.2	# of Bridges or Culverts:		
	Total Length:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
	Data Armoring:	None	
5.4	Straightening Length:		
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:		
	Berm:		
	Path:		
	Road:		
	Railroad:		
6.2	Corridor Development Data:		
	Length:		
6.4	Miander Migration:	None	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	
	Bank Height:	N.E.	