

## Stream Geomorphic Assessment

## Agency of Natural Resouces



July, 31 2025

## FIT Affected Segments Report

## **Dishmill Brook**

Reach - Segment	Affected by FIT (Feature Indexing Tool)
M105 - A	No
M105 - B	No
M101 - A	No
M101 - B	No
M102 - A	No
M102 - B	No
M103 - 0	No
M104 - 0	No
T1.01 - 0	No