



**FIT Affected Segments Report**

**Walloomsac Woodford**

| <b>Reach - Segment</b> | <b>Affected by FIT (Feature Indexing Tool)</b> |
|------------------------|--|
| M6T3.05S1.03 - 0       | No   |
| M6T3.05S1.04 - A       | No   |
| M6T3.05S1.04 - B       | No   |
| M6T3.05S1.04 - C       | No   |
| M6T3.05S1.04 - D       | No   |
| M6T3.05S1.06 - 0       | No   |
| M6T3.06 - 0            | No   |
| M6T3.05S1.01 - A       | No   |
| M6T3.05S1.01 - B       | No   |
| M6T3.05S1.01 - C       | No   |
| M6T3.05S1.02 - A       | No   |
| M6T3.05S1.02 - B       | No   |
| M6T3.05 - A            | No   |
| M6T3.05 - B            | No   |
| M6T3.05 - C            | No   |