



FIT Affected Segments Report

Muddy Brook

Reach - Segment	Affected by FIT (Feature Indexing Tool)
T3.02 - A	No
T3.02 - B	No
M05 - 0	No
M12 - 0	No
M20 - 0	No
M07 - 0	No
M14 - 0	No
M01 - 0	No
T2.01 - A	No
T2.01 - B	No
M04 - 0	No
M11 - A	No
M11 - B	No
M19 - 0	No
M06 - 0	No
M08 - 0	No
M15 - 0	No
M13 - 0	No
M21 - 0	No
M02 - 0	No
M03 - 0	No
M09 - 0	No
M10 - 0	No
T3.01 - A	No
T3.01 - B	No
T3.01 - C	No
T3.01 - D	No
T3.01 - E	No
T3.01 - F	No
M18 - 0	No