



FIT Affected Segments Report

Stevens Branch

Reach - Segment	Affected by FIT (Feature Indexing Tool)
M1.12 - A	No
M1.12 - B	No
M1.13 - 0	No
M1.14 - 0	No
M1.15 - A	No
M1.15 - B	No
M1.16 - A	No
M1.16 - B	No
M1.16 - C	No
M1.17 - 0	No
T7.01 - A	No
T7.01 - B	No
T7.01 - C	No
T3.02S4.01 - A	No
T3.02S4.01 - B	No
T3.02S4.01S1.01 - A	No
T3.02S4.01S1.01 - B	No
T3.02S4.01S1.01 - C	No
T3.02S4.01S1.01 - D	No
T3.02S4.02 - A	No
T3.02S4.02 - B	No
T3.01 - A	No
T3.01 - B	No
T3.02 - A	No
T3.02 - B	No
T3.03 - A	No
T3.03 - B	No
T3.04 - A	No
T3.04 - B	No
T3.04 - C	No
T3.04 - D	No
T3.05 - A	No



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov

June, 17 2026

T3.05 - B	No
M1.18 - A	No
M1.18 - B	No
M1.18 - C	No
M1.18 - D	No
M1.19 - A	No
M1.19 - B	No
M1.10 - A	No
M1.10 - B	No
M1.10 - C	No
M1.10 - D	No
M1.11 - A	No
M1.11 - B	No
M1.11 - C	No
M1.01 - A	Yes
M1.01 - B	Yes