



FIT Affected Segments Report

Dog River

Reach - Segment	Affected by FIT (Feature Indexing Tool)
T2.01 - 0	No
M10 - A	No
M10 - B	No
M04 - 0	No
M13 - 0	No
M15 - 0	No
M03 - 0	No
M05 - 0	No
M06 - A	No
M06 - B	No
M11 - A	No
M11 - B	No
M11 - C	No
M11 - D	No
M08 - A	No
M08 - B	No
M09 - A	No
M09 - B	No
T1.01 - A	No
T1.01 - B	No
T1.01 - C	No
M14 - 0	No
M12 - A	No
M12 - B	No
M02 - 0	No
M01 - A	No
M01 - B	No
M01 - C	No
M07 - A	No
M07 - B	No
M07 - C	No
M16 - 0	No



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov

June, 25 2024

T3.01 - 0	No
M17 - A	No
M17 - B	No
M17 - C	No
M18 - A	No
M18 - B	No
T6.01 - A	No
T6.01 - B	No
T6.01 - C	No
M19 - A	No
M19 - B	No
M19 - C	No
M20 - A	No
M20 - B	No
M20 - C	No
M21 - A	No
M21 - B	No
M21 - C	No
M21 - D	No
T4.01 - 0	No
T5.01 - A	No
T5.01 - B	No