



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
April, 08 2026

Phase 1 - FIT - Legacy Data Report

Black

SGAT Version: **4.56**

Reach: **M01**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		0	0
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	1	
	Total Length:	1.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	880.1700	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	880.1700	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	0.0000
6.4	Miander Migration:	<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000

Reach: **M02**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
5.1	Flow Regulation - Type:		
	Use:		
5.2	# of Bridges or Culverts:		
	Total Length:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
	Data Armoring:	Not Evaluated	
5.4	Straightening Length:		
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	None	
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:		
	Berm:		
	Path:		
	Road:		
	Railroad:		
6.2	Corridor Development Data:	None	
	Length:		
6.4	Miander Migration:	<u>Old</u>	<u>New</u>
7.2	Bank Erosion:		
	Bank Height:		



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
April, 08 2026

Reach: **M03**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		0	515
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	1	
	Total Length:	1.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		364.060	0.00000
		00	
	Data Armoring:		
5.4	Straightening Length:	4246.68994	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	1802.0100	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	1802.0100	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	565.7500	0.0000
6.4	Miander Migration:	Flood Chute	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	1945.200073
			2
	Bank Height:	N.D.	9.861

Reach: **M04**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	Waterfall	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		0	671
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	3	
	Total Length:	32.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	1332.82
			007
	Data Armoring:		
5.4	Straightening Length:	2133.26001	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	2280.2300	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	2280.2300	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	741.5500	0.0000
6.4	Miander Migration:	Flood Chute	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	351.2399902
	Bank Height:	N.D.	7.000



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
April, 08 2026

Reach: **M05**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		404	1318
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	0	
	Total Length:	0.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	2226.64990	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	0.0000
6.4	Miander Migration:	Flood Chute	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	868.7199707
	Bank Height:	N.D.	8.958

Reach: **T1.01**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		1282	767
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	2	
	Total Length:	241.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	159.52000	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	Not Evaluated	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	163.6300	0.0000
6.4	Miander Migration:	Braiding	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
April, 08 2026

Reach: **T1.02**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		3127	2141
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	2	
	Total Length:	187.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	3778.62012	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	Not Evaluated	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	280.5600	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	280.5600	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	33.8300
6.4	Miander Migration:	Migration	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000

Reach: **T1.03**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		256	753
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	0	
	Total Length:	0.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	1292.35999	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	Not Evaluated	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	1335.9399	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	1335.9399	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	162.2500	65.0500
6.4	Miander Migration:	None	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
April, 08 2026

Reach: **T1.06**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		144	89
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	2	
	Total Length:	2.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	341.77002	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	Not Evaluated	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	795.6700	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	795.6700	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	1672.2600	183.7200
6.4	Miander Migration:	None	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000

Reach: **T1.07**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	Multiple	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		258	119
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	2	
	Total Length:	199.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	Not Evaluated	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	379.3300	0.0000
6.4	Miander Migration:	None	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
April, 08 2026

Reach: **M06**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	Waterfall	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		74	186
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	1	
	Total Length:	1.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		108.350	45.8800
		00	0
	Data Armoring:		
5.4	Straightening Length:	64.07000	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	0.0000
6.4	Miander Migration:		
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000

Reach: **M07**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		796	0
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	0	
	Total Length:	0.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		387.590	0.00000
		03	
	Data Armoring:		
5.4	Straightening Length:	2145.92993	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	0.0000
6.4	Miander Migration:	Flood Chute	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	487.4900208
	Bank Height:	N.D.	7.000



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
April, 08 2026

Reach: **T2.01**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		5729	5074
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	3	
	Total Length:	265.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		81.1800	43.8000
		0	0
	Data Armoring:		
5.4	Straightening Length:	1294.96997	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	249.0300	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	249.0300	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	361.3200	23.0200
6.4	Miander Migration:	Multiple	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	1530.969970
			7
	Bank Height:	N.D.	3.825

Reach: **T2.02**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		289	673
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	2	
	Total Length:	388.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	30.8400
			0
	Data Armoring:		
5.4	Straightening Length:	224.53999	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	371.6800	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	371.6800	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	50.1300
6.4	Miander Migration:	Multiple	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	140.6600037
	Bank Height:	N.D.	3.519



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
April, 08 2026

Reach: **T2.03**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		0	0
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	2	
	Total Length:	48.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	Not Evaluated	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	932.0100	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	932.0100	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	0.0000
6.4	Miander Migration:	None	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000

Reach: **T2.04**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:		
3.2	Grade Control:		
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
5.1	Flow Regulation - Type:		
	Use:		
5.2	# of Bridges or Culverts:		
	Total Length:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
	Data Armoring:	None	
5.4	Straightening Length:		
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	Not Evaluated	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:		
	Berm:		
	Path:		
	Road:		
	Railroad:		
6.2	Corridor Development Data:		
	Length:		
6.4	Miander Migration:	None	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:		
	Bank Height:		



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
April, 08 2026

Reach: **T2.05**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:		
3.2	Grade Control:		
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
5.1	Flow Regulation - Type:		
	Use:		
5.2	# of Bridges or Culverts:		
	Total Length:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
	Data Armoring:	None	
5.4	Straightening Length:		
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	Not Evaluated	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:		
	Berm:		
	Path:		
	Road:		
	Railroad:		
6.2	Corridor Development Data:		
	Length:		
6.4	Miander Migration:	None	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:		
	Bank Height:		

Reach: **M08**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	Ledge	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		1621	868
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	2	
	Total Length:	2.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	621.03003
	Data Armoring:		
5.4	Straightening Length:	4813.70996	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	240.2200	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	240.2200	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	180.1400	0.0000
6.4	Miander Migration:	Multiple	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	1818.8599854
	Bank Height:	N.D.	4.440



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
April, 08 2026

Reach: **M09**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		0	0
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	0	
	Total Length:	0.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	416.7700
6.4	Miander Migration:	<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000

Reach: **M10**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
5.1	Flow Regulation - Type:		
	Use:		
5.2	# of Bridges or Culverts:		
	Total Length:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
	Data Armoring:	None	
5.4	Straightening Length:		
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:		
	Berm:		
	Path:		
	Road:		
	Railroad:		
6.2	Corridor Development Data:	None	
	Length:		
6.4	Miander Migration:	<u>Old</u>	<u>New</u>
7.2	Bank Erosion:		
	Bank Height:		



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
April, 08 2026

Reach: **M11**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		382	883
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	0	
	Total Length:	0.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	0.0000
6.4	Miander Migration:	<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000

Reach: **M12**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		962	1053
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	1	
	Total Length:	230.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	158.11000
	Data Armoring:		
5.4	Straightening Length:	1527.41003	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	3763.6499	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	3763.6499	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	131.6300	0.0000
6.4	Miander Migration:	Flood Chute	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	530.2299805
	Bank Height:	N.D.	6.012



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
April, 08 2026

Reach: **M13**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		0	0
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	3	
	Total Length:	152.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	449.0300	0.0000
6.4	Miander Migration:	<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000

Reach: **M14**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		0	0
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	0	
	Total Length:	0.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	906.46997	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	0.0000
6.4	Miander Migration:	<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	381.5500183
	Bank Height:	N.D.	7.197



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
April, 08 2026

Reach: **M15**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		219	0
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	0	
	Total Length:	0.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	2392.15991	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	1197.8900	0.0000
	Berm:	1197.8900	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	26.6700	0.0000
6.4	Miander Migration:	<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	1236.760009
			8
	Bank Height:	N.D.	7.104

Reach: **M16**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		344	422
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	4	
	Total Length:	551.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		34.5100	0.00000
		0	
	Data Armoring:		
5.4	Straightening Length:	4742.85010	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	0.0000
6.4	Miander Migration:	Neck Cutoff	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	2772.689941
			4
	Bank Height:	N.D.	7.323



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
April, 08 2026

Reach: **M17**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		1278	0
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	1	
	Total Length:	1.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	24.97000	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	54.9800
6.4	Miander Migration:	Multiple	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	2296.040039
			1
	Bank Height:	N.D.	5.912

Reach: **M18**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		0	0
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	0	
	Total Length:	0.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:	None	
	Length:	0.0000	0.0000
6.4	Miander Migration:	Neck Cutoff	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	4133.850097
			7
	Bank Height:	N.D.	7.203



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
April, 08 2026

Reach: **M19**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		0	0
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	0	
	Total Length:	0.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	None	
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:	None	
	Length:	0.0000	0.0000
6.4	Miander Migration:	Flood Chute	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	896.9100342
	Bank Height:	N.D.	7.263

Reach: **M20**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		1032	1016
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	0	
	Total Length:	0.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	None	
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:	None	
	Length:	0.0000	0.0000
6.4	Miander Migration:	Multiple	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	3178.840087
			9
	Bank Height:	N.D.	7.000



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
April, 08 2026

Reach: **T5.01**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		0	610
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	2	
	Total Length:	571.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	267.09000	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	Not Evaluated	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	97.4700
6.4	Miander Migration:	Avulsion	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000

Reach: **T5.02**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		579	252
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	1	
	Total Length:	1.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	41.4300
			0
	Data Armoring:		
5.4	Straightening Length:	240.14999	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	165.1200	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	165.1200	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	215.3600	45.2900
6.4	Miander Migration:	Multiple	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	315.8800049
	Bank Height:	N.D.	4.691



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
April, 08 2026

Reach: **T5.03**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	Ledge	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		135	0
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	2	
	Total Length:	71.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	Not Evaluated	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	3625.9500	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	3625.9500	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	23.1000	20.8700
6.4	Miander Migration:	No Data	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000

Reach: **M21**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		0	0
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	1	
	Total Length:	1.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	0.0000
6.4	Miander Migration:	Avulsion	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	3725.820068
			4
	Bank Height:	N.D.	7.485



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
April, 08 2026

Reach: **T6.01**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		0	0
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	0	
	Total Length:	0.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	Not Evaluated	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	0.0000
6.4	Miander Migration:	Avulsion	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000

Reach: **T6.02**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		1161	1160
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	3	
	Total Length:	106.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		74.6300	120.310
		0	00
	Data Armoring:		
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	107.1400	0.0000
	Berm:	107.1400	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	171.7500	283.8600
6.4	Miander Migration:	Multiple	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	629.1300049
	Bank Height:	N.D.	3.312



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
April, 08 2026

Reach: **T6.03**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		0	0
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	0	
	Total Length:	0.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	Not Evaluated	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	1114.3101	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	1114.3101	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	0.0000
6.4	Miander Migration:	No Data	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000

Reach: **T6.04**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
5.1	Flow Regulation - Type:		
	Use:		
5.2	# of Bridges or Culverts:		
	Total Length:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
	Data Armoring:	None	
5.4	Straightening Length:		
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	Not Evaluated	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:		
	Berm:		
	Path:		
	Road:		
	Railroad:		
6.2	Corridor Development Data:		
	Length:		
6.4	Miander Migration:	No Data	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:		
	Bank Height:		



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
April, 08 2026

Reach: **M22**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		0	707
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	1	
	Total Length:	1.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	181.72000
	Data Armoring:		
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	195.1800	0.0000
6.4	Miander Migration:		
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	1597.4300537
	Bank Height:	N.D.	6.510

Reach: **T7.01**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:		
3.2	Grade Control:		
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
5.1	Flow Regulation - Type:		
	Use:		
5.2	# of Bridges or Culverts:		
	Total Length:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
	Data Armoring:		
5.4	Straightening Length:		
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:		
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:		
	Berm:		
	Path:		
	Road:		
	Railroad:		
6.2	Corridor Development Data:		
	Length:		
6.4	Miander Migration:		
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:		0.0000000
	Bank Height:		0.000



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
April, 08 2026

Reach: **T7.02**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:		
3.2	Grade Control:		
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
5.1	Flow Regulation - Type: Use:		
5.2	# of Bridges or Culverts: Total Length:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
5.4	Data Armoring: Straightening Length: Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:		
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:		
	Berm:		
	Path:		
	Road:		
	Railroad:		
6.2	Corridor Development Data:		
	Length:		
6.4	Miander Migration:		
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:		0.000000
	Bank Height:		0.000

Reach: **T7.03**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:		
3.2	Grade Control:		
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
5.1	Flow Regulation - Type: Use:		
5.2	# of Bridges or Culverts: Total Length:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
5.4	Data Armoring: Straightening Length: Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:		
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:		
	Berm:		
	Path:		
	Road:		
	Railroad:		
6.2	Corridor Development Data:		
	Length:		
6.4	Miander Migration:		
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:		0.000000
	Bank Height:		0.000



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
April, 08 2026

Reach: **M23**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		3073	0
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	0	
	Total Length:	0.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	2550.64990	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	0.0000
6.4	Miander Migration:	Flood Chute	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	3291.399902
			3
	Bank Height:	N.D.	5.073

Reach: **T8.01**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		1207	844
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	0	
	Total Length:	0.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	0.0000
6.4	Miander Migration:	Multiple	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	423.1499939
	Bank Height:	N.D.	3.803



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
April, 08 2026

Reach: **T8.02**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		169	514
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	1	
	Total Length:	108.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		228.040	0.00000
		01	
	Data Armoring:		
5.4	Straightening Length:	103.03000	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	128.0900
6.4	Miander Migration:	Multiple	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	189.3200073
	Bank Height:	N.D.	3.804

Reach: **T8.03**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		0	0
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	1	
	Total Length:	1.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	Not Evaluated	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	821.8300	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	821.8300	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	0.0000
6.4	Miander Migration:		
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
April, 08 2026

Reach: **T8.04**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
5.1	Flow Regulation - Type:		
	Use:		
5.2	# of Bridges or Culverts:		
	Total Length:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
	Data Armoring:	None	
5.4	Straightening Length:		
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	Not Evaluated	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:		
	Berm:		
	Path:		
	Road:		
	Railroad:		
6.2	Corridor Development Data:		
	Length:		
6.4	Miander Migration:		
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:		
	Bank Height:		

Reach: **T8.05**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	Dam	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		0	245
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	1	
	Total Length:	116.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	Not Evaluated	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	25.2600
6.4	Miander Migration:		
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
April, 08 2026

Reach: **T8.06**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
5.1	Flow Regulation - Type:		
	Use:		
5.2	# of Bridges or Culverts:		
	Total Length:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
	Data Armoring:	None	
5.4	Straightening Length:		
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	Not Evaluated	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:		
	Berm:		
	Path:		
	Road:		
	Railroad:		
6.2	Corridor Development Data:		
	Length:		
6.4	Miander Migration:	No Data	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:		
	Bank Height:		

Reach: **M24**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		2521	772
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	1	
	Total Length:	1.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		583.960	153.060
		02	00
	Data Armoring:		
5.4	Straightening Length:	741.28003	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	874.0900	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	874.0900	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	0.0000
6.4	Miander Migration:	Flood Chute	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	718.3099976
	Bank Height:	N.D.	3.602



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
April, 08 2026

Reach: **M25**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		0	0
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	0	
	Total Length:	0.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	1279.26001	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	0.0000
6.4	Miander Migration:	<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000

Reach: **M26**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		0	0
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	1	
	Total Length:	200.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	5853.29004	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	0.0000
6.4	Miander Migration:	<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
April, 08 2026

Reach: **M27**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		0	128
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	1	
	Total Length:	1.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	3682.37988	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	0.0000
6.4	Miander Migration:	<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000

Reach: **M28**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		0	668
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	2	
	Total Length:	220.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	0.0000
6.4	Miander Migration:	<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	2316.020019
			5
	Bank Height:	N.D.	5.665



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
April, 08 2026

Reach: **M29**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		3117	4289
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	2	
	Total Length:	2.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	822.40002	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	0.0000
6.4	Miander Migration:	Flood Chute	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	9853.620117
			2
	Bank Height:	N.D.	6.830

Reach: **M30**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
5.1	Flow Regulation - Type:		
	Use:		
5.2	# of Bridges or Culverts:		
	Total Length:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
	Data Armoring:	Not Evaluated	
5.4	Straightening Length:		
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:		
	Berm:		
	Path:		
	Road:		
	Railroad:		
6.2	Corridor Development Data:	None	
	Length:		
6.4	Miander Migration:		
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:		
	Bank Height:		



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
April, 08 2026

Reach: **M31**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		0	0
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	0	
	Total Length:	0.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	2876.1001
6.4	Miander Migration:	<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000

Reach: **M32**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
5.1	Flow Regulation - Type:		
	Use:		
5.2	# of Bridges or Culverts:		
	Total Length:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
	Data Armoring:	Not Evaluated	
5.4	Straightening Length:		
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:		
	Berm:		
	Path:		
	Road:		
	Railroad:		
6.2	Corridor Development Data:	None	
	Length:		
6.4	Miander Migration:	<u>Old</u>	<u>New</u>
7.2	Bank Erosion:		
	Bank Height:		



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
April, 08 2026

Reach: **M33**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	Ledge	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		0	0
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	0	
	Total Length:	0.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	189.4300	0.0000
6.4	Miander Migration:	<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000

Reach: **M34**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		391	0
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	0	
	Total Length:	0.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	125.4100	0.0000
6.4	Miander Migration:	<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
April, 08 2026

Reach: **T12.01**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		605	596
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	0	
	Total Length:	0.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	0.0000
6.4	Miander Migration:	Migration	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	798.9299927
	Bank Height:	N.D.	4.649

Reach: **T12.02**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		143	58
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	2	
	Total Length:	381.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	424.37000	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	Not Evaluated	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	23.1200
6.4	Miander Migration:	Multiple	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
April, 08 2026

Reach: **T12.03**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		0	73
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	1	
	Total Length:	148.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	133.36000	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	Not Evaluated	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	116.9600
6.4	Miander Migration:	Migration	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000

Reach: **T12.04**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		0	0
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	0	
	Total Length:	0.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	Not Evaluated	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	0.0000
6.4	Miander Migration:	Migration	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
April, 08 2026

Reach: **T12.05**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	Dam	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		890	941
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	3	
	Total Length:	237.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	131.37000	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	Not Evaluated	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	238.2400	74.7000
6.4	Miander Migration:	No Data	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000

Reach: **M35**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
5.1	Flow Regulation - Type:		
	Use:		
5.2	# of Bridges or Culverts:		
	Total Length:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
	Data Armoring:	Not Evaluated	
5.4	Straightening Length:		
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:		
	Berm:		
	Path:		
	Road:		
	Railroad:		
6.2	Corridor Development Data:		
	Length:		
6.4	Miander Migration:		
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:		
	Bank Height:		



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
April, 08 2026

Reach: **M36**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
5.1	Flow Regulation - Type: Use:		
5.2	# of Bridges or Culverts: Total Length:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
	Data Armoring:	Not Evaluated	
5.4	Straightening Length: Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:		
	Berm:		
	Path:		
	Road:		
	Railroad:		
6.2	Corridor Development Data:	None	
	Length:		
6.4	Miander Migration:	<u>Old</u>	<u>New</u>
7.2	Bank Erosion:		
	Bank Height:		

Reach: **M37**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
5.1	Flow Regulation - Type: Use:		
5.2	# of Bridges or Culverts: Total Length:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
	Data Armoring:	Not Evaluated	
5.4	Straightening Length: Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:		
	Berm:		
	Path:		
	Road:		
	Railroad:		
6.2	Corridor Development Data:	None	
	Length:		
6.4	Miander Migration:	<u>Old</u>	<u>New</u>
7.2	Bank Erosion:		
	Bank Height:		



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
April, 08 2026

Reach: **T4.01**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		239	919
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	1	
	Total Length:	1.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	Not Evaluated	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	191.1300	0.0000
6.4	Miander Migration:	Multiple	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000

Reach: **T4.02**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		568	3991
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	1	
	Total Length:	105.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	100.84000	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	Not Evaluated	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	1308.5800	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	1308.5800	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	41.0300
6.4	Miander Migration:	None	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
April, 08 2026

Reach: **T4.03**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		8638	10907
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	4	
	Total Length:	295.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		821.330	432.910
		02	00
	Data Armoring:		
5.4	Straightening Length:	972.14001	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	716.5900	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	716.5900	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	859.2400	27.4400
6.4	Miander Migration:	Multiple	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	6202.149902
			3
	Bank Height:	N.D.	5.313

Reach: **T4.04**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		3526	3975
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	3	
	Total Length:	366.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		21.7800	0.00000
		0	
	Data Armoring:		
5.4	Straightening Length:	401.44000	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	340.8400	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	340.8400	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	485.3100	0.0000
6.4	Miander Migration:	Multiple	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	1106.800048
			8
	Bank Height:	N.D.	4.822



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
April, 08 2026

Reach: **T4.05**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		3366	4202
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	0	
	Total Length:	0.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	Not Evaluated	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	461.0100	0.0000
6.4	Miander Migration:	Avulsion	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000

Reach: **T4.06**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		1356	718
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	1	
	Total Length:	97.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	159.03000	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	Not Evaluated	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	84.5500
6.4	Miander Migration:	None	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
April, 08 2026

Reach: **T4.07**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		891	1703
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	0	
	Total Length:	0.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	Not Evaluated	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	0.0000
6.4	Miander Migration:	None	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000

Reach: **T4.08**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		0	0
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	1	
	Total Length:	1.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	Not Evaluated	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	25.7200
6.4	Miander Migration:	No Data	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
April, 08 2026

Reach: **T4.09**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:		
3.2	Grade Control:		
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
5.1	Flow Regulation - Type: Use:		
5.2	# of Bridges or Culverts: Total Length:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
	Data Armoring:	None	
5.4	Straightening Length: Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	Not Evaluated	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:		
	Berm:		
	Path:		
	Road:		
	Railroad:		
6.2	Corridor Development Data:		
	Length:		
6.4	Miander Migration:	No Data	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:		
	Bank Height:		

Reach: **T4.06S1.01**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:		
3.2	Grade Control:		
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
5.1	Flow Regulation - Type: Use:		
5.2	# of Bridges or Culverts: Total Length:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
	Data Armoring:		
5.4	Straightening Length: Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:		
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:		
	Berm:		
	Path:		
	Road:		
	Railroad:		
6.2	Corridor Development Data:		
	Length:		
6.4	Miander Migration:		
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:		0.000000
	Bank Height:		0.000



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
April, 08 2026

Reach: **T4.06S1.02**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:		
3.2	Grade Control:		
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
5.1	Flow Regulation - Type: Use:		
5.2	# of Bridges or Culverts: Total Length:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
	Data Armoring:		
5.4	Straightening Length: Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:		
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:		
	Berm:		
	Path:		
	Road:		
	Railroad:		
6.2	Corridor Development Data:		
	Length:		
6.4	Miander Migration:		
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:		
	Bank Height:		