



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
April, 08 2026

Phase 1 - FIT - Legacy Data Report

Lower Passumpsic

SGAT Version: **4.56**

Reach: **T4.01**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	Ledge	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		2002	1387
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	2	
	Total Length:	53.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		316.500	414.199
		00	98
	Data Armoring:		
5.4	Straightening Length:	2665.11987	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	Dredging	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	658.5300	0.0000
	Path:	0.000	0.000
	Road:	587.7100	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	740.3200	0.0000
6.4	Miander Migration:	Flood Chute	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	429.5899963
	Bank Height:	N.D.	4.421



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
April, 08 2026

Reach: **T4.02**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	Ledge	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		0	442
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	0	
	Total Length:	0.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	198.45000
	Data Armoring:		
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	2231.3999	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	1568.0000	0.0000
6.4	Miander Migration:	None	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	187.6399994
	Bank Height:	N.D.	6.303

Reach: **T4.2S1.01**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		305	210
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	1	
	Total Length:	24.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		192.82001	0.00000
	Data Armoring:		
5.4	Straightening Length:	156.64000	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	301.5200	0.0000
6.4	Miander Migration:	None	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	127.4899979
	Bank Height:	N.D.	8.330



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
April, 08 2026

Reach: **T4.2S1.02**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		0	0
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	2	
	Total Length:	35.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		96.8700	95.0400
		0	0
	Data Armoring:		
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	0.0000
6.4	Miander Migration:	None	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000

Reach: **T4.2S1.04**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		0	0
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	1	
	Total Length:	30.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	0.0000
6.4	Miander Migration:	None	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
April, 08 2026

Reach: **T4.2S1.03**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		0	0
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	2	
	Total Length:	45.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	1392.8500	545.65997
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	202.6600	0.0000
6.4	Miander Migration:	None	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000

Reach: **T3.04**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	Ledge	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		0	3109
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	1	
	Total Length:	12.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	780.69000
	Data Armoring:		
5.4	Straightening Length:	2680.98999	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	2005.6000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	424.9700	0.0000
6.4	Miander Migration:	None	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	397.1000061
	Bank Height:	N.D.	5.813



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
April, 08 2026

Reach: **T3.05**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	Ledge	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		306	1030
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	0	
	Total Length:	0.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	857.15002	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	453.75000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	944.6300	0.0000
6.4	Miander Migration:	Migration	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	232.2899933
	Bank Height:	N.D.	4.094

Reach: **T3.06**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	Ledge	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		1772	76
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	2	
	Total Length:	60.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		1722.31	51.4100
		995	0
	Data Armoring:		
5.4	Straightening Length:	1597.75000	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	Dredging	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	1497.7200	268.64999
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	390.0800	0.0000
6.4	Miander Migration:	None	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	32.6199989
	Bank Height:	N.D.	6.510



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
April, 08 2026

Reach: **T3.07**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	Yes	
3.2	Grade Control:	Ledge	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		1311	0
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	1	
	Total Length:	26.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		1289.44	0.00000
		006	
	Data Armoring:		
5.4	Straightening Length:	1245.38000	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	1231.8700	708.40002
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	298.7300
6.4	Miander Migration:	Multiple	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	438.0199890
	Bank Height:	N.D.	5.013

Reach: **T3.08**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	Multiple	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		2561	0
5.1	Flow Regulation - Type:	Small Run of River	
	Use:	Other	
5.2	# of Bridges or Culverts:	1	
	Total Length:	4.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		911.190	0.00000
		00	
	Data Armoring:		
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	234.1600	0.0000
	Path:	0.000	0.000
	Road:	5010.1401	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	1909.3700	0.0000
6.4	Miander Migration:	Flood Chute	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	318.8900146
	Bank Height:	N.D.	4.820



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
April, 08 2026

Reach: **T3.09**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	Ledge	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		1306	0
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	0	
	Total Length:	0.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		1351.32	0.00000
		996	
	Data Armoring:		
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	97.0100	0.0000
	Path:	0.000	0.000
	Road:	4104.6401	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	272.2900	0.0000
6.4	Miander Migration:	Flood Chute	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	137.0400085
	Bank Height:	N.D.	4.622

Reach: **T3.10**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	Dam	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		260	0
5.1	Flow Regulation - Type:	Large Run of River	
	Use:	Other	
5.2	# of Bridges or Culverts:	1	
	Total Length:	24.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		116.100	0.00000
		00	
	Data Armoring:		
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	Dredging	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	606.6200	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	126.4400	0.0000
6.4	Miander Migration:	None	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	151.0500031
	Bank Height:	N.D.	2.000



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
April, 08 2026

Reach: **T3.11**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	Multiple	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		952	2545
5.1	Flow Regulation - Type:	Small Run of River	
	Use:	Other	
5.2	# of Bridges or Culverts:	4	
	Total Length:	75.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		54.6400	353.670
		0	01
	Data Armoring:		
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	503.0100	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	1030.1801	0.0000
6.4	Miander Migration:	Migration	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	96.9599991
	Bank Height:	N.D.	2.448

Reach: **T3.11S1.01**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	Dam	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		0	343
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	1	
	Total Length:	20.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:	None	
	Length:	0.0000	0.0000
6.4	Miander Migration:	None	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
April, 08 2026

Reach: **T3.12**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		0	250
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	0	
	Total Length:	0.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	None	
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:	None	
	Length:	0.0000	0.0000
6.4	Miander Migration:	None	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000

Reach: **T3.13**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
5.1	Flow Regulation - Type:		
	Use:		
5.2	# of Bridges or Culverts:		
	Total Length:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
	Data Armoring:	None	
5.4	Straightening Length:		
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	None	
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:		
	Berm:		
	Path:		
	Road:		
	Railroad:		
6.2	Corridor Development Data:	None	
	Length:		
6.4	Miander Migration:	None	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:		0.0000000
	Bank Height:		0.000



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
April, 08 2026

Reach: **T3.14**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	Dam	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		0	0
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	1	
	Total Length:	24.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	0.0000
6.4	Miander Migration:	None	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000

Reach: **T3.15**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
5.1	Flow Regulation - Type:		
	Use:		
5.2	# of Bridges or Culverts:		
	Total Length:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
	Data Armoring:	None	
5.4	Straightening Length:		
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:		
	Berm:		
	Path:		
	Road:		
	Railroad:		
6.2	Corridor Development Data:	None	
	Length:		
6.4	Miander Migration:	None	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:		0.0000000
	Bank Height:		0.000



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
April, 08 2026

Reach: **T3.10S1.01**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		0	0
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	0	
	Total Length:	0.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	85.8500
			0
	Data Armoring:		
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	208.3600	0.0000
6.4	Miander Migration:	None	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000

Reach: **T3.10S1.02**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	Weir	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		262	0
5.1	Flow Regulation - Type:	Small Run of River	
	Use:	Other	
5.2	# of Bridges or Culverts:	0	
	Total Length:	0.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:	None	
	Length:	0.0000	0.0000
6.4	Miander Migration:	None	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	236.4900055
	Bank Height:	N.D.	4.000



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
April, 08 2026

Reach: **T3.10S1.03**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	Ledge	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		1049	0
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	1	
	Total Length:	42.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		365.579	0.00000
		99	
	Data Armoring:		
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	197.1100	0.0000
	Path:	0.000	0.000
	Road:	1207.3600	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	15.1500	0.0000
6.4	Miander Migration:	Multiple	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	348.0800171
	Bank Height:	N.D.	8.071

Reach: **T3.10S1.04**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		0	372
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	1	
	Total Length:	30.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	66.2500	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	234.2500	0.0000
6.4	Miander Migration:	Migration	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
April, 08 2026

Reach: **T3.10S1.05**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	Dam	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		0	0
5.1	Flow Regulation - Type:	Small Run of River	
	Use:	Recreation	
5.2	# of Bridges or Culverts:	0	
	Total Length:	0.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	0.0000
6.4	Miander Migration:	None	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000

Reach: **T3.10S1.3s1.01**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		0	0
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	0	
	Total Length:	0.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		38.9700	0.00000
		0	
	Data Armoring:		
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	0.0000
6.4	Miander Migration:	None	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
April, 08 2026

Reach: **T3.10S1.3s1.02**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		130	283
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	1	
	Total Length:	30.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		200.880	0.00000
		00	
	Data Armoring:		
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	203.5400	0.0000
6.4	Miander Migration:	None	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000

Reach: **T3.7S1.01**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	Yes	
3.2	Grade Control:	Multiple	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		450	0
5.1	Flow Regulation - Type:	Small Run of River	
	Use:	Other	
5.2	# of Bridges or Culverts:	2	
	Total Length:	96.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		765.450	0.00000
		01	
	Data Armoring:		
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	3077.4700	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	738.2600	0.0000
6.4	Miander Migration:	Flood Chute	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
April, 08 2026

Reach: **T3.7S1.02**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		45	419
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	0	
	Total Length:	0.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	487.91000
	Data Armoring:		
5.4	Straightening Length:	562.70001	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	142.9500	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	0.0000
6.4	Miander Migration:	Multiple	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	433.8800049
	Bank Height:	N.D.	8.506

Reach: **T3.7S1.03**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		0	0
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	0	
	Total Length:	0.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	563.3600	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	0.0000
6.4	Miander Migration:	Multiple	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	132.3800049
	Bank Height:	N.D.	3.083



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
April, 08 2026

Reach: **T3.7S1.04**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	Yes	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		563	0
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	2	
	Total Length:	138.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	191.98000	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	866.7500	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	0.0000
6.4	Miander Migration:	Multiple	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	361.0700073
	Bank Height:	N.D.	3.079

Reach: **T3.7S1.05**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		0	0
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	2	
	Total Length:	90.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	55.8500
			0
	Data Armoring:		
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	0.0000
6.4	Miander Migration:	Flood Chute	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	375.3999939
	Bank Height:	N.D.	4.030



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
April, 08 2026

Reach: **T3.7S1.06**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		1061	1233
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	3	
	Total Length:	101.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		56.6200	212.1600
	Data Armoring:		
5.4	Straightening Length:	452.73999	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	0.0000
6.4	Miander Migration:	Multiple	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	928.3699951
	Bank Height:	N.D.	6.428

Reach: **T3.7S1.07**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		381	646
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	3	
	Total Length:	320.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		205.6499	331.1399
	Data Armoring:		
5.4	Straightening Length:	125.34000	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	225.0500	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	623.3100	0.0000
6.4	Miander Migration:	Flood Chute	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	292.5000000
	Bank Height:	N.D.	4.366



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
April, 08 2026

Reach: **T2.01**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	Waterfall	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		7	0
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	2	
	Total Length:	60.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	0.0000
6.4	Miander Migration:	None	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000

Reach: **T2.02**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		229	0
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	0	
	Total Length:	0.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		479.060	0.00000
		00	
	Data Armoring:		
5.4	Straightening Length:	368.70001	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	646.0600	0.0000
6.4	Miander Migration:	None	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
April, 08 2026

Reach: **T2.03**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		160	0
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	0	
	Total Length:	0.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	1332.1899	0.0000
6.4	Miander Migration:	Multiple	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000

Reach: **T2.04**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		0	419
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	0	
	Total Length:	0.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	0.0000
6.4	Miander Migration:	Migration	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
April, 08 2026

Reach: **T2.05**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		1959	926
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	0	
	Total Length:	0.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	0.0000
6.4	Miander Migration:	Migration	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000

Reach: **T2.06**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
5.1	Flow Regulation - Type:		
	Use:		
5.2	# of Bridges or Culverts:		
	Total Length:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
	Data Armoring:	None	
5.4	Straightening Length:		
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	None	
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:		
	Berm:		
	Path:		
	Road:		
	Railroad:		
6.2	Corridor Development Data:	No Data	
	Length:		
6.4	Miander Migration:	None	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:		0.0000000
	Bank Height:		0.000



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
April, 08 2026

Reach: **T2.07**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		2270	0
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	2	
	Total Length:	40.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		814.310	208.970
		00	00
	Data Armoring:		
5.4	Straightening Length:	628.09003	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	921.9200	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	180.4100	0.0000
6.4	Miander Migration:	Multiple	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	325.0199890
	Bank Height:	N.D.	4.774

Reach: **T2.08**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	Ledge	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		376	605
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	1	
	Total Length:	24.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		442.580	276.709
		02	99
	Data Armoring:		
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	2734.5100	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	364.0500	0.0000
6.4	Miander Migration:	Migration	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	73.8099976
	Bank Height:	N.D.	5.157



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
April, 08 2026

Reach: **T2.09**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	Ledge	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		0	0
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	1	
	Total Length:	52.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		610.060	0.00000
		00	
	Data Armoring:		
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	3533.740	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	0.0000
6.4	Miander Migration:	Multiple	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	781.2000122
	Bank Height:	N.D.	4.674

Reach: **T2.10**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	Yes	
3.2	Grade Control:	Ledge	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		0	0
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	0	
	Total Length:	0.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	1279.940	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	0.0000
6.4	Miander Migration:	Multiple	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	74.9900055
	Bank Height:	N.D.	7.211



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
April, 08 2026

Reach: **T2.11**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	Yes	
3.2	Grade Control:	Ledge	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		0	136
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	0	
	Total Length:	0.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		91.3600	0.00000
		0	
	Data Armoring:		
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	2156.510	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	0.0000
6.4	Miander Migration:	Flood Chute	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	430.5400085
	Bank Height:	N.D.	6.624

Reach: **T2.12**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	Weir	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		589	47
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	3	
	Total Length:	144.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		255.110	399.750
		00	00
	Data Armoring:		
5.4	Straightening Length:	437.28000	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	934.5200	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	179.9300	0.0000
6.4	Miander Migration:	Migration	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	1438.530029
			3
	Bank Height:	N.D.	3.916



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
April, 08 2026

Reach: **T1.01**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		1986	2053
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	2	
	Total Length:	80.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		536.929	0.00000
		99	
	Data Armoring:		
5.4	Straightening Length:	1300.77002	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	61.1500	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	287.2000	0.0000
6.4	Miander Migration:	Migration	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000

Reach: **T1.02**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	Ledge	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		0	3305
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	1	
	Total Length:	30.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	2730.22
			998
	Data Armoring:		
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	4050.5400	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	351.2500	0.0000
6.4	Miander Migration:	None	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
April, 08 2026

Reach: **T1.03**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	Dam	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		2421	3973
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	1	
	Total Length:	30.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	1819.78003	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	1755.8400	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	687.8900	0.0000
6.4	Miander Migration:	None	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000

Reach: **T1.04**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		853	0
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	0	
	Total Length:	0.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	0.0000
6.4	Miander Migration:	None	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
April, 08 2026

Reach: **T1.05**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	Dam	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		0	0
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	1	
	Total Length:	30.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	232.25000	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	677.5600	0.0000
6.4	Miander Migration:	None	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000

Reach: **T1.06**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		0	0
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	0	
	Total Length:	0.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	1500.0100	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	0.0000
6.4	Miander Migration:	None	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
April, 08 2026

Reach: **T1.07**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		0	0
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	1	
	Total Length:	20.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		66.6900	67.3900
		0	0
	Data Armoring:		
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	845.7600	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	202.7800
6.4	Miander Migration:	None	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000

Reach: **T1.08**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	Ledge	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		338	1299
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	1	
	Total Length:	30.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	1080.67
			993
	Data Armoring:		
5.4	Straightening Length:	112.31000	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	4007.1099	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	273.6300	0.0000
6.4	Miander Migration:	None	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
April, 08 2026

Reach: **T1.09**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		774	1975
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	2	
	Total Length:	48.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	1395.65002	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	4880.5200	253.85001
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	1017.0500	337.0500
6.4	Miander Migration:	None	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000

Reach: **T1.10**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		295	0
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	1	
	Total Length:	24.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	0.0000
6.4	Miander Migration:	None	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
April, 08 2026

Reach: **T1.11**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	0	
	Total Length:	0.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	None	
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:		
	Berm:		
	Path:		
	Road:		
	Railroad:		
6.2	Corridor Development Data:	None	
	Length:		
6.4	Miander Migration:	None	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	0.0000000	
	Bank Height:	0.000	

Reach: **T1.12**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		146	102
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	0	
	Total Length:	0.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	243.8700	0.0000
6.4	Miander Migration:	None	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
April, 08 2026

Reach: **T1.13**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	Dam	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		529	576
5.1	Flow Regulation - Type:	Large Run of River	
	Use:	Recreation	
5.2	# of Bridges or Culverts:	2	
	Total Length:	48.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	529.15002
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	571.3700
6.4	Miander Migration:	None	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000

Reach: **T4.03**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	Ledge	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		476	502
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	3	
	Total Length:	117.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		439.080	18.7100
		02	0
	Data Armoring:		
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	234.5800	0.0000
	Path:	0.000	0.000
	Road:	891.2400	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	701.1600	0.0000
6.4	Miander Migration:	Flood Chute	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	443.9800110
	Bank Height:	N.D.	7.438



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
April, 08 2026

Reach: **T4.04**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		535	676
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	2	
	Total Length:	46.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		63.6700	235.1900
		0	00
	Data Armoring:		
5.4	Straightening Length:	998.77002	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	273.5900	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	508.4600	481.3800
6.4	Miander Migration:	Neck Cutoff	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	134.6799927
	Bank Height:	N.D.	4.000

Reach: **T5.01**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		212	737
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	3	
	Total Length:	364.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		1145.27	1168.51
		002	001
	Data Armoring:		
5.4	Straightening Length:	1527.81006	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	807.4500	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	205.1000	0.0000
6.4	Miander Migration:	None	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	12.6800003
	Bank Height:	N.D.	3.000



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
April, 08 2026

Reach: **T5.02**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	Ledge	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		643	675
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	2	
	Total Length:	47.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		550.080	605.500
		02	00
	Data Armoring:		
5.4	Straightening Length:	486.95999	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	Dredging	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	165.3400	0.0000
	Path:	0.000	0.000
	Road:	325.3400	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	1139.4500	0.0000
6.4	Miander Migration:	None	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	88.8399963
	Bank Height:	N.D.	4.332

Reach: **T5.03**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	Ledge	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		1382	263
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	0	
	Total Length:	0.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		1294.92	0.00000
		004	
	Data Armoring:		
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	1666.5601	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	930.2500	0.0000
6.4	Miander Migration:	None	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	262.8399963
	Bank Height:	N.D.	5.667



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
April, 08 2026

Reach: **T5.04**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	Ledge	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		400	167
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	0	
	Total Length:	0.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		409.000	0.00000
		00	
	Data Armoring:		
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	591.6800	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	399.6800	0.0000
6.4	Miander Migration:	None	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	276.1499939
	Bank Height:	N.D.	2.718

Reach: **T5.05**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	Ledge	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		1126	750
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	0	
	Total Length:	0.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		159.569	0.00000
		99	
	Data Armoring:		
5.4	Straightening Length:	559.06000	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	809.8100	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	680.0800	0.0000
6.4	Miander Migration:	Flood Chute	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	281.5400085
	Bank Height:	N.D.	3.973



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
April, 08 2026

Reach: **T5.06**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	Ledge	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		714	393
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	2	
	Total Length:	55.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		76.7600	184.7100
	Data Armoring:		
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	1447.9000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	587.4900	0.0000
6.4	Miander Migration:	None	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	106.1999969
	Bank Height:	N.D.	4.460

Reach: **T5.07**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	Ledge	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		337	3771
5.1	Flow Regulation - Type:	Small Withdrawal	
	Use:	Drinking	
5.2	# of Bridges or Culverts:	2	
	Total Length:	26.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		87.0500	298.0000
	Data Armoring:		
5.4	Straightening Length:	582.09998	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	131.4500	209.2400
	Path:	0.000	0.000
	Road:	1348.4900	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	1528.4600	387.5200
6.4	Miander Migration:	Flood Chute	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	504.2000122
	Bank Height:	N.D.	5.249



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
April, 08 2026

Reach: **T5.08**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		196	763
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	1	
	Total Length:	40.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		134.470	754.979
		00	98
	Data Armoring:		
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	1862.2100	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	50.6500	0.0000
6.4	Miander Migration:	None	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000