



FIT Affected Segments Report

Mill Brook - Basin 13

Reach - Segment	Affected by FIT (Feature Indexing Tool)
T4.01 - A	No
T4.01 - B	No
T4.01 - C	No
M02 - 0	No
M08 - 0	No
M09 - A	No
M09 - B	No
M10 - 0	No
M11 - 0	No
M12 - A	No
M12 - B	No
M13 - 0	No
M14 - A	No
M14 - B	No
M14 - C	No
M15 - A	No
M15 - B	No
M16 - A	No
M16 - B	No
T1.01 - 0	No
T1.02 - A	No
T1.02 - B	No
T1.02 - C	No
T2.01 - A	No
T2.01 - B	No
T2.02 - 0	No
T2.03 - A	No
T2.03 - B	No
T2.04 - 0	No
T2.05 - A	No
T2.05 - B	No
T3.01 - 0	No



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov

November, 22 2024

T3.02 - A	No
T3.02 - B	No
T4.02 - A	No
T4.02 - B	No
T4.02 - C	No
T1.01.S4.01 - A	No
T1.01.S4.01 - B	No
T1.01.S4.01 - C	No
T1.01.S4.01 - D	No
M04 - 0	No
M05 - A	No
M05 - B	No
M05 - C	No
M06 - 0	No
M07 - A	No
M07 - B	No
T3.03 - 0	No
T3.04 - 0	No