



FIT Affected Segments Report

Seymour River

Reach - Segment	Affected by FIT (Feature Indexing Tool)
T1.02 - A	No
M04S1.01 - 0	No
M06S3.01 - A	No
M05 - 0	No
M06S3.01 - B	No
M04S1.02 - C	No
T1.02 - C	No
T1.02 - B	No
M04S1.02 - B	No
M04S1.02 - A	No
M06S3.01 - C	No
M01 - A	No
M06 - A	No
M06S1.02 - C	No
M08 - B	No
M09 - 0	No
M12 - A	No
M06S1.01 - 0	No
M06 - B	No
M06S1.02 - B	No
M06S2.02 - A	No
M03 - 0	No
M06S2.02 - B	No
M06S2.02 - C	No
M06S2.03 - 0	No
M10 - B	No
M10S2.02 - A	No
M10 - A	No
T1.01 - 0	No
M07 - A	No
M11 - 0	No
M06S1.02 - A	No



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov

June, 17 2026

M07 - B	No
M01 - B	No
M04 - 0	No
M06S1.03 - 0	No
M10S1.01 - 0	No
M08 - A	No
M10S1.02 - A	No
M06S2.01 - 0	No
M02 - 0	No
M12 - B	No
M07S1.03 - B	No
M10S1.02 - B	No
M07S1.03 - A	No
M10S2.02 - B	No
M10S2.01 - B	No
M10S2.01 - A	No