



FIT Affected Segments Report

Middlebury River

Reach - Segment	Affected by FIT (Feature Indexing Tool)
M12 - A	No
M12 - B	No
M12 - C	No
M04 - 0	Yes
M05 - 0	Yes
M07 - 0	Yes
T4.02 - 0	Yes
T4.03 - A	No
T4.03 - B	No
T4.04 - A	No
T4.04 - B	No
M08 - A	No
M08 - B	No
T4.01 - 0	Yes
M18 - 0	No
M11 - 0	Yes
M01 - 0	Yes
M02 - 0	Yes
M03 - 0	Yes
T3.03 - 0	No
T3.04 - 0	Yes
T3.05 - 0	No
T3.06 - 0	Yes
T3.07 - 0	Yes
T3.08 - 0	Yes
T3.09 - 0	Yes
T3.10 - 0	Yes
M19 - 0	No
T4.05 - 0	Yes
T4.06 - 0	No
T4.07 - A	No
T4.07 - B	No



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov

July, 17 2024

T4.08 - 0	Yes
M13 - A	No
M13 - B	No
M14 - 0	Yes
M15 - 0	No
M16 - 0	No
M17 - 0	No
T3.01 - 0	No
T3.02 - 0	No
M06 - A	No
M06 - B	No