



FIT Affected Segments Report

Huntington River

Reach - Segment	Affected by FIT (Feature Indexing Tool)
M15 - A	Yes
M17 - A	No
M18 - A	No
T22.01 - 0	No
M17 - B	No
M17 - C	No
T22.02 - 0	No
M16 - 0	No
M18 - B	No
T16.01 - 0	No
T26.02 - 0	No
T26.01 - 0	No
M14 - C	Yes
M06 - 0	Yes
M07 - 0	Yes
M08 - 0	Yes
M09 - A	Yes
M09 - B	Yes
M09 - C	Yes
M09 - D	Yes
M10 - 0	Yes
M11 - 0	Yes
M12 - A	Yes
M12 - B	Yes
M13 - A	Yes
M13 - B	Yes
M14 - A	Yes
M14 - B	Yes
M15 - B	Yes
M05 - 0	No
M01 - 0	No
M04 - A	No



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
June, 17 2026

M04 - B	No
M03 - A	No
M03 - B	No
M02 - A	No
M02 - B	No
M02 - C	No