



FIT Affected Segments Report

White River - First Branch

Reach - Segment	Affected by FIT (Feature Indexing Tool)
T3.01 - 0	No
T4.01 - A	No
T6.01 - A	No
T6.01 - B	No
M19 - A	No
M18 - A	No
M17 - A	No
M05 - A	No
M06 - 0	No
M05 - B	No
T5.01 - B	No
T5.01 - A	No
M17 - B	No
M08 - A	No
T1.01 - D	No
M04 - A	No
T1.01 - B	No
T2.01 - A	No
T4.01 - B	No
T4.01 - C	No
M18 - B	No
M04 - B	No
T1.01 - C	No
T4.01 - D	No
M02 - B	No
M16 - C	No
T7.01 - F	No
M03 - 0	No
M01 - B	No
M01 - C	No
T7.01 - B	No
M02 - C	No



# Stream Geomorphic Assessment

## Agency of Natural Resources

VT DEC

Vermont.gov

June, 17 2026

M01 - A	No
M19 - C	No
M15 - A	No
M15 - B	No
T7.01 - D	No
M14 - C	No
T7.01 - E	No
M19 - B	No
M14 - A	No
M16 - A	No
M09 - A	No
M02 - A	No
M08 - B	No
T1.01 - A	No
T1.01 - E	No
T2.01 - B	No
M02 - 0	No
T2.01 - C	No
T7.01 - C	No
T7.01 - A	No
M14 - B	No
M10 - 0	No
M09 - B	No
M12 - 0	No
M13 - B	No
M07 - B	No
M16 - B	No
M13 - A	No
M07 - A	No
M13 - D	No
M11 - 0	No
M13 - C	No