



FIT Affected Segments Report

Winooski - Montpelier to Cabot

Reach - Segment	Affected by FIT (Feature Indexing Tool)
M3.05 - C	No
R20 - 0	No
R26 - 0	No
R24 - 0	No
M3.02 - C	No
R27 - B	No
M3.06 - C	No
M3.06 - A	No
R33 - B	Yes
R33 - A	Yes
R25 - 0	Yes
R19 - 0	Yes
R30 - A	Yes
M3.01 - B	No
M3.02 - A	No
M3.05 - B	No
R22 - A	Yes
R22 - B	Yes
R31 - B	Yes
R29 - 0	Yes
R32 - A	Yes
R32 - B	Yes
R34 - 0	Yes
R33 - C	Yes
M3.07 - C	No
M3.08 - D	No
M3.08 - C	No
R31 - A	Yes
R28 - 0	Yes
M3.01 - C	No
R18 - A	Yes
M3.08 - A	No



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov

November, 24 2024

R30 - B	Yes
M3.08 - B	No
R18 - B	Yes
M3.07 - B	No
M3.06 - B	No
M3.05 - A	No
R21 - A	No
R27 - A	No
R21 - B	No
R23 - 0	No
M3.03 - B	No
M3.04 - B	No
M3.07 - A	No
M3.04 - A	No
M3.03 - A	No
M3.01 - A	No
M3.02 - B	No