



FIT Affected Segments Report

Winooski - Cabot

Reach - Segment	Affected by FIT (Feature Indexing Tool)
R37 - C	No
R37 - E	No
T2.01 - 0	No
T2.02 - A	No
T2.02 - B	No
T3.01 - 0	No
T3.02 - A	No
T3.02 - B	No
T3.02 - C	No
T3.03 - A	No
T3.03 - B	No
T3.04 - A	No
T3.04 - B	No
T3.04 - C	No
T3.04 - D	No
R37 - A	No
R37 - B	No
R37 - D	No
R38 - A	No
R38 - B	No
R39 - A	No
R39 - B	No
R39 - C	No
R39 - D	No
R39 - E	No
R40 - A	No
R40 - B	No
R41 - A	No
R41 - B	No
R41 - C	No
R41 - D	No
R42 - 0	No