



FIT Affected Segments Report

Mad River

| Reach - Segment | Affected by FIT (Feature Indexing Tool) |
|-----------------|---|
| T2.01 - A | No |
| M10 - 0 | No |
| T13.04 - 0 | No |
| T13.2-S1.01 - 0 | No |
| M20 - A | No |
| T9.3-S2.01 - A | Yes |
| M21 - 0 | No |
| M23 - A | No |
| M23 - B | No |
| M23 - C | No |
| T12.02 - B | No |
| T12.2-S1.01 - 0 | No |
| M12 - 0 | Yes |
| T12.03 - A | No |
| T12.2-S4.01 - 0 | No |
| M13 - 0 | Yes |
| M20 - B | No |
| T6.1-S1.01 - 0 | Yes |
| M14 - 0 | Yes |
| M19 - A | Yes |
| M19 - B | Yes |
| M11 - 0 | Yes |
| M17 - 0 | Yes |
| M15 - 0 | Yes |
| T9.3-S1.01 - B | Yes |
| T9.3-S2.01 - B | Yes |
| T9.3-S1.01 - A | Yes |
| T9.2-S1.01 - 0 | Yes |
| T9.01 - 0 | Yes |
| T9.02 - 0 | Yes |
| M18 - 0 | Yes |
| M16 - 0 | Yes |



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov

November, 24 2024

| | |
|-----------------|-----|
| T1.01 - B | No |
| T1.01 - A | No |
| T2.01 - B | No |
| T3.01 - C | No |
| M05 - 0 | Yes |
| T9.04 - 0 | Yes |
| T5.02 - A | Yes |
| T5.02 - B | Yes |
| T9.03 - A | Yes |
| T9.03 - B | Yes |
| M22 - 0 | No |
| T12.01 - 0 | No |
| T12.02 - A | No |
| T3.01 - A | No |
| T12.03 - B | No |
| T12.2-S2.01 - 0 | No |
| T13.01 - 0 | No |
| T13.02 - 0 | No |
| T13.03 - 0 | No |
| M06 - 0 | No |
| M20 - C | No |
| T12.2-S3.01 - 0 | No |
| T3.01 - B | No |
| M08 - 0 | No |
| M09 - A | No |
| M09 - B | No |
| M03 - 0 | No |
| M04 - 0 | No |