



FIT Affected Segments Report

Munroe Brook

Reach - Segment	Affected by FIT (Feature Indexing Tool)
T1.02 - 0	No
T1.03 - 0	No
T1.04 - 0	No
M01 - 0	No
M02 - A	No
M03 - 0	No
M04 - A	No
M04 - B	No
M05 - 0	No
M06 - A	No
M06 - B	No
T1.01 - A	No
T1.01 - B	No
M02 - B	No
M07 - A	No
M07 - B	No