



FIT Affected Segments Report

Rock River

| Reach - Segment | Affected by FIT (Feature Indexing Tool) |
|------------------------|--|
| M09 - A | No |
| M09 - E | No |
| M1S1.03 - B | Yes |
| M5S4.01 - A | Yes |
| M5S5.01 - D | Yes |
| M5S5.01 - B | No |
| M5S5.01 - C | Yes |
| M6S1.01 - B | Yes |
| M6S1.01 - C | Yes |
| M6S1.01 - D | Yes |
| M6S1.1S1.01 - B | Yes |
| M6S1.1S1.01 - A | Yes |
| M1S1.02 - A | Yes |
| M09 - B | No |
| M5S2.01 - A | Yes |
| M5S2.01 - B | Yes |
| M5S2.01 - C | Yes |
| M5S3.01 - B | Yes |
| M5S3.01 - C | Yes |
| M5S3.01 - D | Yes |
| M5S4.01 - D | Yes |
| M5S4.01 - E | Yes |
| M5S4.01 - F | Yes |
| M5S4.01 - G | No |
| M04 - A | No |
| M06 - 0 | No |
| M09 - F | No |
| M05 - 0 | No |
| QM.02 - 0 | No |
| QM.06 - C | No |
| QT1.01 - B | No |
| QT1.03 - B | No |



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov

April, 08 2026

| | |
|-------------|----|
| QT2.01 - 0 | No |
| QT2.03 - 0 | No |
| QT3.01 - 0 | No |
| QT3.02 - 0 | No |
| QT3.06 - 0 | No |
| QT3.08 - 0 | No |
| QM.03 - 0 | No |
| QT2.07 - 0 | No |
| QT3.05 - 0 | No |
| M04 - B | No |
| M07 - A | No |
| M07 - B | No |
| M09 - C | No |
| M09 - D | No |
| M1S1.03 - A | No |
| M5S4.01 - B | No |
| M5S4.01 - C | No |
| M10 - 0 | No |
| M1S1.02 - B | No |
| M6S1.01 - A | No |
| M1S1.01 - A | No |
| M1S1.01 - B | No |
| M5S3.01 - A | No |
| M5S5.01 - A | No |
| M03 - 0 | No |
| QT2.05 - 0 | No |
| QT3.04 - 0 | No |
| QT3.07 - 0 | No |
| QT1.01 - A | No |
| QT1.02 - 0 | No |
| QM.01 - 0 | No |
| QM.04 - 0 | No |
| QM.05 - 0 | No |
| QM.06 - A | No |
| QM.06 - B | No |



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov

April, 08 2026

| | |
|--------------|----|
| QT1.03 - A | No |
| QT2.02 - 0 | No |
| QT2.04 - 0 | No |
| QT2.06 - 0 | No |
| QT2S3.01 - 0 | No |
| QT2S3.02 - 0 | No |
| QT3.03 - 0 | No |
| QT3.09 - 0 | No |
| QT3S1.01 - 0 | No |