



FIT Affected Segments Report

Poultney - Hubbardton River

| Reach - Segment | Affected by FIT (Feature Indexing Tool) |
|------------------------|--|
| M07 - 0 | Yes |
| M16 - A | Yes |
| M17 - C | Yes |
| M17 - A | Yes |
| M17 - B | Yes |
| M01 - 0 | No |
| M03 - 0 | No |
| M09 - A | No |
| M09 - B | No |
| M15 - 0 | Yes |
| T01.01 - 0 | No |
| T01.02 - 0 | No |
| T01.03 - 0 | No |
| T01.04 - 0 | No |
| T01.06 - 0 | No |
| T01.07 - 0 | No |
| M02 - 0 | Yes |
| M04 - 0 | Yes |
| M05 - 0 | Yes |
| M06 - 0 | Yes |
| M13 - 0 | Yes |
| M14 - A | Yes |
| M14 - B | Yes |
| M14 - C | Yes |
| M08 - 0 | Yes |
| M10 - 0 | Yes |
| M11 - A | Yes |
| M11 - B | Yes |
| M12 - A | Yes |
| M12 - B | Yes |
| M16 - B | Yes |
| M16 - C | Yes |