



FIT Affected Segments Report

Ottauquechee - Roaring Brook

Reach - Segment	Affected by FIT (Feature Indexing Tool)
T6.01 - B	No
T6.02 - 0	No
T6.01 - A	No
T6.03 - 0	No
T6.04 - 0	No
T6.05 - 0	No
T6.06 - 0	No
T6.07 - 0	No
T6.08 - 0	No