



Phase 1 - FIT - Legacy Data Report

Ottauquechee - Roaring Brook

SGAT Version: 3

Reach: T6.01		<u>Step</u>	<u>Description</u>	<u>Value</u>
	<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None		
3.2	Grade Control:	Ledge		
5.2	# of Bridges or Culverts:	2		
	Total Length:	320.000		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	
	Data Armoring:			
5.4	Straightening Length:	425.00000		
	Straightening Data:			
	<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	No Data		
6.1	Berms & Roads Data:			
		<u>One Side</u>	<u>Both Sides</u>	
	Berms & Roads:	576.0000	335.0000	
6.2	Dev. Length:	75.0000	279.0000	
	Corridor Development Data:			
		<u>Old</u>	<u>New</u>	
7.2	Bank Erosion:	None	0.0000000	
	Bank Height:	Medium		

Phase 1 - FIT - Legacy Data Report

Ottauquechee - Roaring Brook

SGAT Version: 3

Reach: T6.02		<u>Step</u>	<u>Description</u>	<u>Value</u>
	<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None		
3.2	Grade Control:	Ledge		
5.2	# of Bridges or Culverts:	1		
	Total Length:	200.000		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	
	Data Armoring:			
5.4	Straightening Length:	456.00000		
	Straightening Data:			
	<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	No Data		
6.1	Berms & Roads Data:	None		
		<u>One Side</u>	<u>Both Sides</u>	
	Berms & Roads:			
6.2	Dev. Length:	270.0000	714.0000	
	Corridor Development Data:			
		<u>Old</u>	<u>New</u>	
7.2	Bank Erosion:	Low	273.5000000	
	Bank Height:	Medium	3.431	



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
July, 17 2024

Phase 1 - FIT - Legacy Data Report

Ottauquechee - Roaring Brook

SGAT Version: 3

Reach: T6.03		<u>Step</u>	<u>Description</u>	<u>Value</u>
		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	6.1	Berms & Roads Data:	
			<u>One Side</u>	<u>Both Sides</u>
3.2	Grade Control:		Berms & Roads:	870.0000
		6.2	Dev. Length:	0.0000
5.2	# of Bridges or Culverts:		Corridor Development Data:	
			<u>Old</u>	<u>New</u>
	Total Length:	7.2	Bank Erosion:	231.0000000
			Bank Height:	4.000
5.3	Armoring Length			
	Data Armoring:			
5.4	Straightening Length:			
	Straightening Data:			

Phase 1 - FIT - Legacy Data Report

Ottauquechee - Roaring Brook

SGAT Version: 3

Reach: T6.03-S1.01		<u>Step</u>	<u>Description</u>	<u>Value</u>
		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	6.1	Berms & Roads Data:	
			<u>One Side</u>	<u>Both Sides</u>
3.2	Grade Control:		Berms & Roads:	267.0000
5.2	# of Bridges or Culverts:	6.2	Dev. Length:	0.0000
			Corridor Development Data:	
	Total Length:		<u>Old</u>	<u>New</u>
		7.2	Bank Erosion:	Low
5.3	Armoring Length		Bank Height:	Medium
	Data Armoring:			
5.4	Straightening Length:			
	Straightening Data:			



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
July, 17 2024

Phase 1 - FIT - Legacy Data Report

Ottauquechee - Roaring Brook

SGAT Version: 3

Reach: T6.03-S1.02				<u>Step</u>	<u>Description</u>	<u>Value</u>
	<u>Step</u>	<u>Description</u>	<u>Value</u>	5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
5.2	# of Bridges or Culverts:	0			Berms & Roads:	431.0000
	Total Length:	0.000		6.2	Dev. Length:	331.0000 0.0000
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Corridor Development Data:	
	Data Armoring:	None			<u>Old</u>	<u>New</u>
5.4	Straightening Length:			7.2	Bank Erosion:	None
	Straightening Data:	None			Bank Height:	Low

Phase 1 - FIT - Legacy Data Report

Ottauquechee - Roaring Brook

SGAT Version: 3

Reach: T6.04				<u>Step</u>	<u>Description</u>	<u>Value</u>
	<u>Step</u>	<u>Description</u>	<u>Value</u>	5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
5.2	# of Bridges or Culverts:	0			Berms & Roads:	671.0000
	Total Length:	0.000		6.2	Dev. Length:	1730.0000 215.0000
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Corridor Development Data:	
	Data Armoring:				<u>Old</u>	<u>New</u>
5.4	Straightening Length:	743.00000		7.2	Bank Erosion:	Low 297.5000000
	Straightening Data:				Bank Height:	Medium 5.000



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
July, 17 2024

Phase 1 - FIT - Legacy Data Report

Ottauquechee - Roaring Brook

SGAT Version: 3

Reach: T6.05		<u>Step</u>	<u>Description</u>	<u>Value</u>
	<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None		
3.2	Grade Control:	Ledge		
5.2	# of Bridges or Culverts:	1		
	Total Length:	100.000		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	
	Data Armoring:			
5.4	Straightening Length:			
	Straightening Data:	None		
5.5	Dredging History:			No Data
6.1	Berms & Roads Data:			
		<u>One Side</u>	<u>Both Sides</u>	
	Berms & Roads:	335.0000		
6.2	Dev. Length:	0.0000		43.0000
	Corridor Development Data:			
		<u>Old</u>	<u>New</u>	
7.2	Bank Erosion:	Low		227.0000000
	Bank Height:	Low		3.000

Phase 1 - FIT - Legacy Data Report

Ottauquechee - Roaring Brook

SGAT Version: 3

Reach: T6.06		<u>Step</u>	<u>Description</u>	<u>Value</u>
	<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None		
3.2	Grade Control:	Ledge		
5.2	# of Bridges or Culverts:	2		
	Total Length:	270.000		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	
	Data Armoring:	None		
5.4	Straightening Length:			
	Straightening Data:	None		
5.5	Dredging History:			No Data
6.1	Berms & Roads Data:			
		<u>One Side</u>	<u>Both Sides</u>	
	Berms & Roads:	300.0000		
6.2	Dev. Length:	230.0000		249.0000
	Corridor Development Data:			
		<u>Old</u>	<u>New</u>	
7.2	Bank Erosion:	Low		146.0000000
	Bank Height:	Low		3.000



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
July, 17 2024

Phase 1 - FIT - Legacy Data Report

Ottauquechee - Roaring Brook

SGAT Version: 3

Reach: T6.06-S1.01		<u>Step</u>	<u>Description</u>	<u>Value</u>
		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	6.1	Berms & Roads Data:	
			<u>One Side</u>	<u>Both Sides</u>
3.2	Grade Control:		Berms & Roads:	
		6.2	Dev. Length:	0.0000 66.0000
5.2	# of Bridges or Culverts:		Corridor Development Data:	
	Total Length:		<u>Old</u>	<u>New</u>
5.3	Armoring Length:	7.2	Bank Erosion:	None
			Bank Height:	High
	Data Armoring:			
5.4	Straightening Length:			
	Straightening Data:			

Phase 1 - FIT - Legacy Data Report

Ottauquechee - Roaring Brook

SGAT Version: 3

Reach: T6.06-S1.02		<u>Step</u>	<u>Description</u>	<u>Value</u>
		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	6.1	Berms & Roads Data:	None
			<u>One Side</u>	<u>Both Sides</u>
3.2	Grade Control:		Berms & Roads:	
5.2	# of Bridges or Culverts:	6.2	Dev. Length:	0.0000 0.0000
	Total Length:		Corridor Development Data:	
			<u>Old</u>	<u>New</u>
5.3	Armoring Length:	7.2	Bank Erosion:	None
	Data Armoring:		Bank Height:	Medium
5.4	Straightening Length:			
	Straightening Data:			



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
July, 17 2024

Phase 1 - FIT - Legacy Data Report

Ottauquechee - Roaring Brook

SGAT Version: 3

Reach: T6.07		<u>Step</u>	<u>Description</u>	<u>Value</u>
		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	6.1	Berms & Roads Data:	
			<u>One Side</u>	<u>Both Sides</u>
3.2	Grade Control:		Berms & Roads:	1037.0000
		6.2	Dev. Length:	1475.0000
5.2	# of Bridges or Culverts:		Corridor Development Data:	
			<u>Old</u>	<u>New</u>
	Total Length:	7.2	Bank Erosion:	None
			Bank Height:	0.0000000
5.3	Armoring Length			
	Data Armoring:			
5.4	Straightening Length:			
	Straightening Data:			

Phase 1 - FIT - Legacy Data Report

Ottauquechee - Roaring Brook

SGAT Version: 3

Reach: T6.07-S1.01		<u>Step</u>	<u>Description</u>	<u>Value</u>
		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	6.1	Berms & Roads Data:	None
			<u>One Side</u>	<u>Both Sides</u>
3.2	Grade Control:		Berms & Roads:	
		6.2	Dev. Length:	0.0000
5.2	# of Bridges or Culverts:		Corridor Development Data:	
			<u>Old</u>	<u>New</u>
	Total Length:	7.2	Bank Erosion:	None
			Bank Height:	High
5.3	Armoring Length			
	Data Armoring:			
5.4	Straightening Length:			
	Straightening Data:			



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
July, 17 2024

Phase 1 - FIT - Legacy Data Report

Ottauquechee - Roaring Brook

SGAT Version: 3

Reach: T6.08			<u>Step</u> <u>Description</u> <u>Value</u>		
<u>Step</u>	<u>Description</u>	<u>Value</u>	5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None	6.1	Berms & Roads Data:	
3.2	Grade Control:	Ledge		<u>One Side</u>	<u>Both Sides</u>
5.2	# of Bridges or Culverts:	4		Berms & Roads:	1257.0000
	Total Length:	500.000	6.2	Dev. Length:	400.0000 472.0000
5.3	Armoring Length	<u>Left</u> <u>Right</u>		Corridor Development Data:	
	Data Armoring:			<u>Old</u>	<u>New</u>
5.4	Straightening Length:	479.00000	7.2	Bank Erosion:	Low 108.5000000
	Straightening Data:			Bank Height:	Low 3.500

Phase 1 - FIT - Legacy Data Report

Ottauquechee - Roaring Brook

SGAT Version: 3

Reach: T6.05-S1.01			<u>Step</u> <u>Description</u> <u>Value</u>		
<u>Step</u>	<u>Description</u>	<u>Value</u>	5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None	6.1	Berms & Roads Data:	
3.2	Grade Control:	None		<u>One Side</u>	<u>Both Sides</u>
5.2	# of Bridges or Culverts:	1		Berms & Roads:	245.0000
	Total Length:	100.000	6.2	Dev. Length:	0.0000 89.0000
5.3	Armoring Length	<u>Left</u> <u>Right</u>		Corridor Development Data:	
	Data Armoring:	None		<u>Old</u>	<u>New</u>
5.4	Straightening Length:	56.00000	7.2	Bank Erosion:	None
	Straightening Data:			Bank Height:	Medium



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
July, 17 2024

Phase 1 - FIT - Legacy Data Report

Ottauquechee - Roaring Brook

SGAT Version: 3

Reach: T6.05-S1.02		<u>Step</u>	<u>Description</u>	<u>Value</u>
		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	6.1	Berms & Roads Data:	
			<u>One Side</u>	<u>Both Sides</u>
3.2	Grade Control:		Berms & Roads:	215.0000
			Dev. Length:	925.0000
5.2	# of Bridges or Culverts:	6.2	Corridor Development Data:	0.0000
			<u>Old</u>	<u>New</u>
	Total Length:	7.2	Bank Erosion:	Low
			Bank Height:	Medium
5.3	Armoring Length			
	Data Armoring:			
5.4	Straightening Length:			
	Straightening Data:			