

## Stream Geomorphic Assessment



## **Agency of Natural Resouces**

## FIT Affected Segments Report Keyer Brook

Reach - Segment	Affected by FIT (Feature Indexing Tool)
M01 - 0	No
M04 - 0	No
M02 - A	No
M02 - B	No
M03 - A	No
M03 - B	No
M03 - C	No