



FIT Affected Segments Report

West Branch Little River

Reach - Segment	Affected by FIT (Feature Indexing Tool)
M01 - 0	No
M03 - A	No
M08.S1.03 - A	No
M07.T6.01 - B	No
M08 - C	No
M08 - B	No
M07 - B	No
M07 - E	No
M07.T6.01 - A	No
M08 - A	No
M07 - D	No
M09 - C	No
M07.T5.01.S1.01 - B	No
M08.S1.01 - A	No
M08.S1.01 - B	No
M08.S1.02 - A	No
M08.S1.02 - B	No
M09 - A	No
M07 - C	No
M09.S4.01 - 0	No
M07.T5.01.S1.01 - D	No
M07.T5.01.S1.01 - A	No
M07.T5.01.S1.01 - C	No
M04 - B	No
M07 - A	No
M301 - 0	No
M302 - 0	No
M303 - A	No
M303 - B	No
M304 - A	No
M304 - B	No
M304 - C	No



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov

June, 17 2026

M305 - 0	No
M306 - 0	No
M04 - A	No
M09 - B	No
M07 - F	No
M08.S1.03 - B	No
M05 - 0	No
M06 - 0	No
M02 - 0	No
M03 - B	No