



FIT Affected Segments Report

Mill Brook

| Reach - Segment | Affected by FIT (Feature Indexing Tool) |
|-----------------|---|
| M01 - 0 | No |
| M02 - 0 | No |
| M03 - 0 | No |
| M04 - 0 | No |
| M05 - A | No |
| M05 - B | No |
| M05 - C | No |
| M06 - 0 | No |
| M07 - 0 | No |
| M08 - 0 | No |
| M09 - 0 | No |
| M10 - 0 | No |
| M11 - 0 | No |
| M12 - A | No |
| M12 - B | No |
| M13 - A | No |
| M13 - B | No |
| M13 - C | No |
| M14 - A | No |
| M14 - B | No |
| M15 - 0 | No |