



FIT Affected Segments Report

Laplatte

Reach - Segment	Affected by FIT (Feature Indexing Tool)
T1.08 - 0	No
M03 - 0	No
T1.05 - C	No
T1.02 - A	No
T1.06 - A	No
M09 - B	No
M11 - 0	No
M12S5.01 - B	No
M12S5.01 - C	No
M12S5.01 - D	No
M12S5.01 - E	No
M12S5.01 - F	No
M12S5.01 - G	No
M06S2.01 - A	No
M06S2.01 - B	No
T2.01 - 0	No
T2.02 - A	No
T2.02 - B	No
T1.05 - A	No
T5.01 - E	Yes
T4.06 - 0	Yes
M18 - A	Yes
M12 - 0	Yes
T1.03 - 0	No
T5.01 - A	Yes
M18 - B	Yes
T5.01 - B	Yes
T5.01 - C	Yes
T5.01 - D	Yes
M15S2.01 - 0	Yes
T3.01 - 0	Yes
T3.02 - 0	Yes



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov

April, 10 2026

M13 - 0	Yes
M14 - 0	Yes
M15 - A	Yes
M15 - B	Yes
M16 - 0	Yes
M17 - 0	Yes
T4.01 - 0	Yes
T4.02 - 0	Yes
T4.03 - 0	Yes
T4.04 - 0	Yes
M10 - 0	No
T1.04 - A	No
T1.04 - B	No
T1.07 - B	No
T1.02 - B	No
T1.06 - B	No
T2.03 - A	No
T2.03 - B	No
M13S3.01 - A	No
M13S3.01 - B	No
M12S5.01 - A	No
T1.05 - B	No
M04 - A	No
M04 - B	No
M06 - 0	No
M07 - 0	No
M08 - 0	No
M09 - A	No
T1.07 - A	No