



FIT Affected Segments Report

Gihon

Reach - Segment	Affected by FIT (Feature Indexing Tool)
M17 - B	Yes
M08 - 0	Yes
M16 - A	Yes
M06 - 0	Yes
M07 - 0	Yes
M03 - 0	Yes
M18 - A	Yes
M14 - A	Yes
M16 - B	Yes
M16 - C	Yes
M01 - A	Yes
M01 - B	Yes
M17 - A	Yes
M18 - B	Yes
M14 - B	Yes
M14 - C	Yes
M15 - 0	Yes
M10 - 0	Yes
M11 - A	Yes
M09 - A	Yes
M09 - B	Yes
M13 - A	Yes
M13 - B	Yes
M11 - B	Yes
M12 - 0	Yes
M02 - 0	Yes
M04 - A	Yes
M04 - B	Yes
M05 - 0	Yes