



FIT Affected Segments Report

Clyde

| Reach - Segment | Affected by FIT (Feature Indexing Tool) |
|-----------------|---|
| M20 - 0 | No |
| T6.01 - A | Yes |
| T6.01 - B | Yes |
| T6.03 - 0 | Yes |
| T2.01 - 0 | No |
| T2.03 - A | No |
| T2.03 - B | No |
| T2.03 - C | No |
| M15 - 0 | No |
| M01 - 0 | No |
| T1.11 - A | No |
| T1.11 - B | No |
| T6.02 - 0 | Yes |
| M16 - 0 | Yes |
| T2.02 - 0 | No |
| T2.04 - A | No |
| T2.04 - B | No |
| T2.05 - A | No |
| T2.05 - B | No |
| T1.12 - A | No |
| T1.12 - B | No |
| T1.08 - 0 | No |
| T1.09 - A | No |
| T1.09 - B | No |
| T4.01 - A | Yes |
| T4.01 - B | Yes |
| T5.03 - A | Yes |
| T5.03 - B | Yes |
| T5.03 - C | No |
| T5.03 - D | Yes |
| T5.03 - E | Yes |
| M08 - A | No |



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
March, 26 2026

| | |
|--------------|-----|
| M08 - B | No |
| M15S2.01 - A | Yes |
| M15S2.01 - B | Yes |
| M15S2.01 - C | Yes |