



FIT Affected Segments Report

Clyde

Reach - Segment	Affected by FIT (Feature Indexing Tool)
M15S2.01 - A	Yes
M15 - 0	No
T5.03 - D	Yes
M16 - 0	Yes
T6.01 - A	Yes
T6.01 - B	Yes
T6.03 - 0	Yes
T4.01 - A	Yes
T5.03 - E	Yes
M15S2.01 - C	Yes
T6.02 - 0	Yes
T4.01 - B	Yes
T5.03 - B	Yes
T5.03 - A	Yes
T5.03 - C	No
M15S2.01 - B	Yes
M08 - A	No
M08 - B	No
M01 - 0	No
M20 - 0	No
T2.03 - A	No
T1.11 - B	No
T2.03 - B	No
T2.04 - A	No
T1.08 - 0	No
T2.01 - 0	No
T2.04 - B	No
T1.09 - B	No
T1.12 - A	No
T2.05 - A	No
T1.09 - A	No
T1.12 - B	No



# Stream Geomorphic Assessment

## Agency of Natural Resources

VT DEC

Vermont.gov  
June, 17 2026

T2.02 - 0	No
T2.03 - C	No
T2.05 - B	No
T1.11 - A	No