



FIT Affected Segments Report

West River - Rock River

Reach - Segment	Affected by FIT (Feature Indexing Tool)
T02.04 - 0	Yes
T02.05 - A	Yes
T02.05 - B	Yes
T02.05 - C	Yes
T02.06 - A	Yes
T02.06 - B	Yes
T02.07 - 0	Yes
T02.08 - 0	Yes
T02.09 - 0	Yes
T02.10 - 0	Yes
T02.11 - 0	Yes
T02.12 - 0	Yes
T02.11-S1.01 - A	Yes
T02.11-S1.01 - B	Yes
T02.11-S1.01 - C	Yes
T02.05-S1.01 - 0	Yes
T02.05-S1.02 - 0	Yes
T02.05-S1.03 - 0	Yes
T02.05-S1.04 - 0	Yes
T02.05-S1.05 - 0	Yes
T02.01 - 0	Yes
T02.02 - 0	Yes
T02.03 - 0	Yes
T2.03-S2.01 - 0	Yes
T2.03-S2.02 - 0	Yes