



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
June, 17 2026

Phase 1 - FIT - Legacy Data Report

Foote Brook

SGAT Version: 4.56

Reach: **R13S0301**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		104	98
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	1	
	Total Length:	150.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		483.600	87.6000
		01	0
	Data Armoring:		
5.4	Straightening Length:	543.42999	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	222.6100	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	222.6100	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	208.0100	0.0000
6.4	Miander Migration:	Multiple	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
June, 17 2026

Reach: **R13S0302**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		69	0
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	0	
	Total Length:	0.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		109.790	0.00000
		00	
	Data Armoring:		
5.4	Straightening Length:	33.18000	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	64.4900	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	64.4900	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	58.8800	0.0000
6.4	Miander Migration:	Flood Chute	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000

Reach: **R13S0305**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		0	0
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	0	
	Total Length:	0.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		138.300	0.00000
		00	
	Data Armoring:		
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	0.0000
6.4	Miander Migration:	Flood Chute	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	174.1999969
	Bank Height:	N.D.	5.000



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
June, 17 2026

Reach: **R13S0306**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:		
3.2	Grade Control:		
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
5.1	Flow Regulation - Type:		
	Use:		
5.2	# of Bridges or Culverts:		
	Total Length:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
	Data Armoring:		
5.4	Straightening Length:		
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:		
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:		
	Berm:		
	Path:		
	Road:		
	Railroad:		
6.2	Corridor Development Data:		
	Length:		
6.4	Miander Migration:		
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:		
	Bank Height:		

Reach: **R13S0307**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	Multiple	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		0	0
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	0	
	Total Length:	0.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	248.0100	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	248.0100	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	68.0000	0.0000
6.4	Miander Migration:	Flood Chute	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
June, 17 2026

Reach: **R13S0308**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	Ledge	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		0	0
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	1	
	Total Length:	41.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	287.8200	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	287.8200	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	152.8600	0.0000
6.4	Miander Migration:	<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000

Reach: **R13S0309**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		0	0
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	0	
	Total Length:	0.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	648.0900	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	648.0900	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	0.0000
6.4	Miander Migration:	<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
June, 17 2026

Reach: **R13S0303**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	Ledge	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		0	0
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	0	
	Total Length:	0.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	53.2100
			0
	Data Armoring:		
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	103.7200	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	103.7200	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	0.0000
6.4	Miander Migration:	Flood Chute	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000

Reach: **R13S0304**

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	None	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		0	0
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	0	
	Total Length:	0.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	0.0000	0.0000
6.4	Miander Migration:	Flood Chute	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	None	0.0000000
	Bank Height:	N.D.	0.000