



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Phase 1 - FIT - Legacy Data Report

Elmore Branch

SGAT Version: 4.56

Reach: T01

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	Multiple	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		840	609
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	1	
	Total Length:	130.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		110.140	104.399
		00	99
	Data Armoring:		
5.4	Straightening Length:	428.57001	
	Straightening Data:		

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:		
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	207.3800	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	207.3800	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	413.8000	169.0900
6.4	Miander Migration:	Flood Chute	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	Low	385.9200134
	Bank Height:	Low	3.388

Reach: T02

<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	None	
3.2	Grade Control:	Multiple	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>
		0	0
5.1	Flow Regulation - Type:	None	
	Use:		
5.2	# of Bridges or Culverts:	0	
	Total Length:	0.000	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>
		0.00000	0.00000
	Data Armoring:	None	
5.4	Straightening Length:	0.00000	
	Straightening Data:	None	

<u>Step</u>	<u>Description</u>	<u>Value</u>	
5.5	Dredging History:	None	
6.1	Berms & Roads Data:	None	
		<u>One Side</u>	<u>Both Sides</u>
	Berms & Roads:	0.0000	0.0000
	Berm:	0.0000	0.0000
	Path:	0.000	0.000
	Road:	0.0000	0.00000
	Railroad:	0.0000	0.00
6.2	Corridor Development Data:		
	Length:	112.5900	0.0000
6.4	Miander Migration:	None	
		<u>Old</u>	<u>New</u>
7.2	Bank Erosion:	N.S.	263.3200073
	Bank Height:	Low	4.946



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
May, 20 2024

Reach: T03				<u>Step</u>	<u>Description</u>	<u>Value</u>	
	<u>Step</u>	<u>Description</u>	<u>Value</u>	5.5	Dredging History:	None	
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:		
3.2	Grade Control:	Ledge			<u>One Side</u>	<u>Both Sides</u>	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	940.3200	0.0000	
		0	167	Berm:	0.0000	0.0000	
5.1	Flow Regulation - Type:	None		Path:	0.000	0.000	
	Use:			Road:	940.3200	0.00000	
5.2	# of Bridges or Culverts:	0		Railroad:	0.0000	0.00	
	Total Length:	0.000		6.2	Corridor Development Data:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	97.3700	0.0000	
		0.00000	0.00000	6.4	Miander Migration:	None	
	Data Armoring:	None			<u>Old</u>	<u>New</u>	
5.4	Straightening Length:	0.00000		7.2	Bank Erosion:	None	0.0000000
	Straightening Data:	None			Bank Height:	N.D.	0.000

Reach: T04				<u>Step</u>	<u>Description</u>	<u>Value</u>	
	<u>Step</u>	<u>Description</u>	<u>Value</u>	5.5	Dredging History:	None	
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:		
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	3166.5200	159.3500	
		2767	2967	Berm:	0.0000	0.0000	
5.1	Flow Regulation - Type:	None		Path:	0.000	0.000	
	Use:			Road:	3166.5200	159.35001	
5.2	# of Bridges or Culverts:	1		Railroad:	0.0000	0.00	
	Total Length:	460.000		6.2	Corridor Development Data:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	178.4100	35.0500	
		284.419	554.599	6.4	Miander Migration:	Flood Chute	
		98	98		<u>Old</u>	<u>New</u>	
	Data Armoring:			7.2	Bank Erosion:	N.S.	2421.260009
5.4	Straightening Length:	2981.91992				8	
	Straightening Data:				Bank Height:	Low	3.967



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: T05				<u>Step</u>	<u>Description</u>	<u>Value</u>	
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	None	
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:		
3.2	Grade Control:	Waterfall			<u>One Side</u>	<u>Both Sides</u>	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	985.0300	0.0000	
		279	449	Berm:	0.0000	0.0000	
5.1	Flow Regulation - Type:	None		Path:	0.000	0.000	
	Use:			Road:	985.0300	0.00000	
5.2	# of Bridges or Culverts:	1		Railroad:	0.0000	0.00	
	Total Length:	60.000		6.2	Corridor Development Data:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	63.4600	0.0000	
		245.600	384.130	6.4	Miander Migration:	Flood Chute	
		01	00		<u>Old</u>	<u>New</u>	
	Data Armoring:			7.2	Bank Erosion:	Low	170.3300018
5.4	Straightening Length:	987.19000		Bank Height:	Low	3.000	
	Straightening Data:						

Reach: T06				<u>Step</u>	<u>Description</u>	<u>Value</u>	
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	None	
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:		
3.2	Grade Control:	Ledge			<u>One Side</u>	<u>Both Sides</u>	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	396.3400	0.0000	
		0	135	Berm:	0.0000	0.0000	
5.1	Flow Regulation - Type:	None		Path:	0.000	0.000	
	Use:			Road:	396.3400	0.00000	
5.2	# of Bridges or Culverts:	0		Railroad:	0.0000	0.00	
	Total Length:	0.000		6.2	Corridor Development Data:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	0.0000	0.0000	
		0.00000	0.00000	6.4	Miander Migration:	None	
	Data Armoring:	None			<u>Old</u>	<u>New</u>	
5.4	Straightening Length:	0.00000		7.2	Bank Erosion:	Low	104.5599976
	Straightening Data:	None		Bank Height:	Medium	6.000	



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: T07				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	None
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	Multiple			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	0.0000	0.0000
		0	0	Berm:	0.0000	0.0000
5.1	Flow Regulation - Type:	None		Path:	0.000	0.000
	Use:			Road:	0.0000	0.00000
5.2	# of Bridges or Culverts:	0		Railroad:	0.0000	0.00
	Total Length:	0.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	0.0000	0.0000
		0.00000	0.00000	6.4	Miander Migration:	None
	Data Armoring:	None			<u>Old</u>	<u>New</u>
5.4	Straightening Length:	0.00000		7.2	Bank Erosion:	Low 335.7999878
	Straightening Data:	None			Bank Height:	Low 3.478

Reach: T08				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	None
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	
3.2	Grade Control:	Ledge			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	432.7600	0.0000
		19	267	Berm:	0.0000	0.0000
5.1	Flow Regulation - Type:	None		Path:	0.000	0.000
	Use:			Road:	432.7600	0.00000
5.2	# of Bridges or Culverts:	0		Railroad:	0.0000	0.00
	Total Length:	0.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	0.0000	0.0000
		0.00000	74.1000	6.4	Miander Migration:	Flood Chute
			0		<u>Old</u>	<u>New</u>
	Data Armoring:			7.2	Bank Erosion:	N.S. 669.8800049
5.4	Straightening Length:	168.81000			Bank Height:	Low 3.843
	Straightening Data:					



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: T09				<u>Step</u>	<u>Description</u>	<u>Value</u>	
	<u>Step</u>	<u>Description</u>	<u>Value</u>	5.5	Dredging History:	None	
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:		
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	442.7700	0.0000	
		189	162	Berm:	0.0000	0.0000	
5.1	Flow Regulation - Type:	None		Path:	0.000	0.000	
	Use:			Road:	442.7700	0.00000	
5.2	# of Bridges or Culverts:	1		Railroad:	0.0000	0.00	
	Total Length:	100.000		6.2	Corridor Development Data:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	0.0000	92.7800	
		0.00000	94.2100	6.4	Miander Migration:	None	
			0		<u>Old</u>	<u>New</u>	
	Data Armoring:			7.2	Bank Erosion:	Low	181.3499908
5.4	Straightening Length:	344.09000		Bank Height:	Medium	5.000	
	Straightening Data:						

Reach: T09.01				<u>Step</u>	<u>Description</u>	<u>Value</u>	
	<u>Step</u>	<u>Description</u>	<u>Value</u>	5.5	Dredging History:	None	
3.1	Alluvial Fan:	Yes		6.1	Berms & Roads Data:	None	
3.2	Grade Control:	Multiple			<u>One Side</u>	<u>Both Sides</u>	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:			
		602	579	Berm:			
5.1	Flow Regulation - Type:	None		Path:			
	Use:			Road:			
5.2	# of Bridges or Culverts:	1		Railroad:			
	Total Length:	147.000		6.2	Corridor Development Data:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	0.0000	44.0000	
				6.4	Miander Migration:	None	
	Data Armoring:	None			<u>Old</u>	<u>New</u>	
5.4	Straightening Length:			7.2	Bank Erosion:	None	
	Straightening Data:	None		Bank Height:	N.D.		



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: T09.02				<u>Step</u>	<u>Description</u>	<u>Value</u>
	<u>Step</u>	<u>Description</u>	<u>Value</u>	5.5	Dredging History:	None
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	Multiple			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		76	76		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	1			Railroad:	
	Total Length:	390.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 77.0000
	Data Armoring:	None		6.4	Miander Migration:	None
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	None		7.2	Bank Erosion:	None
					Bank Height:	N.D.

Reach: T09.03				<u>Step</u>	<u>Description</u>	<u>Value</u>
	<u>Step</u>	<u>Description</u>	<u>Value</u>	5.5	Dredging History:	None
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	Ledge			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		0	0		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	0			Railroad:	
	Total Length:	0.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	None		6.4	Miander Migration:	None
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	None		7.2	Bank Erosion:	None
					Bank Height:	N.D.



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
May, 20 2024

Reach: T09.04				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	None
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	Ledge			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		0	0		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	0			Railroad:	
	Total Length:	0.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	None		6.4	Miander Migration:	None
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	None		7.2	Bank Erosion:	None
					Bank Height:	N.D.

Reach: T09.05				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	None
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		0	0		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	0			Railroad:	
	Total Length:	0.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	None		6.4	Miander Migration:	None
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	None		7.2	Bank Erosion:	None
					Bank Height:	N.D.



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: T09.06				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	None
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		0	0		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	0			Railroad:	
	Total Length:	0.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	None		6.4	Miander Migration:	None
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	None		7.2	Bank Erosion:	None
					Bank Height:	N.D.

Reach: T09.07				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	None
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		184	336		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	1			Railroad:	
	Total Length:	406.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 204.0000
	Data Armoring:	None		6.4	Miander Migration:	None
5.4	Straightening Length:	288.15900			<u>Old</u>	<u>New</u>
	Straightening Data:			7.2	Bank Erosion:	None
					Bank Height:	N.D.



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: T10				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	None
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	
3.2	Grade Control:	Ledge			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	1635.2900	0.0000
		909	721	Berm:	0.0000	0.0000
5.1	Flow Regulation - Type:	None		Path:	0.000	0.000
	Use:			Road:	1635.2900	0.00000
5.2	# of Bridges or Culverts:	0		Railroad:	0.0000	0.00
	Total Length:	0.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	1250.1700	0.0000
		52.8600	272.549	6.4	Miander Migration:	Flood Chute
		0	99		<u>Old</u>	<u>New</u>
	Data Armoring:			7.2	Bank Erosion:	N.S.
5.4	Straightening Length:	333.45001				1503.489990
	Straightening Data:					2
				Bank Height:	Medium	5.055

Reach: T11				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	None
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	
3.2	Grade Control:	Multiple			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	694.9660	
		1314	1502	Berm:		
5.1	Flow Regulation - Type:	None		Path:		
	Use:			Road:		
5.2	# of Bridges or Culverts:	0		Railroad:		
	Total Length:	0.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	0.0000	0.0000
				6.4	Miander Migration:	Avulsion
	Data Armoring:	None			<u>Old</u>	<u>New</u>
5.4	Straightening Length:	273.29599		7.2	Bank Erosion:	None
	Straightening Data:				Bank Height:	N.D.



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
May, 20 2024

Reach: T12				<u>Step</u>	<u>Description</u>	<u>Value</u>
	<u>Step</u>	<u>Description</u>	<u>Value</u>	5.5	Dredging History:	None
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	
3.2	Grade Control:	Ledge			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	556.8030
		476	1409		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	0			Railroad:	
	Total Length:	0.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	None		6.4	Miander Migration:	None
5.4	Straightening Length:	126.36500			<u>Old</u>	<u>New</u>
	Straightening Data:			7.2	Bank Erosion:	None
					Bank Height:	N.D.

Reach: T13				<u>Step</u>	<u>Description</u>	<u>Value</u>
	<u>Step</u>	<u>Description</u>	<u>Value</u>	5.5	Dredging History:	None
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	2010.6420
		0	899		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	2			Railroad:	
	Total Length:	546.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 133.0000
	Data Armoring:			6.4	Miander Migration:	None
5.4	Straightening Length:	734.40198			<u>Old</u>	<u>New</u>
	Straightening Data:			7.2	Bank Erosion:	None
					Bank Height:	N.D.



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: T14				<u>Step</u>	<u>Description</u>	<u>Value</u>
	<u>Step</u>	<u>Description</u>	<u>Value</u>	5.5	Dredging History:	None
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	
3.2	Grade Control:	Ledge			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	1824.9709
		257	55		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	1			Railroad:	
	Total Length:	268.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 147.0000
	Data Armoring:	None		6.4	Miander Migration:	None
5.4	Straightening Length:	234.53500			<u>Old</u>	<u>New</u>
	Straightening Data:			7.2	Bank Erosion:	None
					Bank Height:	N.D.

Reach: T15				<u>Step</u>	<u>Description</u>	<u>Value</u>
	<u>Step</u>	<u>Description</u>	<u>Value</u>	5.5	Dredging History:	None
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	935.3380
		198	544		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	1			Railroad:	
	Total Length:	152.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 45.0000
	Data Armoring:	None		6.4	Miander Migration:	Avulsion
5.4	Straightening Length:	79.33300			<u>Old</u>	<u>New</u>
	Straightening Data:			7.2	Bank Erosion:	None
					Bank Height:	N.D.



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
May, 20 2024

Reach: T16				<u>Step</u>	<u>Description</u>	<u>Value</u>
	<u>Step</u>	<u>Description</u>	<u>Value</u>	5.5	Dredging History:	None
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	416.3020
		62	157		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	1			Railroad:	
	Total Length:	138.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 104.0000
	Data Armoring:	None		6.4	Miander Migration:	None
5.4	Straightening Length:	313.94800			<u>Old</u>	<u>New</u>
	Straightening Data:			7.2	Bank Erosion:	None
					Bank Height:	N.D.

Reach: T17				<u>Step</u>	<u>Description</u>	<u>Value</u>
	<u>Step</u>	<u>Description</u>	<u>Value</u>	5.5	Dredging History:	None
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	
3.2	Grade Control:	Ledge			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	1216.1060
		390	0		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	0			Railroad:	
	Total Length:	0.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	None		6.4	Miander Migration:	None
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	None		7.2	Bank Erosion:	None
					Bank Height:	N.D.



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
May, 20 2024

Reach: T18				<u>Step</u>	<u>Description</u>	<u>Value</u>
	<u>Step</u>	<u>Description</u>	<u>Value</u>	5.5	Dredging History:	None
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	
3.2	Grade Control:	Ledge			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	969.5410
		929	1474		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	1			Railroad:	
	Total Length:	142.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 166.0000
	Data Armoring:	None		6.4	Miander Migration:	None
5.4	Straightening Length:	236.50999			<u>Old</u>	<u>New</u>
	Straightening Data:			7.2	Bank Erosion:	None
					Bank Height:	N.D.

Reach: T19				<u>Step</u>	<u>Description</u>	<u>Value</u>
	<u>Step</u>	<u>Description</u>	<u>Value</u>	5.5	Dredging History:	None
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		0	0		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	1			Railroad:	
	Total Length:	146.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	None		6.4	Miander Migration:	None
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	None		7.2	Bank Erosion:	None
					Bank Height:	N.D.