



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: M02				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	None
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	0.0000	0.0000
		0	0	Berm:	0.0000	0.0000
5.1	Flow Regulation - Type:	None		Path:	0.000	0.000
	Use:			Road:	0.0000	0.00000
5.2	# of Bridges or Culverts:	1		Railroad:	0.0000	0.00
	Total Length:	31.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	0.0000	0.0000
		36.6600	143.179	6.4	Miander Migration:	Multiple
		0	99		<u>Old</u>	<u>New</u>
	Data Armoring:			7.2	Bank Erosion:	None
5.4	Straightening Length:	1021.82996				1990.719970
	Straightening Data:					7
				Bank Height:	N.D.	4.879

Reach: M03				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	None
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	
3.2	Grade Control:	Multiple			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	0.0000	0.0000
		0	0	Berm:	0.0000	0.0000
5.1	Flow Regulation - Type:	None		Path:	0.000	0.000
	Use:			Road:	0.0000	0.00000
5.2	# of Bridges or Culverts:	1		Railroad:	0.0000	0.00
	Total Length:	112.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	0.0000	0.0000
		86.5700	89.9700	6.4	Miander Migration:	Flood Chute
		0	0		<u>Old</u>	<u>New</u>
	Data Armoring:			7.2	Bank Erosion:	None
5.4	Straightening Length:	0.00000				69.4800034
	Straightening Data:	None		Bank Height:	N.D.	5.000



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: M04				<u>Step</u>	<u>Description</u>	<u>Value</u>	
	<u>Step</u>	<u>Description</u>	<u>Value</u>	5.5	Dredging History:	None	
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:		
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	0.0000	0.0000	
		0	0	Berm:	0.0000	0.0000	
5.1	Flow Regulation - Type:	None		Path:	0.000	0.000	
	Use:			Road:	0.0000	0.00000	
5.2	# of Bridges or Culverts:	0		Railroad:	0.0000	0.00	
	Total Length:	0.000		6.2	Corridor Development Data:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	0.0000	0.0000	
		0.00000	0.00000	6.4	Miander Migration:	Flood Chute	
	Data Armoring:	None			<u>Old</u>	<u>New</u>	
5.4	Straightening Length:	0.00000		7.2	Bank Erosion:	None	274.0100098
	Straightening Data:	None			Bank Height:	N.D.	3.000

Reach: M05				<u>Step</u>	<u>Description</u>	<u>Value</u>	
	<u>Step</u>	<u>Description</u>	<u>Value</u>	5.5	Dredging History:	None	
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:		
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	0.0000	0.0000	
		0	0	Berm:	0.0000	0.0000	
5.1	Flow Regulation - Type:	None		Path:	0.000	0.000	
	Use:			Road:	0.0000	0.00000	
5.2	# of Bridges or Culverts:	1		Railroad:	0.0000	0.00	
	Total Length:	95.000		6.2	Corridor Development Data:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	138.4400	0.0000	
		55.6500	27.1900	6.4	Miander Migration:	Flood Chute	
		0	0		<u>Old</u>	<u>New</u>	
	Data Armoring:			7.2	Bank Erosion:	None	180.9299927
5.4	Straightening Length:	0.00000			Bank Height:	N.D.	2.987
	Straightening Data:	None					



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
May, 20 2024

Reach: M06				<u>Step</u>	<u>Description</u>	<u>Value</u>	
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	None	
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:		
3.2	Grade Control:	None				<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	0.0000	0.0000	
		0	0	Berm:	0.0000	0.0000	
5.1	Flow Regulation - Type:	None		Path:	0.000	0.000	
	Use:			Road:	0.0000	0.00000	
5.2	# of Bridges or Culverts:	0		Railroad:	0.0000	0.00	
	Total Length:	0.000		6.2	Corridor Development Data:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	0.0000	0.0000	
		0.00000	0.00000	6.4	Miander Migration:	Flood Chute	
	Data Armoring:	None				<u>Old</u>	<u>New</u>
5.4	Straightening Length:	0.00000		7.2	Bank Erosion:	None	146.0199890
	Straightening Data:	None			Bank Height:	N.D.	3.000

Reach: M07				<u>Step</u>	<u>Description</u>	<u>Value</u>	
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	None	
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:		
3.2	Grade Control:	None				<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	537.1600	0.0000	
		99	0	Berm:	0.0000	0.0000	
5.1	Flow Regulation - Type:	None		Path:	0.000	0.000	
	Use:			Road:	537.1600	0.00000	
5.2	# of Bridges or Culverts:	2		Railroad:	0.0000	0.00	
	Total Length:	100.000		6.2	Corridor Development Data:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	0.0000	0.0000	
		181.390	172.539	6.4	Miander Migration:		
		00	99			<u>Old</u>	<u>New</u>
	Data Armoring:			7.2	Bank Erosion:	None	695.3900146
5.4	Straightening Length:	2167.39990			Bank Height:	N.D.	3.939
	Straightening Data:						



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: M08				<u>Step</u>	<u>Description</u>	<u>Value</u>	
	<u>Step</u>	<u>Description</u>	<u>Value</u>	5.5	Dredging History:	None	
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:		
3.2	Grade Control:	Ledge			<u>One Side</u>	<u>Both Sides</u>	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	100.5500	0.0000	
		194	95	Berm:	0.0000	0.0000	
5.1	Flow Regulation - Type:	None		Path:	0.000	0.000	
	Use:			Road:	100.5500	0.00000	
5.2	# of Bridges or Culverts:	1		Railroad:	0.0000	0.00	
	Total Length:	45.000		6.2	Corridor Development Data:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	0.0000	0.0000	
		85.4800	82.7800	6.4	Miander Migration:		
		0	0		<u>Old</u>	<u>New</u>	
	Data Armoring:			7.2	Bank Erosion:	None	489.8500061
5.4	Straightening Length:	0.00000		Bank Height:	N.D.	4.699	
	Straightening Data:	None					

Reach: M09				<u>Step</u>	<u>Description</u>	<u>Value</u>	
	<u>Step</u>	<u>Description</u>	<u>Value</u>	5.5	Dredging History:	None	
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:		
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	0.0000	0.0000	
		0	0	Berm:	0.0000	0.0000	
5.1	Flow Regulation - Type:	None		Path:	0.000	0.000	
	Use:			Road:	0.0000	0.00000	
5.2	# of Bridges or Culverts:	0		Railroad:	0.0000	0.00	
	Total Length:	0.000		6.2	Corridor Development Data:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	0.0000	0.0000	
		0.00000	0.00000	6.4	Miander Migration:	Multiple	
	Data Armoring:	None			<u>Old</u>	<u>New</u>	
5.4	Straightening Length:	0.00000		7.2	Bank Erosion:	None	561.9400024
	Straightening Data:	None		Bank Height:	N.D.	3.376	



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: M10				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	None
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	0.0000	0.0000
		474	0	Berm:	0.0000	0.0000
5.1	Flow Regulation - Type:	None		Path:	0.000	0.000
	Use:			Road:	0.0000	0.00000
5.2	# of Bridges or Culverts:	1		Railroad:	0.0000	0.00
	Total Length:	30.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	184.4000	0.0000
		289.010	20.5800	6.4	Miander Migration:	Migration
		01	0		<u>Old</u>	<u>New</u>
	Data Armoring:			7.2	Bank Erosion:	None
5.4	Straightening Length:	467.01001				1421.839965
						8
	Straightening Data:			Bank Height:	N.D.	4.760

Reach: M11				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	None
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	0.0000	0.0000
		0	0	Berm:	0.0000	0.0000
5.1	Flow Regulation - Type:	None		Path:	0.000	0.000
	Use:			Road:	0.0000	0.00000
5.2	# of Bridges or Culverts:	1		Railroad:	0.0000	0.00
	Total Length:	22.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	0.0000	0.0000
		0.00000	0.00000	6.4	Miander Migration:	Neck Cutoff
	Data Armoring:	None			<u>Old</u>	<u>New</u>
5.4	Straightening Length:	0.00000		7.2	Bank Erosion:	None
						467.7099915
	Straightening Data:	None		Bank Height:	N.D.	5.039



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: M12				<u>Step</u>	<u>Description</u>	<u>Value</u>	
	<u>Step</u>	<u>Description</u>	<u>Value</u>	5.5	Dredging History:	None	
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:		
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	0.0000	0.0000	
		332	0	Berm:	0.0000	0.0000	
5.1	Flow Regulation - Type:	None		Path:	0.000	0.000	
	Use:			Road:	0.0000	0.00000	
5.2	# of Bridges or Culverts:	0		Railroad:	0.0000	0.00	
	Total Length:	0.000		6.2	Corridor Development Data:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	0.0000	0.0000	
		0.00000	0.00000	6.4	Miander Migration:		
	Data Armoring:	None			<u>Old</u>	<u>New</u>	
5.4	Straightening Length:	0.00000		7.2	Bank Erosion:	None	0.0000000
	Straightening Data:	None		Bank Height:	N.D.	0.000	

Reach: M13				<u>Step</u>	<u>Description</u>	<u>Value</u>	
	<u>Step</u>	<u>Description</u>	<u>Value</u>	5.5	Dredging History:	None	
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:		
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	0.0000	0.0000	
		214	0	Berm:	0.0000	0.0000	
5.1	Flow Regulation - Type:	None		Path:	0.000	0.000	
	Use:			Road:	0.0000	0.00000	
5.2	# of Bridges or Culverts:	1		Railroad:	0.0000	0.00	
	Total Length:	28.000		6.2	Corridor Development Data:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	0.0000	0.0000	
		0.00000	0.00000	6.4	Miander Migration:		
	Data Armoring:	None			<u>Old</u>	<u>New</u>	
5.4	Straightening Length:	0.00000		7.2	Bank Erosion:	None	0.0000000
	Straightening Data:	None		Bank Height:	N.D.	0.000	



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: M14				<u>Step</u>	<u>Description</u>	<u>Value</u>	
	<u>Step</u>	<u>Description</u>	<u>Value</u>	5.5	Dredging History:	None	
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:		
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	0.0000	0.0000	
		272	1620	Berm:	0.0000	0.0000	
5.1	Flow Regulation - Type:	None		Path:	0.000	0.000	
	Use:			Road:	0.0000	0.00000	
5.2	# of Bridges or Culverts:	0		Railroad:	0.0000	0.00	
	Total Length:	0.000		6.2	Corridor Development Data:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	0.0000	0.0000	
		0.00000	0.00000	6.4	Miander Migration:		
	Data Armoring:	None			<u>Old</u>	<u>New</u>	
5.4	Straightening Length:	0.00000		7.2	Bank Erosion:	None	0.0000000
	Straightening Data:	None		Bank Height:	N.D.	0.000	

Reach: M15				<u>Step</u>	<u>Description</u>	<u>Value</u>	
	<u>Step</u>	<u>Description</u>	<u>Value</u>	5.5	Dredging History:	None	
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:		
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	0.0000	0.0000	
		751	604	Berm:	0.0000	0.0000	
5.1	Flow Regulation - Type:	None		Path:	0.000	0.000	
	Use:			Road:	0.0000	0.00000	
5.2	# of Bridges or Culverts:	0		Railroad:	0.0000	0.00	
	Total Length:	0.000		6.2	Corridor Development Data:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	0.0000	0.0000	
		0.00000	0.00000	6.4	Miander Migration:		
	Data Armoring:	None			<u>Old</u>	<u>New</u>	
5.4	Straightening Length:	0.00000		7.2	Bank Erosion:	None	0.0000000
	Straightening Data:	None		Bank Height:	N.D.	0.000	



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
May, 20 2024

Reach: M18				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	None
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
					Berm:	
5.1	Flow Regulation - Type:				Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:				Railroad:	
	Total Length:			6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	
	Data Armoring:	None		6.4	Miander Migration:	
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	None		7.2	Bank Erosion:	
					Bank Height:	

Reach: T8.01				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	None
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	0.0000
		3353	3467		Berm:	0.0000
5.1	Flow Regulation - Type:	Large Run of River			Path:	0.000
	Use:	Other			Road:	0.0000
5.2	# of Bridges or Culverts:	0			Railroad:	0.0000
	Total Length:	0.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000
		0.00000	0.00000	6.4	Miander Migration:	Migration
	Data Armoring:	None			<u>Old</u>	<u>New</u>
5.4	Straightening Length:	9674.04980		7.2	Bank Erosion:	None
	Straightening Data:				Bank Height:	0.0000000
						N.D.
						0.000



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: M19				<u>Step</u>	<u>Description</u>	<u>Value</u>	
	<u>Step</u>	<u>Description</u>	<u>Value</u>	5.5	Dredging History:	None	
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:		
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	0.0000	0.0000	
		1886	1895	Berm:	0.0000	0.0000	
5.1	Flow Regulation - Type:	None		Path:	0.000	0.000	
	Use:			Road:	0.0000	0.00000	
5.2	# of Bridges or Culverts:	0		Railroad:	0.0000	0.00	
	Total Length:	0.000		6.2	Corridor Development Data:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	0.0000	0.0000	
		0.00000	0.00000	6.4	Miander Migration:	Avulsion	
	Data Armoring:	None			<u>Old</u>	<u>New</u>	
5.4	Straightening Length:	1402.14990		7.2	Bank Erosion:	None	0.0000000
	Straightening Data:			Bank Height:	N.D.	0.000	

Reach: M20				<u>Step</u>	<u>Description</u>	<u>Value</u>	
	<u>Step</u>	<u>Description</u>	<u>Value</u>	5.5	Dredging History:	None	
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:		
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	85.4700	0.0000	
		524	623	Berm:	85.4700	0.0000	
5.1	Flow Regulation - Type:	None		Path:	0.000	0.000	
	Use:			Road:	0.0000	0.00000	
5.2	# of Bridges or Culverts:	4		Railroad:	0.0000	0.00	
	Total Length:	185.000		6.2	Corridor Development Data:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	0.0000	0.0000	
		0.00000	0.00000	6.4	Miander Migration:		
	Data Armoring:	None			<u>Old</u>	<u>New</u>	
5.4	Straightening Length:	2725.43994		7.2	Bank Erosion:	None	0.0000000
	Straightening Data:			Bank Height:	N.D.	0.000	



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: M21				<u>Step</u>	<u>Description</u>	<u>Value</u>	
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	None	
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:		
3.2	Grade Control:	None				<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	0.0000	0.0000	
		1833	1690	Berm:	0.0000	0.0000	
5.1	Flow Regulation - Type:	Large Run of River		Path:	0.000	0.000	
	Use:	Other		Road:	0.0000	0.00000	
5.2	# of Bridges or Culverts:	6		Railroad:	0.0000	0.00	
	Total Length:	164.000		6.2	Corridor Development Data:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	0.0000	949.3600	
		0.00000	0.00000	6.4	Miander Migration:		
	Data Armoring:	None				<u>Old</u>	<u>New</u>
5.4	Straightening Length:	7496.08984		7.2	Bank Erosion:	None	0.0000000
	Straightening Data:				Bank Height:	N.D.	0.000

Reach: T9.01				<u>Step</u>	<u>Description</u>	<u>Value</u>	
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	None	
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:		
3.2	Grade Control:	None				<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	0.0000	0.0000	
		2224	2036	Berm:	0.0000	0.0000	
5.1	Flow Regulation - Type:	Large Run of River		Path:	0.000	0.000	
	Use:	Other		Road:	0.0000	0.00000	
5.2	# of Bridges or Culverts:	3		Railroad:	0.0000	0.00	
	Total Length:	195.000		6.2	Corridor Development Data:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	862.4300	0.0000	
		0.00000	0.00000	6.4	Miander Migration:		
	Data Armoring:	None				<u>Old</u>	<u>New</u>
5.4	Straightening Length:	5256.18994		7.2	Bank Erosion:	None	0.0000000
	Straightening Data:				Bank Height:	N.D.	0.000



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: T7.01-S1.01				<u>Step</u>	<u>Description</u>	<u>Value</u>	
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	None	
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:		
3.2	Grade Control:	None				<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	0.0000	0.0000	
		443	0	Berm:	0.0000	0.0000	
5.1	Flow Regulation - Type:	None		Path:	0.000	0.000	
	Use:			Road:	0.0000	0.00000	
5.2	# of Bridges or Culverts:	1		Railroad:	0.0000	0.00	
	Total Length:	45.000		6.2	Corridor Development Data:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	0.0000	71.0500	
		0.00000	0.00000	6.4	Miander Migration:		
	Data Armoring:	None				<u>Old</u>	<u>New</u>
5.4	Straightening Length:	1652.51001		7.2	Bank Erosion:	None	0.0000000
	Straightening Data:				Bank Height:	N.D.	0.000

Reach: T7.01-S1.02				<u>Step</u>	<u>Description</u>	<u>Value</u>	
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	None	
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:		
3.2	Grade Control:	None				<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	0.0000	0.0000	
		501	1605	Berm:	0.0000	0.0000	
5.1	Flow Regulation - Type:	Large Run of River		Path:	0.000	0.000	
	Use:	Other		Road:	0.0000	0.00000	
5.2	# of Bridges or Culverts:	4		Railroad:	0.0000	0.00	
	Total Length:	130.000		6.2	Corridor Development Data:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	669.5900	260.0000	
		0.00000	0.00000	6.4	Miander Migration:		
	Data Armoring:	None				<u>Old</u>	<u>New</u>
5.4	Straightening Length:	5025.39990		7.2	Bank Erosion:	None	0.0000000
	Straightening Data:				Bank Height:	N.D.	0.000



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: T7.02				<u>Step</u>	<u>Description</u>	<u>Value</u>	
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	None	
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:		
3.2	Grade Control:	None				<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	0.0000	0.0000	
		0	0	Berm:	0.0000	0.0000	
5.1	Flow Regulation - Type:	None		Path:	0.000	0.000	
	Use:			Road:	0.0000	0.00000	
5.2	# of Bridges or Culverts:	1		Railroad:	0.0000	0.00	
	Total Length:	42.000		6.2	Corridor Development Data:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	0.0000	0.0000	
		0.00000	0.00000	6.4	Miander Migration:		
	Data Armoring:	None				<u>Old</u>	<u>New</u>
5.4	Straightening Length:	1134.17004		7.2	Bank Erosion:	None	0.0000000
	Straightening Data:				Bank Height:	N.D.	0.000

Reach: T7.03				<u>Step</u>	<u>Description</u>	<u>Value</u>	
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	None	
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:		
3.2	Grade Control:	None				<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	0.0000	0.0000	
		1548	1556	Berm:	0.0000	0.0000	
5.1	Flow Regulation - Type:	None		Path:	0.000	0.000	
	Use:			Road:	0.0000	0.00000	
5.2	# of Bridges or Culverts:	0		Railroad:	0.0000	0.00	
	Total Length:	0.000		6.2	Corridor Development Data:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	0.0000	0.0000	
		0.00000	0.00000	6.4	Miander Migration:		
	Data Armoring:	None				<u>Old</u>	<u>New</u>
5.4	Straightening Length:	1992.14001		7.2	Bank Erosion:	None	0.0000000
	Straightening Data:				Bank Height:	N.D.	0.000



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: T6.02				<u>Step</u>	<u>Description</u>	<u>Value</u>	
	<u>Step</u>	<u>Description</u>	<u>Value</u>	5.5	Dredging History:	None	
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:		
3.2	Grade Control:	None				<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	0.0000	0.0000	
		2348	1724	Berm:	0.0000	0.0000	
5.1	Flow Regulation - Type:	None		Path:	0.000	0.000	
	Use:			Road:	0.0000	0.00000	
5.2	# of Bridges or Culverts:	1		Railroad:	0.0000	0.00	
	Total Length:	60.000		6.2	Corridor Development Data:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	0.0000	0.0000	
		0.00000	0.00000	6.4	Miander Migration:		
	Data Armoring:	None				<u>Old</u>	<u>New</u>
5.4	Straightening Length:	1752.30005		7.2	Bank Erosion:	None	0.0000000
	Straightening Data:				Bank Height:	N.D.	0.000

Reach: T4.01				<u>Step</u>	<u>Description</u>	<u>Value</u>	
	<u>Step</u>	<u>Description</u>	<u>Value</u>	5.5	Dredging History:	None	
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:		
3.2	Grade Control:	None				<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	0.0000	0.0000	
		1103	943	Berm:	0.0000	0.0000	
5.1	Flow Regulation - Type:	None		Path:	0.000	0.000	
	Use:			Road:	0.0000	0.00000	
5.2	# of Bridges or Culverts:	3		Railroad:	0.0000	0.00	
	Total Length:	127.000		6.2	Corridor Development Data:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	163.1200	0.0000	
		0.00000	0.00000	6.4	Miander Migration:		
	Data Armoring:	None				<u>Old</u>	<u>New</u>
5.4	Straightening Length:	907.65997		7.2	Bank Erosion:	None	0.0000000
	Straightening Data:				Bank Height:	N.D.	0.000



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: T3.01				<u>Step</u>	<u>Description</u>	<u>Value</u>	
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	None	
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:		
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	884.0300	0.0000	
		146	0	Berm:	0.0000	0.0000	
5.1	Flow Regulation - Type:	None		Path:	0.000	0.000	
	Use:			Road:	884.0300	0.00000	
5.2	# of Bridges or Culverts:	3		Railroad:	0.0000	0.00	
	Total Length:	155.000		6.2	Corridor Development Data:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	274.6700	0.0000	
		97.8300	96.3000	6.4	Miander Migration:	Multiple	
		0	0		<u>Old</u>	<u>New</u>	
	Data Armoring:			7.2	Bank Erosion:	None	629.4299927
5.4	Straightening Length:	2365.62988		Bank Height:	N.D.	4.781	
	Straightening Data:						

Reach: T3.01-S1.01				<u>Step</u>	<u>Description</u>	<u>Value</u>	
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	None	
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:		
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	539.5000	0.0000	
		817	990	Berm:	0.0000	0.0000	
5.1	Flow Regulation - Type:	None		Path:	0.000	0.000	
	Use:			Road:	539.5000	0.00000	
5.2	# of Bridges or Culverts:	3		Railroad:	0.0000	0.00	
	Total Length:	135.000		6.2	Corridor Development Data:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	0.0000	0.0000	
		0.00000	0.00000	6.4	Miander Migration:		
	Data Armoring:	None			<u>Old</u>	<u>New</u>	
5.4	Straightening Length:	1822.07996		7.2	Bank Erosion:	None	0.0000000
	Straightening Data:			Bank Height:	N.D.	0.000	



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
May, 20 2024

Reach: T3.02				<u>Step</u>	<u>Description</u>	<u>Value</u>	
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	None	
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:		
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	1128.8199	914.0200	
		1875	1171	Berm:	548.7000	0.0000	
5.1	Flow Regulation - Type:	None		Path:	0.000	0.000	
	Use:			Road:	580.1200	914.02002	
5.2	# of Bridges or Culverts:	6		Railroad:	0.0000	0.00	
	Total Length:	505.000		6.2	Corridor Development Data:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	2481.0601	0.0000	
		58.0100	37.6800	6.4	Miander Migration:	Multiple	
		0	0		<u>Old</u>	<u>New</u>	
	Data Armoring:			7.2	Bank Erosion:	None	462.1400146
5.4	Straightening Length:	3010.52002		Bank Height:	N.D.	2.983	
	Straightening Data:						

Reach: T3.01-S2.01				<u>Step</u>	<u>Description</u>	<u>Value</u>	
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	None	
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:		
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	357.7900	0.0000	
		0	0	Berm:	0.0000	0.0000	
5.1	Flow Regulation - Type:	None		Path:	0.000	0.000	
	Use:			Road:	357.7900	0.00000	
5.2	# of Bridges or Culverts:	1		Railroad:	0.0000	0.00	
	Total Length:	105.000		6.2	Corridor Development Data:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	1499.8101	0.0000	
		0.00000	0.00000	6.4	Miander Migration:		
	Data Armoring:	None			<u>Old</u>	<u>New</u>	
5.4	Straightening Length:	0.00000		7.2	Bank Erosion:	None	0.0000000
	Straightening Data:	None		Bank Height:	N.D.	0.000	



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: T2.01				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	None
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	0.0000	0.0000
		0	0	Berm:	0.0000	0.0000
5.1	Flow Regulation - Type:	None		Path:	0.000	0.000
	Use:			Road:	0.0000	0.00000
5.2	# of Bridges or Culverts:	3		Railroad:	0.0000	0.00
	Total Length:	159.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	0.0000	0.0000
		112.130	114.620	6.4	Miander Migration:	
		00	00		<u>Old</u>	<u>New</u>
	Data Armoring:			7.2	Bank Erosion:	None 293.3399963
5.4	Straightening Length:	192.53000		Bank Height:	N.D.	1.810
	Straightening Data:					