



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Phase 1 - FIT - Legacy Data Report

Huntington River

SGAT Version: 4.56

Reach: **T8.09**

<u>Step</u>	<u>Description</u>	<u>Value</u>
3.1	Alluvial Fan:	None
3.2	Grade Control:	None
4.3	Buffer Less Than 25 ft	<u>Left</u> <u>Right</u> 228 114
5.1	Flow Regulation - Type:	None
	Use:	
5.2	# of Bridges or Culverts:	1
	Total Length:	64.200
5.3	Armoring Length	<u>Left</u> <u>Right</u>
	Data Armoring:	No Data
5.4	Straightening Length:	
	Straightening Data:	N.D.

<u>Step</u>	<u>Description</u>	<u>Value</u>
5.5	Dredging History:	No Data
6.1	Berms & Roads Data:	None
		<u>One Side</u> <u>Both Sides</u>
	Berms & Roads:	
	Berm:	
	Path:	
	Road:	
	Railroad:	
6.2	Corridor Development Data:	
	Length:	0.0000 0.0000
6.4	Miander Migration:	No Data
		<u>Old</u> <u>New</u>
7.2	Bank Erosion:	N.E.
	Bank Height:	N.E.

Reach: **M03**

<u>Step</u>	<u>Description</u>	<u>Value</u>
3.1	Alluvial Fan:	None
3.2	Grade Control:	Ledge
4.3	Buffer Less Than 25 ft	<u>Left</u> <u>Right</u> 0 118
5.1	Flow Regulation - Type:	None
	Use:	
5.2	# of Bridges or Culverts:	0
	Total Length:	0.000
5.3	Armoring Length	<u>Left</u> <u>Right</u> 0.00000 0.00000
	Data Armoring:	None
5.4	Straightening Length:	0.00000
	Straightening Data:	None

<u>Step</u>	<u>Description</u>	<u>Value</u>
5.5	Dredging History:	No Data
6.1	Berms & Roads Data:	
		<u>One Side</u> <u>Both Sides</u>
	Berms & Roads:	990.0300 0.0000
	Berm:	0.0000 0.0000
	Path:	0.000 0.000
	Road:	990.0300 0.00000
	Railroad:	0.0000 0.00
6.2	Corridor Development Data:	
	Length:	553.3300 0.0000
6.4	Miander Migration:	Flood Chute
		<u>Old</u> <u>New</u>
7.2	Bank Erosion:	None 274.3200073
	Bank Height:	N.D. 10.741



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: T3.01				<u>Step</u>	<u>Description</u>	<u>Value</u>	
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data	
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None	
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:		
		238	0		Berm:		
5.1	Flow Regulation - Type:	None			Path:		
	Use:				Road:		
5.2	# of Bridges or Culverts:	2			Railroad:		
	Total Length:	191.000		6.2	Corridor Development Data:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000	0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data	
5.4	Straightening Length:				<u>Old</u>	<u>New</u>	
	Straightening Data:	N.D.		7.2	Bank Erosion:	Low	
					Bank Height:	N.E.	

Reach: M01				<u>Step</u>	<u>Description</u>	<u>Value</u>	
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data	
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:		
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	1375.3999	0.0000
		673	1383		Berm:	0.0000	0.0000
5.1	Flow Regulation - Type:	None			Path:	0.000	0.000
	Use:				Road:	1375.3999	0.00000
5.2	# of Bridges or Culverts:	1			Railroad:	0.0000	0.00
	Total Length:	160.000		6.2	Corridor Development Data:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	2024.9301	167.6000
		527.440	412.620	6.4	Miander Migration:	Flood Chute	
		00	00		<u>Old</u>	<u>New</u>	
	Data Armoring:			7.2	Bank Erosion:	None	1173.770019
5.4	Straightening Length:	0.00000				5	
	Straightening Data:	None			Bank Height:	N.D.	6.565



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: M02				<u>Step</u>	<u>Description</u>	<u>Value</u>	
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data	
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:		
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	1484.2600	0.0000	
		0	0	Berm:	0.0000	0.0000	
5.1	Flow Regulation - Type:	None		Path:	0.000	0.000	
	Use:			Road:	1484.2600	0.00000	
5.2	# of Bridges or Culverts:	0		Railroad:	0.0000	0.00	
	Total Length:	0.000		6.2	Corridor Development Data:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	267.4200	0.0000	
		0.00000	0.00000	6.4	Miander Migration:	None	
	Data Armoring:	None			<u>Old</u>	<u>New</u>	
5.4	Straightening Length:	0.00000		7.2	Bank Erosion:	None	157.3399963
	Straightening Data:	None			Bank Height:	N.D.	18.728

Reach: T8.06				<u>Step</u>	<u>Description</u>	<u>Value</u>	
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data	
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None	
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:			
		383	383	Berm:			
5.1	Flow Regulation - Type:	None		Path:			
	Use:			Road:			
5.2	# of Bridges or Culverts:	1		Railroad:			
	Total Length:	88.300		6.2	Corridor Development Data:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	0.0000	0.0000	
				6.4	Miander Migration:	No Data	
	Data Armoring:	No Data			<u>Old</u>	<u>New</u>	
5.4	Straightening Length:			7.2	Bank Erosion:	N.E.	
	Straightening Data:	N.D.			Bank Height:	N.E.	



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: T8.S11.01				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		1088	1088		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	2			Railroad:	
	Total Length:	227.200		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	73.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.

Reach: T8.07				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		588	980		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	0			Railroad:	
	Total Length:	0.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: T8.08				<u>Step</u>	<u>Description</u>	<u>Value</u>
	<u>Step</u>	<u>Description</u>	<u>Value</u>	5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		1373	1177		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	1			Railroad:	
	Total Length:	126.200		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.

Reach: T8.S12.01				<u>Step</u>	<u>Description</u>	<u>Value</u>
	<u>Step</u>	<u>Description</u>	<u>Value</u>	5.5	Dredging History:	No Data
3.1	Alluvial Fan:	Yes		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		1340	1005		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	0			Railroad:	
	Total Length:	0.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: T8.S10.01				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		895	1119		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	1			Railroad:	
	Total Length:	203.800		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.

Reach: T12.04				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	1723.0000
		325	325		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	2			Railroad:	
	Total Length:	225.700		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: T12.05				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	695.0000
		94	0		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	0			Railroad:	
	Total Length:	0.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.

Reach: T12.S7.01				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		475	475		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	1			Railroad:	
	Total Length:	276.500		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: T16.03				<u>Step</u>	<u>Description</u>	<u>Value</u>
	<u>Step</u>	<u>Description</u>	<u>Value</u>	5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		294	294		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	1			Railroad:	
	Total Length:	419.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	145.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.

Reach: T16.04				<u>Step</u>	<u>Description</u>	<u>Value</u>
	<u>Step</u>	<u>Description</u>	<u>Value</u>	5.5	Dredging History:	No Data
3.1	Alluvial Fan:	Yes		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		509	764		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	2			Railroad:	
	Total Length:	646.700		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: T16.S10.01				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	Yes		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		0	0		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	1			Railroad:	
	Total Length:	301.800		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	None
					Bank Height:	N.E.

Reach: T16.05				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	1573.0000
		389	389		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	2			Railroad:	
	Total Length:	645.500		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	90.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	Low
					Bank Height:	N.E.



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: T16.06				<u>Step</u>	<u>Description</u>	<u>Value</u>
	<u>Step</u>	<u>Description</u>	<u>Value</u>	5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		889	222		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	3			Railroad:	
	Total Length:	260.800		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.

Reach: T16.07				<u>Step</u>	<u>Description</u>	<u>Value</u>
	<u>Step</u>	<u>Description</u>	<u>Value</u>	5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		1518	1349		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	2			Railroad:	
	Total Length:	257.800		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: T16.S8.01				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	Yes		6.1	Berms & Roads Data:	
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	695.0000
		919	919		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	1			Railroad:	
	Total Length:	179.800		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.

Reach: T16.S6.01				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		0	0		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	0			Railroad:	
	Total Length:	0.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	648.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: M04				<u>Step</u>	<u>Description</u>	<u>Value</u>	
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data	
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:		
3.2	Grade Control:	Ledge			<u>One Side</u>	<u>Both Sides</u>	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	3735.7200	0.0000	
		2137	0	Berm:	0.0000	0.0000	
5.1	Flow Regulation - Type:	None		Path:	0.000	0.000	
	Use:			Road:	3735.7200	0.00000	
5.2	# of Bridges or Culverts:	0		Railroad:	0.0000	0.00	
	Total Length:	0.000		6.2	Corridor Development Data:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	1328.7400	0.0000	
		0.00000	0.00000	6.4	Miander Migration:	None	
	Data Armoring:	None			<u>Old</u>	<u>New</u>	
5.4	Straightening Length:	0.00000		7.2	Bank Erosion:	None	143.9799957
	Straightening Data:	None			Bank Height:	N.D.	4.986

Reach: M05				<u>Step</u>	<u>Description</u>	<u>Value</u>	
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data	
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:		
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	2417.5300	0.0000	
		2157	1116	Berm:	0.0000	0.0000	
5.1	Flow Regulation - Type:	None		Path:	0.000	0.000	
	Use:			Road:	2417.5300	0.00000	
5.2	# of Bridges or Culverts:	0		Railroad:	0.0000	0.00	
	Total Length:	0.000		6.2	Corridor Development Data:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	141.5500	0.0000	
		1419.87	0.00000	6.4	Miander Migration:	Flood Chute	
	Data Armoring:				<u>Old</u>	<u>New</u>	
5.4	Straightening Length:	0.00000		7.2	Bank Erosion:	None	205.2299957
	Straightening Data:	None			Bank Height:	N.D.	11.411



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: T8.01				<u>Step</u>	<u>Description</u>	<u>Value</u>
	<u>Step</u>	<u>Description</u>	<u>Value</u>	5.5	Dredging History:	No Data
3.1	Alluvial Fan:	Yes		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		181	363		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	1			Railroad:	
	Total Length:	292.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	204.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.

Reach: T8.S1.01				<u>Step</u>	<u>Description</u>	<u>Value</u>
	<u>Step</u>	<u>Description</u>	<u>Value</u>	5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		0	0		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	0			Railroad:	
	Total Length:	0.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: T8.02				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		0	0		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	0			Railroad:	
	Total Length:	0.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.

Reach: T8.03				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		687	0		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	1			Railroad:	
	Total Length:	144.700		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: T8.S4.01				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		1347	1077		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	1			Railroad:	
	Total Length:	278.400		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	354.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.

Reach: T8.04				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	Yes		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		2333	823		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	1			Railroad:	
	Total Length:	213.900		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
May, 20 2024

Reach: T8.05				<u>Step</u>	<u>Description</u>	<u>Value</u>
	<u>Step</u>	<u>Description</u>	<u>Value</u>	5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		1717	1717		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	0			Railroad:	
	Total Length:	0.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.

Reach: T8.S8.01				<u>Step</u>	<u>Description</u>	<u>Value</u>
	<u>Step</u>	<u>Description</u>	<u>Value</u>	5.5	Dredging History:	No Data
3.1	Alluvial Fan:	Yes		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		351	351		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	0			Railroad:	
	Total Length:	0.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: T8.S5.01				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	Yes		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		297	297		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	1			Railroad:	
	Total Length:	171.300		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.

Reach: M06				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	None
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	Ledge			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	0.0000 0.0000
		0	0		Berm:	0.0000 0.0000
5.1	Flow Regulation - Type:	None			Path:	0.000 0.000
	Use:				Road:	0.0000 0.00000
5.2	# of Bridges or Culverts:	1			Railroad:	0.0000 0.00
	Total Length:	750.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
		955.909 97	318.539 98	6.4	Miander Migration:	Flood Chute
	Data Armoring:				<u>Old</u>	<u>New</u>
5.4	Straightening Length:	0.00000		7.2	Bank Erosion:	None 765.5700073
	Straightening Data:	None			Bank Height:	N.D. 0.000



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: T12.01				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	Yes		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		0	0		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	0			Railroad:	
	Total Length:	0.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.

Reach: T12.02				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		0	0		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	0			Railroad:	
	Total Length:	0.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: T12.03				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		4393	3844		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	2			Railroad:	
	Total Length:	270.400		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	149.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	Migration
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.

Reach: M07				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	None
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	341.3800 0.0000
		0	0		Berm:	0.0000 0.0000
5.1	Flow Regulation - Type:	None			Path:	0.000 0.000
	Use:				Road:	341.3800 0.00000
5.2	# of Bridges or Culverts:	1			Railroad:	0.0000 0.00
	Total Length:	300.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
		174.110 00	592.079 96	6.4	Miander Migration:	Flood Chute
	Data Armoring:				<u>Old</u>	<u>New</u>
5.4	Straightening Length:	0.00000		7.2	Bank Erosion:	None 563.7799683
	Straightening Data:	None			Bank Height:	N.D. 0.000



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: M08				<u>Step</u>	<u>Description</u>	<u>Value</u>	
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	None	
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:		
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	95.8800	0.0000	
		0	0	Berm:	0.0000	0.0000	
5.1	Flow Regulation - Type:	None		Path:	0.000	0.000	
	Use:			Road:	95.8800	0.00000	
5.2	# of Bridges or Culverts:	0		Railroad:	0.0000	0.00	
	Total Length:	0.000		6.2	Corridor Development Data:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	1185.3301	0.0000	
		309.019	43.3500	6.4	Miander Migration:	Migration	
		99	0		<u>Old</u>	<u>New</u>	
	Data Armoring:			7.2	Bank Erosion:	None	432.7699890
5.4	Straightening Length:	0.00000			Bank Height:	N.D.	0.000
	Straightening Data:	None					

Reach: T16.01				<u>Step</u>	<u>Description</u>	<u>Value</u>	
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data	
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None	
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	0.0000	0.0000	
		549	286	Berm:	0.0000	0.0000	
5.1	Flow Regulation - Type:	None		Path:	0.000	0.000	
	Use:			Road:	0.0000	0.00000	
5.2	# of Bridges or Culverts:	1		Railroad:	0.0000	0.00	
	Total Length:	150.000		6.2	Corridor Development Data:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	564.6200	351.4900	
		390.840	135.459	6.4	Miander Migration:	Multiple	
		00	99		<u>Old</u>	<u>New</u>	
	Data Armoring:			7.2	Bank Erosion:	None	1472.140014
5.4	Straightening Length:	394.47000				6	
	Straightening Data:				Bank Height:	N.D.	4.906



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: T16.02				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	Yes		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		1240	413		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	1			Railroad:	
	Total Length:	277.900		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	501.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.

Reach: M09				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	None
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	1302.1901 0.0000
		0	0		Berm:	0.0000 0.0000
5.1	Flow Regulation - Type:	None			Path:	0.000 0.000
	Use:				Road:	1302.1901 0.00000
5.2	# of Bridges or Culverts:	1			Railroad:	0.0000 0.00
	Total Length:	540.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	1564.4600 0.0000
		841.549 99	77.4800 0	6.4	Miander Migration:	Multiple
	Data Armoring:				<u>Old</u>	<u>New</u>
5.4	Straightening Length:	0.00000		7.2	Bank Erosion:	None 2303.100097 7
	Straightening Data:	None			Bank Height:	N.D. 0.000



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
May, 20 2024

Reach: T13.01				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	Yes		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		0	0		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	1			Railroad:	
	Total Length:	107.800		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.

Reach: T13.02				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		0	0		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	0			Railroad:	
	Total Length:	0.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: T13.03				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	Yes		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		1016	1016		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	0			Railroad:	
	Total Length:	0.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.

Reach: T5.01				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	Yes		6.1	Berms & Roads Data:	None
3.2	Grade Control:	Dam			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		0	0		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	0			Railroad:	
	Total Length:	0.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	None
					Bank Height:	N.E.



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
May, 20 2024

Reach: T5.02				<u>Step</u>	<u>Description</u>	<u>Value</u>	
	<u>Step</u>	<u>Description</u>	<u>Value</u>	5.5	Dredging History:	No Data	
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None	
3.2	Grade Control:	Dam			<u>One Side</u>	<u>Both Sides</u>	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:			
		2330	0		Berm:		
5.1	Flow Regulation - Type:				Path:		
	Use:				Road:		
5.2	# of Bridges or Culverts:	1			Railroad:		
	Total Length:	90.500		6.2	Corridor Development Data:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000	0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data	
5.4	Straightening Length:				<u>Old</u>	<u>New</u>	
	Straightening Data:	N.D.		7.2	Bank Erosion:	None	
					Bank Height:	N.E.	

Reach: T5.03				<u>Step</u>	<u>Description</u>	<u>Value</u>	
	<u>Step</u>	<u>Description</u>	<u>Value</u>	5.5	Dredging History:	No Data	
3.1	Alluvial Fan:	Yes		6.1	Berms & Roads Data:	None	
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:			
		0	0		Berm:		
5.1	Flow Regulation - Type:	None			Path:		
	Use:				Road:		
5.2	# of Bridges or Culverts:	0			Railroad:		
	Total Length:	0.000		6.2	Corridor Development Data:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000	0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data	
5.4	Straightening Length:				<u>Old</u>	<u>New</u>	
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.	
					Bank Height:	N.E.	



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
May, 20 2024

Reach: T5.04				<u>Step</u>	<u>Description</u>	<u>Value</u>
	<u>Step</u>	<u>Description</u>	<u>Value</u>	5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		233	934		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	2			Railroad:	
	Total Length:	375.900		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	424.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	Low
					Bank Height:	N.E.

Reach: T5.05				<u>Step</u>	<u>Description</u>	<u>Value</u>
	<u>Step</u>	<u>Description</u>	<u>Value</u>	5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	Ledge			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		0	433		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	1			Railroad:	
	Total Length:	147.300		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	120.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
May, 20 2024

Reach: T5.S4.01				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		286	573		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	1			Railroad:	
	Total Length:	121.700		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.

Reach: T5.06				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		327	327		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	0			Railroad:	
	Total Length:	0.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	82.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
May, 20 2024

Reach: T5.S6.01				<u>Step</u>	<u>Description</u>	<u>Value</u>
	<u>Step</u>	<u>Description</u>	<u>Value</u>	5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		153	153		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	1			Railroad:	
	Total Length:	57.800		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.

Reach: T3.S1.01				<u>Step</u>	<u>Description</u>	<u>Value</u>
	<u>Step</u>	<u>Description</u>	<u>Value</u>	5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		0	0		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	1			Railroad:	
	Total Length:	99.400		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	None
					Bank Height:	N.E.



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: T3.02				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		0	663		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	0			Railroad:	
	Total Length:	0.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	193.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	None
					Bank Height:	N.E.

Reach: T23.04				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	Yes		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		274	548		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	0			Railroad:	
	Total Length:	0.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: M10				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	None
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	218.8100	0.0000
		0	0	Berm:	0.0000	0.0000
5.1	Flow Regulation - Type:	None		Path:	0.000	0.000
	Use:			Road:	218.8100	0.00000
5.2	# of Bridges or Culverts:	1		Railroad:	0.0000	0.00
	Total Length:	720.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	1710.4200	1971.4399
		670.420	0.00000	6.4	Miander Migration:	Flood Chute
		04			<u>Old</u>	<u>New</u>
	Data Armoring:			7.2	Bank Erosion:	None
5.4	Straightening Length:	0.00000				1615.320068
						4
	Straightening Data:	None		Bank Height:	N.D.	0.000

Reach: M11				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	None
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	0.0000	0.0000
		0	0	Berm:	0.0000	0.0000
5.1	Flow Regulation - Type:	None		Path:	0.000	0.000
	Use:			Road:	0.0000	0.00000
5.2	# of Bridges or Culverts:	0		Railroad:	0.0000	0.00
	Total Length:	0.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	345.0600	0.0000
		0.00000	0.00000	6.4	Miander Migration:	Flood Chute
	Data Armoring:	None			<u>Old</u>	<u>New</u>
5.4	Straightening Length:	0.00000		7.2	Bank Erosion:	None
						722.6400146
	Straightening Data:	None		Bank Height:	N.D.	0.000



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: T23.01				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		968	968		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	1			Railroad:	
	Total Length:	135.100		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	Migration
5.4	Straightening Length:	505.00000			<u>Old</u>	<u>New</u>
	Straightening Data:			7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.

Reach: T23.S1.01				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	Yes		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		307	615		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	1			Railroad:	
	Total Length:	130.800		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	154.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
May, 20 2024

Reach: T23.02				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		1458	1093		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	0			Railroad:	
	Total Length:	0.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	Migration
5.4	Straightening Length:	1205.00000			<u>Old</u>	<u>New</u>
	Straightening Data:			7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.

Reach: T23.S2.01				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		543	135		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	1			Railroad:	
	Total Length:	211.700		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	596.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: T23.03				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	Yes		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		661	2865		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	4			Railroad:	
	Total Length:	1405.100		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	278.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:	2213.00000			<u>Old</u>	<u>New</u>
	Straightening Data:			7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.

Reach: M12				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	None
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	
3.2	Grade Control:	Ledge			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	1475.4301 0.0000
		0	0		Berm:	0.0000 0.0000
5.1	Flow Regulation - Type:	None			Path:	0.000 0.000
	Use:				Road:	1475.4301 0.00000
5.2	# of Bridges or Culverts:	2			Railroad:	0.0000 0.00
	Total Length:	730.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	143.6100 0.0000
		385.179 99	1646.40 002	6.4	Miander Migration:	Migration
	Data Armoring:				<u>Old</u>	<u>New</u>
5.4	Straightening Length:	901.35999		7.2	Bank Erosion:	None 0.0000000
	Straightening Data:				Bank Height:	N.D. 0.000



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: T22.01				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	Multiple			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	0.0000	0.0000
		0	210	Berm:	0.0000	0.0000
5.1	Flow Regulation - Type:	None		Path:	0.000	0.000
	Use:			Road:	0.0000	0.00000
5.2	# of Bridges or Culverts:	0		Railroad:	0.0000	0.00
	Total Length:	0.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	778.5200	0.0000
		0.00000	0.00000	6.4	Miander Migration:	Flood Chute
	Data Armoring:	None			<u>Old</u>	<u>New</u>
5.4	Straightening Length:	0.00000		7.2	Bank Erosion:	None 319.1799927
	Straightening Data:	None			Bank Height:	N.D. 2.763

Reach: T22.02				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	Ledge			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	0.0000	0.0000
		457	527	Berm:	0.0000	0.0000
5.1	Flow Regulation - Type:	None		Path:	0.000	0.000
	Use:			Road:	0.0000	0.00000
5.2	# of Bridges or Culverts:	3		Railroad:	0.0000	0.00
	Total Length:	83.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	673.2400	0.0000
		216.460	80.0400	6.4	Miander Migration:	Flood Chute
		01	0		<u>Old</u>	<u>New</u>
	Data Armoring:			7.2	Bank Erosion:	None 426.2500000
5.4	Straightening Length:	0.00000			Bank Height:	N.D. 2.404
	Straightening Data:	None				



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
May, 20 2024

Reach: T22.03				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		0	0		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	0			Railroad:	
	Total Length:	0.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.

Reach: T22.04				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		0	0		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	2			Railroad:	
	Total Length:	189.200		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
May, 20 2024

Reach: T22.S4.01				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		1611	805		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	1			Railroad:	
	Total Length:	119.100		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.

Reach: T26.S10.01				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		0	0		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	0			Railroad:	
	Total Length:	0.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: T26.05				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		0	0		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	0			Railroad:	
	Total Length:	0.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.

Reach: M13				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	None
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	1000.7400 0.0000
		0	0		Berm:	0.0000 0.0000
5.1	Flow Regulation - Type:	None			Path:	0.000 0.000
	Use:				Road:	1000.7400 0.00000
5.2	# of Bridges or Culverts:	1			Railroad:	0.0000 0.00
	Total Length:	300.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	333.2100 365.4400
		850.549 99	140.509 99	6.4	Miander Migration:	Flood Chute
	Data Armoring:				<u>Old</u>	<u>New</u>
5.4	Straightening Length:	3998.36987		7.2	Bank Erosion:	None 361.1999817
	Straightening Data:				Bank Height:	N.D. 0.000



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: T30.01				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	Yes		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		723	723		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	0			Railroad:	
	Total Length:	0.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	High
					Bank Height:	N.E.

Reach: T30.S1.01				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	Yes		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		1456	1456		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	2			Railroad:	
	Total Length:	230.100		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
May, 20 2024

Reach: T30.02				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	Yes		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		437	0		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	0			Railroad:	
	Total Length:	0.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.

Reach: T30.03				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		0	0		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	1			Railroad:	
	Total Length:	132.200		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	117.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
May, 20 2024

Reach: T30.04				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		0	0		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	0			Railroad:	
	Total Length:	0.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.

Reach: T30.S4.01				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		927	927		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	1			Railroad:	
	Total Length:	102.700		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: T30.05				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	Ledge			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		204	204		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	1			Railroad:	
	Total Length:	347.300		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	Low
					Bank Height:	N.E.

Reach: T30.S6.01				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		0	0		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	1			Railroad:	
	Total Length:	407.700		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: T30.06				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		0	0		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	1			Railroad:	
	Total Length:	94.900		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.

Reach: T30.S7.01				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		0	0		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	0			Railroad:	
	Total Length:	0.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: T30.07				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		0	0		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	0			Railroad:	
	Total Length:	0.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.

Reach: T30.S3.01				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		0	0		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	0			Railroad:	
	Total Length:	0.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: M14				<u>Step</u>	<u>Description</u>	<u>Value</u>	
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	None	
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:		
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	671.6400	0.0000	
		0	0	Berm:	671.6400	0.0000	
5.1	Flow Regulation - Type:	None		Path:	0.000	0.000	
	Use:			Road:	0.0000	0.00000	
5.2	# of Bridges or Culverts:	0		Railroad:	0.0000	0.00	
	Total Length:	0.000		6.2	Corridor Development Data:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	0.0000	0.0000	
		0.00000	28.5600	6.4	Miander Migration:	Flood Chute	
			0		<u>Old</u>	<u>New</u>	
	Data Armoring:			7.2	Bank Erosion:	None	719.6099854
5.4	Straightening Length:	1162.77002		Bank Height:	N.D.	1.705	
	Straightening Data:						

Reach: M15				<u>Step</u>	<u>Description</u>	<u>Value</u>	
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	None	
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:		
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	515.8400	0.0000	
		0	0	Berm:	0.0000	0.0000	
5.1	Flow Regulation - Type:	None		Path:	0.000	0.000	
	Use:			Road:	515.8400	0.00000	
5.2	# of Bridges or Culverts:	1		Railroad:	0.0000	0.00	
	Total Length:	350.000		6.2	Corridor Development Data:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	283.9900	0.0000	
		339.979	43.3400	6.4	Miander Migration:	Flood Chute	
		98	0		<u>Old</u>	<u>New</u>	
	Data Armoring:			7.2	Bank Erosion:	None	0.0000000
5.4	Straightening Length:	0.00000		Bank Height:	N.D.	0.000	
	Straightening Data:	None					



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: T33.01				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	Yes		6.1	Berms & Roads Data:	
3.2	Grade Control:	Ledge			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	409.0000
		523	523		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	2			Railroad:	
	Total Length:	461.800		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	None
					Bank Height:	N.E.

Reach: T26.01				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	
3.2	Grade Control:	Ledge			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	380.3800 0.0000
		673	1805		Berm:	0.0000 0.0000
5.1	Flow Regulation - Type:	None			Path:	0.000 0.000
	Use:				Road:	380.3800 0.00000
5.2	# of Bridges or Culverts:	4			Railroad:	0.0000 0.00
	Total Length:	695.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
		200.370 00	359.260 01	6.4	Miander Migration:	Multiple
	Data Armoring:				<u>Old</u>	<u>New</u>
5.4	Straightening Length:	625.42999		7.2	Bank Erosion:	None 703.5800171
	Straightening Data:				Bank Height:	N.D. 5.862



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: T33.02				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		0	0		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	0			Railroad:	
	Total Length:	0.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.

Reach: T33.03				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		0	0		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	1			Railroad:	
	Total Length:	236.200		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: T33.04				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		0	0		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	0			Railroad:	
	Total Length:	0.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.

Reach: T33.S5.01				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	Ledge			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		0	0		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	0			Railroad:	
	Total Length:	0.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: T33.05				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		0	0		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	0			Railroad:	
	Total Length:	0.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.

Reach: T33.S3.01				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		0	0		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	0			Railroad:	
	Total Length:	0.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: T33.S1.01				<u>Step</u>	<u>Description</u>	<u>Value</u>	
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data	
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None	
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:		
		0	0		Berm:		
5.1	Flow Regulation - Type:	None			Path:		
	Use:				Road:		
5.2	# of Bridges or Culverts:	1			Railroad:		
	Total Length:	141.600		6.2	Corridor Development Data:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000	0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data	
5.4	Straightening Length:				<u>Old</u>	<u>New</u>	
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.	
					Bank Height:	N.E.	

Reach: T26.02				<u>Step</u>	<u>Description</u>	<u>Value</u>	
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data	
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:		
3.2	Grade Control:	Ledge			<u>One Side</u>	<u>Both Sides</u>	
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	1841.6599	0.0000
		615	516		Berm:	0.0000	0.0000
5.1	Flow Regulation - Type:	None			Path:	0.000	0.000
	Use:				Road:	1841.6599	0.00000
5.2	# of Bridges or Culverts:	2			Railroad:	0.0000	0.00
	Total Length:	72.000		6.2	Corridor Development Data:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	1288.2100	0.0000
		24.0300	40.0600	6.4	Miander Migration:	Flood Chute	
		0	0		<u>Old</u>	<u>New</u>	
	Data Armoring:			7.2	Bank Erosion:	None	276.8500061
5.4	Straightening Length:	0.00000			Bank Height:	N.D.	7.296
	Straightening Data:	None					



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: T26.S5.01				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		0	0		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	0			Railroad:	
	Total Length:	0.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.

Reach: T26.03				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	698.0000
		0	0		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	2			Railroad:	
	Total Length:	158.600		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
May, 20 2024

Reach: T26.S8.01				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		0	0		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	0			Railroad:	
	Total Length:	0.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.

Reach: T26.04				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		0	0		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	0			Railroad:	
	Total Length:	0.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: T26.S2.01				<u>Step</u>	<u>Description</u>	<u>Value</u>	
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data	
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None	
3.2	Grade Control:	None				<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:		
		0	0		Berm:		
5.1	Flow Regulation - Type:	None			Path:		
	Use:				Road:		
5.2	# of Bridges or Culverts:	0			Railroad:		
	Total Length:	0.000		6.2	Corridor Development Data:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000	0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data	
5.4	Straightening Length:					<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.	
					Bank Height:	N.E.	

Reach: M16				<u>Step</u>	<u>Description</u>	<u>Value</u>	
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data	
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:		
3.2	Grade Control:	None				<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	2122.8301	0.0000
		1906	727		Berm:	0.0000	0.0000
5.1	Flow Regulation - Type:	None			Path:	0.000	0.000
	Use:				Road:	2122.8301	0.00000
5.2	# of Bridges or Culverts:	0			Railroad:	0.0000	0.00
	Total Length:	0.000		6.2	Corridor Development Data:		
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	797.6300	0.0000
	Data Armoring:	443.390	0.00000	6.4	Miander Migration:	Flood Chute	
		01				<u>Old</u>	<u>New</u>
5.4	Straightening Length:	0.00000		7.2	Bank Erosion:	None	180.6699982
	Straightening Data:	None			Bank Height:	N.D.	6.000



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: M17				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History: No Data	
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	
3.2	Grade Control:	Multiple			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	3058.0300	314.7900
		2438	834	Berm:	0.0000	0.0000
5.1	Flow Regulation - Type:	None		Path:	0.000	0.000
	Use:			Road:	3058.0300	314.79001
5.2	# of Bridges or Culverts:	2		Railroad:	0.0000	0.00
	Total Length:	400.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	733.2800	100.7000
		740.299	0.00000	6.4	Miander Migration: None	
		99			<u>Old</u>	<u>New</u>
	Data Armoring:			7.2	Bank Erosion:	None 131.9799957
5.4	Straightening Length:	0.00000		Bank Height:	N.D.	7.000
	Straightening Data:	None				

Reach: M18				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	Ledge				<u>One Side</u> <u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	0.0000	0.0000
		337	361	Berm:	0.0000	0.0000
5.1	Flow Regulation - Type:	None		Path:	0.000	0.000
	Use:			Road:	0.0000	0.00000
5.2	# of Bridges or Culverts:	0		Railroad:	0.0000	0.00
	Total Length:	0.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	483.5500	61.4300
		95.2100	256.149	6.4	Miander Migration:	Multiple
		0	99			<u>Old</u> <u>New</u>
	Data Armoring:			7.2	Bank Erosion:	None 272.2000122
5.4	Straightening Length:	0.00000		Bank Height:	N.D.	4.243
	Straightening Data:	None				



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: M19				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	0.0000	0.0000
		0	0	Berm:	0.0000	0.0000
5.1	Flow Regulation - Type:	None		Path:	0.000	0.000
	Use:			Road:	0.0000	0.00000
5.2	# of Bridges or Culverts:	1		Railroad:	0.0000	0.00
	Total Length:	50.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	0.0000	0.0000
		0.00000	0.00000	6.4	Miander Migration:	No Data
	Data Armoring:	None			<u>Old</u>	<u>New</u>
5.4	Straightening Length:	0.00000		7.2	Bank Erosion:	None 0.0000000
	Straightening Data:	None			Bank Height:	N.D. 0.000

Reach: M20				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	0.0000	0.0000
		0	0	Berm:	0.0000	0.0000
5.1	Flow Regulation - Type:	None		Path:	0.000	0.000
	Use:			Road:	0.0000	0.00000
5.2	# of Bridges or Culverts:	1		Railroad:	0.0000	0.00
	Total Length:	50.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	0.0000	0.0000
		0.00000	0.00000	6.4	Miander Migration:	Migration
	Data Armoring:	None			<u>Old</u>	<u>New</u>
5.4	Straightening Length:	0.00000		7.2	Bank Erosion:	None 0.0000000
	Straightening Data:	None			Bank Height:	N.D. 0.000



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: T36.01				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		219	0		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	0			Railroad:	
	Total Length:	0.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.

Reach: T36.02				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		394	394		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	1			Railroad:	
	Total Length:	181.800		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	354.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: T36.S1.01				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		0	0		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	0			Railroad:	
	Total Length:	0.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.

Reach: T36.03				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		0	0		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	0			Railroad:	
	Total Length:	0.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	361.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: M21				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	0.0000	0.0000
		0	0	Berm:	0.0000	0.0000
5.1	Flow Regulation - Type:	None		Path:	0.000	0.000
	Use:			Road:	0.0000	0.00000
5.2	# of Bridges or Culverts:	3		Railroad:	0.0000	0.00
	Total Length:	360.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	0.0000	0.0000
		0.00000	0.00000	6.4	Miander Migration:	None
	Data Armoring:	None			<u>Old</u>	<u>New</u>
5.4	Straightening Length:	0.00000		7.2	Bank Erosion:	None 0.0000000
	Straightening Data:	None			Bank Height:	N.D. 0.000

Reach: M22				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	Yes		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:		
		0	0	Berm:		
5.1	Flow Regulation - Type:	None		Path:		
	Use:			Road:		
5.2	# of Bridges or Culverts:	1		Railroad:		
	Total Length:	132.700		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	1123.0000	0.0000
				6.4	Miander Migration:	Migration
	Data Armoring:				<u>Old</u>	<u>New</u>
5.4	Straightening Length:			7.2	Bank Erosion:	Low
	Straightening Data:	N.D.			Bank Height:	N.E.



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: T53.01				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	Yes		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		0	0		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	0			Railroad:	
	Total Length:	0.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.

Reach: T48.01				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		52	0		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	1			Railroad:	
	Total Length:	416.400		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
May, 20 2024

Reach: T48.02				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	
3.2	Grade Control:	Ledge			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	2740.0000
		340	340		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	1			Railroad:	
	Total Length:	246.700		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	2921.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.

Reach: T48.03				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		148	148		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	1			Railroad:	
	Total Length:	257.100		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: T48.S1.01				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		0	0		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	1			Railroad:	
	Total Length:	83.800		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.

Reach: M23				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	No Data
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	
		0	0		Berm:	
5.1	Flow Regulation - Type:	None			Path:	
	Use:				Road:	
5.2	# of Bridges or Culverts:	0			Railroad:	
	Total Length:	0.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000 0.0000
	Data Armoring:	No Data		6.4	Miander Migration:	No Data
5.4	Straightening Length:				<u>Old</u>	<u>New</u>
	Straightening Data:	N.D.		7.2	Bank Erosion:	N.E.
					Bank Height:	N.E.