



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Phase 1 - FIT - Legacy Data Report

Otter Creek - Cold River

SGAT Version: 4.56

Reach: M01

<u>Step</u>	<u>Description</u>	<u>Value</u>		<u>Step</u>	<u>Description</u>	<u>Value</u>	
3.1	Alluvial Fan:	Yes		5.5	Dredging History:	Multiple	
3.2	Grade Control:	None		6.1	Berms & Roads Data:		
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>			<u>One Side</u>	<u>Both Sides</u>
		3209	1849		Berms & Roads:	3906.6802	1475.9301
5.1	Flow Regulation - Type:	Small Withdrawal			Berm:	2906.1602	1475.9301
	Use:	Other			Path:	0.000	0.000
5.2	# of Bridges or Culverts:	4			Road:	1000.5200	0.00000
	Total Length:	2770.000			Railroad:	0.0000	0.00
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	6.2	Corridor Development Data:		
		1011.91	448.220		Length:	1616.2400	1967.5100
		998	00	6.4	Miander Migration:	Multiple	
	Data Armoring:					<u>Old</u>	<u>New</u>
5.4	Straightening Length:	6217.97998		7.2	Bank Erosion:	None	5134.479980
	Straightening Data:						5
					Bank Height:	N.D.	7.174



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
May, 20 2024

Reach: M02				<u>Step</u>	<u>Description</u>	<u>Value</u>	
	<u>Step</u>	<u>Description</u>	<u>Value</u>	5.5	Dredging History:	None	
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:		
3.2	Grade Control:	Ledge				<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft		<u>Left</u> <u>Right</u>	Berms & Roads:	36.0600	0.0000	
			0 0	Berm:	0.0000	0.0000	
5.1	Flow Regulation - Type:	None		Path:	0.000	0.000	
	Use:			Road:	36.0600	0.00000	
5.2	# of Bridges or Culverts:	1		Railroad:	0.0000	0.00	
	Total Length:	150.000		6.2	Corridor Development Data:		
5.3	Armoring Length		<u>Left</u> <u>Right</u>	Length:	473.1900	0.0000	
			0.00000 0.00000	6.4	Miander Migration:	Migration	
	Data Armoring:	None				<u>Old</u>	<u>New</u>
5.4	Straightening Length:	0.00000		7.2	Bank Erosion:	None	0.0000000
	Straightening Data:	None			Bank Height:	N.D.	0.000

Reach: M03				<u>Step</u>	<u>Description</u>	<u>Value</u>	
	<u>Step</u>	<u>Description</u>	<u>Value</u>	5.5	Dredging History:	None	
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:		
3.2	Grade Control:	Ledge				<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft		<u>Left</u> <u>Right</u>	Berms & Roads:	1051.8600	0.0000	
			810 0	Berm:	0.0000	0.0000	
5.1	Flow Regulation - Type:	None		Path:	0.000	0.000	
	Use:			Road:	1051.8600	0.00000	
5.2	# of Bridges or Culverts:	0		Railroad:	0.0000	0.00	
	Total Length:	0.000		6.2	Corridor Development Data:		
5.3	Armoring Length		<u>Left</u> <u>Right</u>	Length:	1591.7100	0.0000	
			206.340 0.00000	6.4	Miander Migration:	Flood Chute	
	Data Armoring:					<u>Old</u>	<u>New</u>
5.4	Straightening Length:	1770.21997		7.2	Bank Erosion:	None	3826.909912
	Straightening Data:					1	
					Bank Height:	N.D.	5.332



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: M04				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	None
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	0.0000	0.0000
		0	0	Berm:	0.0000	0.0000
5.1	Flow Regulation - Type:	None		Path:	0.000	0.000
	Use:			Road:	0.0000	0.00000
5.2	# of Bridges or Culverts:	0		Railroad:	0.0000	0.00
	Total Length:	0.000		6.2	Corridor Development Data:	None
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	0.0000	0.0000
		0.00000	0.00000	6.4	Miander Migration:	Flood Chute
	Data Armoring:	None			<u>Old</u>	<u>New</u>
5.4	Straightening Length:	0.00000		7.2	Bank Erosion:	None
	Straightening Data:	None				1086.920043
						9
				Bank Height:	N.D.	4.074

Reach: M05				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	None
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	0.0000	0.0000
		0	0	Berm:	0.0000	0.0000
5.1	Flow Regulation - Type:	None		Path:	0.000	0.000
	Use:			Road:	0.0000	0.00000
5.2	# of Bridges or Culverts:	1		Railroad:	0.0000	0.00
	Total Length:	450.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	0.0000	94.4800
		0.00000	0.00000	6.4	Miander Migration:	Flood Chute
	Data Armoring:	None			<u>Old</u>	<u>New</u>
5.4	Straightening Length:	0.00000		7.2	Bank Erosion:	None
	Straightening Data:	None				2328.520019
						5
				Bank Height:	N.D.	4.645



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: M06				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History: Dredging	
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	5170.2798	0.0000
		2471	0	Berm:	294.2000	0.0000
5.1	Flow Regulation - Type:	None		Path:	0.000	0.000
	Use:			Road:	4876.0801	0.00000
5.2	# of Bridges or Culverts:	0		Railroad:	0.0000	0.00
	Total Length:	0.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	2213.7800	0.0000
		762.320	0.00000	6.4	Miander Migration:	Flood Chute
		01			<u>Old</u>	<u>New</u>
	Data Armoring:			7.2	Bank Erosion:	None
5.4	Straightening Length:	2281.19995				3752.790039
	Straightening Data:					1
				Bank Height:	N.D.	4.681

Reach: M07				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History: Dredging	
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	8052.7700	375.3700
		2049	0	Berm:	1866.0900	375.3700
5.1	Flow Regulation - Type:	None		Path:	0.000	0.000
	Use:			Road:	6186.6797	0.00000
5.2	# of Bridges or Culverts:	1		Railroad:	0.0000	0.00
	Total Length:	415.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	3574.1201	0.0000
		2530.20	557.479	6.4	Miander Migration:	Migration
		996	98		<u>Old</u>	<u>New</u>
	Data Armoring:			7.2	Bank Erosion:	None
5.4	Straightening Length:	5373.83008				1520.010009
	Straightening Data:					8
				Bank Height:	N.D.	5.845



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: M08				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	Dredging
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	1523.4600	0.0000
		350	0	Berm:	78.5900	0.0000
5.1	Flow Regulation - Type:	None		Path:	0.000	0.000
	Use:			Road:	1444.8700	0.00000
5.2	# of Bridges or Culverts:	2		Railroad:	0.0000	0.00
	Total Length:	300.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	432.8800	0.0000
		83.8800	172.649	6.4	Miander Migration:	Flood Chute
		0	99		<u>Old</u>	<u>New</u>
	Data Armoring:			7.2	Bank Erosion:	None
5.4	Straightening Length:	909.53003				2182.109863
	Straightening Data:					3
				Bank Height:	N.D.	3.898

Reach: M09				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	None
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	59.3100	0.0000
		383	503	Berm:	0.0000	0.0000
5.1	Flow Regulation - Type:	None		Path:	0.000	0.000
	Use:			Road:	59.3100	0.00000
5.2	# of Bridges or Culverts:	1		Railroad:	0.0000	0.00
	Total Length:	100.000		6.2	Corridor Development Data:	None
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	0.0000	0.0000
		0.00000	0.00000	6.4	Miander Migration:	Multiple
	Data Armoring:	None			<u>Old</u>	<u>New</u>
5.4	Straightening Length:	225.67999		7.2	Bank Erosion:	None
	Straightening Data:					575.9000244
				Bank Height:	N.D.	3.148



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: M10				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	None
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	
3.2	Grade Control:	Multiple			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	2790.1401	0.0000
		604	1906	Berm:	0.0000	0.0000
5.1	Flow Regulation - Type:	Small Run of River		Path:	0.000	0.000
	Use:	Recreation		Road:	2790.1401	0.00000
5.2	# of Bridges or Culverts:	5		Railroad:	0.0000	0.00
	Total Length:	560.000		6.2	Corridor Development Data:	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	679.4100	693.8900
		409.179	1078.01	6.4	Miander Migration:	Flood Chute
		99	001		<u>Old</u>	<u>New</u>
	Data Armoring:			7.2	Bank Erosion:	None 383.6900024
5.4	Straightening Length:	2898.42993		Bank Height:	N.D.	2.941
	Straightening Data:					

Reach: T2.01				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	Not Evaluated
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	Not Evaluated			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	0.0000	0.0000
		0	0	Berm:		
5.1	Flow Regulation - Type:	None		Path:		
	Use:			Road:		
5.2	# of Bridges or Culverts:	0		Railroad:		
	Total Length:	0.000		6.2	Corridor Development Data:	None
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	0.0000	0.0000
		0.00000	0.00000	6.4	Miander Migration:	Migration
	Data Armoring:	None			<u>Old</u>	<u>New</u>
5.4	Straightening Length:	1650.42004		7.2	Bank Erosion:	N.E.
	Straightening Data:			Bank Height:	N.D.	



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: T2-s1.01				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	Not Evaluated
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	Not Evaluated			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	0.0000	0.0000
		0	0	Berm:		
5.1	Flow Regulation - Type:	None		Path:		
	Use:			Road:		
5.2	# of Bridges or Culverts:	2		Railroad:		
	Total Length:	157.000		6.2	Corridor Development Data:	None
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	0.0000	0.0000
		0.00000	0.00000	6.4	Miander Migration:	Migration
	Data Armoring:	None			<u>Old</u>	<u>New</u>
5.4	Straightening Length:	240.92999		7.2	Bank Erosion:	N.E.
	Straightening Data:			Bank Height:	N.D.	

Reach: T2-s1.02				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	Not Evaluated
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	Not Evaluated			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:		
		0	0	Berm:		
5.1	Flow Regulation - Type:	None		Path:		
	Use:			Road:		
5.2	# of Bridges or Culverts:			Railroad:		
	Total Length:			6.2	Corridor Development Data:	None
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:		
				6.4	Miander Migration:	Migration
	Data Armoring:	None			<u>Old</u>	<u>New</u>
5.4	Straightening Length:			7.2	Bank Erosion:	N.E.
	Straightening Data:	None		Bank Height:		



Stream Geomorphic Assessment

Agency of Natural Resources

VT DEC

Vermont.gov
May, 20 2024

Reach: T2-s1.03				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	Not Evaluated
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	Not Evaluated			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	0.0000	0.0000
		0	0	Berm:		
5.1	Flow Regulation - Type:	None		Path:		
	Use:			Road:		
5.2	# of Bridges or Culverts:	1		Railroad:		
	Total Length:	39.000		6.2	Corridor Development Data:	None
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	0.0000	0.0000
		0.00000	0.00000	6.4	Miander Migration:	No Data
	Data Armoring:	None			<u>Old</u>	<u>New</u>
5.4	Straightening Length:	0.00000		7.2	Bank Erosion:	N.E.
	Straightening Data:	None			Bank Height:	N.D.

Reach: T2.02				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	Not Evaluated
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	Not Evaluated			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	0.0000	0.0000
		0	0	Berm:		
5.1	Flow Regulation - Type:	None		Path:		
	Use:			Road:		
5.2	# of Bridges or Culverts:	1		Railroad:		
	Total Length:	195.000		6.2	Corridor Development Data:	None
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	0.0000	0.0000
		0.00000	0.00000	6.4	Miander Migration:	Migration
	Data Armoring:	None			<u>Old</u>	<u>New</u>
5.4	Straightening Length:	0.00000		7.2	Bank Erosion:	N.E.
	Straightening Data:	None			Bank Height:	N.D.



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
May, 20 2024

Reach: T2.03				<u>Step</u>	<u>Description</u>	<u>Value</u>	
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	Not Evaluated	
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None	
3.2	Grade Control:	Not Evaluated				<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	0.0000	0.0000
		0	0		Berm:		
5.1	Flow Regulation - Type:	None			Path:		
	Use:				Road:		
5.2	# of Bridges or Culverts:	1			Railroad:		
	Total Length:	107.000		6.2	Corridor Development Data:	None	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000	0.0000
		0.00000	0.00000	6.4	Miander Migration:	Multiple	
	Data Armoring:	None				<u>Old</u>	<u>New</u>
5.4	Straightening Length:	0.00000		7.2	Bank Erosion:	N.E.	
	Straightening Data:	None			Bank Height:	N.D.	

Reach: T2.04				<u>Step</u>	<u>Description</u>	<u>Value</u>	
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	Not Evaluated	
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None	
3.2	Grade Control:	Not Evaluated				<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>		Berms & Roads:	0.0000	0.0000
		0	0		Berm:		
5.1	Flow Regulation - Type:	None			Path:		
	Use:				Road:		
5.2	# of Bridges or Culverts:	2			Railroad:		
	Total Length:	78.000		6.2	Corridor Development Data:	None	
5.3	Armoring Length	<u>Left</u>	<u>Right</u>		Length:	0.0000	0.0000
		0.00000	0.00000	6.4	Miander Migration:	Migration	
	Data Armoring:	None				<u>Old</u>	<u>New</u>
5.4	Straightening Length:	0.00000		7.2	Bank Erosion:	N.E.	
	Straightening Data:	None			Bank Height:	N.D.	



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
May, 20 2024

Reach: T1.01				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	Not Evaluated
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	Not Evaluated			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	0.0000	0.0000
		0	0	Berm:		
5.1	Flow Regulation - Type:	None		Path:		
	Use:			Road:		
5.2	# of Bridges or Culverts:	1		Railroad:		
	Total Length:	90.000		6.2	Corridor Development Data:	None
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	0.0000	0.0000
		0.00000	0.00000	6.4	Miander Migration:	Migration
	Data Armoring:	None			<u>Old</u>	<u>New</u>
5.4	Straightening Length:	473.42999		7.2	Bank Erosion:	N.E.
	Straightening Data:			Bank Height:	N.D.	

Reach: T1.02				<u>Step</u>	<u>Description</u>	<u>Value</u>
<u>Step</u>	<u>Description</u>	<u>Value</u>		5.5	Dredging History:	Not Evaluated
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	None			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	0.0000	0.0000
		0	0	Berm:		
5.1	Flow Regulation - Type:	None		Path:		
	Use:			Road:		
5.2	# of Bridges or Culverts:	2		Railroad:		
	Total Length:	270.000		6.2	Corridor Development Data:	None
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	0.0000	0.0000
		0.00000	0.00000	6.4	Miander Migration:	Migration
	Data Armoring:	None			<u>Old</u>	<u>New</u>
5.4	Straightening Length:	816.50000		7.2	Bank Erosion:	N.E.
	Straightening Data:			Bank Height:	N.D.	



Stream Geomorphic Assessment

Agency of Natural Resources



Vermont.gov
May, 20 2024

Reach: T1.04				<u>Step</u>	<u>Description</u>	<u>Value</u>
	<u>Step</u>	<u>Description</u>	<u>Value</u>	5.5	Dredging History:	Not Evaluated
3.1	Alluvial Fan:	Yes		6.1	Berms & Roads Data:	None
3.2	Grade Control:	Not Evaluated			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:	0.0000	0.0000
		0	0	Berm:		
5.1	Flow Regulation - Type:	None		Path:		
	Use:			Road:		
5.2	# of Bridges or Culverts:	2		Railroad:		
	Total Length:	165.000		6.2	Corridor Development Data:	None
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:	0.0000	0.0000
		0.00000	0.00000	6.4	Miander Migration:	No Data
	Data Armoring:	None			<u>Old</u>	<u>New</u>
5.4	Straightening Length:	0.00000		7.2	Bank Erosion:	N.E.
	Straightening Data:	None			Bank Height:	N.D.

Reach: T1.05				<u>Step</u>	<u>Description</u>	<u>Value</u>
	<u>Step</u>	<u>Description</u>	<u>Value</u>	5.5	Dredging History:	Not Evaluated
3.1	Alluvial Fan:	None		6.1	Berms & Roads Data:	None
3.2	Grade Control:	Not Evaluated			<u>One Side</u>	<u>Both Sides</u>
4.3	Buffer Less Than 25 ft	<u>Left</u>	<u>Right</u>	Berms & Roads:		
		0	0	Berm:		
5.1	Flow Regulation - Type:	None		Path:		
	Use:			Road:		
5.2	# of Bridges or Culverts:			Railroad:		
	Total Length:			6.2	Corridor Development Data:	None
5.3	Armoring Length	<u>Left</u>	<u>Right</u>	Length:		
				6.4	Miander Migration:	No Data
	Data Armoring:	None			<u>Old</u>	<u>New</u>
5.4	Straightening Length:			7.2	Bank Erosion:	N.E.
	Straightening Data:	None			Bank Height:	